

FRITZ!Box 6660 Cable

System > Event Log

All

27.11.21	11:43:57	Login to the FRITZ!Box user interface from the IP address 192.168.178.20.
27.11.21	11:43:27	Login to the FRITZ!Box user interface from the IP address 192.168.178.20 failed (incorrect password).
27.11.21	11:43:01	Login to the FRITZ!Box user interface from the IP address 192.168.178.20.
27.11.21	11:41:44	Cable internet synchronization starting (training). [2 messages since 27.11.21 11:36:14]
27.11.21	11:36:12	IPv6 internet connection was cleared; prefix no longer valid.
27.11.21	11:36:12	Internet connection cleared.
27.11.21	11:36:12	Cable internet not responding (no synchronization).
27.11.21	11:36:09	Internet via cable is available (synchronized with 0/1000000 kbit/s).
27.11.21	11:23:27	Internet connection established successfully. IPv4 is used over DS Lite. AFTR gateway: kllieb-af72-1.superkabel.de, IPv4 MTU: 1500.
27.11.21	11:23:27	IPv6 prefix was updated successfully. New prefix: 2a02:810b:89c0:ba::/64
27.11.21	11:23:22	IPv6 prefix obtained successfully. New prefix: 2a02:810b:89c0:ba::/64
27.11.21	11:23:22	IPv6 internet connection established successfully. IP address: 2a02:810b:8000:13:f52b:1b6:5bb6:4635
27.11.21	11:23:22	Cable internet available.
27.11.21	11:22:16	Cable internet synchronization starting (training).
27.11.21	11:22:15	IPv6 internet connection was cleared; prefix no longer valid.
27.11.21	11:22:15	Internet connection cleared.
27.11.21	11:22:15	Cable internet not responding (no synchronization).
27.11.21	11:22:12	Internet via cable is available (synchronized with 0/1000000 kbit/s).
27.11.21	11:00:25	Network device: PC-192-168-178-25, MAC: 9E:A6:7B:6F:B6:CE connected with the FRITZ!Box.
27.11.21	11:00:14	Network device: TL-WPA4220, MAC: 28:EE:52:EE:C5:3E connected with the FRITZ!Box.
27.11.21	11:00:13	Connected the powerline adapter 28:EE:52:EE:C5:3F.
27.11.21	11:00:11	Connected the powerline adapter 28:EE:52:EE:EA:19.
27.11.21	11:00:04	Network device: PC---729e-29ff-fef3-3ef5, MAC: 70:9E:29:F3:3E:F5 connected with the FRITZ!Box.
27.11.21	10:56:25	FRITZ!OS updated to 07.28. The previously used version was 07.28.

27.11.21 10:56:25 Internet connection established successfully. IPv4 is used over DS Lite. AFTR gateway: kllieb-af72-1.superkabel.de, IPv4 MTU: 1500.

27.11.21 10:56:22 The system time was updated successfully by time server 2001:41d0:a:25b3::1.

27.11.21 10:56:20 IPv6 prefix obtained successfully. New prefix: 2a02:810b:89c0:ba::/64

27.11.21 10:56:20 IPv6 internet connection established successfully. IP address: 2a02:810b:8000:13:f52b:1b6:5bb6:4635

27.11.21 10:56:14 Cable internet available.

27.11.21 10:55:49 Time server 2.europe.pool.ntp.org not responding.

27.11.21 10:55:42 Cable internet synchronization starting (training). [2 messages since 27.11.21 10:55:00]

27.11.21 10:55:00 No automatic configuration or updates by the service provider possible for this device: Connection to auto-configuration server failed.

27.11.21 10:55:00 IPv6 internet connection was cleared; prefix no longer valid.

27.11.21 10:54:59 Internet connection cleared.

27.11.21 10:54:59 Cable internet not responding (no synchronization).

27.11.21 10:54:56 Internet via cable is available (synchronized with 0/1000000 kbit/s).

27.11.21 10:54:28 Internet connection established successfully. IPv4 is used over DS Lite. AFTR gateway: kllieb-af72-1.superkabel.de, IPv4 MTU: 1500.

27.11.21 10:54:28 IPv6 prefix obtained successfully. New prefix: 2a02:810b:89c0:ba::/64

27.11.21 10:54:28 IPv6 internet connection established successfully. IP address: 2a02:810b:8000:13:f52b:1b6:5bb6:4635

27.11.21 10:54:23 Cable internet available.

27.11.21 10:54:23 Cable internet not responding (no synchronization).

27.11.21 10:54:22 Cable internet available.

27.11.21 10:54:22 Login to the FRITZ!Box user interface from the IP address 192.168.178.20.

27.11.21 10:54:11 Network device: EX3700, MAC: 02:0F:B5:18:CC:1D connected with the FRITZ!Box.

27.11.21 10:53:55 Network device: PC-192-168-178-21, MAC: F8:77:B8:5B:5E:31 connected with the FRITZ!Box.

27.11.21 10:53:22 Cable internet synchronization starting (training).