

[INFO][System] 12-10-2021 15:58:33 FSM---- Switch to Connect State.
[WARNING][VoIP] 12-10-2021 15:58:25 Registering to arcor.de with
VoIP number 03062203134 failed: Reason: Send request failed
[INFO][System] 12-10-2021 15:58:24 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 15:58:23 LAN sending RA to ff02::1
[INFO][VoIP] 12-10-2021 15:58:19 Switch to primary proxy server
arcor.de on line 0
[INFO][System] 12-10-2021 15:58:15 FSM---- Switch to Connect State.
[EMERG][WAN] 12-10-2021 15:58:14 DSL link down.
[INFO][WAN] 12-10-2021 15:58:07 WAN VDSL-DT has been stopped, please
check your PHY link
[INFO][LAN] 12-10-2021 15:58:07 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:58:07 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:58:07 Stopping VDSL interface OK.
[INFO][WAN] 12-10-2021 15:58:07 Stop WAN 10 DSL Connection
[INFO][LAN] 12-10-2021 15:58:07 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:58:07 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 15:58:07 Starting HTTP redirect OK.
[INFO][LAN] 12-10-2021 15:58:07 LAN sending RA to ff02::1
[INFO][DNS] 12-10-2021 15:58:07 DNSMasq proxy server enable redirect
[INFO][System] 12-10-2021 15:58:06 Stopping NTP Client OK.
[INFO][System] 12-10-2021 16:58:06 FSM---- Switch to Connect State.
[INFO][VoIP] 12-10-2021 16:58:06 VoIP WAN down, no available
connection
[INFO][VoIP] 12-10-2021 16:58:06 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-10-2021 16:58:06 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-10-2021 16:58:06 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-10-2021 16:58:06 ===start stop voice wan
[INFO][DNS] 12-10-2021 16:58:06 Internet DNS deactivated.
[INFO][LAN] 12-10-2021 16:58:06 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 16:58:05 Starting NTP Client OK.
[INFO][System] 12-10-2021 16:58:05 Sync up with NTP Server failed.
[INFO][System] 12-10-2021 15:58:05 Stopping NTP Client OK.
[INFO][VoIP] 12-10-2021 16:58:05 VoIP WAN down, no available
connection
[INFO][VoIP] 12-10-2021 16:58:05 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-10-2021 16:58:05 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-10-2021 16:58:05 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-10-2021 16:58:05 ===start stop voice wan
[INFO][WAN] 12-10-2021 16:58:04 WAN VDSL-DATA has been stopped,
please check your PHY link
[INFO][DNS] 12-10-2021 16:58:04 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 16:58:04 Internet DNS ready.
[INFO][DNS] 12-10-2021 16:58:04 Internet DNS Servers 176.95.16.250,
176.95.16.251.

[INFO][DNS] 12-10-2021 16:58:04 Internet DNS ready.
[INFO][DNS] 12-10-2021 16:58:04 Internet DNS deactivated.
[INFO][System] 12-10-2021 16:58:03 Starting NTP Client OK.
[INFO][System] 12-10-2021 16:58:03 Sync up with NTP Server failed.
[INFO][System] 12-10-2021 15:58:03 Stopping NTP Client OK.
[INFO][VoIP] 12-10-2021 16:58:03 VoIP WAN down, no available
connection
[INFO][VoIP] 12-10-2021 16:58:03 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-10-2021 16:58:03 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-10-2021 16:58:03 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-10-2021 16:58:03 ===start stop voice wan
[INFO][WAN] 12-10-2021 16:58:03 Stop WAN 8 DSL Connection
[INFO][DNS] 12-10-2021 16:58:03 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 16:58:03 Internet DNS ready.
[INFO][LAN] 12-10-2021 16:58:03 LAN sending RA to ff02::1
[INFO][DNS] 12-10-2021 16:58:03 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][WAN] 12-10-2021 16:58:03 Stop WAN 4 DSL Connection
[INFO][DNS] 12-10-2021 16:58:02 Internet DNS ready.
[INFO][DNS] 12-10-2021 16:58:02 Internet DNS deactivated.
[INFO][DNS] 12-10-2021 16:58:02 Internet DNS deactivated.
[INFO][WAN] 12-10-2021 16:58:02 Stop WAN 10 IP Connection
[INFO][WAN] 12-10-2021 16:58:02 IPTV WAN11 DeActivated!
[INFO][WAN] 12-10-2021 16:58:02 bud update WAN11 status to 0.
[INFO][LAN] 12-10-2021 16:58:02 LAN sending RA to ff02::1
[EMERG][WAN] 12-10-2021 16:58:02 DSL link down.
[INFO][LAN] 12-10-2021 16:57:58 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 16:57:55 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 16:57:55 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][System] 12-10-2021 16:57:50 No permission to get
wps20_enable, access right: 0x08.
[NOTICE][LAN] 12-10-2021 16:57:45 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 16:57:45 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-10-2021 16:57:42 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 15:57:41 Sync up with NTP Server
successfully.
[INFO][System] 12-10-2021 15:57:38 Sync up with NTP Server
successfully.
[INFO][System] 12-10-2021 15:57:37 No permission to get
wps20_enable, access right: 0x08.
[INFO][VoIP] 12-10-2021 15:57:31 Send data/single wan update to
VGW,wan id 10,ifName is ppp10,ipv4 address 188.96.64.186,ipv6
address ,default_wan_id 10,wan type 1
[INFO][VoIP] 12-10-2021 15:57:31 line 371 ,wan 10 start do data wan
up

```
[INFO][VoIP] 12-10-2021 15:57:31 wanipv6 = ,size = 0
[INFO][VoIP] 12-10-2021 15:57:31 Voice binding wan_id is
10,default_wan_id is 10
[INFO][VoIP] 12-10-2021 15:57:31 Voice binding wan_id is
10,default_wan_id is 10,is_ipv6 = 0
[INFO][VoIP] 12-10-2021 15:57:31 wan 10 service_type =
DATA,VOIP,MGNT,IPTV bud_voip_wan_id = 10
[INFO][VoIP] 12-10-2021 15:57:31 Interface wan_ip is 188.96.64.186,
wan_ip_v6 ,is_ipv6 0 wan up id 10
[INFO][LAN] 12-10-2021 15:57:31 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO][LAN] 12-10-2021 15:57:31 adapter index 19
[INFO][LAN] 12-10-2021 15:57:31 br1 (our ip) = 192.168.3.1
[INFO][LAN] 12-10-2021 15:57:31 Attaching option timezone to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option t2 to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option t1 to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option lease to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option dns to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option router to list
[INFO][LAN] 12-10-2021 15:57:31 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-10-2021 15:57:31 adapter index 18
[INFO][LAN] 12-10-2021 15:57:31 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-10-2021 15:57:31 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-10-2021 15:57:31 adapter index 18
[INFO][LAN] 12-10-2021 15:57:31 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-10-2021 15:57:31 Attaching option subnet to list
[INFO][LAN] 12-10-2021 15:57:31 error on select
[INFO][LAN] 12-10-2021 15:57:31 Attaching option timezone to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option t2 to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option t1 to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option lease to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option dns to existing
member of list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option dns to existing
member of list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option dns to list
[INFO][LAN] 12-10-2021 15:57:31 udhcp server receive signal 12
[INFO][LAN] 12-10-2021 15:57:31 Attaching option router to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option subnet to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option timezone to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option t2 to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option t1 to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option lease to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option dns to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option hostname to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option domain to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option router to list
[INFO][LAN] 12-10-2021 15:57:31 Attaching option subnet to list
[INFO][LAN] 12-10-2021 15:57:31 error on select
[INFO][LAN] 12-10-2021 15:57:31 udhcp server receive signal 12
[INFO][System] 12-10-2021 15:57:29 Starting MCPD OK.
[INFO][System] 12-10-2021 15:57:29 Stopping MCPD OK.
```

[INFO][UMTS] 12-10-2021 15:57:29 iPhone DNS Policy activated
[INFO][VoIP] 12-10-2021 15:57:29 276 start wan service Voice
binding wan_id is 10
[INFO][VoIP] 12-10-2021 15:57:29 Voice binding wan_id is 10
[INFO][System] 12-10-2021 15:57:29 Starting NTP Client OK.
[INFO][System] 12-10-2021 15:57:29 Sync up with NTP Server failed.
[INFO][System] 12-10-2021 15:57:29 Stopping NTP Client OK.
[INFO][Firewall] 12-10-2021 15:57:28 PortMapping Rules have been
flushed on WAN VDSL-DT.
[INFO][Firewall] 12-10-2021 15:57:28 DMZ Rules has been flushed on
WAN VDSL-DT.
[INFO][Firewall] 12-10-2021 15:57:28 Static NAT Rules have been
flushed on WAN VDSL-DT.
[INFO][System] 12-10-2021 15:57:27 Stopping HTTP redirect OK.
[INFO][DNS] 12-10-2021 15:57:27 DNSMasq proxy server disable
redirect
[INFO][DNS] 12-10-2021 15:57:27 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:57:27 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:57:27 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:57:27 Internet DNS ready.
[WARNING][DNS] 12-10-2021 15:57:27 ignoring nameserver 127.0.0.1 -
local interface
[WARNING][DNS] 12-10-2021 15:57:27 ignoring nameserver ::1 - local
interface
[INFO][DNS] 12-10-2021 15:57:27 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:57:27 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:57:27 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:57:27 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:57:27 Starting DNSMasq proxy server OK.
[INFO][DNS] 12-10-2021 15:57:27 Stopping DNSMasq proxy OK.
[INFO][System] 12-10-2021 15:57:26 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 15:57:26 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:57:26 LAN sending RA to ff02::1
[INFO][DNS] 12-10-2021 15:57:26 DNSMasq proxy server disable
redirect
[INFO][UMTS] 12-10-2021 15:57:25 iPhone DNS Policy activated
[INFO][VoIP] 12-10-2021 15:57:25 Remove interface wan_id is 10,wan
type 2.
[INFO][VoIP] 12-10-2021 15:57:25 VoIP WAN down, Voice trying to run
in backup mode, try binding wan_id is 10
[INFO][VoIP] 12-10-2021 15:57:25 bud data ipv4 wan status 10,ipv6
wan status -1
[INFO][VoIP] 12-10-2021 15:57:25 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-10-2021 15:57:25 ignore useless wan down
[INFO][VoIP] 12-10-2021 15:57:25 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-10-2021 15:57:25 ===start stop voice wan

[INFO][VoIP] 12-10-2021 15:57:25 ===start stop voice wan
[INFO][System] 12-10-2021 15:57:25 Starting MCPD OK.
[INFO][System] 12-10-2021 15:57:25 Stopping MCPD OK.
[INFO][VoIP] 12-10-2021 15:57:24 ignore useless wan down
[INFO][VoIP] 12-10-2021 15:57:24 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-10-2021 15:57:24 ===start stop voice wan
[NOTICE][LAN] 12-10-2021 15:57:24 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:57:24 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][WAN] 12-10-2021 15:57:24 Stop WAN 8 IP Connection
[INFO][DNS] 12-10-2021 15:57:24 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:57:24 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:57:24 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:57:24 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:57:24 Internet DNS deactivated.
[WARNING][WAN] 12-10-2021 15:57:23 WAN default route add to ppp10
gateway 84.59.211.1.
[INFO][WAN] 12-10-2021 15:57:23 Data WAN11 Activated!
[INFO][WAN] 12-10-2021 15:57:23 bud update WAN11 status to 2.
[WARNING][WAN] 12-10-2021 15:57:22 WAN VDSL-DT is up, mode is PPPoE,
IP is 188.96.64.186.
[WARNING][WAN] 12-10-2021 15:57:22 WAN VDSL-DT is down.
[INFO][WAN] 12-10-2021 15:57:22 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][LAN] 12-10-2021 15:57:22 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:57:22 PPP CHAP MD5 authentication is
successful on WAN VDSL-DT
[INFO][LAN] 12-10-2021 15:57:22 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:57:22 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:57:22 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:57:22 PPPoE PADS has been received from
WAN VDSL-DT
[INFO][WAN] 12-10-2021 15:57:22 PPPoE PADR has been sent from WAN
VDSL-DT
[INFO][WAN] 12-10-2021 15:57:22 PPPoE PADO has been received from
WAN VDSL-DT, BRAS name is BLNCOS69101.
[INFO][WAN] 12-10-2021 15:57:22 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-10-2021 15:57:19 FSM---- Switch to Connect State.
[NOTICE][LAN] 12-10-2021 15:57:11 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:57:10 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][System] 12-10-2021 15:57:09 FSM---- Switch to Connect State.
[INFO][WAN] 12-10-2021 15:57:05 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-10-2021 15:57:05 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-10-2021 15:56:59 FSM---- Switch to Connect State.

[INFO][System] 12-10-2021 15:56:49 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 15:56:44 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 15:56:39 User 'vodafone' login
successfully via HTTP from 192.168.2.100
[INFO][System] 12-10-2021 15:56:38 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 15:56:28 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 15:56:28 LAN sending RA to ff02::1
[EMERG][WAN] 12-10-2021 15:56:27 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:27 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:26 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:26 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:25 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:25 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:24 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:24 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:24 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:23 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:23 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:22 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:21 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:21 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:21 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:20 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:20 DSL link up.
[INFO][LAN] 12-10-2021 15:56:19 Successfully assign IP
[192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time
[86400]
[INFO][LAN] 12-10-2021 15:56:19 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 15:56:19 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 15:56:19 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-10-2021 15:56:19 Received REQUEST from client ip
[0.0.0.0] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-10-2021 15:56:19 Received a packet
[EMERG][WAN] 12-10-2021 15:56:19 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:19 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:18 DSL link up.
[INFO][System] 12-10-2021 15:56:18 FSM---- Switch to Connect State.
[EMERG][WAN] 12-10-2021 15:56:18 DSL link up.
[NOTICE][LAN] 12-10-2021 15:56:18 wl1: AP-STA-CONNECTED
50:ed:3c:2f:b6:42
[NOTICE][LAN] 12-10-2021 15:56:18 wl0: AP-STA-DISCONNECTED
50:ed:3c:2f:b6:42
[EMERG][WAN] 12-10-2021 15:56:17 DSL link up.
[EMERG][WAN] 12-10-2021 15:56:14 DSL link up.
[INFO][LAN] 12-10-2021 15:56:12 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 15:56:11 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:56:11 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][WAN] 12-10-2021 15:56:09 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-10-2021 15:56:09 PPPoE PADI has been sent from WAN

VDSL-DT

[INFO][System] 12-10-2021 15:56:08 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 15:55:58 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 15:55:56 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:55:56 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:55:56 PPPoE PADI has been sent from WAN

VDSL-DATA

[INFO][LAN] 12-10-2021 15:55:56 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:55:56 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:55:56 PPPoE PADI has been sent from WAN

VDSL-DT

[INFO][LAN] 12-10-2021 15:55:56 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:55:55 Start WAN 8 IP Connection
[INFO][LAN] 12-10-2021 15:55:55 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:55:55 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:55:55 WAN VDSL-DATA has been started, PHY link up

[INFO][LAN] 12-10-2021 15:55:55 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:55:55 Start WAN 10 IP Connection
[INFO][WAN] 12-10-2021 15:55:55 WAN VDSL-DT has been started, PHY link up

[INFO][LAN] 12-10-2021 15:55:55 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:55:54 Start WAN 8 DSL Connection
[INFO][WAN] 12-10-2021 15:55:54 Start WAN 4 DSL Connection
[INFO][LAN] 12-10-2021 15:55:54 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:55:54 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:55:54 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:55:54 Starting VDSL interface OK.
[INFO][WAN] 12-10-2021 15:55:54 Start WAN 10 DSL Connection

[EMERG][WAN] 12-10-2021 15:55:54 DSL link up.

[INFO][System] 12-10-2021 15:55:48 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 15:55:39 FSM---- Switch to Connect State.
[NOTICE][LAN] 12-10-2021 15:55:35 w11: AP-STA-CONNECTED

bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-10-2021 15:55:35 w10: AP-STA-DISCONNECTED

bc:a5:8b:27:2d:ac

[INFO][System] 12-10-2021 15:55:28 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 15:55:18 FSM---- Switch to Connect State.
[NOTICE][LAN] 12-10-2021 15:55:14 w10: AP-STA-CONNECTED

bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-10-2021 15:55:14 w11: AP-STA-DISCONNECTED

bc:a5:8b:27:2d:ac

[INFO][System] 12-10-2021 15:55:07 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 15:54:58 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 15:54:48 FSM---- Switch to Connect State.

[INFO][LAN] 12-10-2021 15:54:48 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 15:54:38 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 15:54:32 LAN sending RA to ff02::1

[INFO][System] 12-10-2021 15:54:29 FSM---- Switch to Connect State.
[NOTICE][LAN] 12-10-2021 15:54:27 w11: AP-STA-CONNECTED

bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-10-2021 15:54:27 w10: AP-STA-DISCONNECTED

bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-10-2021 15:54:22 w10: AP-STA-CONNECTED

bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:54:22 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:54:21 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:54:21 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:54:21 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:54:21 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][System] 12-10-2021 15:54:20 FSM---- Switch to Connect State.
[NOTICE][LAN] 12-10-2021 15:54:18 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:54:18 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:54:18 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:54:18 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-10-2021 15:54:16 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 15:54:15 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:54:15 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:54:15 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:54:14 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][System] 12-10-2021 15:54:10 FSM---- Switch to Connect State.
[EMERG][WAN] 12-10-2021 15:54:07 DSL link down.
[INFO][System] 12-10-2021 15:54:02 FSM---- Switch to Connect State.
[INFO][WAN] 12-10-2021 15:54:00 WAN VDSL-DT has been stopped, please
check your PHY link
[INFO][LAN] 12-10-2021 15:54:00 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:54:00 LAN sending RA to ff02::1
[WARNING][Firewall] 12-10-2021 15:54:00 SRC=192.168.2.106
DST=40.101.12.2 PROTO=TCP SPT=56916 DPT=443 MARK=0x3 DROP
[INFO][WAN] 12-10-2021 15:54:00 Stopping VDSL interface OK.
[INFO][WAN] 12-10-2021 15:53:59 Stop WAN 10 DSL Connection
[INFO][LAN] 12-10-2021 15:53:59 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:53:59 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:53:59 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 15:53:59 Starting HTTP redirect OK.
[INFO][DNS] 12-10-2021 15:53:59 DNSMasq proxy server enable redirect
[INFO][System] 12-10-2021 15:53:59 Stopping NTP Client OK.
[INFO][VoIP] 12-10-2021 15:53:59 VoIP WAN down, no available
connection
[INFO][VoIP] 12-10-2021 15:53:59 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-10-2021 15:53:59 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-10-2021 15:53:59 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =


```
0,default_wan_id= 10
[INFO][VoIP] 12-10-2021 15:53:59 ===start stop voice wan
[INFO][DNS] 12-10-2021 15:53:58 Internet DNS deactivated.
[INFO][LAN] 12-10-2021 15:53:58 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 15:53:58 Starting NTP Client OK.
[INFO][System] 12-10-2021 15:53:58 Sync up with NTP Server failed.
[INFO][System] 12-10-2021 15:53:58 Stopping NTP Client OK.
[INFO][VoIP] 12-10-2021 15:53:58 VoIP WAN down, no available
connection
[INFO][VoIP] 12-10-2021 15:53:58 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-10-2021 15:53:58 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-10-2021 15:53:58 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-10-2021 15:53:58 ===start stop voice wan
[INFO][DNS] 12-10-2021 15:53:57 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:53:57 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:53:57 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:53:57 Internet DNS ready.
[INFO][WAN] 12-10-2021 15:53:57 WAN VDSL-DATA has been stopped,
please check your PHY link
[INFO][DNS] 12-10-2021 15:53:57 Internet DNS deactivated.
[INFO][System] 12-10-2021 15:53:57 Starting NTP Client OK.
[INFO][System] 12-10-2021 15:53:57 Sync up with NTP Server failed.
[INFO][System] 12-10-2021 15:53:57 Stopping NTP Client OK.
[INFO][VoIP] 12-10-2021 15:53:57 VoIP WAN down, no available
connection
[INFO][VoIP] 12-10-2021 15:53:57 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-10-2021 15:53:57 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-10-2021 15:53:57 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-10-2021 15:53:56 ===start stop voice wan
[INFO][LAN] 12-10-2021 15:53:56 LAN sending RA to ff02::1
[WARNING][Firewall] 12-10-2021 15:53:56 SRC=192.168.2.106
DST=40.101.12.2 PROTO=TCP SPT=56916 DPT=443 MARK=0x3 DROP
[INFO][WAN] 12-10-2021 15:53:56 Stop WAN 8 DSL Connection
[INFO][DNS] 12-10-2021 15:53:56 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:53:56 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:53:56 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:53:56 Internet DNS ready.
[INFO][WAN] 12-10-2021 15:53:56 Stop WAN 4 DSL Connection
[INFO][DNS] 12-10-2021 15:53:56 Internet DNS deactivated.
[INFO][DNS] 12-10-2021 15:53:56 Internet DNS deactivated.
[INFO][WAN] 12-10-2021 15:53:56 Stop WAN 10 IP Connection
[INFO][WAN] 12-10-2021 15:53:56 IPTV WAN11 DeActivated!
```

[INFO][WAN] 12-10-2021 15:53:56 bud update WAN11 status to 0.
[INFO][LAN] 12-10-2021 15:53:55 LAN sending RA to ff02::1
[EMERG][WAN] 12-10-2021 15:53:55 DSL link down.
[WARNING][Firewall] 12-10-2021 15:53:55 SRC=192.168.2.106
DST=40.101.12.2 PROTO=TCP SPT=56916 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:53:55 SRC=192.168.2.106
DST=40.101.12.2 PROTO=TCP SPT=56916 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 15:51:01 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:51:01 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:50:06 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:50:06 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.19.213.33 PROTO=TCP SPT=56926 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.19.213.33 PROTO=TCP SPT=56926 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=92.122.76.107 PROTO=TCP SPT=56911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.22.241.88 PROTO=TCP SPT=53018 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.19.213.33 PROTO=TCP SPT=56926 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.19.213.33 PROTO=TCP SPT=56926 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.19.213.33 PROTO=TCP SPT=56926 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.19.213.33 PROTO=TCP SPT=56926 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.19.213.33 PROTO=TCP SPT=56926 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=92.122.76.107 PROTO=TCP SPT=56911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.22.241.88 PROTO=TCP SPT=53018 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56906 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56905 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=92.122.76.107 PROTO=TCP SPT=56911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.22.241.88 PROTO=TCP SPT=53018 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=92.122.76.107 PROTO=TCP SPT=56911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.22.241.88 PROTO=TCP SPT=53018 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=92.122.76.107 PROTO=TCP SPT=56911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.22.241.88 PROTO=TCP SPT=53018 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106

DST=92.122.76.107 PROTO=TCP SPT=56911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.22.241.88 PROTO=TCP SPT=53018 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=92.122.76.107 PROTO=TCP SPT=56911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=2.22.241.88 PROTO=TCP SPT=53018 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56906 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56905 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56905 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56906 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56906 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56905 DPT=443 MARK=0x3 DROP
[EMERG][Firewall] 12-10-2021 15:50:06 DoS attack: SYN With Data
Attack from source: 193.46.255.152:5061
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=52.222.179.113 PROTO=TCP SPT=57777 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56906 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56905 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56905 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56906 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56905 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=13.107.21.200 PROTO=TCP SPT=56906 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=52.222.179.113 PROTO=TCP SPT=57777 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=52.222.179.113 PROTO=TCP SPT=57777 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=52.222.179.113 PROTO=TCP SPT=57777 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:50:06 SRC=192.168.2.106
DST=52.222.179.113 PROTO=TCP SPT=57777 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 15:49:43 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 15:46:05 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 15:44:57 LAN sending RA to ff02::1
[ERROR][System] 12-10-2021 15:44:53 TR069 connects to ACS server
failed, http error 503.
[INFO][System] 12-10-2021 15:44:52 FSM---- Switch to Connect State.
[INFO][VoIP] 12-10-2021 15:44:46 Switch to primary proxy server
arcor.de on line 0
[INFO][LAN] 12-10-2021 15:44:41 LAN sending RA to ff02::1

```
[ERROR][System] 12-10-2021 15:44:28 TR069 connects to ACS server
failed, http error 503.
[INFO][System] 12-10-2021 15:44:26 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 15:44:25 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 15:44:24 Sync up with NTP Server
successfully.
[INFO][System] 12-10-2021 15:44:21 Sync up with NTP Server
successfully.
[INFO][VoIP] 12-10-2021 15:44:14 Send data/single wan update to
VGW,wan id 10,ifName is ppp10,ipv4 address 178.14.78.81,ipv6
address ,default_wan_id 10,wan type 1
[INFO][VoIP] 12-10-2021 15:44:14 line 371 ,wan 10 start do data wan
up
[INFO][VoIP] 12-10-2021 15:44:14 wanipv6 = ,size = 0
[INFO][VoIP] 12-10-2021 15:44:14 Voice binding wan_id is
10,default_wan_id is 10
[INFO][VoIP] 12-10-2021 15:44:14 Voice binding wan_id is
10,default_wan_id is 10,is_ipv6 = 0
[INFO][VoIP] 12-10-2021 15:44:14 wan 10 service_type =
DATA,VOIP,MGNT,IPTV bud_voip_wan_id = 10
[INFO][VoIP] 12-10-2021 15:44:14 Interface wan_ip is 178.14.78.81,
wan_ip_v6 ,is_ipv6 0 wan up id 10
[INFO][LAN] 12-10-2021 15:44:13 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-10-2021 15:44:13 adapter index 18
[INFO][LAN] 12-10-2021 15:44:13 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-10-2021 15:44:13 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-10-2021 15:44:13 adapter index 18
[INFO][LAN] 12-10-2021 15:44:13 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-10-2021 15:44:13 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO][LAN] 12-10-2021 15:44:13 adapter index 19
[INFO][LAN] 12-10-2021 15:44:13 br1 (our ip) = 192.168.3.1
[INFO][LAN] 12-10-2021 15:44:13 Attaching option timezone to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option t2 to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option t1 to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option lease to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option dns to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option router to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option subnet to list
[INFO][LAN] 12-10-2021 15:44:13 error on select
[INFO][LAN] 12-10-2021 15:44:13 udhcp server receive signal 12
[INFO][LAN] 12-10-2021 15:44:13 Attaching option timezone to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option t2 to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option t1 to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option lease to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option dns to existing
member of list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option dns to existing
member of list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option dns to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option router to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option subnet to list
```

```
[INFO][LAN] 12-10-2021 15:44:13 Attaching option timezone to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option t2 to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option t1 to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option lease to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option dns to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option hostname to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option domain to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option router to list
[INFO][LAN] 12-10-2021 15:44:13 Attaching option subnet to list
[INFO][LAN] 12-10-2021 15:44:13 error on select
[INFO][LAN] 12-10-2021 15:44:13 udhcp server receive signal 12
[INFO][System] 12-10-2021 15:44:12 Starting MCPD OK.
[INFO][System] 12-10-2021 15:44:12 Stopping MCPD OK.
[INFO][UMTS] 12-10-2021 15:44:12 iPhone DNS Policy activated
[INFO][VoIP] 12-10-2021 15:44:11 276 start wan service Voice
binding wan_id is 10
[INFO][VoIP] 12-10-2021 15:44:11 Voice binding wan_id is 10
[INFO][System] 12-10-2021 15:44:11 Starting NTP Client OK.
[INFO][System] 12-10-2021 15:44:11 Sync up with NTP Server failed.
[INFO][System] 12-10-2021 15:44:11 Stopping NTP Client OK.
[INFO][Firewall] 12-10-2021 15:44:11 PortMapping Rules have been
flushed on WAN VDSL-DT.
[INFO][Firewall] 12-10-2021 15:44:11 DMZ Rules has been flushed on
WAN VDSL-DT.
[INFO][Firewall] 12-10-2021 15:44:11 Static NAT Rules have been
flushed on WAN VDSL-DT.
[INFO][System] 12-10-2021 15:44:11 Stopping HTTP redirect OK.
[INFO][DNS] 12-10-2021 15:44:11 DNSMasq proxy server disable
redirect
[ERROR][DNS] 12-10-2021 15:44:11 failed to load names from /tmp/
dnsmasq_hosts.d/data_hosts: No such file or directory
[INFO][DNS] 12-10-2021 15:44:10 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:44:10 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:44:10 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:44:10 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:44:10 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:44:10 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:44:10 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 15:44:10 Internet DNS ready.
[WARNING][DNS] 12-10-2021 15:44:10 ignoring nameserver 127.0.0.1 -
local interface
[WARNING][DNS] 12-10-2021 15:44:10 ignoring nameserver ::1 - local
interface
[INFO][DNS] 12-10-2021 15:44:10 Starting DNSMasq proxy server OK.
[INFO][DNS] 12-10-2021 15:44:10 Stopping DNSMasq proxy OK.
[INFO][DNS] 12-10-2021 15:44:09 DNSMasq proxy server disable
redirect
[INFO][LAN] 12-10-2021 15:44:09 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:44:09 LAN sending RA to ff02::1
[INFO][UMTS] 12-10-2021 15:44:08 iPhone DNS Policy activated
```

[INFO][VoIP] 12-10-2021 15:44:08 Remove interface wan_id is 10,wan type 2.
[INFO][VoIP] 12-10-2021 15:44:08 VoIP WAN down, Voice trying to run in backup mode, try binding wan_id is 10
[INFO][VoIP] 12-10-2021 15:44:08 bud data ipv4 wan status 10,ipv6 wan status -1
[INFO][VoIP] 12-10-2021 15:44:08 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 = 0,default_wan_id= 10
[INFO][VoIP] 12-10-2021 15:44:08 ===start stop voice wan
[INFO][System] 12-10-2021 15:44:08 Starting MCPD OK.
[INFO][System] 12-10-2021 15:44:08 Stopping MCPD OK.
[INFO][VoIP] 12-10-2021 15:44:08 ignore useless wan down
[INFO][VoIP] 12-10-2021 15:44:08 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 = 0,default_wan_id= 10
[INFO][VoIP] 12-10-2021 15:44:08 ===start stop voice wan
[ERROR][System] 12-10-2021 15:44:07 TR069 connects to ACS server failed, http error 503.
[INFO][DNS] 12-10-2021 15:44:07 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-10-2021 15:44:07 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:44:07 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-10-2021 15:44:07 Internet DNS ready.
[INFO][VoIP] 12-10-2021 15:44:07 ignore useless wan down
[INFO][VoIP] 12-10-2021 15:44:07 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 = 1,default_wan_id= 10
[INFO][VoIP] 12-10-2021 15:44:07 ===start stop voice wan
[INFO][DNS] 12-10-2021 15:44:06 Internet DNS deactivated.
[INFO][WAN] 12-10-2021 15:44:06 Stop WAN 8 IP Connection
[WARNING][WAN] 12-10-2021 15:44:06 WAN default route add to ppp10 gateway 84.59.211.1.
[INFO][WAN] 12-10-2021 15:44:06 Data WAN11 Activated!
[INFO][WAN] 12-10-2021 15:44:06 bud update WAN11 status to 2.
[INFO][System] 12-10-2021 15:44:05 FSM---- Switch to Connect State.
[WARNING][WAN] 12-10-2021 15:44:05 WAN VDSL-DT is up, mode is PPPoE, IP is 178.14.78.81.
[WARNING][WAN] 12-10-2021 15:44:05 WAN VDSL-DT is down.
[INFO][LAN] 12-10-2021 15:44:05 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:44:05 PPP CHAP MD5 authentication is successful on WAN VDSL-DT
[INFO][LAN] 12-10-2021 15:44:05 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:44:05 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:44:05 PPPoE PADI has been sent from WAN VDSL-DATA
[INFO][LAN] 12-10-2021 15:44:05 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:44:05 PPPoE PADS has been received from WAN VDSL-DT
[INFO][WAN] 12-10-2021 15:44:05 PPPoE PADR has been sent from WAN VDSL-DT
[INFO][WAN] 12-10-2021 15:44:05 PPPoE PADO has been received from WAN VDSL-DT, BRAS name is BLNCOS69101.

[INFO][WAN] 12-10-2021 15:44:05 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-10-2021 15:44:01 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 15:43:52 FSM---- Switch to Connect State.
[INFO][WAN] 12-10-2021 15:43:48 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-10-2021 15:43:48 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-10-2021 15:43:43 FSM---- Switch to Connect State.
[NOTICE][LAN] 12-10-2021 15:43:35 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:43:35 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][System] 12-10-2021 15:43:33 FSM---- Switch to Connect State.
[EMERG][WAN] 12-10-2021 15:43:32 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:32 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:32 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:31 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:31 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:30 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:30 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:29 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:29 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:29 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:28 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:28 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:27 DSL link up.
[INFO][LAN] 12-10-2021 15:43:27 LAN sending RA to ff02::1
[EMERG][WAN] 12-10-2021 15:43:26 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:26 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:26 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:25 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:25 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:24 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:24 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:23 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:23 DSL link up.
[EMERG][WAN] 12-10-2021 15:43:23 DSL link up.
[INFO][System] 12-10-2021 15:43:22 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 15:43:11 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 15:43:11 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 15:43:01 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 15:42:55 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 15:42:52 FSM---- Switch to Connect State.
[INFO][WAN] 12-10-2021 15:42:52 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-10-2021 15:42:51 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-10-2021 15:42:41 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 15:42:39 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 15:42:39 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-10-2021 15:42:38 PPPoE PADI has been sent from WAN
VDSL-DT

```
[INFO] [LAN] 12-10-2021 15:42:38 LAN sending RA to ff02::1
[INFO] [LAN] 12-10-2021 15:42:38 LAN sending RA to ff02::1
[INFO] [LAN] 12-10-2021 15:42:38 LAN sending RA to ff02::1
[INFO] [LAN] 12-10-2021 15:42:38 LAN sending RA to ff02::1
[INFO] [LAN] 12-10-2021 15:42:38 LAN sending RA to ff02::1
[INFO] [LAN] 12-10-2021 15:42:38 LAN sending RA to ff02::1
[INFO] [WAN] 12-10-2021 15:42:38 Start WAN 8 IP Connection
[INFO] [WAN] 12-10-2021 15:42:38 WAN VDSL-DATA has been started, PHY
link up
[INFO] [WAN] 12-10-2021 15:42:38 Start WAN 10 IP Connection
[INFO] [WAN] 12-10-2021 15:42:38 WAN VDSL-DT has been started, PHY
link up
[INFO] [WAN] 12-10-2021 15:42:37 Start WAN 4 DSL Connection
[INFO] [WAN] 12-10-2021 15:42:37 Start WAN 8 DSL Connection
[INFO] [LAN] 12-10-2021 15:42:37 LAN sending RA to ff02::1
[INFO] [LAN] 12-10-2021 15:42:37 LAN sending RA to ff02::1
[INFO] [LAN] 12-10-2021 15:42:36 LAN sending RA to ff02::1
[INFO] [WAN] 12-10-2021 15:42:36 Starting VDSL interface OK.
[INFO] [WAN] 12-10-2021 15:42:36 Start WAN 10 DSL Connection
[EMERG] [WAN] 12-10-2021 15:42:36 DSL link up.
[INFO] [System] 12-10-2021 15:42:31 FSM---- Switch to Connect State.
[INFO] [System] 12-10-2021 15:42:20 FSM---- Switch to Connect State.
[INFO] [System] 12-10-2021 15:42:10 FSM---- Switch to Connect State.
[INFO] [System] 12-10-2021 15:42:01 FSM---- Switch to Connect State.
[INFO] [System] 12-10-2021 15:41:52 FSM---- Switch to Connect State.
[INFO] [System] 12-10-2021 15:41:42 FSM---- Switch to Connect State.
[INFO] [System] 12-10-2021 15:41:33 FSM---- Switch to Connect State.
[INFO] [LAN] 12-10-2021 15:41:29 LAN sending RA to ff02::1
[INFO] [System] 12-10-2021 15:41:23 FSM---- Switch to Connect State.
[INFO] [LAN] 12-10-2021 15:41:13 LAN sending RA to ff02::1
[INFO] [System] 12-10-2021 15:41:12 FSM---- Switch to Connect State.
[INFO] [System] 12-10-2021 15:41:01 FSM---- Switch to Connect State.
[INFO] [LAN] 12-10-2021 15:40:57 LAN sending RA to ff02::1
[INFO] [System] 12-10-2021 15:40:52 FSM---- Switch to Connect State.
[EMERG] [WAN] 12-10-2021 15:40:48 DSL link down.
[INFO] [WAN] 12-10-2021 15:40:41 WAN VDSL-DT has been stopped, please
check your PHY link
[INFO] [LAN] 12-10-2021 15:40:41 LAN sending RA to ff02::1
[INFO] [LAN] 12-10-2021 15:40:41 LAN sending RA to ff02::1
[INFO] [WAN] 12-10-2021 15:40:41 Stopping VDSL interface OK.
[INFO] [WAN] 12-10-2021 15:40:41 Stop WAN 10 DSL Connection
[INFO] [LAN] 12-10-2021 15:40:41 LAN sending RA to ff02::1
[INFO] [LAN] 12-10-2021 15:40:41 LAN sending RA to ff02::1
[INFO] [LAN] 12-10-2021 15:40:41 LAN sending RA to ff02::1
[INFO] [System] 12-10-2021 15:40:41 Starting HTTP redirect OK.
[INFO] [System] 12-10-2021 15:40:41 FSM---- Switch to Connect State.
[INFO] [DNS] 12-10-2021 15:40:40 DNSMasq proxy server enable redirect
[INFO] [System] 12-10-2021 15:40:40 Stopping NTP Client OK.
[INFO] [VoIP] 12-10-2021 15:40:40 VoIP WAN down, no available
connection
[INFO] [VoIP] 12-10-2021 15:40:40 Remove interface wan_id is 10,wan
type 1.
[INFO] [VoIP] 12-10-2021 15:40:40 bud data ipv4 wan status -1,ipv6
wan status -1
```


[INFO][VoIP] 12-10-2021 15:40:40 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 10, is_ipv6 = 0, default_wan_id= 10
[INFO][VoIP] 12-10-2021 15:40:40 ===start stop voice wan
[INFO][DNS] 12-10-2021 15:40:40 Internet DNS deactivated.
[INFO][LAN] 12-10-2021 15:40:40 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 15:40:39 Starting NTP Client OK.
[INFO][System] 12-10-2021 15:40:39 Sync up with NTP Server failed.
[INFO][System] 12-10-2021 15:40:39 Stopping NTP Client OK.
[INFO][VoIP] 12-10-2021 15:40:39 VoIP WAN down, no available connection
[INFO][VoIP] 12-10-2021 15:40:39 Remove interface wan_id is 10, wan type 1.
[INFO][VoIP] 12-10-2021 15:40:39 bud data ipv4 wan status -1, ipv6 wan status -1
[INFO][VoIP] 12-10-2021 15:40:39 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 10, is_ipv6 = 0, default_wan_id= 10
[INFO][VoIP] 12-10-2021 15:40:39 ===start stop voice wan
[INFO][DNS] 12-10-2021 15:40:38 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-10-2021 15:40:38 Internet DNS ready.
[INFO][WAN] 12-10-2021 15:40:38 WAN VDSL-DATA has been stopped, please check your PHY link
[INFO][DNS] 12-10-2021 15:40:38 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-10-2021 15:40:38 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:40:38 Internet DNS deactivated.
[INFO][System] 12-10-2021 15:40:38 Starting NTP Client OK.
[INFO][System] 12-10-2021 15:40:38 Sync up with NTP Server failed.
[INFO][System] 12-10-2021 15:40:38 Stopping NTP Client OK.
[INFO][VoIP] 12-10-2021 15:40:37 VoIP WAN down, no available connection
[INFO][VoIP] 12-10-2021 15:40:37 Remove interface wan_id is 10, wan type 1.
[INFO][VoIP] 12-10-2021 15:40:37 bud data ipv4 wan status -1, ipv6 wan status -1
[INFO][VoIP] 12-10-2021 15:40:37 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 10, is_ipv6 = 1, default_wan_id= 10
[INFO][VoIP] 12-10-2021 15:40:37 ===start stop voice wan
[INFO][WAN] 12-10-2021 15:40:37 Stop WAN 8 DSL Connection
[INFO][DNS] 12-10-2021 15:40:37 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-10-2021 15:40:37 Internet DNS ready.
[INFO][LAN] 12-10-2021 15:40:37 LAN sending RA to ff02::1
[INFO][DNS] 12-10-2021 15:40:37 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-10-2021 15:40:37 Internet DNS ready.
[INFO][DNS] 12-10-2021 15:40:37 Internet DNS deactivated.
[INFO][DNS] 12-10-2021 15:40:37 Internet DNS deactivated.
[INFO][WAN] 12-10-2021 15:40:37 Stop WAN 10 IP Connection
[INFO][WAN] 12-10-2021 15:40:37 IPTV WAN11 DeActivated!
[INFO][WAN] 12-10-2021 15:40:37 bud update WAN11 status to 0.

[INFO][WAN] 12-10-2021 15:40:36 Stop WAN 4 DSL Connection
[INFO][LAN] 12-10-2021 15:40:36 LAN sending RA to ff02::1
[EMERG][WAN] 12-10-2021 15:40:36 DSL link down.
[INFO][LAN] 12-10-2021 15:40:11 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:40:07 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:40:03 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:40:02 Transmit reply to
fe80::2437:8029:575f:331b%br0 on LAN
[INFO][LAN] 12-10-2021 15:40:02 Received information request from
fe80::2437:8029:575f:331b%br0 on LAN
[INFO][LAN] 12-10-2021 15:40:02 Successfully assign IP
[192.168.2.106] to client mac [9c:b6:d0:20:44:69], lease time
[86400]
[INFO][LAN] 12-10-2021 15:40:02 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 15:40:02 Received REQUEST from client ip
[0.0.0.0] mac [9c:b6:d0:20:44:69]
[INFO][LAN] 12-10-2021 15:40:02 Received a packet
[NOTICE][LAN] 12-10-2021 15:40:02 wl0: AP-STA-CONNECTED
9c:b6:d0:20:44:69
[NOTICE][LAN] 12-10-2021 15:40:02 wl0: AP-STA-DISCONNECTED
9c:b6:d0:20:44:69
[NOTICE][LAN] 12-10-2021 15:39:55 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:39:55 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-10-2021 15:39:55 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:39:51 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:39:47 Transmit reply to
fe80::2437:8029:575f:331b%br0 on LAN
[INFO][LAN] 12-10-2021 15:39:47 Received information request from
fe80::2437:8029:575f:331b%br0 on LAN
[INFO][LAN] 12-10-2021 15:39:47 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:39:46 Transmit reply to
fe80::2437:8029:575f:331b%br0 on LAN
[INFO][LAN] 12-10-2021 15:39:46 Received information request from
fe80::2437:8029:575f:331b%br0 on LAN
[INFO][LAN] 12-10-2021 15:39:46 Successfully assign IP
[192.168.2.106] to client mac [9c:b6:d0:20:44:69], lease time
[86400]
[INFO][LAN] 12-10-2021 15:39:46 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 15:39:46 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 15:39:46 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-10-2021 15:39:46 Transmit advertise to
fe80::2437:8029:575f:331b%br0 on LAN
[INFO][LAN] 12-10-2021 15:39:46 Received solicit from
fe80::2437:8029:575f:331b%br0 on LAN
[INFO][LAN] 12-10-2021 15:39:46 Received REQUEST from client ip
[0.0.0.0] mac [9c:b6:d0:20:44:69]
[INFO][LAN] 12-10-2021 15:39:46 Received a packet
[NOTICE][LAN] 12-10-2021 15:39:46 wl0: AP-STA-CONNECTED
9c:b6:d0:20:44:69
[INFO][LAN] 12-10-2021 15:39:30 LAN sending RA to ff02::1

[INFO][LAN] 12-10-2021 15:39:14 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:38:58 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:38:42 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:38:42 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:38:42 LAN sending RA to ff02::1
[EMERG][LAN] 12-10-2021 15:38:42 LAN2 Link DOWN.
[NOTICE][LAN] 12-10-2021 15:37:50 wl0: AP-STA-DISCONNECTED
9c:b6:d0:20:44:69
[INFO][LAN] 12-10-2021 15:37:50 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:37:47 Successfully assign IP
[192.168.2.107] to client mac [d4:5d:df:04:2f:31], lease time
[86400]
[INFO][LAN] 12-10-2021 15:37:47 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 15:37:47 server_id = c0a80201
[INFO][LAN] 12-10-2021 15:37:47 Received REQUEST from client ip
[0.0.0.0] mac [d4:5d:df:04:2f:31]
[INFO][LAN] 12-10-2021 15:37:47 Received a packet
[INFO][LAN] 12-10-2021 15:37:47 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 15:37:47 Send OFFER of ip [192.168.2.107] to
client mac [d4:5d:df:04:2f:31]
[INFO][LAN] 12-10-2021 15:37:47 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 15:37:46 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:37:45 Received DISCOVER from client mac
[d4:5d:df:04:2f:31]
[INFO][LAN] 12-10-2021 15:37:45 Received a packet
[INFO][LAN] 12-10-2021 15:37:42 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:37:41 Transmit reply to
fe80::288b:339f:c527:3ec8%br0 on LAN
[INFO][LAN] 12-10-2021 15:37:41 Received information request from
fe80::288b:339f:c527:3ec8%br0 on LAN
[INFO][LAN] 12-10-2021 15:37:41 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:37:41 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:37:41 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:37:41 LAN sending RA to ff02::1
[EMERG][LAN] 12-10-2021 15:37:41 LAN2 Link UP 1000 mbps full duplex
[NOTICE][LAN] 12-10-2021 15:35:26 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:35:26 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:35:25 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:35:25 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:35:25 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:35:25 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:35:24 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:35:24 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:35:14 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-10-2021 15:35:14 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:35:14 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:35:13 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-10-2021 15:35:03 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:34:59 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:34:57 Successfully assign IP
[192.168.2.106] to client mac [9c:b6:d0:20:44:69], lease time
[86400]
[INFO][LAN] 12-10-2021 15:34:57 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 15:34:57 server_id = c0a80201
[INFO][LAN] 12-10-2021 15:34:57 Received REQUEST from client ip
[0.0.0.0] mac [9c:b6:d0:20:44:69]
[INFO][LAN] 12-10-2021 15:34:57 Received a packet
[INFO][LAN] 12-10-2021 15:34:57 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 15:34:57 Send OFFER of ip [192.168.2.106] to
client mac [9c:b6:d0:20:44:69]
[INFO][LAN] 12-10-2021 15:34:57 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 15:34:55 Received DISCOVER from client mac
[9c:b6:d0:20:44:69]
[INFO][LAN] 12-10-2021 15:34:55 Received a packet
[INFO][LAN] 12-10-2021 15:34:55 Transmit reply to
fe80::2437:8029:575f:331b%br0 on LAN
[INFO][LAN] 12-10-2021 15:34:55 Received information request from
fe80::2437:8029:575f:331b%br0 on LAN
[INFO][LAN] 12-10-2021 15:34:55 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:34:54 Transmit advertise to
fe80::2437:8029:575f:331b%br0 on LAN
[INFO][LAN] 12-10-2021 15:34:54 Received solicit from
fe80::2437:8029:575f:331b%br0 on LAN
[NOTICE][LAN] 12-10-2021 15:34:54 wl0: AP-STA-CONNECTED
9c:b6:d0:20:44:69
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=87.98.161.162 PROTO=TCP SPT=61368 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=193.36.45.36 PROTO=TCP SPT=61330 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=41166 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=52.3.41.33 PROTO=TCP SPT=61283 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=52.3.41.33 PROTO=TCP SPT=61285 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=52.3.41.33 PROTO=TCP SPT=61284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=54.194.29.148 PROTO=TCP SPT=61277 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=52.48.8.186 PROTO=TCP SPT=61289 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=63.32.159.255 PROTO=TCP SPT=61276 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100

DST=2.22.241.72 PROTO=TCP SPT=61265 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.90 PROTO=TCP SPT=61281 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.72 PROTO=TCP SPT=61264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.72 PROTO=TCP SPT=61265 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.90 PROTO=TCP SPT=61281 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.72 PROTO=TCP SPT=61264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.72 PROTO=TCP SPT=61265 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.90 PROTO=TCP SPT=61281 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.72 PROTO=TCP SPT=61264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.72 PROTO=TCP SPT=61265 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.90 PROTO=TCP SPT=61281 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.72 PROTO=TCP SPT=61265 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.72 PROTO=TCP SPT=61264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=2.22.241.90 PROTO=TCP SPT=61281 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:34:54 TCP Scan SRC=17.248.172.139
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=61137 MARK=0x80000001
[INFO][LAN] 12-10-2021 15:30:55 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 15:22:33 wlan0: AP-STA-DISCONNECTED
68:2f:67:8a:e3:07
[WARNING][Firewall] 12-10-2021 15:22:33 SRC=192.168.2.101
DST=185.86.138.121 PROTO=TCP SPT=55955 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:22:33 SRC=192.168.2.101
DST=70.42.32.159 PROTO=TCP SPT=55978 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:22:33 SRC=192.168.2.101
DST=176.32.108.97 PROTO=TCP SPT=55841 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 15:22:31 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 15:18:36 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:18:36 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:18:13 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:18:12 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=185.29.132.245 PROTO=TCP SPT=55761 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.15.145.115 PROTO=TCP SPT=55889 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=212.129.3.112 PROTO=TCP SPT=55885 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.28.82 PROTO=TCP SPT=55888 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=52.87.48.29 PROTO=TCP SPT=55855 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=35.186.224.47 PROTO=TCP SPT=61126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101

DST=35.186.224.47 PROTO=TCP SPT=61126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61115 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=61124 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.102
DST=80.156.82.166 PROTO=TCP SPT=38274 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:18:12 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=55822 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 15:18:00 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 15:15:37 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=85.114.159.118 PROTO=TCP SPT=55792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=62.149.0.72 PROTO=TCP SPT=55707 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.102
DST=172.217.19.67 PROTO=TCP SPT=34620 DPT=80 MARK=0x3 DROP

```
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=44.236.133.43 PROTO=TCP SPT=55674 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=212.129.3.112 PROTO=TCP SPT=55662 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=55666 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=212.83.160.162 PROTO=TCP SPT=55661 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=212.83.160.162 PROTO=TCP SPT=55624 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=52.58.95.54 PROTO=TCP SPT=55665 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=52.58.95.54 PROTO=TCP SPT=55667 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=216.52.2.39 PROTO=TCP SPT=55636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=216.52.2.39 PROTO=TCP SPT=55636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=216.52.2.39 PROTO=TCP SPT=55636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=216.52.2.39 PROTO=TCP SPT=55636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=216.52.2.39 PROTO=TCP SPT=55636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=216.52.2.39 PROTO=TCP SPT=55636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=216.52.2.39 PROTO=TCP SPT=55636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=216.52.2.39 PROTO=TCP SPT=55636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=216.52.2.39 PROTO=TCP SPT=55636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=216.52.2.39 PROTO=TCP SPT=55636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=216.52.2.39 PROTO=TCP SPT=55636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:15:37 SRC=192.168.2.101
DST=216.52.2.39 PROTO=TCP SPT=55636 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 15:11:27 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-10-2021 15:11:27 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-10-2021 15:11:27 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 15:11:24 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-10-2021 15:11:24 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 15:11:24 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 15:11:24 Arp reply received from the
```

requesting device itself.

[INFO][LAN] 12-10-2021 15:11:24 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]

[INFO][LAN] 12-10-2021 15:11:24 Received a packet

[NOTICE][LAN] 12-10-2021 15:11:23 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.102
DST=172.217.19.67 PROTO=TCP SPT=34620 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=55507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=55491 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55509 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55512 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.102
DST=172.217.19.67 PROTO=TCP SPT=34620 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.102
DST=172.217.19.67 PROTO=TCP SPT=34620 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.102
DST=172.217.19.67 PROTO=TCP SPT=34620 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.102
DST=172.217.19.67 PROTO=TCP SPT=34620 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.102
DST=172.217.19.67 PROTO=TCP SPT=34620 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=185.86.139.103 PROTO=TCP SPT=55435 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.102
DST=172.217.19.67 PROTO=TCP SPT=34620 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.102
DST=172.217.19.67 PROTO=TCP SPT=34620 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 TCP Scan SRC=172.217.19.68
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=35944 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.102
DST=172.217.19.67 PROTO=TCP SPT=34620 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.102
DST=172.217.19.67 PROTO=TCP SPT=34620 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=185.86.139.103 PROTO=TCP SPT=55435 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=55443 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=185.86.139.103 PROTO=TCP SPT=55430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:11:23 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=55441 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 15:07:29 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 15:02:48 wlan1: AP-STA-CONNECTED

DST=185.86.139.114 PROTO=TCP SPT=55443 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:02:48 SRC=192.168.2.101
DST=23.92.190.68 PROTO=TCP SPT=55421 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:02:48 SRC=192.168.2.101
DST=72.251.249.13 PROTO=TCP SPT=55422 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 15:01:50 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 15:01:50 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61115 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61115 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61115 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61115 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61115 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61115 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61115 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61115 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61115 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61107 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=61086 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55319 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55319 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55319 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101

DST=52.1.200.181 PROTO=TCP SPT=55316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55319 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55319 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55319 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=55301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55319 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55314 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55315 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55311 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 15:01:50 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=55316 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 15:01:49 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 14:52:19 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 14:48:45 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-10-2021 14:48:45 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 14:48:45 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 14:48:45 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-10-2021 14:48:45 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 14:48:45 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-10-2021 14:48:45 Received a packet
[NOTICE][LAN] 12-10-2021 14:48:45 wlan0: AP-STA-CONNECTED

DST=35.186.224.47 PROTO=TCP SPT=61107 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61107 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61107 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61100 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=61103 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.175.82 PROTO=TCP SPT=54489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=54828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.175.82 PROTO=TCP SPT=54489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=54828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=54828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=54828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=54828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=62.149.0.72 PROTO=TCP SPT=54898 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=54828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.175.82 PROTO=TCP SPT=54489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=62.149.0.72 PROTO=TCP SPT=54898 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=54828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=62.149.0.72 PROTO=TCP SPT=54898 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=54828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=54828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=54828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=62.149.0.72 PROTO=TCP SPT=54898 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=54828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=54828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=8.2.110.114 PROTO=TCP SPT=54888 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=51.222.105.60 PROTO=TCP SPT=54922 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101

DST=2.23.94.49 PROTO=TCP SPT=54791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.86.138.119 PROTO=TCP SPT=54762 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.174.234 PROTO=TCP SPT=54807 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.86.138.32 PROTO=TCP SPT=54731 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=2.23.94.49 PROTO=TCP SPT=54791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=63.251.86.51 PROTO=TCP SPT=54802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.175.82 PROTO=TCP SPT=54489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.175.82 PROTO=TCP SPT=54489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.175.82 PROTO=TCP SPT=54489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.175.82 PROTO=TCP SPT=54489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.175.82 PROTO=TCP SPT=54489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.175.82 PROTO=TCP SPT=54489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.175.82 PROTO=TCP SPT=54489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.175.82 PROTO=TCP SPT=54494 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=185.239.175.82 PROTO=TCP SPT=54489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=72.251.249.13 PROTO=TCP SPT=54527 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=72.251.249.13 PROTO=TCP SPT=54536 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=72.251.249.13 PROTO=TCP SPT=54528 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=35.244.174.68 PROTO=TCP SPT=54592 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=52.17.84.146 PROTO=TCP SPT=54577 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=52.17.84.146 PROTO=TCP SPT=54577 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:46:22 SRC=192.168.2.101
DST=52.17.84.146 PROTO=TCP SPT=54577 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 14:42:10 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 14:41:15 Sync up with NTP Server
successfully.
[INFO][LAN] 12-10-2021 14:36:20 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 14:34:49 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 14:34:49 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-10-2021 14:32:18 Successfully assign IP

[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time [86400]
[INFO][LAN] 12-10-2021 14:32:18 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 14:32:18 server_id = c0a80201
[INFO][LAN] 12-10-2021 14:32:18 Received REQUEST from client ip [0.0.0.0] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-10-2021 14:32:18 Received a packet
[INFO][LAN] 12-10-2021 14:32:18 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 14:32:18 Send OFFER of ip [192.168.2.102] to client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-10-2021 14:32:18 Find a lease info, and use the ip:6602a8c0
[INFO][LAN] 12-10-2021 14:32:18 Received DISCOVER from client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-10-2021 14:32:18 Received a packet
[INFO][LAN] 12-10-2021 14:32:18 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 14:32:18 Send OFFER of ip [192.168.2.102] to client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-10-2021 14:32:18 Find a lease info, and use the ip:6602a8c0
[INFO][LAN] 12-10-2021 14:32:18 Received DISCOVER from client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-10-2021 14:32:18 Received a packet
[INFO][LAN] 12-10-2021 14:32:18 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 14:32:17 Send OFFER of ip [192.168.2.102] to client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-10-2021 14:32:17 Find a lease info, and use the ip:6602a8c0
[INFO][LAN] 12-10-2021 14:32:17 Received DISCOVER from client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-10-2021 14:32:17 Received a packet
[INFO][LAN] 12-10-2021 14:32:17 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 14:32:17 Send OFFER of ip [192.168.2.102] to client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-10-2021 14:32:17 Find a lease info, and use the ip:6602a8c0
[INFO][LAN] 12-10-2021 14:32:17 No valid arp replies for this address
[INFO][LAN] 12-10-2021 14:32:16 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 14:32:15 Received DISCOVER from client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-10-2021 14:32:15 Received a packet
[NOTICE][LAN] 12-10-2021 14:32:15 wl0: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=61100 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=61100 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=61100 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=61100 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=61100 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=54270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61082 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61082 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61082 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61082 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61082 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61082 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61082 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61075 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 14:32:15 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=61055 MARK=0x8000001
[INFO][LAN] 12-10-2021 14:30:47 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 14:24:07 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 14:14:41 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 14:09:43 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 14:02:29 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 13:55:58 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 13:48:39 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 13:48:15 wlan1: AP-STA-DISCONNECTED

DST=35.186.224.47 PROTO=TCP SPT=61075 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:47:03 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61075 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:47:03 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61067 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:47:03 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=61072 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 13:47:03 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=40018 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:47:03 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=40020 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:47:03 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=40022 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 13:44:01 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 13:34:54 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 13:27:48 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 13:21:54 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-10-2021 13:21:54 TCP Scan SRC=172.217.16.74
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60226 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 13:21:54 SRC=192.168.2.105
DST=172.217.16.67 PROTO=TCP SPT=64430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:21:54 SRC=192.168.2.105
DST=172.217.16.67 PROTO=TCP SPT=64430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:21:54 SRC=192.168.2.105
DST=172.217.16.67 PROTO=TCP SPT=64430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:21:54 SRC=192.168.2.105
DST=172.217.16.67 PROTO=TCP SPT=64430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:21:54 SRC=192.168.2.105
DST=172.217.16.67 PROTO=TCP SPT=64430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:21:54 SRC=192.168.2.105
DST=172.217.16.67 PROTO=TCP SPT=64430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:21:54 SRC=192.168.2.105
DST=172.217.16.67 PROTO=TCP SPT=64430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:21:54 SRC=192.168.2.105
DST=172.217.16.67 PROTO=TCP SPT=64430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:21:54 SRC=192.168.2.105
DST=172.217.16.67 PROTO=TCP SPT=64430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:21:54 SRC=192.168.2.105
DST=172.217.16.67 PROTO=TCP SPT=64430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:21:54 SRC=192.168.2.105
DST=172.217.16.67 PROTO=TCP SPT=64430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:21:54 SRC=192.168.2.105
DST=172.217.16.67 PROTO=TCP SPT=64430 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 13:18:22 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 13:12:03 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 13:12:02 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 13:11:39 wl0: AP-STA-CONNECTED

[WARNING][Firewall] 12-10-2021 13:01:25 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61059 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:01:25 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61059 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:01:25 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61050 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 13:01:25 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=61057 MARK=0x8000001
[INFO][LAN] 12-10-2021 12:58:09 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 12:51:16 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:51:16 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:50:49 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:50:49 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:50:48 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:50:47 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:49:59 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:49:59 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:49:52 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:49:52 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:49:51 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:49:50 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:49:40 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:49:40 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 12:49:40 SRC=192.168.2.102
DST=92.122.21.101 PROTO=TCP SPT=47078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:49:40 SRC=192.168.2.102
DST=92.122.21.101 PROTO=TCP SPT=47078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:49:40 SRC=192.168.2.102
DST=92.122.21.101 PROTO=TCP SPT=47060 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:49:40 SRC=192.168.2.102
DST=92.122.21.101 PROTO=TCP SPT=47060 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:49:40 SRC=192.168.2.102
DST=92.122.21.101 PROTO=TCP SPT=47058 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:49:40 SRC=192.168.2.102
DST=92.122.21.101 PROTO=TCP SPT=47058 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:49:40 SRC=192.168.2.105
DST=185.60.217.28 PROTO=TCP SPT=63678 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:49:40 SRC=192.168.2.105
DST=185.60.217.28 PROTO=TCP SPT=63678 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 12:49:19 LAN sending RA to ff02::1

[NOTICE][LAN] 12-10-2021 12:47:36 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:47:36 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 12:47:36 SRC=192.168.2.102
DST=62.149.0.72 PROTO=TCP SPT=55306 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:47:36 SRC=192.168.2.102
DST=62.149.0.72 PROTO=TCP SPT=55306 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 12:46:54 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:46:54 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 12:46:54 SRC=192.168.2.105
DST=37.252.172.123 PROTO=TCP SPT=63584 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 12:45:52 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:45:52 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 12:45:52 SRC=192.168.2.102
DST=62.149.0.72 PROTO=TCP SPT=55114 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:45:52 SRC=192.168.2.102
DST=62.149.0.72 PROTO=TCP SPT=55114 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 12:45:21 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:45:20 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 12:45:20 SRC=192.168.2.102
DST=54.230.205.109 PROTO=TCP SPT=48714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:45:20 SRC=192.168.2.102
DST=54.230.205.109 PROTO=TCP SPT=48714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:45:20 SRC=192.168.2.102
DST=92.122.21.101 PROTO=TCP SPT=45302 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:45:20 SRC=192.168.2.102
DST=92.122.21.101 PROTO=TCP SPT=45302 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 12:42:28 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:42:28 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 12:42:28 SRC=192.168.2.102
DST=23.92.190.69 PROTO=TCP SPT=57576 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:42:28 SRC=192.168.2.102
DST=23.92.190.69 PROTO=TCP SPT=57576 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:42:28 SRC=192.168.2.102
DST=151.101.194.217 PROTO=TCP SPT=49278 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:42:28 SRC=192.168.2.102
DST=151.101.194.217 PROTO=TCP SPT=49278 DPT=80 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 12:40:52 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:40:52 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 12:40:52 SRC=192.168.2.102
DST=74.125.128.139 PROTO=TCP SPT=35616 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 12:39:55 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-10-2021 12:39:55 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 12:39:55 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=44216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:39:55 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=37448 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:39:55 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=44216 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 12:39:36 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 12:37:11 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:37:11 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=44216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.102
DST=172.217.16.74 PROTO=TCP SPT=56210 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=44216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=44216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=44216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=44216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=44216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=44216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61050 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61050 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61050 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61050 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61050 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61050 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61040 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:37:11 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=61020 MARK=0x8000001
[NOTICE][LAN] 12-10-2021 12:36:32 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:36:32 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.101

DST=146.0.227.109 PROTO=TCP SPT=53626 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.101
DST=216.52.2.48 PROTO=TCP SPT=53623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.101
DST=146.0.227.109 PROTO=TCP SPT=53626 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.101
DST=216.52.2.48 PROTO=TCP SPT=53623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.101
DST=146.0.227.109 PROTO=TCP SPT=53626 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.101
DST=34.122.159.175 PROTO=TCP SPT=53586 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.101
DST=146.0.227.109 PROTO=TCP SPT=53626 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.101
DST=216.52.2.48 PROTO=TCP SPT=53623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.101
DST=52.95.125.22 PROTO=TCP SPT=53519 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=59214 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=59214 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=59214 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=59214 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:36:32 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=59214 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 12:34:40 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 12:31:18 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:31:18 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:30:58 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-10-2021 12:30:58 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-10-2021 12:30:42 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:30:42 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-10-2021 12:30:28 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-10-2021 12:30:28 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-10-2021 12:30:27 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 12:30:26 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-10-2021 12:30:26 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 12:30:26 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 12:30:26 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-10-2021 12:30:26 Received REQUEST from client ip

[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=33026 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=33026 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:30:25 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=62699 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 12:21:15 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 12:15:28 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:15:28 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:15:16 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:15:16 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:14:37 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:14:37 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:14:35 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:14:35 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-10-2021 12:11:54 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 12:11:30 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 12:11:30 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac

[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=43730 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=43740 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 TCP Scan SRC=142.250.186.138
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=39638 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=62259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=142.250.185.206 PROTO=TCP SPT=42188 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=74.125.128.139 PROTO=TCP SPT=34902 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=34.149.12.213 PROTO=TCP SPT=53184 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=172.217.16.67 PROTO=TCP SPT=48748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=34.149.12.213 PROTO=TCP SPT=53184 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=34.149.12.213 PROTO=TCP SPT=53184 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=152.199.21.118 PROTO=TCP SPT=35112 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=172.217.16.67 PROTO=TCP SPT=48748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=34.149.12.213 PROTO=TCP SPT=53184 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=34.149.12.213 PROTO=TCP SPT=53184 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=43742 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=43742 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=43742 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=43742 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=43742 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=43742 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=43742 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.105
DST=92.122.21.240 PROTO=TCP SPT=61625 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.101
DST=168.100.65.137 PROTO=TCP SPT=53227 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.101
DST=51.15.145.115 PROTO=TCP SPT=53211 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 12:11:30 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=40902 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 12:07:54 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 11:58:05 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 11:53:24 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 11:44:47 LAN sending RA to ff02::1

[WARNING][Firewall] 12-10-2021 11:41:27 SRC=192.168.2.101
DST=104.86.40.114 PROTO=TCP SPT=53003 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:41:27 SRC=192.168.2.101
DST=216.52.2.19 PROTO=TCP SPT=53026 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:41:27 SRC=192.168.2.101
DST=104.86.40.114 PROTO=TCP SPT=53003 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:41:27 SRC=192.168.2.101
DST=216.52.2.19 PROTO=TCP SPT=53026 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:41:27 SRC=192.168.2.101
DST=104.86.40.114 PROTO=TCP SPT=53003 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:41:27 SRC=192.168.2.101
DST=216.52.2.19 PROTO=TCP SPT=53026 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:41:27 SRC=192.168.2.101
DST=62.149.0.72 PROTO=TCP SPT=53071 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:41:27 SRC=192.168.2.101
DST=104.86.40.114 PROTO=TCP SPT=53003 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:41:27 SRC=192.168.2.101
DST=216.52.2.19 PROTO=TCP SPT=53026 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 11:37:36 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 11:29:27 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 11:20:56 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 11:20:56 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 11:20:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61016 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61016 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61016 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61016 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61016 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61016 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61016 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61016 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61009 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:56 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60987 MARK=0x8000001
[INFO][LAN] 12-10-2021 11:20:55 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 11:20:30 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 11:20:30 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=3.217.216.1 PROTO=TCP SPT=53018 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=95.216.21.205 PROTO=TCP SPT=52940 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101

DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=34.227.41.227 PROTO=TCP SPT=52916 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:20:30 SRC=192.168.2.101
DST=52.92.163.72 PROTO=TCP SPT=52891 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 11:16:57 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 11:12:57 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 11:12:57 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 11:12:57 SRC=192.168.2.101
DST=3.209.172.72 PROTO=TCP SPT=52874 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:12:57 SRC=192.168.2.101
DST=3.209.172.72 PROTO=TCP SPT=52873 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:12:57 SRC=192.168.2.105
DST=52.73.6.213 PROTO=TCP SPT=60766 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:12:57 SRC=192.168.2.102
DST=142.250.185.234 PROTO=TCP SPT=41494 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:12:57 SRC=192.168.2.102
DST=142.250.185.234 PROTO=TCP SPT=41494 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:12:57 SRC=192.168.2.102
DST=142.250.185.234 PROTO=TCP SPT=41494 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:12:57 SRC=192.168.2.102
DST=142.250.185.234 PROTO=TCP SPT=41494 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:12:57 SRC=192.168.2.102
DST=142.250.185.234 PROTO=TCP SPT=41494 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 11:09:33 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 11:06:12 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 11:06:12 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=61009 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61009 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61009 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61009 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61009 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61009 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61009 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=61000 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.105
DST=136.243.25.83 PROTO=TCP SPT=60666 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.105
DST=54.144.85.208 PROTO=TCP SPT=60633 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.105
DST=161.156.47.59 PROTO=TCP SPT=60481 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.105
DST=85.114.159.118 PROTO=TCP SPT=60543 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.105
DST=216.52.2.39 PROTO=TCP SPT=60611 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.105
DST=178.250.2.130 PROTO=TCP SPT=60536 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:06:12 SRC=192.168.2.105
DST=178.250.2.130 PROTO=TCP SPT=60536 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 11:01:08 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 11:01:04 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-10-2021 11:01:04 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-10-2021 11:01:04 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 11:01:03 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-10-2021 11:01:03 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 11:01:03 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 11:01:03 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-10-2021 11:01:03 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-10-2021 11:01:03 Received a packet
[INFO][LAN] 12-10-2021 11:01:02 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-10-2021 11:01:02 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 11:01:02 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-10-2021 11:01:02 Received a packet
[INFO][LAN] 12-10-2021 11:01:02 Successfully assign IP

[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time [86400]
[INFO][LAN] 12-10-2021 11:01:02 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 11:01:02 No valid arp replies for this address
[NOTICE][LAN] 12-10-2021 11:01:01 wl0: AP-STA-CONNECTED 10:94:bb:d5:73:92
[INFO][LAN] 12-10-2021 11:01:00 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 11:01:00 Received REQUEST from client ip [0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-10-2021 11:01:00 Received a packet
[NOTICE][LAN] 12-10-2021 11:00:59 wl1: AP-STA-CONNECTED 0e:d3:bc:3c:3b:3d
[NOTICE][LAN] 12-10-2021 11:00:58 wl1: AP-STA-DISCONNECTED 0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=54.186.120.221 PROTO=TCP SPT=52802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52774 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52764 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52764 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 11:00:58 SRC=192.168.2.101 DST=193.22.180.100 PROTO=TCP SPT=52763 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52743 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52744 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52743 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52744 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52743 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52744 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52743 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:55:18 SRC=192.168.2.101
DST=193.22.180.100 PROTO=TCP SPT=52734 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 10:54:48 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 10:49:34 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 10:49:32 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-10-2021 10:49:32 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 10:49:32 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-10-2021 10:49:32 Received a packet
[INFO][LAN] 12-10-2021 10:49:32 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]

DST=178.250.2.144 PROTO=TCP SPT=52637 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36428 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59776 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36432 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.247.232.194 PROTO=TCP SPT=52565 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=178.250.2.144 PROTO=TCP SPT=52637 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=70.42.32.31 PROTO=TCP SPT=52651 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=178.250.2.144 PROTO=TCP SPT=52637 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.252.94.119 PROTO=TCP SPT=52511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.252.94.119 PROTO=TCP SPT=52511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=178.250.2.144 PROTO=TCP SPT=52637 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.252.94.119 PROTO=TCP SPT=52511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=70.42.32.31 PROTO=TCP SPT=52651 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=178.250.2.144 PROTO=TCP SPT=52637 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.139.100 PROTO=TCP SPT=52636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.252.94.119 PROTO=TCP SPT=52511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52628 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=81.17.55.114 PROTO=TCP SPT=52635 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=52552 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.139.100 PROTO=TCP SPT=52636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52628 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=81.17.55.114 PROTO=TCP SPT=52635 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=52552 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=178.250.2.144 PROTO=TCP SPT=52637 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.252.94.119 PROTO=TCP SPT=52511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.139.100 PROTO=TCP SPT=52636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52628 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101

DST=81.17.55.114 PROTO=TCP SPT=52635 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=52552 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=70.42.32.31 PROTO=TCP SPT=52651 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=178.250.2.144 PROTO=TCP SPT=52637 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.252.94.119 PROTO=TCP SPT=52511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.139.100 PROTO=TCP SPT=52636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52628 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=81.17.55.114 PROTO=TCP SPT=52635 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=52552 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=51.75.146.162 PROTO=TCP SPT=52496 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.149.12.213 PROTO=TCP SPT=52552 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=70.42.32.31 PROTO=TCP SPT=52651 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.139.100 PROTO=TCP SPT=52636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=81.17.55.114 PROTO=TCP SPT=52635 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52628 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=52417 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=51.158.29.13 PROTO=TCP SPT=52414 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=37.252.172.38 PROTO=TCP SPT=52627 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=37.252.173.22 PROTO=TCP SPT=52643 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=37.252.173.62 PROTO=TCP SPT=52600 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.252.94.119 PROTO=TCP SPT=52499 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.252.94.119 PROTO=TCP SPT=52511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=51.158.28.82 PROTO=TCP SPT=52415 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=51.158.29.13 PROTO=TCP SPT=52413 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=216.52.2.48 PROTO=TCP SPT=52617 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=34.232.235.22 PROTO=TCP SPT=52483 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=178.250.2.144 PROTO=TCP SPT=52637 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101

DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=44.233.142.216 PROTO=TCP SPT=52317 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52147 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=18.197.46.208 PROTO=TCP SPT=52167 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.137.108 PROTO=TCP SPT=52126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.137.108 PROTO=TCP SPT=52126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.137.131 PROTO=TCP SPT=52166 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.137.108 PROTO=TCP SPT=52118 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.137.108 PROTO=TCP SPT=52126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.137.131 PROTO=TCP SPT=52166 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.137.108 PROTO=TCP SPT=52118 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:49:30 SRC=192.168.2.101
DST=185.86.137.108 PROTO=TCP SPT=52126 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 10:49:12 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 10:41:38 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 10:33:41 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 10:29:49 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 10:24:14 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 10:20:41 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 10:18:14 wlan1: AP-STA-CONNECTED

bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:18:14 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 10:18:14 SRC=192.168.2.101
DST=52.46.130.91 PROTO=TCP SPT=51864 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:18:14 SRC=192.168.2.101
DST=52.46.130.91 PROTO=TCP SPT=51863 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:18:14 SRC=192.168.2.101
DST=52.94.222.140 PROTO=TCP SPT=51870 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 10:17:29 ACSD: Timestamp(ms):1639131449
ACS-Trigger:TIMER Selected Channel:#13 (0x100d)
[EMERG][LAN] 12-10-2021 10:17:29 WIFI 2.4G Channel has been changed
from channel 8 to 13.
[NOTICE][LAN] 12-10-2021 10:16:23 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:16:23 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:15:46 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:15:46 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:15:45 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:15:45 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:15:42 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:15:42 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:15:41 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:15:41 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:15:15 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:15:15 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:14:46 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:14:46 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:14:43 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:14:43 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:14:07 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:14:07 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.101
DST=18.195.106.43 PROTO=TCP SPT=51822 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.101
DST=18.195.106.43 PROTO=TCP SPT=51809 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.101

DST=18.203.197.143 PROTO=TCP SPT=51917 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.101
DST=18.203.197.143 PROTO=TCP SPT=51911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.101
DST=52.50.27.147 PROTO=TCP SPT=51916 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.101
DST=52.87.48.29 PROTO=TCP SPT=51812 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60978 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60978 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60978 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60978 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60978 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60978 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60978 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60969 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60978 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60947 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.101
DST=212.129.3.113 PROTO=TCP SPT=51738 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.101
DST=51.158.29.13 PROTO=TCP SPT=51739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 10:14:07 SRC=192.168.2.101
DST=3.127.63.9 PROTO=TCP SPT=51747 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 10:11:18 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 10:03:18 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 10:00:22 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 10:00:22 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:59:40 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:59:40 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:59:34 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:59:34 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 09:59:34 SRC=192.168.2.101
DST=54.239.38.253 PROTO=TCP SPT=51352 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:59:34 SRC=192.168.2.101
DST=54.239.38.253 PROTO=TCP SPT=51351 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 09:58:08 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:58:07 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:58:05 wl1: AP-STA-CONNECTED

[WARNING][Firewall] 12-10-2021 09:53:47 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60959 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:53:47 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60964 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 09:53:47 SRC=192.168.2.101
DST=185.29.132.245 PROTO=TCP SPT=51322 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:53:47 SRC=192.168.2.101
DST=136.243.12.72 PROTO=TCP SPT=51438 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 09:52:37 wI0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:52:37 wI1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:52:33 wI1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:52:33 wI0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 09:52:33 SRC=192.168.2.101
DST=185.29.132.245 PROTO=TCP SPT=51318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:33 SRC=192.168.2.101
DST=3.209.172.72 PROTO=TCP SPT=51450 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:33 SRC=192.168.2.101
DST=3.209.172.72 PROTO=TCP SPT=51449 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 09:52:06 wI0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:52:06 wI1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=18.66.180.124 PROTO=TCP SPT=51147 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=35.203.55.194 PROTO=TCP SPT=51149 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 TCP Scan SRC=107.178.240.159
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=55186 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.218.180.0 PROTO=TCP SPT=51131 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=51063 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=51064 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=51063 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=51064 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=51064 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=51061 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=51063 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60959 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60959 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60959 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60959 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60959 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60959 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60959 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60959 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:52:06 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60955 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 09:52:06 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=60949 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 09:51:57 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 09:45:24 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 09:42:00 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 09:36:28 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:36:28 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-10-2021 09:35:27 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 09:33:40 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:33:40 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:33:33 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:33:33 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:32:51 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:32:51 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac

DST=52.2.204.41 PROTO=TCP SPT=50964 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:30:49 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=50968 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:30:49 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=50964 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:30:49 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=50968 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 09:29:50 Successfully assign IP
[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time
[86400]
[INFO][LAN] 12-10-2021 09:29:50 unicasting packet to client ciaddr
[INFO][LAN] 12-10-2021 09:29:50 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 09:29:50 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-10-2021 09:29:50 Received REQUEST from client ip
[192.168.2.102] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-10-2021 09:29:50 Received a packet
[NOTICE][LAN] 12-10-2021 09:28:38 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:28:38 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=50964 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=50968 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=50964 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=50968 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=50964 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=50968 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=50964 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=50968 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=50963 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=50964 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=50968 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.101
DST=3.220.66.61 PROTO=TCP SPT=50912 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:28:38 SRC=192.168.2.102
DST=54.189.231.6 PROTO=TCP SPT=34832 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 09:27:54 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 09:26:20 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:26:20 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102

DST=172.217.19.78 PROTO=TCP SPT=42420 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.101
DST=18.66.188.90 PROTO=TCP SPT=50811 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36128 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36124 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59468 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36128 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36124 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59468 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36128 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59468 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36124 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36128 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36124 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59468 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36128 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59468 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36124 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36124 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.35 PROTO=TCP SPT=59468 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:26:20 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=36128 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 09:24:10 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 09:19:45 wlan1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-10-2021 09:19:44 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:19:44 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:19:44 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:19:37 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:19:37 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:19:16 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:19:15 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:18:26 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:18:26 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=50790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=50789 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=60949 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=60949 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=60949 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=60949 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60937 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=60949 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=60949 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:18:26 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60948 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 09:18:26 SRC=192.168.2.101
DST=18.203.197.143 PROTO=TCP SPT=50747 DPT=443 MARK=0x3 DROP

[INFO][LAN] 12-10-2021 09:16:13 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 09:12:40 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:12:40 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:12:22 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:12:22 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:12:01 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:12:00 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:11:33 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:11:33 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:11:11 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:11:11 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 09:11:11 SRC=192.168.2.101
DST=18.66.188.149 PROTO=TCP SPT=50665 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 09:10:42 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 09:07:13 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:07:13 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:06:49 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 09:06:49 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60937 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60937 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60937 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60937 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60937 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60919 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60937 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60930 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60937 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=50608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=50608 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50547 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50549 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=50537 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50550 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50547 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50549 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=50537 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50550 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50547 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50549 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=50537 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=50548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=50537 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50550 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50549 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50542 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50546 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50545 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=50547 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 09:06:49 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=50442 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 09:04:47 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 08:57:57 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 08:49:08 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:49:08 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50398 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:49:08 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50400 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 08:49:06 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 08:44:52 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:44:52 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:42:09 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:42:09 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:42:08 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:42:08 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 08:42:08 SRC=192.168.2.101
DST=192.229.233.55 PROTO=TCP SPT=50345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:42:08 SRC=192.168.2.101
DST=192.229.233.55 PROTO=TCP SPT=50342 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:42:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60930 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:42:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60930 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:42:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60930 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:42:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60930 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:42:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60930 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:42:08 SRC=192.168.2.100
DST=93.184.220.29 PROTO=TCP SPT=60873 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:42:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60930 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:42:08 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=60930 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:42:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:42:08 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60926 MARK=0x8000001
[INFO][LAN] 12-10-2021 08:41:41 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 08:40:39 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:40:39 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 08:40:39 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50318 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 08:39:47 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:39:47 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 08:39:47 SRC=192.168.2.102
DST=142.250.186.138 PROTO=TCP SPT=38110 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 08:37:35 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 08:34:00 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:34:00 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:33:58 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:33:58 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 08:33:58 SRC=192.168.2.101
DST=178.162.146.164 PROTO=TCP SPT=50175 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:33:58 SRC=192.168.2.101
DST=192.229.233.55 PROTO=TCP SPT=50235 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:33:58 SRC=192.168.2.101
DST=192.229.233.55 PROTO=TCP SPT=50232 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:33:58 SRC=192.168.2.102
DST=80.156.82.165 PROTO=TCP SPT=46802 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 08:29:31 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 08:28:24 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:28:24 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[EMERG][LAN] 12-10-2021 08:26:01 WIFI 2.4G Channel has been changed
from channel 9 to 8.
[WARNING][Firewall] 12-10-2021 08:26:01 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50198 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 08:24:55 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:24:55 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.101
DST=193.169.66.132 PROTO=TCP SPT=50193 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.100
DST=93.184.220.29 PROTO=TCP SPT=60873 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60918 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.100
DST=93.184.220.29 PROTO=TCP SPT=60873 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.100
DST=93.184.220.29 PROTO=TCP SPT=60873 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60910 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60920 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.100
DST=93.184.220.29 PROTO=TCP SPT=60873 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.102
DST=80.158.50.118 PROTO=TCP SPT=47388 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 08:24:55 SRC=192.168.2.102
DST=80.158.36.25 PROTO=TCP SPT=52226 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 08:21:10 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 08:17:58 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:17:58 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:17:01 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:17:01 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:16:49 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:16:49 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:16:28 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:16:28 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 08:16:28 SRC=192.168.2.101
DST=52.95.125.22 PROTO=TCP SPT=49669 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 08:14:51 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:14:51 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:14:50 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 08:14:50 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-10-2021 08:14:47 LAN sending RA to ff02::1

[NOTICE] [LAN] 12-10-2021 08:14:16 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:14:16 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:14:15 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:14:14 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:14:12 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:14:12 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:14:05 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:14:05 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:14:03 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:14:03 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:14:03 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:14:03 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING] [Firewall] 12-10-2021 08:14:03 SRC=192.168.2.101
DST=52.95.125.22 PROTO=TCP SPT=49667 DPT=443 MARK=0x3 DROP
[WARNING] [Firewall] 12-10-2021 08:14:03 SRC=192.168.2.101
DST=176.32.111.2 PROTO=TCP SPT=49845 DPT=443 MARK=0x3 DROP
[NOTICE] [LAN] 12-10-2021 08:13:50 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:50 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:48 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:48 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:35 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:35 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:34 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:34 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:31 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:31 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:31 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:31 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:26 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE] [LAN] 12-10-2021 08:13:26 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:20 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:20 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:17 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:17 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:15 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:15 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:09 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:09 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:01 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:13:01 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING] [Firewall] 12-10-2021 08:13:01 SRC=192.168.2.101
DST=192.229.233.55 PROTO=TCP SPT=50048 DPT=443 MARK=0x3 DROP
[NOTICE] [LAN] 12-10-2021 08:12:37 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:12:36 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:12:15 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:12:15 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING] [Firewall] 12-10-2021 08:12:15 SRC=192.168.2.101
DST=207.120.36.106 PROTO=TCP SPT=50030 DPT=443 MARK=0x3 DROP
[NOTICE] [LAN] 12-10-2021 08:12:07 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:12:07 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:12:07 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-10-2021 08:12:07 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING] [Firewall] 12-10-2021 08:12:07 SRC=192.168.2.101
DST=52.34.131.7 PROTO=TCP SPT=49974 DPT=443 MARK=0x3 DROP
[WARNING] [Firewall] 12-10-2021 08:12:07 SRC=192.168.2.101
DST=92.122.76.51 PROTO=TCP SPT=49858 DPT=443 MARK=0x3 DROP
[WARNING] [Firewall] 12-10-2021 08:12:07 SRC=192.168.2.100
DST=93.184.220.29 PROTO=TCP SPT=60873 DPT=80 MARK=0x3 DROP
[WARNING] [Firewall] 12-10-2021 08:12:07 SRC=192.168.2.100
DST=93.184.220.29 PROTO=TCP SPT=60873 DPT=80 MARK=0x3 DROP
[WARNING] [Firewall] 12-10-2021 08:12:07 SRC=192.168.2.100
DST=93.184.220.29 PROTO=TCP SPT=60873 DPT=80 MARK=0x3 DROP
[WARNING] [Firewall] 12-10-2021 08:12:07 SRC=192.168.2.100
DST=93.184.220.29 PROTO=TCP SPT=60873 DPT=80 MARK=0x3 DROP
[WARNING] [Firewall] 12-10-2021 08:12:07 SRC=192.168.2.100
DST=93.184.220.29 PROTO=TCP SPT=60873 DPT=80 MARK=0x3 DROP

DST=35.186.224.47 PROTO=TCP SPT=60891 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:42:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60884 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:42:57 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60888 MARK=0x8000001
[INFO][LAN] 12-10-2021 07:39:30 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 07:34:11 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 07:26:27 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 07:21:57 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 07:21:27 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:21:27 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 07:21:27 TCP Scan SRC=172.217.16.74
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=56114 MARK=0x8000001
[NOTICE][LAN] 12-10-2021 07:21:03 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:21:03 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[EMERG][Firewall] 12-10-2021 07:21:03 DoS attack: SYN With Data
Attack from source: 146.88.240.4:5060
[WARNING][Firewall] 12-10-2021 07:21:03 SRC=192.168.2.102
DST=172.217.16.138 PROTO=TCP SPT=41188 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 07:15:27 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:15:26 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:14:53 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:14:53 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:14:42 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:14:42 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:14:41 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:14:41 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-10-2021 07:14:23 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 07:13:37 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:13:37 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:13:14 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:13:14 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:12:53 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:12:53 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 07:12:52 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

DST=35.186.224.47 PROTO=TCP SPT=60866 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60859 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60838 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.102
DST=40.70.161.7 PROTO=TCP SPT=43930 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.102
DST=54.72.21.97 PROTO=TCP SPT=34356 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60859 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60859 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60859 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60859 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60859 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60859 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60859 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60859 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60852 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60854 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=60690 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=60690 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=60690 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=60690 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=60690 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=60690 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=60690 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=60690 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=60690 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 07:00:42 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=60690 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 06:59:28 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 06:54:41 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 06:49:21 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 06:39:57 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 06:34:09 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 06:24:12 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 06:18:02 LAN sending RA to ff02::1

[INFO][LAN] 12-10-2021 05:03:39 Successfully assign IP [192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time [86400]
[INFO][LAN] 12-10-2021 05:03:39 unicasting packet to client ciaddr
[INFO][LAN] 12-10-2021 05:03:39 No valid arp replies for this address
[INFO][LAN] 12-10-2021 05:03:39 Arp reply received from the requesting device itself.
[INFO][LAN] 12-10-2021 05:03:39 Received REQUEST from client ip [192.168.2.100] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-10-2021 05:03:39 Received a packet
[INFO][LAN] 12-10-2021 05:00:10 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 04:58:17 wl0: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 04:58:17 wl1: AP-STA-DISCONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 04:58:16 ACS-D: Timestamp(ms):1639112296 ACS-Trigger:TIMER Selected Channel:#9 (0x1009)
[EMERG][LAN] 12-10-2021 04:58:16 WIFI 2.4G Channel has been changed from channel 1 to 9.
[WARNING][Firewall] 12-10-2021 04:58:16 TCP Scan SRC=104.21.59.155 DST=188.104.233.90 PROTO=TCP SPT=443 DPT=37930 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 04:58:16 SRC=192.168.2.102 DST=172.217.19.74 PROTO=TCP SPT=32920 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:58:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:58:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:58:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:58:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:58:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:58:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:58:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:58:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:58:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:58:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60808 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:58:16 TCP Scan SRC=35.186.224.25 DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60811 MARK=0x8000001
[INFO][LAN] 12-10-2021 04:50:41 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 04:47:02 wl0: AP-STA-CONNECTED 6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-10-2021 04:47:02 wl1: AP-STA-DISCONNECTED 6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-10-2021 04:47:02 SRC=192.168.2.101 DST=17.57.146.53 PROTO=TCP SPT=57796 DPT=5223 MARK=0x1 DROP
[WARNING][Firewall] 12-10-2021 04:47:02 SRC=192.168.2.101 DST=35.186.224.25 PROTO=TCP SPT=64975 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:47:02 SRC=192.168.2.101 DST=35.186.224.25 PROTO=TCP SPT=64976 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:47:02 SRC=192.168.2.102

DST=216.58.213.237 PROTO=TCP SPT=53176 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:47:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60808 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:47:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60808 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:47:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60808 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:47:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60808 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:47:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60808 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:47:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60808 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:47:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60808 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:47:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60800 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:47:02 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60806 MARK=0x8000001
[INFO][LAN] 12-10-2021 04:42:09 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 04:36:33 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 04:32:46 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 04:26:44 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 04:26:44 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 04:26:13 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 04:26:13 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 04:26:13 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=57336 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:26:13 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=57336 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 04:25:18 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 04:20:52 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 04:16:52 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-10-2021 04:16:52 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 04:16:52 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 04:16:52 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-10-2021 04:16:52 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 04:16:52 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-10-2021 04:16:52 Received a packet
[NOTICE][LAN] 12-10-2021 04:16:52 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-10-2021 04:16:52 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-10-2021 04:16:52 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=57336 DPT=443 MARK=0x3 DROP

DST=34.104.35.123 PROTO=TCP SPT=41848 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:07:16 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=41848 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:07:16 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=35502 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:07:16 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=35504 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:07:16 SRC=192.168.2.102
DST=52.222.179.24 PROTO=TCP SPT=42434 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:07:16 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=41848 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:07:16 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=41848 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:07:16 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=41848 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:07:16 SRC=192.168.2.102
DST=216.58.213.237 PROTO=TCP SPT=53096 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:07:16 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=41228 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 04:07:16 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=41848 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 04:04:52 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 03:57:08 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 03:55:53 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 03:55:53 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 03:55:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:55:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:55:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:55:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:55:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:55:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:55:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:55:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:55:53 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60784 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 03:55:53 SRC=192.168.2.102
DST=142.250.185.74 PROTO=TCP SPT=33440 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 03:51:01 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 03:44:51 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 03:38:41 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-10-2021 03:38:41 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-10-2021 03:38:41 SRC=192.168.2.102

DST=142.250.185.74 PROTO=TCP SPT=33440 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 03:37:30 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 03:36:39 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 03:36:39 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.102
DST=142.250.185.74 PROTO=TCP SPT=33440 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.102
DST=142.250.185.74 PROTO=TCP SPT=33440 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.102
DST=142.250.185.74 PROTO=TCP SPT=33440 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.102
DST=142.250.185.74 PROTO=TCP SPT=33440 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.102
DST=142.250.185.74 PROTO=TCP SPT=33440 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.102
DST=142.250.185.74 PROTO=TCP SPT=33440 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.102
DST=142.250.185.74 PROTO=TCP SPT=33440 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.102
DST=104.21.59.155 PROTO=TCP SPT=37820 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.102
DST=142.250.185.74 PROTO=TCP SPT=33440 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.102
DST=104.21.59.155 PROTO=TCP SPT=37818 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60772 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:36:39 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60778 MARK=0x8000001
[INFO][LAN] 12-10-2021 03:28:30 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 03:25:52 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 03:25:52 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 03:25:52 SRC=192.168.2.102
DST=216.239.38.135 PROTO=TCP SPT=41468 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 03:23:06 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 03:16:34 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time

DST=54.72.5.132 PROTO=TCP SPT=58056 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:16:33 SRC=192.168.2.102
DST=54.72.5.132 PROTO=TCP SPT=58056 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:16:33 SRC=192.168.2.102
DST=54.72.5.132 PROTO=TCP SPT=58056 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 03:14:14 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 03:06:35 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[NOTICE][LAN] 12-10-2021 03:06:13 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 03:06:13 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-10-2021 03:05:52 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-10-2021 03:05:52 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 03:05:52 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 03:05:52 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-10-2021 03:05:52 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 03:05:52 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-10-2021 03:05:52 Received a packet
[NOTICE][LAN] 12-10-2021 03:05:52 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-10-2021 03:05:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:05:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:05:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:05:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:05:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:05:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:05:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:05:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:05:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60755 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:05:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 03:05:52 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60732 MARK=0x8000001
[INFO][LAN] 12-10-2021 03:05:05 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:55:47 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 02:55:24 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 02:55:24 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 02:55:11 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[NOTICE][LAN] 12-10-2021 02:54:50 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-10-2021 02:54:50 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 02:54:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60755 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:54:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60755 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:54:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60755 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:54:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60755 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:54:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60755 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:54:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60755 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:54:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60745 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:54:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60755 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:54:50 TCP Scan SRC=35.186.224.25
DST=188.104.233.90 PROTO=TCP SPT=443 DPT=60751 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 02:54:50 SRC=192.168.2.102
DST=142.250.184.202 PROTO=TCP SPT=37284 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 02:47:22 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:41:29 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:41:13 LAN sending RA to ff02::1
[INFO][VoIP] 12-10-2021 02:41:13 Switch to primary proxy server
arcor.de on line 0
[INFO][LAN] 12-10-2021 02:40:57 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 02:40:56 Sync up with NTP Server
successfully.
[INFO][System] 12-10-2021 02:40:53 Sync up with NTP Server
successfully.
[INFO][VoIP] 12-10-2021 02:40:45 Send data/single wan update to
VGW,wan id 10,ifName is ppp10,ipv4 address 188.104.233.90,ipv6
address ,default_wan_id 10,wan type 1
[INFO][VoIP] 12-10-2021 02:40:45 line 371 ,wan 10 start do data wan
up
[INFO][VoIP] 12-10-2021 02:40:45 wanipv6 = ,size = 0
[INFO][VoIP] 12-10-2021 02:40:45 Voice binding wan_id is
10,default_wan_id is 10
[INFO][VoIP] 12-10-2021 02:40:45 Voice binding wan_id is
10,default_wan_id is 10,is_ipv6 = 0
[INFO][VoIP] 12-10-2021 02:40:45 wan 10 service_type =
DATA,VOIP,MGNT,IPTV bud_voip_wan_id = 10
[INFO][VoIP] 12-10-2021 02:40:45 Interface wan_ip is 188.104.233.90,
wan_ip_v6 ,is_ipv6 0 wan up id 10
[INFO][LAN] 12-10-2021 02:40:45 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO][LAN] 12-10-2021 02:40:45 adapter index 19
[INFO][LAN] 12-10-2021 02:40:45 br1 (our ip) = 192.168.3.1
[INFO][LAN] 12-10-2021 02:40:45 Attaching option timezone to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option t2 to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option t1 to list
[INFO][LAN] 12-10-2021 02:40:45 adapter hardware address

```
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-10-2021 02:40:45 adapter index 18
[INFO][LAN] 12-10-2021 02:40:45 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-10-2021 02:40:45 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-10-2021 02:40:45 adapter index 18
[INFO][LAN] 12-10-2021 02:40:45 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-10-2021 02:40:45 Attaching option timezone to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option t2 to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option t1 to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option lease to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option dns to existing
member of list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option dns to existing
member of list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option dns to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option router to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option subnet to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option timezone to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option t2 to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option t1 to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option lease to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option dns to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option hostname to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option lease to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option domain to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option dns to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option router to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option router to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option subnet to list
[INFO][LAN] 12-10-2021 02:40:45 Attaching option subnet to list
[INFO][LAN] 12-10-2021 02:40:45 error on select
[INFO][LAN] 12-10-2021 02:40:45 error on select
[INFO][LAN] 12-10-2021 02:40:45 udhcp server receive signal 12
[INFO][LAN] 12-10-2021 02:40:45 udhcp server receive signal 12
[INFO][System] 12-10-2021 02:40:44 Starting MCPD OK.
[INFO][System] 12-10-2021 02:40:44 Stopping MCPD OK.
[INFO][UMTS] 12-10-2021 02:40:43 iPhone DNS Policy actived
[INFO][VoIP] 12-10-2021 02:40:43 276 start wan service Voice
binding wan_id is 10
[INFO][VoIP] 12-10-2021 02:40:43 Voice binding wan_id is 10
[INFO][System] 12-10-2021 02:40:43 Starting NTP Client OK.
[INFO][System] 12-10-2021 02:40:43 Sync up with NTP Server failed.
[INFO][System] 12-10-2021 02:40:43 Stopping NTP Client OK.
[INFO][Firewall] 12-10-2021 02:40:43 PortMapping Rules have been
flushed on WAN VDSL-DT.
[INFO][Firewall] 12-10-2021 02:40:43 DMZ Rules has been flushed on
WAN VDSL-DT.
[INFO][Firewall] 12-10-2021 02:40:43 Static NAT Rules have been
flushed on WAN VDSL-DT.
[INFO][System] 12-10-2021 02:40:42 Stopping HTTP redirect OK.
[INFO][DNS] 12-10-2021 02:40:42 DNSMasq proxy server disable
redirect
[INFO][DNS] 12-10-2021 02:40:42 Internet DNS Servers 176.95.16.250,
```

176.95.16.251.
[INFO][DNS] 12-10-2021 02:40:42 Internet DNS ready.
[INFO][DNS] 12-10-2021 02:40:42 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 02:40:42 Internet DNS ready.
[INFO][DNS] 12-10-2021 02:40:42 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 02:40:42 Internet DNS ready.
[INFO][DNS] 12-10-2021 02:40:42 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 02:40:42 Internet DNS ready.
[WARNING][DNS] 12-10-2021 02:40:42 ignoring nameserver 127.0.0.1 -
local interface
[WARNING][DNS] 12-10-2021 02:40:42 ignoring nameserver ::1 - local
interface
[INFO][DNS] 12-10-2021 02:40:42 Starting DNSMasq proxy server OK.
[INFO][DNS] 12-10-2021 02:40:42 Stopping DNSMasq proxy OK.
[INFO][DNS] 12-10-2021 02:40:41 DNSMasq proxy server disable
redirect
[INFO][LAN] 12-10-2021 02:40:41 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:40:41 LAN sending RA to ff02::1
[INFO][UMTS] 12-10-2021 02:40:40 iPhone DNS Policy actived
[INFO][VoIP] 12-10-2021 02:40:40 Remove interface wan_id is 10,wan
type 2.
[INFO][VoIP] 12-10-2021 02:40:40 VoIP WAN down, Voice trying to run
in backup mode, try binding wan_id is 10
[INFO][VoIP] 12-10-2021 02:40:40 bud data ipv4 wan status 10,ipv6
wan status -1
[INFO][VoIP] 12-10-2021 02:40:40 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-10-2021 02:40:40 ===start stop voice wan
[INFO][VoIP] 12-10-2021 02:40:40 ignore useless wan down
[INFO][VoIP] 12-10-2021 02:40:40 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-10-2021 02:40:40 ===start stop voice wan
[INFO][System] 12-10-2021 02:40:40 Starting MCPD OK.
[INFO][System] 12-10-2021 02:40:39 Stopping MCPD OK.
[INFO][VoIP] 12-10-2021 02:40:39 ignore useless wan down
[INFO][VoIP] 12-10-2021 02:40:39 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-10-2021 02:40:39 ===start stop voice wan
[INFO][DNS] 12-10-2021 02:40:38 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 02:40:38 Internet DNS ready.
[INFO][WAN] 12-10-2021 02:40:38 Stop WAN 8 IP Connection
[INFO][DNS] 12-10-2021 02:40:38 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 02:40:38 Internet DNS ready.
[INFO][DNS] 12-10-2021 02:40:38 Internet DNS deactivated.
[INFO][System] 12-10-2021 02:40:37 FSM---- Switch to Connect State.
[WARNING][WAN] 12-10-2021 02:40:37 WAN default route add to ppp10

gateway 84.59.211.1.
[INFO][WAN] 12-10-2021 02:40:37 Data WAN11 Activated!
[INFO][WAN] 12-10-2021 02:40:37 bud update WAN11 status to 2.
[INFO][WAN] 12-10-2021 02:40:37 PPPoE PADI has been sent from WAN
VDSL-DATA
[WARNING][WAN] 12-10-2021 02:40:37 WAN VDSL-DT is up, mode is PPPoE,
IP is 188.104.233.90.
[WARNING][WAN] 12-10-2021 02:40:37 WAN VDSL-DT is down.
[INFO][LAN] 12-10-2021 02:40:37 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 02:40:37 PPP CHAP MD5 authentication is
successful on WAN VDSL-DT
[INFO][LAN] 12-10-2021 02:40:37 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:40:37 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:40:37 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 02:40:37 PPPoE PADS has been received from
WAN VDSL-DT
[INFO][WAN] 12-10-2021 02:40:37 PPPoE PADR has been sent from WAN
VDSL-DT
[INFO][WAN] 12-10-2021 02:40:37 PPPoE PADO has been received from
WAN VDSL-DT, BRAS name is BLNCOS69101.
[INFO][WAN] 12-10-2021 02:40:37 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-10-2021 02:40:34 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 02:40:23 FSM---- Switch to Connect State.
[INFO][WAN] 12-10-2021 02:40:20 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-10-2021 02:40:20 PPPoE PADI has been sent from WAN
VDSL-DT
[EMERG][WAN] 12-10-2021 02:40:19 DSL link up.
[INFO][System] 12-10-2021 02:40:13 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 02:40:03 FSM---- Switch to Connect State.
[EMERG][WAN] 12-10-2021 02:40:00 DSL link up.
[INFO][LAN] 12-10-2021 02:39:59 LAN sending RA to ff02::1
[EMERG][WAN] 12-10-2021 02:39:59 DSL link up.
[EMERG][WAN] 12-10-2021 02:39:57 DSL link up.
[INFO][System] 12-10-2021 02:39:52 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 02:39:43 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 02:39:43 LAN sending RA to ff02::1
[EMERG][WAN] 12-10-2021 02:39:43 DSL link up.
[EMERG][WAN] 12-10-2021 02:39:41 DSL link up.
[EMERG][WAN] 12-10-2021 02:39:40 DSL link up.
[EMERG][WAN] 12-10-2021 02:39:39 DSL link up.
[EMERG][WAN] 12-10-2021 02:39:37 DSL link up.
[EMERG][WAN] 12-10-2021 02:39:36 DSL link up.
[EMERG][WAN] 12-10-2021 02:39:35 DSL link up.
[EMERG][WAN] 12-10-2021 02:39:33 DSL link up.
[INFO][System] 12-10-2021 02:39:33 FSM---- Switch to Connect State.
[EMERG][WAN] 12-10-2021 02:39:32 DSL link up.
[EMERG][WAN] 12-10-2021 02:39:31 DSL link up.
[EMERG][WAN] 12-10-2021 02:39:29 DSL link up.
[INFO][LAN] 12-10-2021 02:39:27 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 02:39:24 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-10-2021 02:39:24 PPPoE PADI has been sent from WAN

VDSL-DT

[INFO][System] 12-10-2021 02:39:22 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 02:39:13 FSM---- Switch to Connect State.
[INFO][WAN] 12-10-2021 02:39:11 PPPoE PADI has been sent from WAN

VDSL-DATA

[INFO][LAN] 12-10-2021 02:39:11 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:39:11 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:39:11 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:39:11 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:39:11 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 02:39:10 PPPoE PADI has been sent from WAN

VDSL-DT

[INFO][WAN] 12-10-2021 02:39:10 Start WAN 8 IP Connection
[INFO][WAN] 12-10-2021 02:39:10 WAN VDSL-DATA has been started, PHY link up

[INFO][LAN] 12-10-2021 02:39:10 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:39:10 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:39:10 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 02:39:10 Start WAN 10 IP Connection
[INFO][WAN] 12-10-2021 02:39:10 WAN VDSL-DT has been started, PHY link up

[INFO][LAN] 12-10-2021 02:39:10 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 02:39:09 Start WAN 8 DSL Connection
[INFO][LAN] 12-10-2021 02:39:09 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:39:09 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:39:09 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 02:39:09 Starting VDSL interface OK.
[INFO][WAN] 12-10-2021 02:39:09 Start WAN 10 DSL Connection
[INFO][WAN] 12-10-2021 02:39:09 Start WAN 4 DSL Connection
[EMERG][WAN] 12-10-2021 02:39:08 DSL link up.

[INFO][System] 12-10-2021 02:39:04 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 02:38:54 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 02:38:44 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 02:38:34 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 02:38:25 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 02:38:14 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 02:38:04 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 02:38:00 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 02:37:55 FSM---- Switch to Connect State.
[INFO][System] 12-10-2021 02:37:45 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 02:37:44 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 02:37:34 FSM---- Switch to Connect State.
[INFO][LAN] 12-10-2021 02:37:28 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 02:37:23 FSM---- Switch to Connect State.
[EMERG][WAN] 12-10-2021 02:37:22 DSL link down.
[INFO][System] 12-10-2021 02:37:13 FSM---- Switch to Connect State.
[INFO][WAN] 12-10-2021 02:37:12 WAN VDSL-DT has been stopped, please check your PHY link

[INFO][LAN] 12-10-2021 02:37:12 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:37:12 LAN sending RA to ff02::1
[INFO][WAN] 12-10-2021 02:37:12 Stopping VDSL interface OK.
[INFO][WAN] 12-10-2021 02:37:12 Stop WAN 10 DSL Connection
[INFO][LAN] 12-10-2021 02:37:12 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:37:12 LAN sending RA to ff02::1

[INFO][LAN] 12-10-2021 02:37:12 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 02:37:12 Starting HTTP redirect OK.
[INFO][DNS] 12-10-2021 02:37:12 DNSMasq proxy server enable redirect
[INFO][System] 12-10-2021 02:37:11 Stopping NTP Client OK.
[INFO][VoIP] 12-10-2021 02:37:11 VoIP WAN down, no available
connection
[INFO][VoIP] 12-10-2021 02:37:11 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-10-2021 02:37:11 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-10-2021 02:37:11 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-10-2021 02:37:11 ===start stop voice wan
[INFO][DNS] 12-10-2021 02:37:11 Internet DNS deactivated.
[INFO][LAN] 12-10-2021 02:37:11 LAN sending RA to ff02::1
[INFO][System] 12-10-2021 02:37:10 Starting NTP Client OK.
[INFO][System] 12-10-2021 02:37:10 Sync up with NTP Server failed.
[INFO][System] 12-10-2021 02:37:10 Stopping NTP Client OK.
[INFO][VoIP] 12-10-2021 02:37:10 VoIP WAN down, no available
connection
[INFO][VoIP] 12-10-2021 02:37:10 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-10-2021 02:37:10 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-10-2021 02:37:10 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-10-2021 02:37:10 ===start stop voice wan
[INFO][DNS] 12-10-2021 02:37:10 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 02:37:09 Internet DNS ready.
[INFO][DNS] 12-10-2021 02:37:09 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 02:37:09 Internet DNS ready.
[INFO][DNS] 12-10-2021 02:37:09 Internet DNS deactivated.
[INFO][System] 12-10-2021 02:37:09 Starting NTP Client OK.
[INFO][System] 12-10-2021 02:37:09 Sync up with NTP Server failed.
[INFO][WAN] 12-10-2021 02:37:09 WAN VDSL-DATA has been stopped,
please check your PHY link
[INFO][System] 12-10-2021 02:37:09 Stopping NTP Client OK.
[INFO][VoIP] 12-10-2021 02:37:09 VoIP WAN down, no available
connection
[INFO][VoIP] 12-10-2021 02:37:09 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-10-2021 02:37:09 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-10-2021 02:37:09 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-10-2021 02:37:09 ===start stop voice wan
[INFO][LAN] 12-10-2021 02:37:08 LAN sending RA to ff02::1
[INFO][DNS] 12-10-2021 02:37:08 Internet DNS Servers 176.95.16.250,
176.95.16.251.

[INFO][WAN] 12-10-2021 02:37:08 Stop WAN 4 DSL Connection
[INFO][DNS] 12-10-2021 02:37:08 Internet DNS ready.
[INFO][DNS] 12-10-2021 02:37:08 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-10-2021 02:37:08 Internet DNS ready.
[INFO][DNS] 12-10-2021 02:37:08 Internet DNS deactivated.
[INFO][WAN] 12-10-2021 02:37:08 Stop WAN 8 DSL Connection
[INFO][DNS] 12-10-2021 02:37:08 Internet DNS deactivated.
[INFO][WAN] 12-10-2021 02:37:08 Stop WAN 10 IP Connection
[INFO][WAN] 12-10-2021 02:37:08 IPTV WAN11 DeActivated!
[INFO][WAN] 12-10-2021 02:37:08 bud update WAN11 status to 0.
[INFO][LAN] 12-10-2021 02:37:07 LAN sending RA to ff02::1
[EMERG][WAN] 12-10-2021 02:37:07 DSL link down.
[WARNING][Firewall] 12-10-2021 02:37:07 SRC=192.168.2.102
DST=142.250.184.202 PROTO=TCP SPT=37284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:37:07 SRC=192.168.2.102
DST=142.250.184.202 PROTO=TCP SPT=37284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:37:07 SRC=192.168.2.102
DST=142.250.184.202 PROTO=TCP SPT=37284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:37:07 SRC=192.168.2.102
DST=142.250.184.202 PROTO=TCP SPT=37284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:37:07 SRC=192.168.2.102
DST=142.250.184.202 PROTO=TCP SPT=37284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:37:07 SRC=192.168.2.102
DST=142.250.184.202 PROTO=TCP SPT=37284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:37:07 SRC=192.168.2.102
DST=142.250.184.202 PROTO=TCP SPT=37284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:37:07 SRC=192.168.2.102
DST=104.21.59.155 PROTO=TCP SPT=37694 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:37:07 SRC=192.168.2.102
DST=104.21.59.155 PROTO=TCP SPT=37696 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:37:07 SRC=192.168.2.102
DST=142.250.184.202 PROTO=TCP SPT=37284 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 02:34:45 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 02:24:57 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 02:24:55 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 02:24:55 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 02:24:20 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 02:24:20 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 02:24:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60745 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:24:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60745 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:24:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60745 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:24:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60745 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 02:24:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60745 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60727 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60719 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60727 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 TCP Scan SRC=35.186.224.25
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60699 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.102
DST=172.67.179.219 PROTO=TCP SPT=58844 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.102
DST=172.67.179.219 PROTO=TCP SPT=58846 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39220 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60719 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60719 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60719 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60719 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60719 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60719 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60719 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60719 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60719 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60719 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:53:49 TCP Scan SRC=35.186.224.25
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60714 MARK=0x8000001
[INFO][LAN] 12-10-2021 01:49:03 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 01:45:21 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 01:38:13 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 01:34:07 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 01:29:59 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 01:23:46 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 01:23:46 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 01:23:07 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 01:23:06 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-10-2021 01:20:39 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 01:20:35 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 01:20:30 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-10-2021 01:20:30 unicasting packet to client yiaddr
[INFO][LAN] 12-10-2021 01:20:30 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 01:20:30 Arp reply received from the

requesting device itself.
[INFO][LAN] 12-10-2021 01:20:30 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 01:20:30 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-10-2021 01:20:30 Received a packet
[NOTICE][LAN] 12-10-2021 01:20:30 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-10-2021 01:20:30 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60711 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60711 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60711 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60711 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60711 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60711 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60703 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60711 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 TCP Scan SRC=35.186.224.25
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60707 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=33230 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=33226 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=33228 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=33224 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39194 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=33230 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=33226 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=33228 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=33224 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39194 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=33230 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=33226 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=33228 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102

DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60701 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=36614 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60922 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60920 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 01:20:30 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60924 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 01:14:30 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 01:05:46 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 00:55:54 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 00:52:33 wlan1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=36614 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60922 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60920 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60924 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=36614 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60922 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60920 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60924 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=36614 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60922 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60920 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60924 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=36614 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60922 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60920 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=60924 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=56884 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=56884 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=56884 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=56884 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60693 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.100
DST=104.156.59.44 PROTO=TCP SPT=60680 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60693 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60693 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60693 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60693 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60693 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60683 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60693 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 TCP Scan SRC=35.186.224.25
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60660 MARK=0x8000001
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39096 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=172.217.18.99 PROTO=TCP SPT=39586 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=172.217.18.99 PROTO=TCP SPT=39586 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=172.217.18.99 PROTO=TCP SPT=39586 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=172.217.18.99 PROTO=TCP SPT=39586 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=172.217.18.99 PROTO=TCP SPT=39586 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39096 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=172.217.18.99 PROTO=TCP SPT=39586 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=172.217.18.99 PROTO=TCP SPT=39586 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 00:52:33 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=172.217.18.99 PROTO=TCP SPT=39586 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=172.217.18.99 PROTO=TCP SPT=39586 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=172.217.18.99 PROTO=TCP SPT=39586 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=172.217.18.99 PROTO=TCP SPT=39586 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39096 DPT=443 MARK=0x3 DROP

```
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39096 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39096 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39096 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39096 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39096 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39096 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:52:33 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=39096 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-10-2021 00:52:31 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 00:47:59 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 00:38:09 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 00:36:22 Successfully assign IP
[192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time
[86400]
[INFO][LAN] 12-10-2021 00:36:22 unicasting packet to client ciaddr
[INFO][LAN] 12-10-2021 00:36:22 No valid arpreplies for this
address
[INFO][LAN] 12-10-2021 00:36:22 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-10-2021 00:36:22 Received REQUEST from client ip
[192.168.2.100] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-10-2021 00:36:22 Received a packet
[INFO][LAN] 12-10-2021 00:28:59 LAN sending RA to ff02::1
[NOTICE][LAN] 12-10-2021 00:28:12 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 00:28:12 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 00:25:43 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 00:25:43 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 00:25:22 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 00:25:22 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 00:23:37 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 00:23:37 SRC=192.168.2.102
DST=34.102.182.62 PROTO=TCP SPT=40348 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 00:23:37 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-10-2021 00:23:18 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 00:23:18 SRC=192.168.2.102
DST=34.102.182.62 PROTO=TCP SPT=40348 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-10-2021 00:23:18 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-10-2021 00:23:18 SRC=192.168.2.102
```


[WARNING][Firewall] 12-10-2021 00:07:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60673 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-10-2021 00:07:42 TCP Scan SRC=35.186.224.25
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60668 MARK=0x8000001
[INFO][LAN] 12-10-2021 00:03:24 LAN sending RA to ff02::1
[INFO][LAN] 12-10-2021 00:02:41 Successfully assign IP
[192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time
[86400]
[INFO][LAN] 12-10-2021 00:02:41 unicasting packet to client ciaddr
[INFO][LAN] 12-10-2021 00:02:41 No valid arp replies for this
address
[INFO][LAN] 12-10-2021 00:02:41 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-10-2021 00:02:41 Received REQUEST from client ip
[192.168.2.101] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-10-2021 00:02:41 Received a packet
[NOTICE][LAN] 12-09-2021 23:54:14 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 23:54:14 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 23:54:11 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 23:51:46 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 23:51:45 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 23:48:00 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 23:40:41 ACS: Timestamp(ms):1639093241
ACS-Trigger:TIMER Selected Channel:#1 (0x1001)
[EMERG][LAN] 12-09-2021 23:40:41 WIFI 2.4G Channel has been changed
from channel 10 to 1.
[WARNING][Firewall] 12-09-2021 23:40:41 TCP Scan SRC=107.178.240.159
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=53930 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 23:40:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60664 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:40:41 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=60649 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:40:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60664 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:40:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60664 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:40:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60664 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:40:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60664 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:40:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60664 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:40:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60664 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:40:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60650 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:40:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60664 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:40:41 SRC=192.168.2.100
DST=172.67.182.162 PROTO=TCP SPT=60653 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:40:41 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=60649 DPT=443 MARK=0x3 DROP

[INFO][LAN] 12-09-2021 23:40:11 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 23:37:00 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 23:36:27 TCP Scan SRC=142.250.186.42
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=39324 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.103
DST=54.77.160.229 PROTO=TCP SPT=49854 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.103
DST=54.77.160.229 PROTO=TCP SPT=49854 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.102 PROTO=TCP SPT=58800 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=60934 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.102 PROTO=TCP SPT=58800 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=60934 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.102 PROTO=TCP SPT=58800 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=60934 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.102 PROTO=TCP SPT=58800 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=60934 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.102 PROTO=TCP SPT=58800 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=60934 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.102 PROTO=TCP SPT=58800 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=60934 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.102 PROTO=TCP SPT=58800 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=60934 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.102 PROTO=TCP SPT=58800 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=60934 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.102 PROTO=TCP SPT=58800 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60650 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=172.67.182.162 PROTO=TCP SPT=60653 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100

DST=17.253.79.201 PROTO=TCP SPT=60649 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60650 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=172.67.182.162 PROTO=TCP SPT=60653 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60650 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=60649 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60650 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=172.67.182.162 PROTO=TCP SPT=60653 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60650 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=60649 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60650 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=172.67.182.162 PROTO=TCP SPT=60653 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60650 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=60649 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=172.67.182.162 PROTO=TCP SPT=60653 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=60649 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 TCP Scan SRC=17.253.79.201
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60649 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.8 PROTO=TCP SPT=38828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.41 PROTO=TCP SPT=40772 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.13.71 PROTO=TCP SPT=49318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=57556 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.8 PROTO=TCP SPT=38828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.41 PROTO=TCP SPT=40772 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.13.71 PROTO=TCP SPT=49318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=57556 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.8 PROTO=TCP SPT=38828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.41 PROTO=TCP SPT=40772 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102

DST=74.125.110.8 PROTO=TCP SPT=38828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.13.71 PROTO=TCP SPT=49318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=57556 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.106 PROTO=TCP SPT=39660 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=35700 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45086 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=173.194.165.138 PROTO=TCP SPT=52284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=44418 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.106 PROTO=TCP SPT=39660 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=35700 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45086 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=173.194.165.138 PROTO=TCP SPT=52284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=44418 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.106 PROTO=TCP SPT=39660 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 23:36:27 w11: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=35700 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45086 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=173.194.165.138 PROTO=TCP SPT=52284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=44418 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.106 PROTO=TCP SPT=39660 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=35700 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45086 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=173.194.165.138 PROTO=TCP SPT=52284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=44418 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.106 PROTO=TCP SPT=39660 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=35700 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45086 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102

DST=173.194.165.138 PROTO=TCP SPT=52284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=44418 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.106 PROTO=TCP SPT=39660 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=35700 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45086 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=173.194.165.138 PROTO=TCP SPT=52284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=44418 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=35700 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.106 PROTO=TCP SPT=39660 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45086 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=173.194.165.138 PROTO=TCP SPT=52284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=44418 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=35700 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.106 PROTO=TCP SPT=39660 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45086 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=173.194.165.138 PROTO=TCP SPT=52284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=44418 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.106 PROTO=TCP SPT=39660 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=35700 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=173.194.165.138 PROTO=TCP SPT=52284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=44418 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45086 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 TCP Scan SRC=142.250.184.195

```
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=59732 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45046 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=56682 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=172.217.19.78 PROTO=TCP SPT=41170 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45046 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=56682 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45046 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=56682 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45046 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=56682 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45046 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=56682 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45046 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=56682 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45046 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=56682 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45046 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=56682 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45046 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=56682 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=45046 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:36:27 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=56682 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 23:31:28 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 23:24:45 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 23:19:41 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 23:12:03 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 23:07:42 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-09-2021 23:07:36 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 23:07:36 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 23:07:36 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 23:07:36 Arp reply received from the
```

requesting device itself.
[INFO][LAN] 12-09-2021 23:07:36 Received REQUEST from client ip [0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 23:07:36 Received a packet
[INFO][LAN] 12-09-2021 23:07:35 Transmit reply to fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 23:07:35 Received information request from fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 23:07:35 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 23:07:35 wl0: AP-STA-CONNECTED 10:94:bb:d5:73:92
[INFO][LAN] 12-09-2021 23:06:59 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 23:06:31 wl0: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 23:06:31 wl1: AP-STA-DISCONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 23:06:24 wl1: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 23:06:24 wl0: AP-STA-DISCONNECTED bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 23:06:24 SRC=192.168.2.102 DST=142.250.185.129 PROTO=TCP SPT=38110 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:06:24 SRC=192.168.2.102 DST=142.250.181.214 PROTO=TCP SPT=52840 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 23:05:42 wl0: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 23:05:42 wl1: AP-STA-DISCONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 23:05:37 wl1: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 23:05:37 wl0: AP-STA-DISCONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 23:04:57 wl1: AP-STA-CONNECTED 6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 23:04:57 wl0: AP-STA-DISCONNECTED 6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60629 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 TCP Scan SRC=35.186.224.25 DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60631 MARK=0x8000001

[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=41546 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=37318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=37320 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=41548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=41546 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=37318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=37320 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=41548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=41546 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=37318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=37320 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=41548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=41546 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=37318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=37320 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=41548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=41546 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=37318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=37320 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=41548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 23:04:57 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=41546 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 22:57:25 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 22:53:37 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 22:53:37 wl1: AP-STA-DISCONNECTED

6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 22:52:35 wlo: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-09-2021 22:52:35 SRC=192.168.2.105
DST=52.98.214.66 PROTO=TCP SPT=59231 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 22:52:31 wlo: AP-STA-CONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.102
DST=74.125.110.8 PROTO=TCP SPT=37570 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.102
DST=74.125.110.8 PROTO=TCP SPT=37570 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.102
DST=74.125.110.8 PROTO=TCP SPT=37570 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.102
DST=74.125.110.8 PROTO=TCP SPT=37570 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.102
DST=74.125.110.8 PROTO=TCP SPT=37570 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.102
DST=74.125.110.8 PROTO=TCP SPT=37570 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.102
DST=74.125.110.8 PROTO=TCP SPT=37570 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.102
DST=74.125.110.8 PROTO=TCP SPT=37570 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.102
DST=74.125.110.8 PROTO=TCP SPT=37570 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60629 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60629 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60629 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60629 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60629 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60617 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60629 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:52:31 TCP Scan SRC=35.186.224.25
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60625 MARK=0x8000001
[INFO][LAN] 12-09-2021 22:49:37 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 22:45:34 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 22:40:37 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-09-2021 22:40:37 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 22:40:37 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-09-2021 22:40:37 Received a packet

[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=41900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=41900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=74.125.108.102 PROTO=TCP SPT=57488 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=74.125.108.102 PROTO=TCP SPT=57488 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=41900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=41900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=74.125.108.102 PROTO=TCP SPT=57488 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=173.194.165.139 PROTO=TCP SPT=34726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=173.194.165.139 PROTO=TCP SPT=34726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=173.194.165.139 PROTO=TCP SPT=34726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=173.194.165.139 PROTO=TCP SPT=34726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=173.194.165.139 PROTO=TCP SPT=34726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=173.194.165.139 PROTO=TCP SPT=34726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=173.194.165.139 PROTO=TCP SPT=34726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=173.194.165.139 PROTO=TCP SPT=34726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=173.194.165.139 PROTO=TCP SPT=34726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:39:37 SRC=192.168.2.102
DST=216.58.213.238 PROTO=TCP SPT=47546 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 22:33:31 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 22:28:23 wlan1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-09-2021 22:28:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60617 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:28:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60617 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:28:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60617 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:28:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60617 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:28:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60617 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:28:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60617 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:28:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:28:23 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=60617 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:28:23 TCP Scan SRC=35.186.224.25
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60616 MARK=0x8000001
[NOTICE][LAN] 12-09-2021 22:27:12 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:27:12 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 22:27:12 SRC=192.168.2.103
DST=54.77.160.229 PROTO=TCP SPT=49483 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:27:12 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=59580 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:27:12 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=59580 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:27:12 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=59580 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 22:24:24 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 22:22:01 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:22:01 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 22:22:01 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=59580 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:22:01 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=59580 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:22:01 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=59580 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:22:01 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=59580 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:22:01 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=59580 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:22:01 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=59580 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:22:01 SRC=192.168.2.102
DST=74.125.160.8 PROTO=TCP SPT=59580 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 22:20:23 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:20:23 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:20:13 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:20:13 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:20:02 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 22:20:02 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 22:19:56 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 22:19:39 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 22:19:21 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 22:19:11 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:19:11 wl1: AP-STA-DISCONNECTED

bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 22:19:11 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=53866 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:19:11 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=53868 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:19:11 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=53866 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:19:11 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=53868 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 22:17:08 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 22:17:08 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 22:17:08 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=53866 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:17:08 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=53868 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 22:17:00 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:17:00 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 22:17:00 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=53868 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:17:00 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=53866 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:17:00 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=53868 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:17:00 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=53866 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:17:00 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=53868 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:17:00 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=53866 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 22:16:34 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:16:34 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60600 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 TCP Scan SRC=35.186.224.25

DST=142.250.185.110 PROTO=TCP SPT=56416 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56412 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=74.125.160.9 PROTO=TCP SPT=39184 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=74.125.160.9 PROTO=TCP SPT=39182 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56414 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56416 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56412 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=74.125.160.9 PROTO=TCP SPT=39184 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=74.125.160.9 PROTO=TCP SPT=39182 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56414 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56416 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56412 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=74.125.160.9 PROTO=TCP SPT=39184 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=74.125.160.9 PROTO=TCP SPT=39182 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56414 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56416 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56412 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=74.125.160.9 PROTO=TCP SPT=39184 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56416 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56414 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=56412 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=74.125.160.9 PROTO=TCP SPT=39184 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:16:34 SRC=192.168.2.102
DST=74.125.160.9 PROTO=TCP SPT=39182 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 22:14:20 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 22:05:07 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:05:07 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 22:05:07 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=46526 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:05:07 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=46010 DPT=80 MARK=0x3 DROP

[INFO][LAN] 12-09-2021 22:05:06 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 22:04:28 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:04:28 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=46526 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=46010 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=142.250.181.194 PROTO=TCP SPT=49304 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=46526 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=46010 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=46526 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=46010 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=46526 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=46010 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=46526 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=46010 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=46526 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=46010 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=46526 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=46010 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=46526 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=46010 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=46526 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=46010 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=46526 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=46010 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=46526 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=46010 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 22:04:28 TCP Scan SRC=35.186.224.25
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=64739 MARK=0x8000001
[NOTICE][LAN] 12-09-2021 22:01:45 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:01:45 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:00:53 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 22:00:52 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][System] 12-09-2021 21:59:57 FSM---- Switch to Connect State.

[ERROR][System] 12-09-2021 21:59:48 TR069 connects to ACS server failed, http error 503.
[INFO][System] 12-09-2021 21:59:47 FSM---- Switch to Connect State.
[NOTICE][LAN] 12-09-2021 21:59:21 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 21:59:21 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 21:58:36 Successfully assign IP [192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time [86400]
[INFO][LAN] 12-09-2021 21:58:36 unicasting packet to client yiaddr [INFO][LAN] 12-09-2021 21:58:36 server_id = c0a80201
[INFO][LAN] 12-09-2021 21:58:36 Received REQUEST from client ip [0.0.0.0] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-09-2021 21:58:36 Received a packet
[INFO][LAN] 12-09-2021 21:58:36 unicasting packet to client yiaddr [INFO][LAN] 12-09-2021 21:58:36 Send OFFER of ip [192.168.2.102] to client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-09-2021 21:58:36 Find a lease info, and use the ip:6602a8c0
[INFO][LAN] 12-09-2021 21:58:36 Received DISCOVER from client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-09-2021 21:58:36 Received a packet
[INFO][LAN] 12-09-2021 21:58:36 unicasting packet to client yiaddr [INFO][LAN] 12-09-2021 21:58:36 Send OFFER of ip [192.168.2.102] to client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-09-2021 21:58:36 Find a lease info, and use the ip:6602a8c0
[INFO][LAN] 12-09-2021 21:58:36 Received DISCOVER from client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-09-2021 21:58:36 Received a packet
[INFO][LAN] 12-09-2021 21:58:36 unicasting packet to client yiaddr [INFO][LAN] 12-09-2021 21:58:36 Send OFFER of ip [192.168.2.102] to client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-09-2021 21:58:36 Find a lease info, and use the ip:6602a8c0
[INFO][LAN] 12-09-2021 21:58:36 Received DISCOVER from client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-09-2021 21:58:36 Received a packet
[INFO][LAN] 12-09-2021 21:58:36 unicasting packet to client yiaddr [INFO][LAN] 12-09-2021 21:58:36 Send OFFER of ip [192.168.2.102] to client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-09-2021 21:58:36 Find a lease info, and use the ip:6602a8c0
[INFO][LAN] 12-09-2021 21:58:36 No valid arp replies for this address
[INFO][LAN] 12-09-2021 21:58:35 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 21:58:34 Received DISCOVER from client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-09-2021 21:58:34 Received a packet
[NOTICE][LAN] 12-09-2021 21:58:34 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 21:56:29 Successfully assign IP [192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time

[86400]
[INFO][LAN] 12-09-2021 21:56:29 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 21:56:29 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 21:56:29 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 21:56:29 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 21:56:29 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-09-2021 21:56:29 Received a packet
[NOTICE][LAN] 12-09-2021 21:56:29 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-09-2021 21:56:29 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60600 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:56:29 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60600 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:56:29 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60600 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:56:29 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60600 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:56:29 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60600 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:56:29 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60591 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:56:29 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60600 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:56:29 TCP Scan SRC=35.186.224.25
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60595 MARK=0x8000001
[INFO][LAN] 12-09-2021 21:53:59 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 21:48:00 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-09-2021 21:48:00 SRC=192.168.2.105
DST=40.101.12.130 PROTO=TCP SPT=59283 DPT=993 MARK=0x1 DROP
[WARNING][Firewall] 12-09-2021 21:48:00 SRC=192.168.2.105
DST=40.101.12.130 PROTO=TCP SPT=59283 DPT=993 MARK=0x1 DROP
[WARNING][Firewall] 12-09-2021 21:48:00 SRC=192.168.2.105
DST=40.101.12.130 PROTO=TCP SPT=59283 DPT=993 MARK=0x1 DROP
[WARNING][Firewall] 12-09-2021 21:48:00 SRC=192.168.2.105
DST=52.98.214.66 PROTO=TCP SPT=59231 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:48:00 SRC=192.168.2.105
DST=52.98.214.66 PROTO=TCP SPT=59231 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:48:00 SRC=192.168.2.105
DST=52.98.214.66 PROTO=TCP SPT=59231 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:48:00 SRC=192.168.2.105
DST=52.98.214.66 PROTO=TCP SPT=59231 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:48:00 SRC=192.168.2.105
DST=52.98.214.66 PROTO=TCP SPT=59231 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:48:00 SRC=192.168.2.105
DST=52.98.214.66 PROTO=TCP SPT=59231 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 21:44:44 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 21:40:20 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 21:36:16 ACSID: Timestamp(ms):1639085776

ACS-Trigger:TIMER Selected Channel:#10 (0x100a)
[EMERG][LAN] 12-09-2021 21:36:16 WIFI 2.4G Channel has been changed from channel 9 to 10.
[WARNING][Firewall] 12-09-2021 21:36:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60591 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:36:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60591 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:36:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60591 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:36:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60591 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:36:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60591 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:36:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60591 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:36:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60581 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:36:16 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60591 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:36:16 TCP Scan SRC=35.186.224.25 DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60588 MARK=0x8000001
[INFO][LAN] 12-09-2021 21:35:25 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 21:35:09 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 21:35:09 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 21:35:09 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60581 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:35:09 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60581 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:35:09 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60581 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:35:09 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60581 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:35:09 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60581 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:35:09 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60581 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:35:09 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60581 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:35:09 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60581 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:35:09 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60569 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:35:09 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60581 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:35:09 TCP Scan SRC=35.186.224.25 DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60578 MARK=0x8000001
[INFO][LAN] 12-09-2021 21:30:43 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 21:25:27 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 21:17:17 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 21:13:27 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 21:10:38 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 21:10:38 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 21:10:38 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=60569 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 21:10:38 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60569 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:10:38 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60569 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:10:38 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60569 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:10:38 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60569 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:10:38 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60561 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:10:38 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60569 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 21:10:38 TCP Scan SRC=35.186.224.25
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60536 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 21:10:38 SRC=192.168.2.105
DST=3.217.106.147 PROTO=TCP SPT=59113 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 21:03:59 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 20:57:53 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 20:53:28 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 20:47:54 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 20:47:54 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 20:47:54 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 20:47:54 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 20:47:54 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 20:47:54 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 20:47:54 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 20:47:54 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 20:47:54 Received a packet
[NOTICE][LAN] 12-09-2021 20:47:54 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-09-2021 20:47:54 SRC=192.168.2.105
DST=92.122.21.194 PROTO=TCP SPT=58911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:47:54 SRC=192.168.2.105
DST=92.122.21.194 PROTO=TCP SPT=58910 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:47:54 SRC=192.168.2.105
DST=92.122.21.194 PROTO=TCP SPT=58911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:47:54 SRC=192.168.2.105
DST=92.122.21.194 PROTO=TCP SPT=58910 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:47:54 SRC=192.168.2.105
DST=92.122.21.194 PROTO=TCP SPT=58911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:47:54 SRC=192.168.2.105
DST=92.122.21.194 PROTO=TCP SPT=58910 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:47:54 SRC=192.168.2.105
DST=92.122.21.194 PROTO=TCP SPT=58911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:47:54 SRC=192.168.2.105
DST=92.122.21.194 PROTO=TCP SPT=58910 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:47:54 SRC=192.168.2.105
DST=92.122.21.194 PROTO=TCP SPT=58911 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:47:54 SRC=192.168.2.105
DST=92.122.21.194 PROTO=TCP SPT=58910 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60542 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60542 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60542 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=57954 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60542 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=176.31.232.236 PROTO=TCP SPT=57950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60542 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60542 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=60532 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 TCP Scan SRC=35.186.224.25
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=60540 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.100
DST=17.248.172.202 PROTO=TCP SPT=60463 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.100
DST=17.248.172.202 PROTO=TCP SPT=60461 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=57954 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=176.31.232.236 PROTO=TCP SPT=57950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=176.31.232.236 PROTO=TCP SPT=57950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=176.31.232.236 PROTO=TCP SPT=57950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=57954 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=176.31.232.236 PROTO=TCP SPT=57950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=57954 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=176.31.232.236 PROTO=TCP SPT=57950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=57954 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=176.31.232.236 PROTO=TCP SPT=57950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=176.31.232.236 PROTO=TCP SPT=57950 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=37.252.173.215 PROTO=TCP SPT=57967 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=57954 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=57938 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=176.31.232.236 PROTO=TCP SPT=57619 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=176.31.232.236 PROTO=TCP SPT=57619 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=37.252.172.123 PROTO=TCP SPT=57626 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=57622 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 20:38:52 SRC=192.168.2.105
DST=178.250.2.144 PROTO=TCP SPT=57602 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 20:34:10 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 20:27:12 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 20:20:45 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 20:16:01 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 20:09:12 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 19:59:17 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 19:51:56 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 19:42:03 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 19:33:48 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 19:26:03 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 19:26:03 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 19:26:02 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 19:26:01 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 19:26:01 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 19:26:01 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 19:25:59 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 19:25:59 Received a packet
[NOTICE][LAN] 12-09-2021 19:25:57 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-09-2021 19:24:30 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 19:20:34 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 19:20:34 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 19:20:34 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 19:20:34 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 19:20:34 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 19:20:34 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 19:20:34 Received a packet
[NOTICE][LAN] 12-09-2021 19:20:34 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 19:20:34 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=60497 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 19:20:34 SRC=192.168.2.100
DST=2.19.213.26 PROTO=TCP SPT=60505 DPT=443 MARK=0x3 DROP

[INFO][LAN] 12-09-2021 19:02:22 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 18:53:15 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 18:46:29 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 18:42:18 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 18:36:29 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 18:31:05 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 18:21:40 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 18:14:26 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 18:08:13 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 18:08:13 TCP Scan SRC=142.250.185.138
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=44152 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 18:08:13 SRC=192.168.2.102
DST=52.222.190.162 PROTO=TCP SPT=45062 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 18:08:13 SRC=192.168.2.102
DST=18.159.69.61 PROTO=TCP SPT=34902 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 18:08:13 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=52590 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 18:08:13 TCP Scan SRC=142.250.181.202
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=52592 MARK=0x8000001
[INFO][LAN] 12-09-2021 18:05:34 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 17:59:48 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 17:59:48 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 17:59:27 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 17:59:27 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 17:59:27 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:59:27 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 17:57:30 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 17:57:30 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 17:57:30 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:30 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:30 SRC=192.168.2.101
DST=35.162.31.154 PROTO=TCP SPT=64526 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:30 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:30 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 17:57:21 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 17:57:21 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 17:57:21 SRC=192.168.2.101
DST=35.162.31.154 PROTO=TCP SPT=64526 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:21 SRC=192.168.2.101

DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:21 SRC=192.168.2.101
DST=88.221.214.17 PROTO=TCP SPT=57779 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:21 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 17:57:19 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 17:57:19 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=35.186.224.18 PROTO=TCP SPT=64525 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=35.162.31.154 PROTO=TCP SPT=64526 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=35.186.224.18 PROTO=TCP SPT=64525 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=76.223.31.44 PROTO=TCP SPT=64524 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=35.162.31.154 PROTO=TCP SPT=64526 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=88.221.214.17 PROTO=TCP SPT=57779 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=35.186.224.18 PROTO=TCP SPT=64525 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=76.223.31.44 PROTO=TCP SPT=64524 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=35.186.224.18 PROTO=TCP SPT=64525 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=76.223.31.44 PROTO=TCP SPT=64524 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=35.162.31.154 PROTO=TCP SPT=64526 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=35.186.224.18 PROTO=TCP SPT=64525 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=76.223.31.44 PROTO=TCP SPT=64524 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=76.223.31.44 PROTO=TCP SPT=64524 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=35.186.224.18 PROTO=TCP SPT=64525 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=76.223.31.44 PROTO=TCP SPT=64524 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=35.186.224.18 PROTO=TCP SPT=64525 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101

DST=35.162.31.154 PROTO=TCP SPT=64526 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=34.98.74.57 PROTO=TCP SPT=64623 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=162.159.36.1 PROTO=TCP SPT=64621 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=142.251.39.99 PROTO=TCP SPT=57776 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 TCP Scan SRC=142.250.27.188
DST=2.207.1.100 PROTO=TCP SPT=5228 DPT=64517 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=88.221.214.17 PROTO=TCP SPT=57779 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=104.18.30.182 PROTO=TCP SPT=57780 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=162.159.36.1 PROTO=TCP SPT=64621 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:57:19 SRC=192.168.2.101
DST=162.159.36.1 PROTO=TCP SPT=64621 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 17:57:10 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 17:57:10 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 17:57:10 SRC=192.168.2.102
DST=216.58.213.202 PROTO=TCP SPT=53820 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 17:56:07 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 17:55:53 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 17:55:53 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.100
DST=93.184.220.66 PROTO=TCP SPT=60423 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=74.125.128.113 PROTO=TCP SPT=48118 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 TCP Scan SRC=52.3.28.229
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=59202 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 17:55:53 TCP Scan SRC=52.222.186.115
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=58558 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.186.142 PROTO=TCP SPT=59020 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.186.142 PROTO=TCP SPT=59022 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.186.142 PROTO=TCP SPT=59024 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 TCP Scan SRC=52.222.179.2
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=56262 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 17:55:53 TCP Scan SRC=142.250.181.202
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=51182 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=52790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=52790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=52790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=52790 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=52.92.129.243 PROTO=TCP SPT=41236 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=52.92.129.243 PROTO=TCP SPT=41236 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=52.92.129.243 PROTO=TCP SPT=41258 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=52.92.129.243 PROTO=TCP SPT=41256 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=52.92.129.243 PROTO=TCP SPT=41256 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=52.92.129.243 PROTO=TCP SPT=41258 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=52.92.129.243 PROTO=TCP SPT=41236 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=172.217.16.74 PROTO=TCP SPT=47096 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 TCP Scan SRC=52.222.186.64
DST=2.207.1.100 PROTO=TCP SPT=443 DPT=56638 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=52.177.138.113 PROTO=TCP SPT=60934 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=44.236.132.175 PROTO=TCP SPT=54876 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=52.210.133.22 PROTO=TCP SPT=40238 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=54476 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41224 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=54476 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41224 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=54476 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41224 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=54476 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=54476 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41224 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=54476 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=54476 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=54476 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=54476 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=80.156.82.166 PROTO=TCP SPT=54644 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=54476 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41224 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=52.232.209.85 PROTO=TCP SPT=33034 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41224 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41224 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41224 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41224 DPT=80 MARK=0x3 DROP
[EMERG][Firewall] 12-09-2021 17:55:53 DoS attack: SYN With Data
Attack from source: 92.205.26.63:5262
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=49068 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.100
DST=54.230.205.31 PROTO=TCP SPT=60105 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.100
DST=18.64.79.51 PROTO=TCP SPT=60080 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.100
DST=51.15.145.115 PROTO=TCP SPT=60124 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=172.217.16.74 PROTO=TCP SPT=47202 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41062 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 17:55:53 SRC=192.168.2.100
DST=159.223.3.242 PROTO=TCP SPT=60100 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 17:52:07 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 17:44:56 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 17:35:15 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 17:27:18 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 17:20:23 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 17:16:29 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 17:13:00 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 17:06:28 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:59:05 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:52:09 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:47:08 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 16:45:14 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 16:45:14 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 16:45:14 SRC=192.168.2.102
DST=172.217.16.74 PROTO=TCP SPT=47202 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:45:14 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41062 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:45:14 SRC=192.168.2.102
DST=92.122.22.147 PROTO=TCP SPT=47572 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 16:44:24 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 16:44:24 wl0: AP-STA-DISCONNECTED

bc:a5:8b:27:2d:ac

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=172.217.16.74 PROTO=TCP SPT=47202 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41062 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=172.217.16.74 PROTO=TCP SPT=47202 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41062 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=172.217.16.74 PROTO=TCP SPT=47202 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41062 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=172.217.16.74 PROTO=TCP SPT=47202 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41062 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=172.217.16.74 PROTO=TCP SPT=47202 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41062 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=172.217.16.74 PROTO=TCP SPT=47202 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41062 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=172.217.16.74 PROTO=TCP SPT=47202 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41062 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=172.217.16.74 PROTO=TCP SPT=47202 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:44:24 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=41062 DPT=80 MARK=0x3 DROP

[NOTICE][LAN] 12-09-2021 16:39:34 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd

[NOTICE][LAN] 12-09-2021 16:39:26 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d

[INFO][LAN] 12-09-2021 16:37:34 LAN sending RA to ff02::1

[NOTICE][LAN] 12-09-2021 16:34:49 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92

[WARNING][Firewall] 12-09-2021 16:34:49 SRC=192.168.2.105
DST=130.211.33.145 PROTO=TCP SPT=53576 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:34:49 SRC=192.168.2.105
DST=52.232.209.85 PROTO=TCP SPT=53579 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:34:49 SRC=192.168.2.105
DST=130.211.33.145 PROTO=TCP SPT=53576 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:34:49 SRC=192.168.2.105
DST=130.211.33.145 PROTO=TCP SPT=53576 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:34:49 SRC=192.168.2.105
DST=130.211.33.145 PROTO=TCP SPT=53576 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:34:49 SRC=192.168.2.105
DST=52.232.209.85 PROTO=TCP SPT=53579 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 16:34:49 SRC=192.168.2.105
DST=130.211.33.145 PROTO=TCP SPT=53576 DPT=443 MARK=0x3 DROP

DST=172.67.143.23 PROTO=TCP SPT=60021 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:27:36 SRC=192.168.2.100
DST=172.67.143.23 PROTO=TCP SPT=60021 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:27:36 SRC=192.168.2.100
DST=172.67.143.23 PROTO=TCP SPT=60021 DPT=80 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 16:26:11 w11: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 16:26:11 w10: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 16:25:55 w11: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 16:25:55 w10: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.2 PROTO=TCP SPT=50107 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.23 PROTO=TCP SPT=50108 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50112 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50113 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50114 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.2 PROTO=TCP SPT=50107 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.23 PROTO=TCP SPT=50108 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50112 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50113 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50114 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.2 PROTO=TCP SPT=50107 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.23 PROTO=TCP SPT=50108 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50112 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50113 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50114 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103

DST=157.240.210.14 PROTO=TCP SPT=50112 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50113 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50114 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.2 PROTO=TCP SPT=50107 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.23 PROTO=TCP SPT=50108 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50112 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50113 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50114 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.2 PROTO=TCP SPT=50107 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.23 PROTO=TCP SPT=50108 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50112 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50113 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50114 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.2 PROTO=TCP SPT=50107 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.23 PROTO=TCP SPT=50108 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50112 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50113 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50114 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50113 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=157.240.210.14 PROTO=TCP SPT=50112 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.23 PROTO=TCP SPT=50108 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:25:55 SRC=192.168.2.103
DST=179.60.192.2 PROTO=TCP SPT=50107 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 16:24:26 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:18:38 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 16:13:38 wlan1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[NOTICE][LAN] 12-09-2021 16:12:54 ACS-D: Timestamp(ms):1639066374
ACS-Trigger:TIMER Selected Channel:#9 (0x1009)
[EMERG][LAN] 12-09-2021 16:12:54 WIFI 2.4G Channel has been changed
from channel 8 to 9.
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.102

DST=216.58.212.161 PROTO=TCP SPT=49254 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.102
DST=74.125.133.100 PROTO=TCP SPT=52558 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.102
DST=216.58.213.246 PROTO=TCP SPT=42294 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.104
DST=92.122.20.228 PROTO=TCP SPT=61881 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.104
DST=92.122.20.228 PROTO=TCP SPT=61881 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.104
DST=92.122.20.228 PROTO=TCP SPT=61881 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.102
DST=34.120.24.208 PROTO=TCP SPT=50758 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.101
DST=162.159.36.1 PROTO=TCP SPT=64621 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.101
DST=142.251.39.99 PROTO=TCP SPT=57776 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.101
DST=162.159.36.1 PROTO=TCP SPT=64621 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.101
DST=162.159.36.1 PROTO=TCP SPT=64621 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.101
DST=162.159.36.1 PROTO=TCP SPT=64621 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.101
DST=104.18.30.182 PROTO=TCP SPT=57780 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.101
DST=88.221.214.17 PROTO=TCP SPT=57779 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.101
DST=142.251.39.99 PROTO=TCP SPT=57776 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.101
DST=104.18.30.182 PROTO=TCP SPT=57780 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.101
DST=88.221.214.17 PROTO=TCP SPT=57779 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.101
DST=142.251.39.99 PROTO=TCP SPT=57776 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 16:12:54 SRC=192.168.2.101
DST=104.18.30.182 PROTO=TCP SPT=57780 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 16:10:05 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:03:53 LAN sending RA to ff02::1
[INFO][VoIP] 12-09-2021 16:03:51 Switch to primary proxy server
arcor.de on line 0
[INFO][LAN] 12-09-2021 16:03:37 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:03:21 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 16:03:20 Sync up with NTP Server
successfully.
[INFO][System] 12-09-2021 16:03:17 Sync up with NTP Server
successfully.
[INFO][VoIP] 12-09-2021 16:03:10 Send data/single wan update to
VGW,wan id 10,ifName is ppp10,ipv4 address 2.207.1.100,ipv6
address ,default_wan_id 10,wan type 1
[INFO][VoIP] 12-09-2021 16:03:10 line 371 ,wan 10 start do data wan
up
[INFO][VoIP] 12-09-2021 16:03:10 wanipv6 = ,size = 0
[INFO][VoIP] 12-09-2021 16:03:10 Voice binding wan_id is

```
10,default_wan_id is 10
[INFO][VoIP] 12-09-2021 16:03:10 Voice binding wan_id is
10,default_wan_id is 10,is_ipv6 = 0
[INFO][VoIP] 12-09-2021 16:03:10 wan 10 service_type =
DATA,VOIP,MGNT,IPTV bud_voip_wan_id = 10
[INFO][VoIP] 12-09-2021 16:03:10 Interface wan_ip is 2.207.1.100,
wan_ip_v6 ,is_ipv6 0 wan up id 10
[INFO][LAN] 12-09-2021 16:03:10 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-09-2021 16:03:10 adapter index 18
[INFO][LAN] 12-09-2021 16:03:10 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-09-2021 16:03:10 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-09-2021 16:03:10 adapter index 18
[INFO][LAN] 12-09-2021 16:03:10 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-09-2021 16:03:10 Attaching option timezone to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option t2 to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option t1 to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option lease to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option dns to existing
member of list
[INFO][LAN] 12-09-2021 16:03:10 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO][LAN] 12-09-2021 16:03:10 adapter index 19
[INFO][LAN] 12-09-2021 16:03:10 br1 (our ip) = 192.168.3.1
[INFO][LAN] 12-09-2021 16:03:10 Attaching option dns to existing
member of list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option dns to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option router to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option subnet to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option timezone to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option t2 to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option t1 to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option lease to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option dns to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option timezone to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option t2 to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option t1 to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option lease to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option hostname to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option dns to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option domain to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option router to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option router to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option subnet to list
[INFO][LAN] 12-09-2021 16:03:10 Attaching option subnet to list
[INFO][LAN] 12-09-2021 16:03:10 error on select
[INFO][LAN] 12-09-2021 16:03:10 error on select
[INFO][LAN] 12-09-2021 16:03:10 udhcp server receive signal 12
[INFO][LAN] 12-09-2021 16:03:10 udhcp server receive signal 12
[INFO][System] 12-09-2021 16:03:08 Starting MCPD OK.
[INFO][System] 12-09-2021 16:03:08 Stopping MCPD OK.
[INFO][UMTS] 12-09-2021 16:03:08 iPhone DNS Policy activated
[INFO][VoIP] 12-09-2021 16:03:08 276 start wan service Voice
```

```
binding wan_id is 10
[INFO][VoIP] 12-09-2021 16:03:08 Voice binding wan_id is 10
[INFO][System] 12-09-2021 16:03:08 Starting NTP Client OK.
[INFO][System] 12-09-2021 16:03:08 Sync up with NTP Server failed.
[INFO][System] 12-09-2021 16:03:08 Stopping NTP Client OK.
[INFO][Firewall] 12-09-2021 16:03:07 PortMapping Rules have been
flushed on WAN VDSL-DT.
[INFO][Firewall] 12-09-2021 16:03:07 DMZ Rules has been flushed on
WAN VDSL-DT.
[INFO][Firewall] 12-09-2021 16:03:07 Static NAT Rules have been
flushed on WAN VDSL-DT.
[INFO][System] 12-09-2021 16:03:07 Stopping HTTP redirect OK.
[INFO][DNS] 12-09-2021 16:03:07 DNSMasq proxy server disable
redirect
[ERROR][DNS] 12-09-2021 16:03:07 failed to load names from /tmp/
dnsmasq_hosts.d/data_hosts: No such file or directory
[INFO][DNS] 12-09-2021 16:03:06 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 16:03:06 Internet DNS ready.
[INFO][DNS] 12-09-2021 16:03:06 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 16:03:06 Internet DNS ready.
[INFO][DNS] 12-09-2021 16:03:06 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 16:03:06 Internet DNS ready.
[INFO][DNS] 12-09-2021 16:03:06 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 16:03:06 Internet DNS ready.
[WARNING][DNS] 12-09-2021 16:03:06 ignoring nameserver 127.0.0.1 -
local interface
[WARNING][DNS] 12-09-2021 16:03:06 ignoring nameserver ::1 - local
interface
[INFO][DNS] 12-09-2021 16:03:06 Starting DNSMasq proxy server OK.
[INFO][DNS] 12-09-2021 16:03:06 Stopping DNSMasq proxy OK.
[INFO][System] 12-09-2021 16:03:06 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 16:03:05 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:03:05 LAN sending RA to ff02::1
[INFO][DNS] 12-09-2021 16:03:05 DNSMasq proxy server disable
redirect
[INFO][UMTS] 12-09-2021 16:03:04 iPhone DNS Policy actived
[INFO][VoIP] 12-09-2021 16:03:04 ignore useless wan down
[INFO][VoIP] 12-09-2021 16:03:04 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-09-2021 16:03:04 ===start stop voice wan
[INFO][VoIP] 12-09-2021 16:03:04 Remove interface wan_id is 10,wan
type 2.
[INFO][VoIP] 12-09-2021 16:03:04 VoIP WAN down, Voice trying to run
in backup mode, try binding wan_id is 10
[INFO][VoIP] 12-09-2021 16:03:04 bud data ipv4 wan status 10,ipv6
wan status -1
[INFO][VoIP] 12-09-2021 16:03:04 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
```

[INFO][VoIP] 12-09-2021 16:03:04 ===start stop voice wan
[INFO][System] 12-09-2021 16:03:04 Starting MCPD OK.
[INFO][System] 12-09-2021 16:03:04 Stopping MCPD OK.
[INFO][VoIP] 12-09-2021 16:03:04 ignore useless wan down
[INFO][VoIP] 12-09-2021 16:03:04 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-09-2021 16:03:04 ===start stop voice wan
[INFO][WAN] 12-09-2021 16:03:03 Stop WAN 8 IP Connection
[INFO][DNS] 12-09-2021 16:03:03 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 16:03:03 Internet DNS ready.
[INFO][DNS] 12-09-2021 16:03:03 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 16:03:03 Internet DNS ready.
[INFO][DNS] 12-09-2021 16:03:03 Internet DNS deactivated.
[WARNING][WAN] 12-09-2021 16:03:03 WAN default route add to ppp10
gateway 84.59.211.1.
[INFO][WAN] 12-09-2021 16:03:03 Data WAN11 Activated!
[INFO][WAN] 12-09-2021 16:03:03 bud update WAN11 status to 2.
[WARNING][WAN] 12-09-2021 16:03:02 WAN VDSL-DT is up, mode is PPPoE,
IP is 2.207.1.100.
[WARNING][WAN] 12-09-2021 16:03:02 WAN VDSL-DT is down.
[INFO][LAN] 12-09-2021 16:03:02 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 16:03:02 PPP CHAP MD5 authentication is
successful on WAN VDSL-DT
[INFO][LAN] 12-09-2021 16:03:02 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:03:02 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:03:02 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 16:03:02 PPPoE PADS has been received from
WAN VDSL-DT
[INFO][WAN] 12-09-2021 16:03:02 PPPoE PADR has been sent from WAN
VDSL-DT
[INFO][WAN] 12-09-2021 16:03:02 PPPoE PADO has been received from
WAN VDSL-DT, BRAS name is BLNCOS69101.
[INFO][WAN] 12-09-2021 16:03:02 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][WAN] 12-09-2021 16:03:02 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][System] 12-09-2021 16:02:57 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 16:02:48 FSM---- Switch to Connect State.
[INFO][WAN] 12-09-2021 16:02:45 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][WAN] 12-09-2021 16:02:45 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][System] 12-09-2021 16:02:39 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 16:02:30 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 16:02:24 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 16:02:20 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 16:02:10 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 16:02:08 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 16:02:00 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 16:01:52 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 16:01:51 FSM---- Switch to Connect State.

[INFO][WAN] 12-09-2021 16:01:49 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][WAN] 12-09-2021 16:01:49 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][System] 12-09-2021 16:01:42 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 16:01:36 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:01:36 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 16:01:36 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][LAN] 12-09-2021 16:01:36 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:01:36 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 16:01:36 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][LAN] 12-09-2021 16:01:36 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 16:01:35 Start WAN 10 IP Connection
[INFO][WAN] 12-09-2021 16:01:35 WAN VDSL-DT has been started, PHY
link up
[INFO][LAN] 12-09-2021 16:01:35 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:01:35 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:01:35 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 16:01:35 Start WAN 8 IP Connection
[INFO][WAN] 12-09-2021 16:01:35 WAN VDSL-DATA has been started, PHY
link up
[INFO][LAN] 12-09-2021 16:01:35 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 16:01:34 Start WAN 10 DSL Connection
[INFO][LAN] 12-09-2021 16:01:34 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:01:34 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 16:01:34 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 16:01:34 Starting VDSL interface OK.
[INFO][WAN] 12-09-2021 16:01:34 Start WAN 8 DSL Connection
[INFO][WAN] 12-09-2021 16:01:33 Start WAN 4 DSL Connection
[EMERG][WAN] 12-09-2021 16:01:33 DSL link up.
[INFO][System] 12-09-2021 16:01:31 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 16:01:22 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 16:01:13 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 16:01:04 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 16:00:55 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 16:00:47 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 16:00:37 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 16:00:27 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 16:00:22 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 16:00:17 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 16:00:07 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 16:00:06 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 15:59:57 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 15:59:50 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 15:59:46 FSM---- Switch to Connect State.
[EMERG][WAN] 12-09-2021 15:59:41 DSL link down.
[INFO][System] 12-09-2021 15:59:36 FSM---- Switch to Connect State.
[INFO][WAN] 12-09-2021 15:59:34 WAN VDSL-DT has been stopped, please
check your PHY link
[INFO][LAN] 12-09-2021 15:59:34 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 15:59:34 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 15:59:34 Stopping VDSL interface OK.

[INFO][WAN] 12-09-2021 15:59:34 Stop WAN 10 DSL Connection
[INFO][LAN] 12-09-2021 15:59:34 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 15:59:34 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 15:59:34 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 15:59:33 Starting HTTP redirect OK.
[INFO][DNS] 12-09-2021 15:59:33 DNSMasq proxy server enable redirect
[INFO][System] 12-09-2021 15:59:33 Stopping NTP Client OK.
[INFO][VoIP] 12-09-2021 15:59:33 VoIP WAN down, no available connection
[INFO][VoIP] 12-09-2021 15:59:33 Remove interface wan_id is 10,wan type 1.
[INFO][VoIP] 12-09-2021 15:59:33 bud data ipv4 wan status -1,ipv6 wan status -1
[INFO][VoIP] 12-09-2021 15:59:33 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 = 0,default_wan_id= 10
[INFO][VoIP] 12-09-2021 15:59:33 ===start stop voice wan
[INFO][DNS] 12-09-2021 15:59:33 Internet DNS deactivated.
[INFO][LAN] 12-09-2021 15:59:33 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 15:59:32 Starting NTP Client OK.
[INFO][System] 12-09-2021 15:59:32 Sync up with NTP Server failed.
[INFO][System] 12-09-2021 15:59:32 Stopping NTP Client OK.
[INFO][VoIP] 12-09-2021 15:59:32 VoIP WAN down, no available connection
[INFO][VoIP] 12-09-2021 15:59:32 Remove interface wan_id is 10,wan type 1.
[INFO][VoIP] 12-09-2021 15:59:32 bud data ipv4 wan status -1,ipv6 wan status -1
[INFO][VoIP] 12-09-2021 15:59:32 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 = 0,default_wan_id= 10
[INFO][VoIP] 12-09-2021 15:59:32 ===start stop voice wan
[INFO][WAN] 12-09-2021 15:59:32 WAN VDSL-DATA has been stopped, please check your PHY link
[INFO][DNS] 12-09-2021 15:59:31 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 15:59:31 Internet DNS ready.
[INFO][DNS] 12-09-2021 15:59:31 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 15:59:31 Internet DNS ready.
[INFO][DNS] 12-09-2021 15:59:31 Internet DNS deactivated.
[INFO][System] 12-09-2021 15:59:31 Starting NTP Client OK.
[INFO][System] 12-09-2021 15:59:31 Sync up with NTP Server failed.
[INFO][System] 12-09-2021 15:59:31 Stopping NTP Client OK.
[INFO][VoIP] 12-09-2021 15:59:31 VoIP WAN down, no available connection
[INFO][VoIP] 12-09-2021 15:59:31 Remove interface wan_id is 10,wan type 1.
[INFO][VoIP] 12-09-2021 15:59:31 bud data ipv4 wan status -1,ipv6 wan status -1
[INFO][VoIP] 12-09-2021 15:59:31 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 = 1,default_wan_id= 10
[INFO][VoIP] 12-09-2021 15:59:31 ===start stop voice wan

[INFO][LAN] 12-09-2021 15:59:31 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 15:59:31 Stop WAN 8 DSL Connection
[INFO][DNS] 12-09-2021 15:59:30 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 15:59:30 Internet DNS ready.
[INFO][DNS] 12-09-2021 15:59:30 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 15:59:30 Internet DNS ready.
[INFO][WAN] 12-09-2021 15:59:30 Stop WAN 4 DSL Connection
[INFO][DNS] 12-09-2021 15:59:30 Internet DNS deactivated.
[INFO][DNS] 12-09-2021 15:59:30 Internet DNS deactivated.
[INFO][WAN] 12-09-2021 15:59:30 Stop WAN 10 IP Connection
[INFO][WAN] 12-09-2021 15:59:30 IPTV WAN11 DeActivated!
[INFO][WAN] 12-09-2021 15:59:30 bud update WAN11 status to 0.
[INFO][LAN] 12-09-2021 15:59:30 LAN sending RA to ff02::1
[EMERG][WAN] 12-09-2021 15:59:30 DSL link down.
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=52.222.176.80 PROTO=TCP SPT=59566 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=52.222.176.80 PROTO=TCP SPT=59566 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 TCP Scan SRC=17.248.172.164
DST=92.77.119.121 PROTO=TCP SPT=443 DPT=59429 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59466 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:59:30 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=32870 DPT=443 MARK=0x3 DROP

[INFO][LAN] 12-09-2021 15:52:59 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 15:50:31 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:50:30 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=185.86.139.89 PROTO=TCP SPT=64467 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.1.106.65 PROTO=TCP SPT=64506 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=172.217.168.195 PROTO=TCP SPT=64438 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.227.38.32 PROTO=TCP SPT=64419 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=185.86.139.89 PROTO=TCP SPT=64467 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.227.38.32 PROTO=TCP SPT=64419 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.1.106.65 PROTO=TCP SPT=64506 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=172.217.168.195 PROTO=TCP SPT=64438 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=185.86.139.89 PROTO=TCP SPT=64467 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.227.38.32 PROTO=TCP SPT=64419 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.1.106.65 PROTO=TCP SPT=64506 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=172.217.168.195 PROTO=TCP SPT=64438 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=185.86.139.89 PROTO=TCP SPT=64467 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.227.38.32 PROTO=TCP SPT=64419 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.1.106.65 PROTO=TCP SPT=64506 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=172.217.168.195 PROTO=TCP SPT=64438 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.227.38.32 PROTO=TCP SPT=64419 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=185.86.139.89 PROTO=TCP SPT=64467 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.1.106.65 PROTO=TCP SPT=64506 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=172.217.168.195 PROTO=TCP SPT=64438 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101

DST=23.227.38.32 PROTO=TCP SPT=64419 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=185.86.139.89 PROTO=TCP SPT=64467 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.1.106.65 PROTO=TCP SPT=64506 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=172.217.168.195 PROTO=TCP SPT=64438 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.227.38.32 PROTO=TCP SPT=64419 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=185.86.139.89 PROTO=TCP SPT=64467 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.1.106.65 PROTO=TCP SPT=64506 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=172.217.168.195 PROTO=TCP SPT=64438 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.227.38.32 PROTO=TCP SPT=64419 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=185.86.139.89 PROTO=TCP SPT=64467 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=172.217.168.195 PROTO=TCP SPT=64438 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.1.106.65 PROTO=TCP SPT=64506 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.227.38.32 PROTO=TCP SPT=64419 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=172.217.168.195 PROTO=TCP SPT=64438 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=185.86.139.89 PROTO=TCP SPT=64467 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.1.106.65 PROTO=TCP SPT=64506 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.227.38.32 PROTO=TCP SPT=64419 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=172.217.168.195 PROTO=TCP SPT=64438 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=185.86.139.89 PROTO=TCP SPT=64467 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.1.106.65 PROTO=TCP SPT=64506 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:50:30 SRC=192.168.2.101
DST=23.227.38.32 PROTO=TCP SPT=64419 DPT=80 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:49:08 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:49:08 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:49:08 SRC=192.168.2.101
DST=172.217.168.195 PROTO=TCP SPT=64438 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:08 SRC=192.168.2.101
DST=23.227.38.32 PROTO=TCP SPT=64419 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:08 SRC=192.168.2.101
DST=185.86.139.89 PROTO=TCP SPT=64467 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:08 SRC=192.168.2.101
DST=23.1.106.65 PROTO=TCP SPT=64506 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:08 SRC=192.168.2.101

DST=3.214.112.227 PROTO=TCP SPT=64163 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:07 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=64163 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:07 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=64163 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:07 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=64163 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:07 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=64162 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:07 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=64163 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:07 SRC=192.168.2.101
DST=52.20.104.111 PROTO=TCP SPT=64150 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:07 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=64165 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:07 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=64164 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:49:07 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=64157 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 15:46:25 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 15:41:24 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 15:36:56 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:36:56 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:36:45 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:36:45 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:36:37 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:36:37 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:36:15 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:36:15 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:36:09 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:36:09 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:36:08 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:36:08 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:35:41 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:35:41 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:35:40 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:35:40 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101

DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64050 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=64085 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=34.252.255.244 PROTO=TCP SPT=64053 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:35:40 SRC=192.168.2.101
DST=99.84.156.20 PROTO=TCP SPT=63847 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:31:38 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:31:38 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 15:31:37 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 15:31:17 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:31:17 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:31:17 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=63889 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:31:17 SRC=192.168.2.101
DST=50.19.123.12 PROTO=TCP SPT=63900 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:30:59 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:30:59 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:30:53 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:30:53 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac

[WARNING][Firewall] 12-09-2021 15:26:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59417 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:23 TCP Scan SRC=35.186.224.25
DST=92.77.119.121 PROTO=TCP SPT=443 DPT=59347 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 15:26:23 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:23 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=63779 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:23 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63792 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:26:17 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:26:17 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:26:17 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:17 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:26:09 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:26:09 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=63779 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=63779 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=63779 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=63779 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=63779 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:26:09 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63792 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 15:25:34 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 15:25:22 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:25:22 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=63779 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=63779 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=63779 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=63779 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=63779 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101

DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63760 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63762 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63789 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63784 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63788 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=63787 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63760 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63762 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63760 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63762 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:25:22 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63763 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:24:36 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:24:36 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:24:36 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:36 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63760 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:36 SRC=192.168.2.101

DST=54.237.58.113 PROTO=TCP SPT=63762 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:36 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:36 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63770 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:24:25 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:24:25 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:24:25 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63760 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:25 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63762 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:25 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:25 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63770 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:24:13 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:24:13 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:24:13 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63760 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:13 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63762 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:13 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63763 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:24:07 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:24:07 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:24:07 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:07 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63760 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:07 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63762 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:07 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:24:07 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63770 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:23:57 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:23:57 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:23:55 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:23:55 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:23:55 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=63770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:23:55 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63760 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:23:55 SRC=192.168.2.101

DST=54.237.58.113 PROTO=TCP SPT=63761 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:23:55 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=63760 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:22:55 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:22:55 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:22:54 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:22:53 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:22:53 SRC=192.168.2.105
DST=104.131.31.75 PROTO=TCP SPT=52843 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:22:19 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:22:19 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 15:21:58 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 15:21:58 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 15:21:58 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 15:21:55 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 15:21:55 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 15:21:55 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 15:21:55 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 15:21:55 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 15:21:55 Received a packet
[NOTICE][LAN] 12-09-2021 15:21:54 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 15:21:45 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:21:45 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 15:21:03 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 15:20:10 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:20:10 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:20:09 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:20:09 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:19:37 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:19:37 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:19:30 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE] [LAN] 12-09-2021 15:19:30 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:19:30 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:19:29 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:18:35 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:18:35 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:18:18 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:18:18 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:18:00 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:18:00 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:17:59 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:17:59 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:17:58 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:17:58 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:17:49 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:17:49 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:17:34 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:17:34 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO] [LAN] 12-09-2021 15:17:20 LAN sending RA to ff02::1
[NOTICE] [LAN] 12-09-2021 15:17:08 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:17:08 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:16:30 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:16:30 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:16:24 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:16:24 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:16:23 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:16:23 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:16:15 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 15:16:14 w10: AP-STA-DISCONNECTED

bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:16:14 TCP Scan SRC=142.250.186.138
DST=92.77.119.121 PROTO=TCP SPT=443 DPT=58120 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 15:16:14 SRC=192.168.2.102
DST=35.190.25.25 PROTO=TCP SPT=43666 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 15:16:03 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:16:03 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:16:02 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:16:02 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:15:55 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:15:55 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:15:47 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:15:47 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:15:47 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:15:46 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:15:20 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:15:20 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:15:14 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:15:14 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 15:15:14 SRC=192.168.2.101
DST=185.60.217.28 PROTO=TCP SPT=63620 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:15:14 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59417 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:15:14 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59417 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:15:14 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59417 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:15:14 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59417 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:15:14 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59417 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:15:14 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59417 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:15:14 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59417 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 15:15:14 TCP Scan SRC=34.98.74.57
DST=92.77.119.121 PROTO=TCP SPT=443 DPT=59391 MARK=0x8000001
[INFO][LAN] 12-09-2021 15:10:48 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 15:07:10 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-09-2021 15:07:10 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:07:09 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:07:09 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:07:05 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:07:05 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:06:55 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:06:55 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:06:04 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:06:04 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:05:36 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:05:36 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:05:15 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:05:15 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:05:09 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:05:09 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 15:04:16 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 15:04:11 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 15:04:11 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 14:59:25 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 14:58:03 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 14:58:03 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 14:57:00 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 14:57:00 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 14:57:00 SRC=192.168.2.101
DST=35.83.142.224 PROTO=TCP SPT=63498 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 14:56:43 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 14:56:43 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[EMERG][Firewall] 12-09-2021 14:56:43 DoS attack: SYN With Data
Attack from source: 178.239.21.125:5114
[WARNING][Firewall] 12-09-2021 14:56:43 SRC=192.168.2.100
DST=3.222.194.124 PROTO=TCP SPT=59247 DPT=8884 MARK=0x1 DROP

[WARNING][Firewall] 12-09-2021 14:56:43 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=59358 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:56:43 SRC=192.168.2.100
DST=17.57.146.167 PROTO=TCP SPT=59233 DPT=5223 MARK=0x1 DROP
[WARNING][Firewall] 12-09-2021 14:56:43 SRC=192.168.2.101
DST=35.241.11.240 PROTO=TCP SPT=63453 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:56:43 SRC=192.168.2.101
DST=34.139.78.128 PROTO=TCP SPT=63435 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:56:43 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=63407 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:56:43 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=63405 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:56:43 SRC=192.168.2.101
DST=35.162.31.154 PROTO=TCP SPT=63380 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:56:43 SRC=192.168.2.101
DST=35.186.224.25 PROTO=TCP SPT=63388 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:56:43 SRC=192.168.2.101
DST=35.186.224.25 PROTO=TCP SPT=63391 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:56:43 SRC=192.168.2.101
DST=142.250.179.195 PROTO=TCP SPT=63378 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 14:51:36 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:45:20 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:36:17 LAN sending RA to ff02::1
[INFO][VoIP] 12-09-2021 14:36:10 Switch to primary proxy server
arcor.de on line 0
[INFO][LAN] 12-09-2021 14:36:01 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:35:45 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 14:35:44 Sync up with NTP Server
successfully.
[INFO][System] 12-09-2021 14:35:41 Sync up with NTP Server
successfully.
[INFO][VoIP] 12-09-2021 14:35:34 Send data/single wan update to
VGW,wan id 10,ifName is ppp10,ipv4 address 92.77.119.121,ipv6
address ,default_wan_id 10,wan type 1
[INFO][VoIP] 12-09-2021 14:35:34 line 371 ,wan 10 start do data wan
up
[INFO][VoIP] 12-09-2021 14:35:34 wanipv6 = ,size = 0
[INFO][VoIP] 12-09-2021 14:35:34 Voice binding wan_id is
10,default_wan_id is 10
[INFO][VoIP] 12-09-2021 14:35:34 Voice binding wan_id is
10,default_wan_id is 10,is_ipv6 = 0
[INFO][VoIP] 12-09-2021 14:35:34 wan 10 service_type =
DATA,VOIP,MGNT,IPTV bud_voip_wan_id = 10
[INFO][VoIP] 12-09-2021 14:35:34 Interface wan_ip is 92.77.119.121,
wan_ip_v6 ,is_ipv6 0 wan up id 10
[INFO][LAN] 12-09-2021 14:35:34 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-09-2021 14:35:34 adapter index 18
[INFO][LAN] 12-09-2021 14:35:34 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-09-2021 14:35:34 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-09-2021 14:35:34 adapter index 18
[INFO][LAN] 12-09-2021 14:35:34 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-09-2021 14:35:34 Attaching option timezone to list


```
[INFO][LAN] 12-09-2021 14:35:34 Attaching option t2 to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option t1 to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option lease to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option dns to existing
member of list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option dns to existing
member of list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option dns to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option router to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option subnet to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option timezone to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option t2 to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option t1 to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option lease to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option dns to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option hostname to list
[INFO][LAN] 12-09-2021 14:35:34 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO][LAN] 12-09-2021 14:35:34 adapter index 19
[INFO][LAN] 12-09-2021 14:35:34 br1 (our ip) = 192.168.3.1
[INFO][LAN] 12-09-2021 14:35:34 Attaching option timezone to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option t2 to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option t1 to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option lease to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option domain to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option dns to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option router to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option router to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option subnet to list
[INFO][LAN] 12-09-2021 14:35:34 Attaching option subnet to list
[INFO][LAN] 12-09-2021 14:35:34 error on select
[INFO][LAN] 12-09-2021 14:35:34 error on select
[INFO][LAN] 12-09-2021 14:35:34 udhcp server receive signal 12
[INFO][LAN] 12-09-2021 14:35:34 udhcp server receive signal 12
[INFO][System] 12-09-2021 14:35:32 Starting MCPD OK.
[INFO][System] 12-09-2021 14:35:31 Stopping MCPD OK.
[INFO][UMTS] 12-09-2021 14:35:31 iPhone DNS Policy activated
[INFO][VoIP] 12-09-2021 14:35:31 276 start wan service Voice
binding wan_id is 10
[INFO][VoIP] 12-09-2021 14:35:31 Voice binding wan_id is 10
[INFO][System] 12-09-2021 14:35:31 Starting NTP Client OK.
[INFO][System] 12-09-2021 14:35:31 Sync up with NTP Server failed.
[INFO][System] 12-09-2021 14:35:31 Stopping NTP Client OK.
[INFO][Firewall] 12-09-2021 14:35:30 PortMapping Rules have been
flushed on WAN VDSL-DT.
[INFO][System] 12-09-2021 14:35:30 FSM---- Switch to Connect State.
[INFO][Firewall] 12-09-2021 14:35:30 DMZ Rules has been flushed on
WAN VDSL-DT.
[INFO][Firewall] 12-09-2021 14:35:30 Static NAT Rules have been
flushed on WAN VDSL-DT.
[INFO][System] 12-09-2021 14:35:30 Stopping HTTP redirect OK.
[INFO][DNS] 12-09-2021 14:35:30 DNSMasq proxy server disable
redirect
[ERROR][DNS] 12-09-2021 14:35:30 failed to load names from /tmp/
```

```
dnsmasq_hosts.d/data_hosts: No such file or directory
[INFO][DNS] 12-09-2021 14:35:30 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 14:35:30 Internet DNS ready.
[INFO][DNS] 12-09-2021 14:35:30 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 14:35:30 Internet DNS ready.
[INFO][DNS] 12-09-2021 14:35:30 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 14:35:30 Internet DNS ready.
[INFO][DNS] 12-09-2021 14:35:30 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 14:35:30 Internet DNS ready.
[WARNING][DNS] 12-09-2021 14:35:30 ignoring nameserver 127.0.0.1 -
local interface
[WARNING][DNS] 12-09-2021 14:35:30 ignoring nameserver ::1 - local
interface
[INFO][DNS] 12-09-2021 14:35:30 Starting DNSMasq proxy server OK.
[INFO][DNS] 12-09-2021 14:35:29 Stopping DNSMasq proxy OK.
[INFO][LAN] 12-09-2021 14:35:29 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:35:29 LAN sending RA to ff02::1
[INFO][DNS] 12-09-2021 14:35:28 DNSMasq proxy server disable
redirect
[INFO][UMTS] 12-09-2021 14:35:28 iPhone DNS Policy activated
[INFO][VoIP] 12-09-2021 14:35:27 ignore useless wan down
[INFO][VoIP] 12-09-2021 14:35:27 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-09-2021 14:35:27 ===start stop voice wan
[INFO][VoIP] 12-09-2021 14:35:27 Remove interface wan_id is 10,wan
type 2.
[INFO][VoIP] 12-09-2021 14:35:27 VoIP WAN down, Voice trying to run
in backup mode, try binding wan_id is 10
[INFO][VoIP] 12-09-2021 14:35:27 bud data ipv4 wan status 10,ipv6
wan status -1
[INFO][VoIP] 12-09-2021 14:35:27 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-09-2021 14:35:27 ===start stop voice wan
[INFO][System] 12-09-2021 14:35:27 Starting MCPD OK.
[INFO][System] 12-09-2021 14:35:27 Stopping MCPD OK.
[INFO][VoIP] 12-09-2021 14:35:27 ignore useless wan down
[INFO][VoIP] 12-09-2021 14:35:27 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-09-2021 14:35:27 ===start stop voice wan
[INFO][WAN] 12-09-2021 14:35:27 Stop WAN 8 IP Connection
[INFO][DNS] 12-09-2021 14:35:26 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 14:35:26 Internet DNS ready.
[INFO][DNS] 12-09-2021 14:35:26 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 14:35:26 Internet DNS ready.
[INFO][DNS] 12-09-2021 14:35:26 Internet DNS deactivated.
```

[WARNING][WAN] 12-09-2021 14:35:26 WAN default route add to ppp10 gateway 84.59.211.1.
[INFO][WAN] 12-09-2021 14:35:26 Data WAN11 Activated!
[INFO][WAN] 12-09-2021 14:35:26 bud update WAN11 status to 2.
[WARNING][WAN] 12-09-2021 14:35:26 WAN VDSL-DT is up, mode is PPPoE, IP is 92.77.119.121.
[WARNING][WAN] 12-09-2021 14:35:26 WAN VDSL-DT is down.
[INFO][LAN] 12-09-2021 14:35:26 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 14:35:26 PPP CHAP MD5 authentication is successful on WAN VDSL-DT
[INFO][LAN] 12-09-2021 14:35:26 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:35:26 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:35:26 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 14:35:26 PPPoE PADS has been received from WAN VDSL-DT
[INFO][WAN] 12-09-2021 14:35:25 PPPoE PADR has been sent from WAN VDSL-DT
[INFO][WAN] 12-09-2021 14:35:25 PPPoE PADO has been received from WAN VDSL-DT, BRAS name is BLNCOS69101.
[INFO][WAN] 12-09-2021 14:35:25 PPPoE PADI has been sent from WAN VDSL-DT
[INFO][WAN] 12-09-2021 14:35:25 PPPoE PADI has been sent from WAN VDSL-DATA
[INFO][System] 12-09-2021 14:35:22 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 14:35:13 FSM---- Switch to Connect State.
[INFO][WAN] 12-09-2021 14:35:08 PPPoE PADI has been sent from WAN VDSL-DT
[INFO][WAN] 12-09-2021 14:35:08 PPPoE PADI has been sent from WAN VDSL-DATA
[INFO][System] 12-09-2021 14:35:04 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 14:34:54 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 14:34:44 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 14:34:35 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 14:34:26 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 14:34:20 Successfully assign IP [192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time [86400]
[INFO][LAN] 12-09-2021 14:34:20 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 14:34:20 No valid arp replies for this address
[INFO][LAN] 12-09-2021 14:34:20 Arp reply received from the requesting device itself.
[INFO][LAN] 12-09-2021 14:34:20 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:34:20 Received REQUEST from client ip [0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 14:34:20 Received a packet
[NOTICE][LAN] 12-09-2021 14:34:20 wl0: AP-STA-CONNECTED 6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 14:34:16 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 14:34:15 FSM---- Switch to Connect State.
[INFO][WAN] 12-09-2021 14:34:12 PPPoE PADI has been sent from WAN VDSL-DT
[INFO][WAN] 12-09-2021 14:34:12 PPPoE PADI has been sent from WAN VDSL-DATA

[INFO][System] 12-09-2021 14:34:04 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 14:33:59 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 14:33:59 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][LAN] 12-09-2021 14:33:59 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:33:59 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:33:59 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 14:33:59 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-09-2021 14:33:59 Start WAN 10 IP Connection
[INFO][WAN] 12-09-2021 14:33:59 WAN VDSL-DT has been started, PHY
link up
[INFO][LAN] 12-09-2021 14:33:59 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:33:59 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:33:58 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 14:33:58 Start WAN 8 IP Connection
[INFO][WAN] 12-09-2021 14:33:58 WAN VDSL-DATA has been started, PHY
link up
[INFO][WAN] 12-09-2021 14:33:58 Start WAN 10 DSL Connection
[INFO][WAN] 12-09-2021 14:33:57 Start WAN 4 DSL Connection
[INFO][LAN] 12-09-2021 14:33:57 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:33:57 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:33:57 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 14:33:57 Starting VDSL interface OK.
[INFO][WAN] 12-09-2021 14:33:57 Start WAN 8 DSL Connection
[EMERG][WAN] 12-09-2021 14:33:57 DSL link up.
[INFO][System] 12-09-2021 14:33:54 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 14:33:44 FSM---- Switch to Connect State.
[NOTICE][LAN] 12-09-2021 14:33:43 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][System] 12-09-2021 14:33:34 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 14:33:23 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 14:33:13 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 14:33:03 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 14:32:52 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 14:32:50 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 14:32:43 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 14:32:34 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 14:32:33 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 14:32:24 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 14:32:18 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 14:32:14 FSM---- Switch to Connect State.
[EMERG][WAN] 12-09-2021 14:32:10 DSL link down.
[INFO][System] 12-09-2021 14:32:04 FSM---- Switch to Connect State.
[INFO][WAN] 12-09-2021 14:32:02 WAN VDSL-DT has been stopped, please
check your PHY link
[INFO][LAN] 12-09-2021 14:32:02 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:32:02 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 14:32:02 Stopping VDSL interface OK.
[INFO][WAN] 12-09-2021 14:32:02 Stop WAN 10 DSL Connection
[INFO][LAN] 12-09-2021 14:32:02 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:32:02 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 14:32:02 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 14:32:02 Starting HTTP redirect OK.

[INFO][DNS] 12-09-2021 14:32:02 DNSMasq proxy server enable redirect
[INFO][System] 12-09-2021 14:32:02 Stopping NTP Client OK.
[INFO][VoIP] 12-09-2021 14:32:01 VoIP WAN down, no available
connection
[INFO][VoIP] 12-09-2021 14:32:01 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-09-2021 14:32:01 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-09-2021 14:32:01 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-09-2021 14:32:01 ===start stop voice wan
[INFO][DNS] 12-09-2021 14:32:01 Internet DNS deactivated.
[INFO][LAN] 12-09-2021 14:32:01 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 14:32:01 Starting NTP Client OK.
[INFO][System] 12-09-2021 14:32:01 Sync up with NTP Server failed.
[INFO][System] 12-09-2021 14:32:01 Stopping NTP Client OK.
[INFO][VoIP] 12-09-2021 14:32:00 VoIP WAN down, no available
connection
[INFO][VoIP] 12-09-2021 14:32:00 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-09-2021 14:32:00 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-09-2021 14:32:00 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-09-2021 14:32:00 ===start stop voice wan
[INFO][DNS] 12-09-2021 14:32:00 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 14:32:00 Internet DNS ready.
[INFO][DNS] 12-09-2021 14:32:00 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 14:32:00 Internet DNS ready.
[INFO][DNS] 12-09-2021 14:32:00 Internet DNS deactivated.
[INFO][WAN] 12-09-2021 14:32:00 WAN VDSL-DATA has been stopped,
please check your PHY link
[INFO][LAN] 12-09-2021 14:31:59 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 14:31:59 Starting NTP Client OK.
[INFO][System] 12-09-2021 14:31:59 Sync up with NTP Server failed.
[INFO][System] 12-09-2021 14:31:59 Stopping NTP Client OK.
[INFO][VoIP] 12-09-2021 14:31:59 VoIP WAN down, no available
connection
[INFO][VoIP] 12-09-2021 14:31:59 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-09-2021 14:31:59 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-09-2021 14:31:59 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-09-2021 14:31:59 ===start stop voice wan
[INFO][WAN] 12-09-2021 14:31:59 Stop WAN 4 DSL Connection
[INFO][WAN] 12-09-2021 14:31:59 Stop WAN 8 DSL Connection
[INFO][DNS] 12-09-2021 14:31:59 Internet DNS Servers 176.95.16.250,
176.95.16.251.

[INFO][DNS] 12-09-2021 14:31:59 Internet DNS ready.
[INFO][DNS] 12-09-2021 14:31:59 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 14:31:59 Internet DNS ready.
[INFO][DNS] 12-09-2021 14:31:59 Internet DNS deactivated.
[INFO][WAN] 12-09-2021 14:31:59 Stop WAN 10 IP Connection
[INFO][DNS] 12-09-2021 14:31:58 Internet DNS deactivated.
[EMERG][WAN] 12-09-2021 14:31:58 DSL link down.
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=51.158.29.13 PROTO=TCP SPT=62716 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59344 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59344 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59344 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59344 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59344 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59344 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59336 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59344 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59344 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 TCP Scan SRC=35.186.224.25
DST=188.107.212.39 PROTO=TCP SPT=443 DPT=59301 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62646 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62646 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62648 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62646 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62648 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62648 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62646 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62648 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62648 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62646 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62648 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62646 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62648 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 14:31:58 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=62646 DPT=443 MARK=0x3 DROP

DST=2.19.213.32 PROTO=TCP SPT=59317 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=2.19.213.26 PROTO=TCP SPT=59320 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 TCP Scan SRC=2.19.213.26
DST=188.107.212.39 PROTO=TCP SPT=443 DPT=59320 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=52.94.223.37 PROTO=TCP SPT=52055 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=62.149.0.72 PROTO=TCP SPT=51838 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=185.33.221.91 PROTO=TCP SPT=51842 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=37.252.172.38 PROTO=TCP SPT=51823 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=202.241.208.4 PROTO=TCP SPT=51831 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:57:44 SRC=192.168.2.105
DST=54.85.124.37 PROTO=TCP SPT=51708 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 13:57:34 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 13:52:45 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 13:47:24 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 13:42:33 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 13:39:03 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 13:38:43 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:38:43 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac

[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.105
DST=18.185.164.146 PROTO=TCP SPT=51607 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.105
DST=34.194.30.250 PROTO=TCP SPT=51600 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.105
DST=185.33.220.100 PROTO=TCP SPT=51628 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=2.19.213.75 PROTO=TCP SPT=59290 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59300 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59297 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 TCP Scan SRC=35.186.224.25
DST=188.107.212.39 PROTO=TCP SPT=443 DPT=59305 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.102
DST=52.222.186.97 PROTO=TCP SPT=45540 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.102
DST=172.217.16.67 PROTO=TCP SPT=39062 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:38:43 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=54162 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 13:35:12 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 13:30:27 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 13:27:38 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:27:38 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:27:12 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:27:12 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-09-2021 13:27:11 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:27:11 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:26:43 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:26:43 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 13:26:26 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 13:26:26 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 13:26:26 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 13:26:23 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 13:26:23 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 13:26:23 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 13:26:23 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 13:26:23 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 13:26:23 Received a packet
[NOTICE][LAN] 12-09-2021 13:26:22 wl1: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 13:26:22 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=2.19.213.75 PROTO=TCP SPT=59290 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59300 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59297 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59297 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=2.19.213.75 PROTO=TCP SPT=59290 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59300 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59297 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=2.19.213.75 PROTO=TCP SPT=59290 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59300 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59297 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59297 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=2.19.213.75 PROTO=TCP SPT=59290 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59300 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59283 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59297 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59297 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59300 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=2.19.213.75 PROTO=TCP SPT=59290 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59300 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 SRC=192.168.2.100
DST=2.19.213.75 PROTO=TCP SPT=59290 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:26:22 TCP Scan SRC=2.19.213.75
DST=188.107.212.39 PROTO=TCP SPT=443 DPT=59290 MARK=0x8000001
[NOTICE][LAN] 12-09-2021 13:17:32 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:17:32 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 13:16:41 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 13:16:22 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:16:22 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 13:16:22 SRC=192.168.2.105
DST=136.243.157.167 PROTO=TCP SPT=50674 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:16:22 SRC=192.168.2.105
DST=136.243.157.167 PROTO=TCP SPT=50675 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:16:22 SRC=192.168.2.105
DST=136.243.157.167 PROTO=TCP SPT=50676 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:16:22 SRC=192.168.2.105
DST=99.80.191.196 PROTO=TCP SPT=50635 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:16:22 SRC=192.168.2.105
DST=54.217.249.13 PROTO=TCP SPT=50634 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:16:22 SRC=192.168.2.105
DST=3.251.21.8 PROTO=TCP SPT=50636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:16:22 SRC=192.168.2.105
DST=136.243.25.9 PROTO=TCP SPT=50670 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:16:22 SRC=192.168.2.105
DST=136.243.25.9 PROTO=TCP SPT=50671 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:16:22 SRC=192.168.2.105
DST=136.243.25.9 PROTO=TCP SPT=50632 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:16:22 SRC=192.168.2.105
DST=136.243.25.9 PROTO=TCP SPT=50630 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 13:11:12 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:11:12 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 13:11:12 SRC=192.168.2.105
DST=136.243.25.120 PROTO=TCP SPT=50625 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 13:10:53 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:10:53 w11: AP-STA-DISCONNECTED


```

DST=34.149.12.213 PROTO=TCP SPT=50445 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=176.31.110.195 PROTO=TCP SPT=50412 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=34.149.12.213 PROTO=TCP SPT=50545 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=34.149.12.213 PROTO=TCP SPT=50445 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=136.243.25.120 PROTO=TCP SPT=50551 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:10:53 SRC=192.168.2.105
DST=172.217.19.68 PROTO=TCP SPT=50312 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 13:10:46 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 13:06:11 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 13:06:11 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 13:06:10 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 13:06:09 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 13:06:09 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 13:06:09 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 13:06:09 Received a packet
[INFO][LAN] 12-09-2021 13:06:09 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 13:06:09 unicasting packet to client yiaddr

```

[INFO][LAN] 12-09-2021 13:06:09 No valid arp replies for this address
[INFO][LAN] 12-09-2021 13:06:07 Received REQUEST from client ip [0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 13:06:07 Received a packet
[NOTICE][LAN] 12-09-2021 13:06:05 wl0: AP-STA-CONNECTED 10:94:bb:d5:73:92
[INFO][LAN] 12-09-2021 13:05:49 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 13:04:20 wl1: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:04:20 wl0: AP-STA-DISCONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:04:12 wl0: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:04:12 wl1: AP-STA-DISCONNECTED bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 13:04:12 SRC=192.168.2.102 DST=40.70.161.102 PROTO=TCP SPT=60684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:04:12 SRC=192.168.2.102 DST=52.208.115.66 PROTO=TCP SPT=45776 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 13:02:13 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 13:01:37 wl1: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:01:37 wl0: AP-STA-DISCONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:01:33 wl0: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 13:01:33 wl1: AP-STA-DISCONNECTED bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 13:01:33 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=59283 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:01:33 SRC=192.168.2.100 DST=17.253.79.201 PROTO=TCP SPT=59273 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:01:33 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=59283 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:01:33 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=59283 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:01:33 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=59283 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:01:33 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=59283 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:01:33 SRC=192.168.2.100 DST=17.248.172.237 PROTO=TCP SPT=59244 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:01:33 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=59283 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:01:33 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=59283 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:01:33 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=59268 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:01:33 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=59283 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 13:01:33 TCP Scan SRC=35.186.224.25 DST=188.107.212.39 PROTO=TCP SPT=443 DPT=59278 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 13:01:33 SRC=192.168.2.100 DST=17.253.79.202 PROTO=TCP SPT=59263 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 12:57:02 wl1: AP-STA-CONNECTED

bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:57:02 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:56:43 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:56:43 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:56:42 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:56:42 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:56:40 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:56:40 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 12:56:24 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 12:56:21 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-09-2021 12:56:21 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 12:56:21 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-09-2021 12:56:21 Received a packet
[INFO][LAN] 12-09-2021 12:56:21 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-09-2021 12:56:21 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 12:56:21 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 12:56:19 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 12:56:19 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-09-2021 12:56:19 Received a packet
[NOTICE][LAN] 12-09-2021 12:56:19 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-09-2021 12:52:48 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 12:52:46 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 12:52:46 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 12:52:44 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 12:52:44 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 12:52:44 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 12:52:44 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 12:52:43 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 12:52:43 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 12:52:43 Received a packet
[NOTICE][LAN] 12-09-2021 12:52:43 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd

[WARNING][Firewall] 12-09-2021 12:52:43 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=55078 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 12:49:57 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:49:57 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:49:50 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:49:50 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 12:49:50 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=55078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:49:50 SRC=192.168.2.102
DST=80.156.82.165 PROTO=TCP SPT=38144 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:49:50 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=55078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:49:50 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=55078 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 12:49:15 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:49:14 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 12:49:14 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=55078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:49:14 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=55078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:49:14 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=55078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:49:14 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=55078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:49:14 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=55078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:49:14 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=55078 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 12:47:54 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:47:54 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 12:47:54 SRC=192.168.2.102
DST=54.194.133.78 PROTO=TCP SPT=44572 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 12:47:43 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 12:46:21 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:46:21 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 12:46:21 SRC=192.168.2.102
DST=54.194.133.78 PROTO=TCP SPT=44572 DPT=80 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 12:45:59 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:45:59 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:45:41 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:45:41 w10: AP-STA-DISCONNECTED

bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:45:40 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:45:40 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.102
DST=54.194.133.78 PROTO=TCP SPT=44572 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59273 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59268 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=59263 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59273 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59268 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=59263 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59268 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59273 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59243 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=59263 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59268 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59258 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59273 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=17.248.172.237 PROTO=TCP SPT=59244 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59268 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=59263 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59268 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59273 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=59263 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.100
DST=17.253.79.201 PROTO=TCP SPT=59273 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 TCP Scan SRC=17.253.79.202
DST=188.107.212.39 PROTO=TCP SPT=443 DPT=59263 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.102
DST=54.194.133.78 PROTO=TCP SPT=44572 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:45:40 SRC=192.168.2.102

DST=35.186.224.47 PROTO=TCP SPT=59258 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59258 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59258 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.100
DST=17.248.172.237 PROTO=TCP SPT=59244 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59258 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59243 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59258 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59258 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.100
DST=17.248.172.237 PROTO=TCP SPT=59244 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 TCP Scan SRC=35.186.224.25
DST=188.107.212.39 PROTO=TCP SPT=443 DPT=59256 MARK=0x80000001
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.100
DST=17.248.172.237 PROTO=TCP SPT=59244 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=35.188.42.15 PROTO=TCP SPT=61848 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:33:32 SRC=192.168.2.101
DST=99.84.156.80 PROTO=TCP SPT=61836 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 12:27:09 Successfully assign IP
[192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time
[86400]

[INFO][LAN] 12-09-2021 12:27:09 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 12:27:09 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 12:27:09 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 12:27:09 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 12:27:09 Received REQUEST from client ip
[0.0.0.0] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-09-2021 12:27:09 Received a packet
[NOTICE][LAN] 12-09-2021 12:23:08 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:23:08 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:23:08 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:23:08 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 12:23:08 SRC=192.168.2.102
DST=40.70.161.7 PROTO=TCP SPT=35460 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:23:08 SRC=192.168.2.101
DST=51.158.29.13 PROTO=TCP SPT=61833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:23:08 SRC=192.168.2.101
DST=99.84.156.36 PROTO=TCP SPT=61803 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:23:08 SRC=192.168.2.101
DST=54.191.24.14 PROTO=TCP SPT=61813 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:23:08 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=61808 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:23:08 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=61799 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 12:19:37 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 12:16:01 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:16:01 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:15:59 wl0: AP-STA-CONNECTED
50:ed:3c:2f:b6:42
[NOTICE][LAN] 12-09-2021 12:15:59 wl1: AP-STA-DISCONNECTED
50:ed:3c:2f:b6:42
[WARNING][Firewall] 12-09-2021 12:15:59 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=50992 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 12:15:28 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 12:15:07 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:15:07 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:12:40 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:12:40 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:10:45 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:10:45 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 12:10:45 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=59243 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:10:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59243 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:10:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59243 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:10:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=59243 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 12:10:45 TCP Scan SRC=23.63.148.30
DST=188.107.212.39 PROTO=TCP SPT=443 DPT=59249 MARK=0x8000001
[INFO][LAN] 12-09-2021 12:09:26 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 12:06:25 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 12:03:23 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:03:22 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 12:01:35 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 12:00:24 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:00:24 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:00:23 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 12:00:23 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 11:58:09 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 11:57:50 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:57:50 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:57:29 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:57:29 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:56:16 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:56:16 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:56:13 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:56:13 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:56:05 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:56:05 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:56:02 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:56:02 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:54:24 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:54:24 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 11:54:24 SRC=192.168.2.101

DST=173.199.54.10 PROTO=TCP SPT=61605 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:54:24 SRC=192.168.2.101
DST=185.33.220.244 PROTO=TCP SPT=61632 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:54:24 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=61603 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:54:24 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=61599 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:54:24 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=61605 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 11:48:39 LAN sending RA to ff02::1
[INFO][VoIP] 12-09-2021 11:43:07 Switch to primary proxy server
arcor.de on line 0
[INFO][LAN] 12-09-2021 11:43:04 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 11:42:54 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:42:54 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 11:42:48 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:42:41 Successfully assign IP
[192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time
[86400]
[INFO][LAN] 12-09-2021 11:42:41 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 11:42:41 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 11:42:41 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 11:42:41 Received REQUEST from client ip
[0.0.0.0] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-09-2021 11:42:41 Received a packet
[NOTICE][LAN] 12-09-2021 11:42:39 wl1: AP-STA-CONNECTED
50:ed:3c:2f:b6:42
[NOTICE][LAN] 12-09-2021 11:42:39 wl0: AP-STA-DISCONNECTED
50:ed:3c:2f:b6:42
[WARNING][Firewall] 12-09-2021 11:42:39 SRC=192.168.2.101
DST=142.250.185.101 PROTO=TCP SPT=61554 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:42:39 SRC=192.168.2.101
DST=35.186.224.25 PROTO=TCP SPT=61558 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 11:42:32 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 11:42:32 Sync up with NTP Server
successfully.
[INFO][System] 12-09-2021 11:42:28 Sync up with NTP Server
successfully.
[INFO][System] 12-09-2021 11:42:26 Sync up with NTP Server
successfully.
[INFO][VoIP] 12-09-2021 11:42:21 Send data/single wan update to
VGW,wan id 10,ifName is ppp10,ipv4 address 188.107.212.39,ipv6
address ,default_wan_id 10,wan type 1
[INFO][VoIP] 12-09-2021 11:42:21 line 371 ,wan 10 start do data wan
up
[INFO][VoIP] 12-09-2021 11:42:21 wanipv6 = ,size = 0
[INFO][VoIP] 12-09-2021 11:42:21 Voice binding wan_id is
10,default_wan_id is 10
[INFO][VoIP] 12-09-2021 11:42:21 Voice binding wan_id is
10,default_wan_id is 10,is_ipv6 = 0

```
[INFO][VoIP] 12-09-2021 11:42:21 wan 10 service_type =
DATA,VOIP,MGNT,IPTV bud_voip_wan_id = 10
[INFO][VoIP] 12-09-2021 11:42:21 Interface wan_ip is 188.107.212.39,
wan_ip_v6 ,is_ipv6 0 wan up id 10
[INFO][LAN] 12-09-2021 11:42:20 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-09-2021 11:42:20 adapter index 18
[INFO][LAN] 12-09-2021 11:42:20 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-09-2021 11:42:20 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-09-2021 11:42:20 adapter index 18
[INFO][LAN] 12-09-2021 11:42:20 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-09-2021 11:42:20 Attaching option timezone to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option t2 to list
[INFO][LAN] 12-09-2021 11:42:20 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO][LAN] 12-09-2021 11:42:20 adapter index 19
[INFO][LAN] 12-09-2021 11:42:20 br1 (our ip) = 192.168.3.1
[INFO][LAN] 12-09-2021 11:42:20 Attaching option timezone to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option t2 to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option t1 to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option lease to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option dns to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option router to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option subnet to list
[INFO][LAN] 12-09-2021 11:42:20 error on select
[INFO][LAN] 12-09-2021 11:42:20 udhcp server receive signal 12
[INFO][LAN] 12-09-2021 11:42:20 Attaching option t1 to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option lease to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option dns to existing
member of list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option dns to existing
member of list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option dns to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option router to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option subnet to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option timezone to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option t2 to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option t1 to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option lease to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option dns to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option hostname to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option domain to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option router to list
[INFO][LAN] 12-09-2021 11:42:20 Attaching option subnet to list
[INFO][LAN] 12-09-2021 11:42:20 error on select
[INFO][LAN] 12-09-2021 11:42:20 udhcp server receive signal 12
[INFO][System] 12-09-2021 11:42:19 Starting MCPD OK.
[INFO][System] 12-09-2021 11:42:19 Stopping MCPD OK.
[INFO][UMTS] 12-09-2021 11:42:19 iPhone DNS Policy actived
[INFO][VoIP] 12-09-2021 11:42:19 276 start wan service Voice
binding wan_id is 10
[INFO][VoIP] 12-09-2021 11:42:19 Voice binding wan_id is 10
[INFO][System] 12-09-2021 11:42:19 Starting NTP Client OK.
```

[INFO][System] 12-09-2021 11:42:19 Sync up with NTP Server failed.
[INFO][System] 12-09-2021 11:42:19 Stopping NTP Client OK.
[INFO][Firewall] 12-09-2021 11:42:18 PortMapping Rules have been flushed on WAN VDSL-DT.
[INFO][Firewall] 12-09-2021 11:42:18 DMZ Rules has been flushed on WAN VDSL-DT.
[INFO][Firewall] 12-09-2021 11:42:18 Static NAT Rules have been flushed on WAN VDSL-DT.
[INFO][System] 12-09-2021 11:42:18 Stopping HTTP redirect OK.
[INFO][DNS] 12-09-2021 11:42:18 DNSMasq proxy server disable redirect
[INFO][DNS] 12-09-2021 11:42:17 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 11:42:17 Internet DNS ready.
[INFO][DNS] 12-09-2021 11:42:17 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 11:42:17 Internet DNS ready.
[INFO][DNS] 12-09-2021 11:42:17 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 11:42:17 Internet DNS ready.
[INFO][DNS] 12-09-2021 11:42:17 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 11:42:17 Internet DNS ready.
[WARNING][DNS] 12-09-2021 11:42:17 ignoring nameserver 127.0.0.1 - local interface
[WARNING][DNS] 12-09-2021 11:42:17 ignoring nameserver ::1 - local interface
[INFO][DNS] 12-09-2021 11:42:17 Starting DNSMasq proxy server OK.
[INFO][DNS] 12-09-2021 11:42:17 Stopping DNSMasq proxy OK.
[INFO][System] 12-09-2021 11:42:17 FSM---- Switch to Connect State.
[ERROR][System] 12-09-2021 11:42:17 TR069 connects to ACS server failed, couldn't resolve.
[INFO][DNS] 12-09-2021 11:42:16 DNSMasq proxy server disable redirect
[INFO][LAN] 12-09-2021 11:42:16 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:42:15 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 11:42:15 FSM---- Switch to Connect State.
[INFO][UMTS] 12-09-2021 11:42:15 iPhone DNS Policy actived
[INFO][VoIP] 12-09-2021 11:42:14 Remove interface wan_id is 10,wan type 2.
[INFO][VoIP] 12-09-2021 11:42:14 VoIP WAN down, Voice trying to run in backup mode, try binding wan_id is 10
[INFO][VoIP] 12-09-2021 11:42:14 bud data ipv4 wan status 10,ipv6 wan status -1
[INFO][VoIP] 12-09-2021 11:42:14 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 = 0,default_wan_id= 10
[INFO][VoIP] 12-09-2021 11:42:14 ===start stop voice wan
[INFO][System] 12-09-2021 11:42:14 Starting MCPD OK.
[INFO][System] 12-09-2021 11:42:14 Stopping MCPD OK.
[INFO][VoIP] 12-09-2021 11:42:14 ignore useless wan down
[INFO][VoIP] 12-09-2021 11:42:14 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 = 0,default_wan_id= 10

[INFO][VoIP] 12-09-2021 11:42:14 ===start stop voice wan
[INFO][DNS] 12-09-2021 11:42:14 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 11:42:14 Internet DNS ready.
[INFO][DNS] 12-09-2021 11:42:13 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 11:42:13 Internet DNS ready.
[INFO][VoIP] 12-09-2021 11:42:13 ignore useless wan down
[INFO][VoIP] 12-09-2021 11:42:13 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-09-2021 11:42:13 ===start stop voice wan
[INFO][DNS] 12-09-2021 11:42:13 Internet DNS deactivated.
[INFO][WAN] 12-09-2021 11:42:13 Stop WAN 8 IP Connection
[WARNING][WAN] 12-09-2021 11:42:13 WAN default route add to ppp10
gateway 84.59.211.1.
[INFO][WAN] 12-09-2021 11:42:13 Data WAN11 Activated!
[INFO][WAN] 12-09-2021 11:42:13 bud update WAN11 status to 2.
[WARNING][WAN] 12-09-2021 11:42:13 WAN VDSL-DT is up, mode is PPPoE,
IP is 188.107.212.39.
[WARNING][WAN] 12-09-2021 11:42:13 WAN VDSL-DT is down.
[INFO][LAN] 12-09-2021 11:42:13 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 11:42:13 PPP CHAP MD5 authentication is
successful on WAN VDSL-DT
[INFO][LAN] 12-09-2021 11:42:13 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:42:13 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 11:42:13 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][LAN] 12-09-2021 11:42:13 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 11:42:13 PPPoE PADS has been received from
WAN VDSL-DT
[INFO][WAN] 12-09-2021 11:42:13 PPPoE PADR has been sent from WAN
VDSL-DT
[INFO][WAN] 12-09-2021 11:42:13 PPPoE PADO has been received from
WAN VDSL-DT, BRAS name is BLNCOS69101.
[INFO][WAN] 12-09-2021 11:42:12 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-09-2021 11:42:05 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 11:41:56 FSM---- Switch to Connect State.
[INFO][WAN] 12-09-2021 11:41:56 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-09-2021 11:41:55 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-09-2021 11:41:47 FSM---- Switch to Connect State.
[NOTICE][LAN] 12-09-2021 11:41:41 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:41:41 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][System] 12-09-2021 11:41:36 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 11:41:35 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 11:41:27 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 11:41:19 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 11:41:18 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 11:41:08 FSM---- Switch to Connect State.

[INFO][LAN] 12-09-2021 11:41:03 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 11:40:59 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-09-2021 11:40:59 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-09-2021 11:40:59 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 11:40:48 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 11:40:47 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 11:40:46 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-09-2021 11:40:46 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][LAN] 12-09-2021 11:40:46 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:40:46 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:40:46 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:40:46 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:40:46 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:40:46 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:40:46 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 11:40:46 Start WAN 8 IP Connection
[INFO][WAN] 12-09-2021 11:40:46 Start WAN 10 IP Connection
[INFO][WAN] 12-09-2021 11:40:46 WAN VDSL-DATA has been started, PHY
link up
[INFO][WAN] 12-09-2021 11:40:46 WAN VDSL-DT has been started, PHY
link up
[INFO][WAN] 12-09-2021 11:40:45 Start WAN 4 DSL Connection
[INFO][LAN] 12-09-2021 11:40:45 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:40:45 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:40:45 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 11:40:45 Starting VDSL interface OK.
[INFO][WAN] 12-09-2021 11:40:45 Start WAN 10 DSL Connection
[INFO][WAN] 12-09-2021 11:40:45 Start WAN 8 DSL Connection
[EMERG][WAN] 12-09-2021 11:40:44 DSL link up.
[INFO][System] 12-09-2021 11:40:38 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 11:40:30 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 11:40:20 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 11:40:11 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 11:40:00 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 11:39:49 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 11:39:37 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 11:39:34 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 11:39:26 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 11:39:18 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 11:39:15 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 11:39:06 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 11:39:02 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 11:38:57 FSM---- Switch to Connect State.
[EMERG][WAN] 12-09-2021 11:38:54 DSL link down.
[INFO][System] 12-09-2021 11:38:47 FSM---- Switch to Connect State.
[INFO][WAN] 12-09-2021 11:38:46 WAN VDSL-DT has been stopped, please
check your PHY link
[INFO][LAN] 12-09-2021 11:38:46 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:38:46 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 11:38:46 Stopping VDSL interface OK.
[INFO][WAN] 12-09-2021 11:38:46 Stop WAN 10 DSL Connection

[INFO][LAN] 12-09-2021 11:38:46 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:38:46 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:38:46 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 11:38:46 Starting HTTP redirect OK.
[INFO][DNS] 12-09-2021 11:38:46 DNSMasq proxy server enable redirect
[INFO][System] 12-09-2021 11:38:45 Stopping NTP Client OK.
[INFO][VoIP] 12-09-2021 11:38:45 VoIP WAN down, no available
connection
[INFO][VoIP] 12-09-2021 11:38:45 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-09-2021 11:38:45 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-09-2021 11:38:45 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-09-2021 11:38:45 ===start stop voice wan
[NOTICE][LAN] 12-09-2021 11:38:45 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[INFO][DNS] 12-09-2021 11:38:45 Internet DNS deactivated.
[NOTICE][LAN] 12-09-2021 11:38:45 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 11:38:45 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 11:38:45 Starting NTP Client OK.
[INFO][System] 12-09-2021 11:38:44 Sync up with NTP Server failed.
[INFO][System] 12-09-2021 11:38:44 Stopping NTP Client OK.
[INFO][VoIP] 12-09-2021 11:38:44 VoIP WAN down, no available
connection
[INFO][VoIP] 12-09-2021 11:38:44 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-09-2021 11:38:44 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-09-2021 11:38:44 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-09-2021 11:38:44 ===start stop voice wan
[INFO][DNS] 12-09-2021 11:38:44 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 11:38:44 Internet DNS ready.
[INFO][DNS] 12-09-2021 11:38:44 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 11:38:44 Internet DNS ready.
[INFO][DNS] 12-09-2021 11:38:44 Internet DNS deactivated.
[INFO][WAN] 12-09-2021 11:38:43 WAN VDSL-DATA has been stopped,
please check your PHY link
[INFO][System] 12-09-2021 11:38:43 Starting NTP Client OK.
[INFO][System] 12-09-2021 11:38:43 Sync up with NTP Server failed.
[INFO][System] 12-09-2021 11:38:43 Stopping NTP Client OK.
[INFO][LAN] 12-09-2021 11:38:43 LAN sending RA to ff02::1
[INFO][VoIP] 12-09-2021 11:38:43 VoIP WAN down, no available
connection
[INFO][VoIP] 12-09-2021 11:38:43 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-09-2021 11:38:43 bud data ipv4 wan status -1,ipv6
wan status -1

[INFO][VoIP] 12-09-2021 11:38:43 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 10, is_ipv6 = 1, default_wan_id= 10
[INFO][VoIP] 12-09-2021 11:38:43 ==start stop voice wan
[INFO][WAN] 12-09-2021 11:38:43 Stop WAN 4 DSL Connection
[INFO][DNS] 12-09-2021 11:38:42 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 11:38:42 Internet DNS ready.
[INFO][DNS] 12-09-2021 11:38:42 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 11:38:42 Internet DNS ready.
[INFO][DNS] 12-09-2021 11:38:42 Internet DNS deactivated.
[INFO][WAN] 12-09-2021 11:38:42 Stop WAN 8 DSL Connection
[INFO][DNS] 12-09-2021 11:38:42 Internet DNS deactivated.
[INFO][WAN] 12-09-2021 11:38:42 Stop WAN 10 IP Connection
[INFO][WAN] 12-09-2021 11:38:42 IPTV WAN11 DeActivated!
[INFO][WAN] 12-09-2021 11:38:42 bud update WAN11 status to 0.
[INFO][LAN] 12-09-2021 11:38:42 LAN sending RA to ff02::1
[EMERG][WAN] 12-09-2021 11:38:42 DSL link down.
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.151 PROTO=TCP SPT=58094 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.14.150 PROTO=TCP SPT=58087 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.15.147 PROTO=TCP SPT=58091 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100 DST=45.57.15.147 PROTO=TCP SPT=58093 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100

DST=45.57.15.147 PROTO=TCP SPT=58092 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100
DST=45.57.15.147 PROTO=TCP SPT=58090 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100
DST=45.57.14.146 PROTO=TCP SPT=58012 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.100
DST=45.57.14.146 PROTO=TCP SPT=58095 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:38:42 SRC=192.168.2.102
DST=142.250.185.202 PROTO=TCP SPT=44278 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 11:33:20 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:26:25 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 11:19:09 ACS-D: Timestamp(ms):1639048749
ACS-Trigger:TIMER Selected Channel:#8 (0x1008)
[EMERG][LAN] 12-09-2021 11:19:09 WIFI 2.4G Channel has been changed
from channel 9 to 8.
[INFO][LAN] 12-09-2021 11:18:07 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:18:04 Successfully assign IP
[192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time
[86400]
[INFO][LAN] 12-09-2021 11:18:04 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 11:18:04 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 11:18:04 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 11:18:04 Received REQUEST from client ip
[0.0.0.0] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-09-2021 11:18:04 Received a packet
[NOTICE][LAN] 12-09-2021 11:18:02 wl0: AP-STA-CONNECTED
50:ed:3c:2f:b6:42
[NOTICE][LAN] 12-09-2021 11:18:02 wl1: AP-STA-DISCONNECTED
50:ed:3c:2f:b6:42
[INFO][LAN] 12-09-2021 11:15:11 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:15:09 Successfully assign IP
[192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time
[86400]
[INFO][LAN] 12-09-2021 11:15:09 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 11:15:09 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 11:15:09 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 11:15:09 Received REQUEST from client ip
[0.0.0.0] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-09-2021 11:15:09 Received a packet
[NOTICE][LAN] 12-09-2021 11:15:07 wl1: AP-STA-CONNECTED
50:ed:3c:2f:b6:42
[NOTICE][LAN] 12-09-2021 11:15:07 wl0: AP-STA-DISCONNECTED
50:ed:3c:2f:b6:42
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=51776 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.102
DST=2.22.241.90 PROTO=TCP SPT=51778 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57851 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57860 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:15:07 TCP Scan SRC=35.186.224.25
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=57859 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 11:15:07 TCP Scan SRC=172.217.18.106
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=51762 MARK=0x8000001
[INFO][LAN] 12-09-2021 11:11:33 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 11:07:25 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 11:06:04 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 11:06:04 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.102
DST=142.250.185.225 PROTO=TCP SPT=38312 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.102
DST=172.217.19.78 PROTO=TCP SPT=60086 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.102
DST=74.125.133.138 PROTO=TCP SPT=41250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.102
DST=216.58.212.142 PROTO=TCP SPT=53186 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.102
DST=216.58.213.246 PROTO=TCP SPT=40580 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57851 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57851 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57851 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57851 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=57851 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57851 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57851 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57851 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57840 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 TCP Scan SRC=35.186.224.25
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=57817 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57840 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57840 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57840 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57840 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57840 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57840 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57830 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57840 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 11:06:04 TCP Scan SRC=35.186.224.25
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=57834 MARK=0x8000001
[INFO][LAN] 12-09-2021 11:01:29 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 10:57:56 Successfully assign IP
[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time
[86400]
[INFO][LAN] 12-09-2021 10:57:56 unicasting packet to client ciaddr
[INFO][LAN] 12-09-2021 10:57:56 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 10:57:56 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 10:57:56 Received REQUEST from client ip
[192.168.2.102] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-09-2021 10:57:56 Received a packet
[INFO][LAN] 12-09-2021 10:51:53 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 10:43:36 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 10:36:36 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 10:35:52 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 10:35:52 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 10:35:51 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 10:35:51 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 10:35:31 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-09-2021 10:35:31 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 10:35:20 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 10:35:20 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=35.188.42.15 PROTO=TCP SPT=60324 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=35.188.42.15 PROTO=TCP SPT=60332 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60267 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60249 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60267 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60267 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60249 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60249 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60267 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60249 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60267 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57830 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60249 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57830 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57830 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57830 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57830 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57820 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57830 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 TCP Scan SRC=35.186.224.25
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=57825 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60270 DPT=443 MARK=0x3 DROP


```
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=13.227.219.46 PROTO=TCP SPT=60224 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=13.227.219.46 PROTO=TCP SPT=60226 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=13.227.219.46 PROTO=TCP SPT=60221 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60265 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60261 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60267 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60248 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=60249 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=13.32.121.29 PROTO=TCP SPT=60228 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=13.32.121.29 PROTO=TCP SPT=60227 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=52.45.126.198 PROTO=TCP SPT=60264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=54.148.92.153 PROTO=TCP SPT=60274 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:35:20 SRC=192.168.2.101
DST=216.115.208.230 PROTO=TCP SPT=60149 DPT=8200 MARK=0x1 DROP
[INFO][LAN] 12-09-2021 10:30:32 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 10:23:52 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 10:18:09 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 10:08:39 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 10:08:34 Successfully assign IP
[192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time
[86400]
[INFO][LAN] 12-09-2021 10:08:34 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 10:08:34 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 10:08:34 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 10:08:34 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 10:08:34 Received REQUEST from client ip
[0.0.0.0] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-09-2021 10:08:34 Received a packet
[NOTICE][LAN] 12-09-2021 10:08:34 wl0: AP-STA-CONNECTED
68:2f:67:8a:e3:07
[NOTICE][LAN] 12-09-2021 10:07:51 wl0: AP-STA-DISCONNECTED
68:2f:67:8a:e3:07
[INFO][LAN] 12-09-2021 10:06:06 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 10:06:03 Successfully assign IP
[192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time
[86400]
[INFO][LAN] 12-09-2021 10:06:03 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 10:06:03 Received REQUEST from client ip
```

[0.0.0.0] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-09-2021 10:06:03 Received a packet
[INFO][LAN] 12-09-2021 10:06:03 Successfully assign IP
[192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time
[86400]
[INFO][LAN] 12-09-2021 10:06:03 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 10:06:03 Received REQUEST from client ip
[0.0.0.0] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-09-2021 10:06:03 Received a packet
[INFO][LAN] 12-09-2021 10:06:03 Successfully assign IP
[192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time
[86400]
[INFO][LAN] 12-09-2021 10:06:03 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 10:06:03 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 10:06:02 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 10:06:02 wl0: AP-STA-CONNECTED
68:2f:67:8a:e3:07
[NOTICE][LAN] 12-09-2021 10:06:01 wl0: AP-STA-DISCONNECTED
68:2f:67:8a:e3:07
[INFO][LAN] 12-09-2021 10:06:01 Received REQUEST from client ip
[0.0.0.0] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-09-2021 10:06:01 Received a packet
[NOTICE][LAN] 12-09-2021 10:06:00 wl0: AP-STA-CONNECTED
68:2f:67:8a:e3:07
[INFO][LAN] 12-09-2021 10:05:42 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 10:05:23 wl0: AP-STA-DISCONNECTED
68:2f:67:8a:e3:07
[WARNING][Firewall] 12-09-2021 10:05:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57820 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:05:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57820 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:05:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57820 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:05:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57820 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:05:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57820 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:05:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57820 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:05:23 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57809 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:05:23 TCP Scan SRC=35.186.224.25
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=57819 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 10:05:23 SRC=192.168.2.101
DST=216.115.208.230 PROTO=TCP SPT=59958 DPT=8200 MARK=0x1 DROP
[INFO][LAN] 12-09-2021 10:01:29 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 10:01:25 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 10:01:24 Successfully assign IP
[192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time
[86400]
[INFO][LAN] 12-09-2021 10:01:24 unicasting packet to client yiaddr

[INFO][LAN] 12-09-2021 10:01:24 Received REQUEST from client ip [0.0.0.0] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-09-2021 10:01:24 Received a packet
[INFO][LAN] 12-09-2021 10:01:24 Successfully assign IP [192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time [86400]
[INFO][LAN] 12-09-2021 10:01:24 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 10:01:24 Received REQUEST from client ip [0.0.0.0] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-09-2021 10:01:24 Received a packet
[NOTICE][LAN] 12-09-2021 10:01:24 wl0: AP-STA-CONNECTED 68:2f:67:8a:e3:07
[NOTICE][LAN] 12-09-2021 10:01:24 wl0: AP-STA-DISCONNECTED 68:2f:67:8a:e3:07
[INFO][LAN] 12-09-2021 10:01:22 Successfully assign IP [192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time [86400]
[INFO][LAN] 12-09-2021 10:01:22 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 10:01:22 No valid arp replies for this address
[INFO][LAN] 12-09-2021 10:01:22 Arp reply received from the requesting device itself.
[INFO][LAN] 12-09-2021 10:01:22 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 10:01:22 Received REQUEST from client ip [0.0.0.0] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-09-2021 10:01:22 Received a packet
[NOTICE][LAN] 12-09-2021 10:01:22 wl0: AP-STA-CONNECTED 68:2f:67:8a:e3:07
[NOTICE][LAN] 12-09-2021 10:01:03 wl0: AP-STA-DISCONNECTED 68:2f:67:8a:e3:07
[WARNING][Firewall] 12-09-2021 10:01:03 SRC=192.168.2.102 DST=172.217.19.74 PROTO=TCP SPT=52500 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:01:03 SRC=192.168.2.102 DST=172.217.19.74 PROTO=TCP SPT=52500 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:01:03 SRC=192.168.2.102 DST=172.217.19.74 PROTO=TCP SPT=52500 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:01:03 SRC=192.168.2.102 DST=172.217.19.74 PROTO=TCP SPT=52500 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:01:03 SRC=192.168.2.102 DST=172.217.19.74 PROTO=TCP SPT=52500 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:01:03 SRC=192.168.2.102 DST=172.217.19.74 PROTO=TCP SPT=52500 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:01:03 SRC=192.168.2.102 DST=172.217.19.74 PROTO=TCP SPT=52500 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 10:01:03 SRC=192.168.2.102 DST=172.217.19.74 PROTO=TCP SPT=52500 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 09:55:18 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 09:49:45 wl1: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:49:45 wl0: AP-STA-DISCONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:49:01 wl0: AP-STA-CONNECTED

bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:49:01 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57809 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57809 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57809 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57809 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57809 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57809 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57809 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 TCP Scan SRC=35.186.224.25
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=57777 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=99.84.156.77 PROTO=TCP SPT=59759 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59767 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59766 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101

DST=78.108.120.31 PROTO=TCP SPT=59768 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=78.108.120.31 PROTO=TCP SPT=59769 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59758 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59779 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59765 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59761 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:49:01 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59755 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 09:46:30 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 09:40:02 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 09:32:57 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:32:57 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:32:51 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:32:51 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:32:51 TCP Scan SRC=35.186.224.25
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=57798 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.101
DST=54.229.132.88 PROTO=TCP SPT=59568 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.101
DST=51.158.29.13 PROTO=TCP SPT=59375 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.101
DST=212.83.160.162 PROTO=TCP SPT=59378 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:32:51 SRC=192.168.2.101
DST=72.251.249.9 PROTO=TCP SPT=59472 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 09:30:11 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 09:26:09 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-09-2021 09:26:09 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:26:05 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:26:05 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 09:26:05 SRC=192.168.2.101
DST=52.20.104.111 PROTO=TCP SPT=59356 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:26:05 SRC=192.168.2.101
DST=99.84.156.36 PROTO=TCP SPT=59336 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 09:23:04 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:23:04 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 09:22:54 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 09:22:54 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:22:54 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59343 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59341 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59339 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59345 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:22:54 SRC=192.168.2.102

DST=142.250.185.106 PROTO=TCP SPT=56188 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 09:19:35 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:19:35 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 09:19:35 SRC=192.168.2.102
DST=142.250.185.138 PROTO=TCP SPT=38020 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:19:35 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59322 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:19:35 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59323 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:19:35 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59321 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:19:35 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59315 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:19:35 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59317 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:19:35 SRC=192.168.2.101
DST=35.188.42.15 PROTO=TCP SPT=59293 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:19:35 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59286 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:19:35 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59287 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 09:14:09 w11: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 09:14:07 w11: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-09-2021 09:14:07 SRC=192.168.2.101
DST=173.199.54.10 PROTO=TCP SPT=59249 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:14:07 SRC=192.168.2.101
DST=52.40.6.27 PROTO=TCP SPT=59275 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:14:07 SRC=192.168.2.101
DST=52.1.65.14 PROTO=TCP SPT=59263 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:14:07 SRC=192.168.2.101
DST=34.208.6.199 PROTO=TCP SPT=59276 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:14:07 SRC=192.168.2.101
DST=54.229.130.35 PROTO=TCP SPT=59228 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 09:13:46 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 09:13:46 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 09:13:46 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 09:13:44 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 09:13:44 Received a packet
[NOTICE][LAN] 12-09-2021 09:13:35 w11: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 09:13:33 w10: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 09:13:15 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 09:12:44 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:12:44 w11: AP-STA-DISCONNECTED

bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:09:55 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:09:55 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 09:09:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:09:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:09:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:09:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:09:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:09:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:09:55 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57792 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:09:55 TCP Scan SRC=35.186.224.25
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=57788 MARK=0x8000001
[INFO][LAN] 12-09-2021 09:07:24 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 09:04:53 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:04:53 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:04:50 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:04:50 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:04:04 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:04:04 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:03:54 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:03:54 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:03:50 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:03:49 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:03:38 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:03:38 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:03:26 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:03:26 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:03:18 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE] [LAN] 12-09-2021 09:03:18 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:03:11 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:03:11 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:03:08 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:03:08 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:03:02 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:03:02 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:03:01 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:03:01 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:02:48 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:02:48 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:02:47 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:02:47 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:02:46 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:02:46 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:02:40 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:02:39 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:01:43 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:01:43 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:01:39 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:01:38 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 09:01:38 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59127 DPT=443 MARK=0x3 DROP
[NOTICE] [LAN] 12-09-2021 09:00:31 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:00:31 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 09:00:31 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59127 DPT=443 MARK=0x3 DROP
[NOTICE] [LAN] 12-09-2021 09:00:20 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE] [LAN] 12-09-2021 09:00:20 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac

[WARNING][Firewall] 12-09-2021 09:00:20 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59127 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 09:00:20 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59127 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 09:00:10 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 09:00:02 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 09:00:02 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 09:00:02 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59127 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 08:59:56 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:59:56 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 08:59:56 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59127 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:59:56 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59127 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:59:56 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59127 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:59:56 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59127 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:59:56 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59127 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:59:56 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59127 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:59:56 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59138 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:59:56 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59128 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:59:56 SRC=192.168.2.101
DST=54.145.6.147 PROTO=TCP SPT=59127 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:59:56 SRC=192.168.2.101
DST=52.20.104.111 PROTO=TCP SPT=59126 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:59:56 SRC=192.168.2.101
DST=52.20.104.111 PROTO=TCP SPT=59142 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 08:57:14 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:57:14 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:56:09 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:56:09 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 08:56:09 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:56:09 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:56:09 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=57781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:56:09 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:56:09 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:56:09 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:56:09 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57772 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:56:09 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:56:09 TCP Scan SRC=35.186.224.25
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=57779 MARK=0x8000001
[INFO][LAN] 12-09-2021 08:54:19 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 08:45:28 wL0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 08:45:28 wL1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 08:45:23 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 08:43:20 wL0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:43:20 wL1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:42:55 wL1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 08:42:55 wL0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 08:42:51 wL1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:42:51 wL0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57772 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57772 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57772 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57772 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57772 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57772 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57772 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 TCP Scan SRC=35.186.224.25
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=57743 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101
DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101
DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101

DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101
DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101
DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101
DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101
DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101
DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101
DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101
DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101
DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101
DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:42:51 SRC=192.168.2.101
DST=176.31.183.116 PROTO=TCP SPT=58918 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 08:38:31 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 08:33:34 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 08:29:10 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:29:10 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[EMERG][Firewall] 12-09-2021 08:29:10 DoS attack: SYN With Data
Attack from source: 159.65.183.114:5075
[INFO][LAN] 12-09-2021 08:28:56 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 08:26:13 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 08:26:13 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 08:24:36 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:24:36 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 08:22:23 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 08:21:20 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 08:20:48 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=192.229.233.55 PROTO=TCP SPT=58843 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.218.1.43 PROTO=TCP SPT=58833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=58771 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=58773 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101

DST=3.220.66.61 PROTO=TCP SPT=58778 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.218.1.43 PROTO=TCP SPT=58833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.218.1.43 PROTO=TCP SPT=58833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=185.183.112.155 PROTO=TCP SPT=58815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=13.36.153.195 PROTO=TCP SPT=58791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.218.1.43 PROTO=TCP SPT=58833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=185.183.112.155 PROTO=TCP SPT=58815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=13.36.153.195 PROTO=TCP SPT=58791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.218.1.43 PROTO=TCP SPT=58833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=185.183.112.155 PROTO=TCP SPT=58815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=13.36.153.195 PROTO=TCP SPT=58791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=185.183.112.155 PROTO=TCP SPT=58815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=13.36.153.195 PROTO=TCP SPT=58791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.218.1.43 PROTO=TCP SPT=58833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=185.183.112.155 PROTO=TCP SPT=58815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=13.36.153.195 PROTO=TCP SPT=58791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.218.1.43 PROTO=TCP SPT=58833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=185.183.112.155 PROTO=TCP SPT=58815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=13.36.153.195 PROTO=TCP SPT=58791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101

DST=52.218.1.43 PROTO=TCP SPT=58833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=185.183.112.155 PROTO=TCP SPT=58815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=13.36.153.195 PROTO=TCP SPT=58791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.218.1.43 PROTO=TCP SPT=58833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=185.183.112.155 PROTO=TCP SPT=58815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=13.36.153.195 PROTO=TCP SPT=58791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.218.1.43 PROTO=TCP SPT=58833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=185.183.112.155 PROTO=TCP SPT=58815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=13.36.153.195 PROTO=TCP SPT=58791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.218.1.43 PROTO=TCP SPT=58833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=185.183.112.155 PROTO=TCP SPT=58815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=13.36.153.195 PROTO=TCP SPT=58791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=34.252.190.62 PROTO=TCP SPT=58793 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=185.183.112.155 PROTO=TCP SPT=58815 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=52.218.1.43 PROTO=TCP SPT=58833 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=13.36.153.195 PROTO=TCP SPT=58791 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:20:48 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58740 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 08:17:35 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:17:34 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 08:16:55 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 08:16:33 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:16:33 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:16:22 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:16:22 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 08:16:22 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:16:22 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:16:22 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:16:22 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:16:22 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 08:16:22 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:16:22 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:16:22 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:16:22 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 08:16:03 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:16:03 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 08:16:03 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:16:03 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:16:03 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:16:03 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:16:03 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:16:03 SRC=192.168.2.101
DST=99.84.156.61 PROTO=TCP SPT=58739 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 08:15:52 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:15:52 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:15:22 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:15:22 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:15:21 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:15:21 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 08:15:21 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=58716 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:15:21 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=58718 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:15:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:15:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:15:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57756 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:15:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:15:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:15:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:15:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:15:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57763 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 08:15:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57763 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:15:21 TCP Scan SRC=35.186.224.25
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=57759 MARK=0x8000001
[NOTICE][LAN] 12-09-2021 08:14:04 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:14:04 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:14:02 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:14:02 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:14:01 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:14:01 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:13:55 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 08:13:55 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=35.188.42.15 PROTO=TCP SPT=58689 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=50.19.123.12 PROTO=TCP SPT=58726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 08:13:55 SRC=192.168.2.101
DST=167.89.118.52 PROTO=TCP SPT=58663 DPT=80 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 08:08:55 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=99.84.156.58 PROTO=TCP SPT=58567 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=99.84.156.52 PROTO=TCP SPT=58553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 SRC=192.168.2.101
DST=35.190.80.1 PROTO=TCP SPT=58508 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:55:23 TCP Scan SRC=17.248.172.142
DST=88.72.175.147 PROTO=TCP SPT=443 DPT=57061 MARK=0x8000001
[INFO][LAN] 12-09-2021 07:50:01 LAN sending RA to ff02::1
[INFO][VoIP] 12-09-2021 07:46:16 Switch to primary proxy server
arcor.de on line 0
[INFO][LAN] 12-09-2021 07:46:09 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:45:53 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:45:37 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 07:45:36 Sync up with NTP Server
successfully.
[INFO][System] 12-09-2021 07:45:33 Sync up with NTP Server
successfully.
[INFO][System] 12-09-2021 07:45:30 FSM---- Switch to Connect State.
[INFO][VoIP] 12-09-2021 07:45:25 Send data/single wan update to
VGW,wan id 10,ifName is ppp10,ipv4 address 88.72.175.147,ipv6
address ,default_wan_id 10,wan type 1
[INFO][VoIP] 12-09-2021 07:45:25 line 371 ,wan 10 start do data wan
up
[INFO][VoIP] 12-09-2021 07:45:25 wanipv6 = ,size = 0
[INFO][VoIP] 12-09-2021 07:45:25 Voice binding wan_id is
10,default_wan_id is 10
[INFO][VoIP] 12-09-2021 07:45:25 Voice binding wan_id is
10,default_wan_id is 10,is_ipv6 = 0
[INFO][VoIP] 12-09-2021 07:45:25 wan 10 service_type =
DATA,VOIP,MGNT,IPTV bud_voip_wan_id = 10
[INFO][VoIP] 12-09-2021 07:45:25 Interface wan_ip is 88.72.175.147,

```
wan_ip_v6 ,is_ipv6 0 wan up id 10
[INFO][LAN] 12-09-2021 07:45:25 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO][LAN] 12-09-2021 07:45:25 adapter index 19
[INFO][LAN] 12-09-2021 07:45:25 br1 (our ip) = 192.168.3.1
[INFO][LAN] 12-09-2021 07:45:25 Attaching option timezone to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option t2 to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option t1 to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option lease to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option dns to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option router to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option subnet to list
[INFO][LAN] 12-09-2021 07:45:25 error on select
[INFO][LAN] 12-09-2021 07:45:25 udhcp server receive signal 12
[INFO][LAN] 12-09-2021 07:45:25 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-09-2021 07:45:25 adapter index 18
[INFO][LAN] 12-09-2021 07:45:25 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-09-2021 07:45:25 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-09-2021 07:45:25 adapter index 18
[INFO][LAN] 12-09-2021 07:45:25 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-09-2021 07:45:25 Attaching option timezone to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option t2 to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option t1 to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option lease to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option dns to existing
member of list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option dns to existing
member of list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option dns to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option router to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option subnet to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option timezone to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option t2 to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option t1 to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option lease to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option dns to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option hostname to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option domain to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option router to list
[INFO][LAN] 12-09-2021 07:45:25 Attaching option subnet to list
[INFO][LAN] 12-09-2021 07:45:25 error on select
[INFO][LAN] 12-09-2021 07:45:25 udhcp server receive signal 12
[INFO][System] 12-09-2021 07:45:23 Starting MCPD OK.
[INFO][System] 12-09-2021 07:45:23 Stopping MCPD OK.
[INFO][UMTS] 12-09-2021 07:45:23 iPhone DNS Policy actived
[INFO][VoIP] 12-09-2021 07:45:23 276 start wan service Voice
binding wan_id is 10
[INFO][VoIP] 12-09-2021 07:45:23 Voice binding wan_id is 10
[INFO][System] 12-09-2021 07:45:23 Starting NTP Client OK.
[INFO][System] 12-09-2021 07:45:23 Sync up with NTP Server failed.
[INFO][System] 12-09-2021 07:45:23 Stopping NTP Client OK.
[INFO][Firewall] 12-09-2021 07:45:23 PortMapping Rules have been
```

flushed on WAN VDSL-DT.
[INFO][Firewall] 12-09-2021 07:45:22 DMZ Rules has been flushed on WAN VDSL-DT.
[INFO][Firewall] 12-09-2021 07:45:22 Static NAT Rules have been flushed on WAN VDSL-DT.
[INFO][System] 12-09-2021 07:45:22 Stopping HTTP redirect OK.
[INFO][DNS] 12-09-2021 07:45:22 DNSMasq proxy server disable redirect
[INFO][DNS] 12-09-2021 07:45:22 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 07:45:22 Internet DNS ready.
[INFO][DNS] 12-09-2021 07:45:22 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 07:45:22 Internet DNS ready.
[INFO][DNS] 12-09-2021 07:45:22 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 07:45:22 Internet DNS ready.
[INFO][DNS] 12-09-2021 07:45:22 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 07:45:22 Internet DNS ready.
[WARNING][DNS] 12-09-2021 07:45:22 ignoring nameserver 127.0.0.1 - local interface
[WARNING][DNS] 12-09-2021 07:45:22 ignoring nameserver ::1 - local interface
[INFO][DNS] 12-09-2021 07:45:22 Starting DNSMasq proxy server OK.
[INFO][DNS] 12-09-2021 07:45:22 Stopping DNSMasq proxy OK.
[ERROR][System] 12-09-2021 07:45:21 TR069 connects to ACS server failed, couldn't resolve.
[INFO][DNS] 12-09-2021 07:45:21 DNSMasq proxy server disable redirect
[INFO][LAN] 12-09-2021 07:45:21 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:45:20 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 07:45:19 FSM---- Switch to Connect State.
[INFO][UMTS] 12-09-2021 07:45:19 iPhone DNS Policy actived
[INFO][VoIP] 12-09-2021 07:45:19 ignore useless wan down
[INFO][VoIP] 12-09-2021 07:45:19 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 8, is_ipv6 = 0, default_wan_id= 10
[INFO][VoIP] 12-09-2021 07:45:19 ===start stop voice wan
[INFO][VoIP] 12-09-2021 07:45:19 Remove interface wan_id is 10, wan type 2.
[INFO][VoIP] 12-09-2021 07:45:19 VoIP WAN down, Voice trying to run in backup mode, try binding wan_id is 10
[INFO][VoIP] 12-09-2021 07:45:19 bud data ipv4 wan status 10, ipv6 wan status -1
[INFO][VoIP] 12-09-2021 07:45:19 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 10, is_ipv6 = 0, default_wan_id= 10
[INFO][VoIP] 12-09-2021 07:45:19 ===start stop voice wan
[INFO][System] 12-09-2021 07:45:19 Starting MCPD OK.
[INFO][System] 12-09-2021 07:45:19 Stopping MCPD OK.
[INFO][VoIP] 12-09-2021 07:45:19 ignore useless wan down
[INFO][VoIP] 12-09-2021 07:45:19 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 8, is_ipv6 =

1,default_wan_id= 10
[INFO][VoIP] 12-09-2021 07:45:19 ===start stop voice wan
[INFO][DNS] 12-09-2021 07:45:18 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 07:45:18 Internet DNS ready.
[INFO][WAN] 12-09-2021 07:45:18 Stop WAN 8 IP Connection
[INFO][DNS] 12-09-2021 07:45:18 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 07:45:17 Internet DNS ready.
[INFO][DNS] 12-09-2021 07:45:17 Internet DNS deactivated.
[INFO][System] 12-09-2021 07:45:17 FSM---- Switch to Connect State.
[WARNING][WAN] 12-09-2021 07:45:17 WAN default route add to ppp10
gateway 84.59.211.1.
[INFO][WAN] 12-09-2021 07:45:17 Data WAN11 Activated!
[INFO][WAN] 12-09-2021 07:45:17 bud update WAN11 status to 2.
[WARNING][WAN] 12-09-2021 07:45:17 WAN VDSL-DT is up, mode is PPPoE,
IP is 88.72.175.147.
[WARNING][WAN] 12-09-2021 07:45:17 WAN VDSL-DT is down.
[INFO][LAN] 12-09-2021 07:45:17 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 07:45:17 PPP CHAP MD5 authentication is
successful on WAN VDSL-DT
[INFO][LAN] 12-09-2021 07:45:16 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:45:16 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:45:16 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 07:45:16 PPPoE PADS has been received from
WAN VDSL-DT
[INFO][WAN] 12-09-2021 07:45:16 PPPoE PADR has been sent from WAN
VDSL-DT
[INFO][WAN] 12-09-2021 07:45:16 PPPoE PADO has been received from
WAN VDSL-DT, BRAS name is BLNCOS69101.
[INFO][WAN] 12-09-2021 07:45:16 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][WAN] 12-09-2021 07:45:16 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][System] 12-09-2021 07:45:08 FSM---- Switch to Connect State.
[INFO][WAN] 12-09-2021 07:44:59 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-09-2021 07:44:59 FSM---- Switch to Connect State.
[INFO][WAN] 12-09-2021 07:44:59 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][System] 12-09-2021 07:44:49 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 07:44:39 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 07:44:38 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 07:44:30 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 07:44:22 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 07:44:21 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 07:44:10 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 07:44:06 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 07:44:03 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][WAN] 12-09-2021 07:44:03 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][System] 12-09-2021 07:44:01 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 07:43:51 FSM---- Switch to Connect State.

```
[INFO][WAN] 12-09-2021 07:43:50 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][LAN] 12-09-2021 07:43:50 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:43:50 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:43:50 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:43:50 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:43:50 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 07:43:50 Start WAN 10 IP Connection
[INFO][WAN] 12-09-2021 07:43:50 WAN VDSL-DT has been started, PHY
link up
[INFO][WAN] 12-09-2021 07:43:50 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][LAN] 12-09-2021 07:43:49 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:43:49 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:43:49 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 07:43:49 Start WAN 8 IP Connection
[INFO][WAN] 12-09-2021 07:43:49 WAN VDSL-DATA has been started, PHY
link up
[INFO][LAN] 12-09-2021 07:43:49 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 07:43:49 Start WAN 10 DSL Connection
[INFO][WAN] 12-09-2021 07:43:48 Start WAN 4 DSL Connection
[INFO][LAN] 12-09-2021 07:43:48 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:43:48 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:43:48 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 07:43:48 Starting VDSL interface OK.
[INFO][WAN] 12-09-2021 07:43:48 Start WAN 8 DSL Connection
[EMERG][WAN] 12-09-2021 07:43:48 DSL link up.
[INFO][System] 12-09-2021 07:43:41 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 07:43:32 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 07:43:22 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 07:43:11 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 07:43:00 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 07:42:51 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 07:42:41 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 07:42:32 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 07:42:26 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 07:42:26 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 07:42:26 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 07:42:26 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 07:42:26 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:42:26 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 07:42:26 Received a packet
[NOTICE][LAN] 12-09-2021 07:42:26 wlan1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[INFO][System] 12-09-2021 07:42:22 FSM---- Switch to Connect State.
[INFO][System] 12-09-2021 07:42:13 FSM---- Switch to Connect State.
[INFO][LAN] 12-09-2021 07:42:10 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 07:42:04 FSM---- Switch to Connect State.
[EMERG][WAN] 12-09-2021 07:42:01 DSL link down.
```

[INFO][System] 12-09-2021 07:41:55 FSM---- Switch to Connect State.
[INFO][WAN] 12-09-2021 07:41:54 WAN VDSL-DT has been stopped, please check your PHY link
[INFO][LAN] 12-09-2021 07:41:54 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:41:54 LAN sending RA to ff02::1
[INFO][WAN] 12-09-2021 07:41:54 Stopping VDSL interface OK.
[INFO][WAN] 12-09-2021 07:41:54 Stop WAN 10 DSL Connection
[INFO][LAN] 12-09-2021 07:41:54 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:41:54 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:41:54 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 07:41:54 Starting HTTP redirect OK.
[INFO][DNS] 12-09-2021 07:41:54 DNSMasq proxy server enable redirect
[INFO][System] 12-09-2021 07:41:54 Stopping NTP Client OK.
[INFO][VoIP] 12-09-2021 07:41:54 VoIP WAN down, no available connection
[INFO][VoIP] 12-09-2021 07:41:54 Remove interface wan_id is 10,wan type 1.
[INFO][VoIP] 12-09-2021 07:41:54 bud data ipv4 wan status -1,ipv6 wan status -1
[INFO][VoIP] 12-09-2021 07:41:54 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 = 0,default_wan_id= 10
[INFO][VoIP] 12-09-2021 07:41:53 ===start stop voice wan
[INFO][DNS] 12-09-2021 07:41:53 Internet DNS deactivated.
[INFO][LAN] 12-09-2021 07:41:53 LAN sending RA to ff02::1
[INFO][System] 12-09-2021 07:41:53 Starting NTP Client OK.
[INFO][System] 12-09-2021 07:41:53 Sync up with NTP Server failed.
[INFO][System] 12-09-2021 07:41:53 Stopping NTP Client OK.
[INFO][VoIP] 12-09-2021 07:41:53 VoIP WAN down, no available connection
[INFO][VoIP] 12-09-2021 07:41:53 Remove interface wan_id is 10,wan type 1.
[INFO][VoIP] 12-09-2021 07:41:53 bud data ipv4 wan status -1,ipv6 wan status -1
[INFO][VoIP] 12-09-2021 07:41:53 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 = 0,default_wan_id= 10
[INFO][VoIP] 12-09-2021 07:41:53 ===start stop voice wan
[NOTICE][LAN] 12-09-2021 07:41:52 wl1: AP-STA-DISCONNECTED 6a:78:d9:7b:3e:cd
[INFO][DNS] 12-09-2021 07:41:52 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 07:41:52 Internet DNS ready.
[INFO][DNS] 12-09-2021 07:41:52 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-09-2021 07:41:52 Internet DNS ready.
[INFO][DNS] 12-09-2021 07:41:52 Internet DNS deactivated.
[INFO][WAN] 12-09-2021 07:41:52 WAN VDSL-DATA has been stopped, please check your PHY link
[INFO][System] 12-09-2021 07:41:52 Starting NTP Client OK.
[INFO][System] 12-09-2021 07:41:51 Sync up with NTP Server failed.
[INFO][System] 12-09-2021 07:41:51 Stopping NTP Client OK.
[INFO][VoIP] 12-09-2021 07:41:51 VoIP WAN down, no available connection


```
[INFO][VoIP] 12-09-2021 07:41:51 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-09-2021 07:41:51 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-09-2021 07:41:51 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-09-2021 07:41:51 ===start stop voice wan
[INFO][DNS] 12-09-2021 07:41:51 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 07:41:51 Internet DNS ready.
[INFO][LAN] 12-09-2021 07:41:51 LAN sending RA to ff02::1
[INFO][DNS] 12-09-2021 07:41:51 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-09-2021 07:41:51 Internet DNS ready.
[INFO][WAN] 12-09-2021 07:41:51 Stop WAN 8 DSL Connection
[INFO][DNS] 12-09-2021 07:41:51 Internet DNS deactivated.
[INFO][DNS] 12-09-2021 07:41:51 Internet DNS deactivated.
[INFO][WAN] 12-09-2021 07:41:51 Stop WAN 10 IP Connection
[INFO][WAN] 12-09-2021 07:41:51 IPTV WAN11 DeActivated!
[INFO][WAN] 12-09-2021 07:41:51 bud update WAN11 status to 0.
[INFO][WAN] 12-09-2021 07:41:50 Stop WAN 4 DSL Connection
[INFO][LAN] 12-09-2021 07:41:50 LAN sending RA to ff02::1
[EMERG][WAN] 12-09-2021 07:41:50 DSL link down.
[WARNING][Firewall] 12-09-2021 07:41:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:41:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:41:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:41:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:41:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:41:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:41:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:41:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57740 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 07:41:00 Successfully assign IP
[192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time
[86400]
[INFO][LAN] 12-09-2021 07:41:00 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:41:00 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 07:41:00 Received REQUEST from client ip
[0.0.0.0] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-09-2021 07:41:00 Received a packet
[NOTICE][LAN] 12-09-2021 07:41:00 wl0: AP-STA-CONNECTED
68:2f:67:8a:e3:07
[NOTICE][LAN] 12-09-2021 07:41:00 wl1: AP-STA-DISCONNECTED
68:2f:67:8a:e3:07
[INFO][LAN] 12-09-2021 07:40:36 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:40:31 Successfully assign IP
```

[192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time [86400]
[INFO][LAN] 12-09-2021 07:40:31 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 07:40:31 No valid arp replies for this address
[INFO][LAN] 12-09-2021 07:40:31 Arp reply received from the requesting device itself.
[INFO][LAN] 12-09-2021 07:40:31 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:40:31 Received REQUEST from client ip [0.0.0.0] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-09-2021 07:40:31 Received a packet
[NOTICE][LAN] 12-09-2021 07:40:31 wl1: AP-STA-CONNECTED 68:2f:67:8a:e3:07
[INFO][LAN] 12-09-2021 07:40:13 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 07:39:01 wl1: AP-STA-CONNECTED 6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 07:39:01 wl0: AP-STA-DISCONNECTED 6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 07:38:12 wl1: AP-STA-DISCONNECTED 10:94:bb:d5:73:92
[WARNING][Firewall] 12-09-2021 07:38:12 TCP Scan SRC=35.186.224.25 DST=178.10.236.179 PROTO=TCP SPT=443 DPT=50162 MARK=0x8000001
[INFO][LAN] 12-09-2021 07:36:31 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 07:36:19 wl0: AP-STA-CONNECTED 6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 07:35:50 wl1: AP-STA-DISCONNECTED 6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 07:33:38 wl0: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 07:33:38 wl1: AP-STA-DISCONNECTED bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 07:32:17 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:32:03 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:32:00 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:31:58 Successfully assign IP [192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time [86400]
[INFO][LAN] 12-09-2021 07:31:58 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 07:31:58 No valid arp replies for this address
[INFO][LAN] 12-09-2021 07:31:58 Arp reply received from the requesting device itself.
[INFO][LAN] 12-09-2021 07:31:58 Received REQUEST from client ip [0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 07:31:58 Received a packet
[NOTICE][LAN] 12-09-2021 07:31:58 wl1: AP-STA-CONNECTED 6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 07:31:58 wl0: AP-STA-DISCONNECTED 6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 07:31:58 SRC=192.168.2.102 DST=2.22.241.24 PROTO=TCP SPT=40750 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:31:58 SRC=192.168.2.102 DST=2.22.241.24 PROTO=TCP SPT=41140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:31:58 SRC=192.168.2.102

DST=2.22.241.24 PROTO=TCP SPT=40748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:31:58 SRC=192.168.2.102
DST=2.22.241.24 PROTO=TCP SPT=40752 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:31:58 SRC=192.168.2.102
DST=2.22.241.24 PROTO=TCP SPT=41138 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:31:58 SRC=192.168.2.102
DST=92.122.22.147 PROTO=TCP SPT=47650 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:31:58 SRC=192.168.2.102
DST=148.251.193.57 PROTO=TCP SPT=57440 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 07:31:56 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 07:27:29 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 07:21:36 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 07:21:36 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 07:20:09 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 07:20:09 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 07:20:08 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 07:20:08 TCP Scan SRC=142.250.181.202
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=47166 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 07:20:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57740 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:20:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57740 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:20:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57740 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:20:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57740 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:20:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57740 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:20:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57740 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:20:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57740 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:20:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57730 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:20:08 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57740 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:20:08 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57706 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 07:20:08 TCP Scan SRC=52.222.179.122
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=47644 MARK=0x8000001
[INFO][LAN] 12-09-2021 07:15:31 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 07:12:53 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 07:12:53 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 07:12:32 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 07:12:32 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 07:12:11 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]

DST=35.186.224.47 PROTO=TCP SPT=57730 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:00:49 SRC=192.168.2.102
DST=35.186.224.47 PROTO=TCP SPT=57730 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:00:49 SRC=192.168.2.102
DST=35.186.224.47 PROTO=TCP SPT=57721 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:00:49 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57726 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 07:00:49 SRC=192.168.2.102
DST=216.239.38.135 PROTO=TCP SPT=59154 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 07:00:24 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 07:00:24 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 07:00:24 SRC=192.168.2.102
DST=80.158.36.25 PROTO=TCP SPT=41098 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:00:24 SRC=192.168.2.102
DST=80.156.82.167 PROTO=TCP SPT=45904 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 07:00:24 SRC=192.168.2.102
DST=80.158.50.118 PROTO=TCP SPT=36264 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 06:58:18 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 06:56:09 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 06:56:09 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 06:56:09 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=50466 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 06:56:09 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=50466 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 06:56:09 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=50466 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 06:56:09 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=50466 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 06:56:09 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=50466 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 06:56:09 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=50466 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 06:56:09 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=50466 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 06:56:09 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=50466 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 06:56:09 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=50466 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 06:56:09 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=50466 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 06:53:35 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 06:49:13 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 06:49:13 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 06:48:44 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 06:48:44 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 06:46:10 Successfully assign IP


```
DST=35.186.224.47 PROTO=TCP SPT=57710 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.100  
DST=35.186.224.47 PROTO=TCP SPT=57700 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.100  
DST=35.186.224.47 PROTO=TCP SPT=57710 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 TCP Scan SRC=35.186.224.25  
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57708 MARK=0x8000001  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=142.250.186.106 PROTO=TCP SPT=52214 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=142.250.186.138 PROTO=TCP SPT=55298 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 TCP Scan SRC=142.250.186.138  
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=55302 MARK=0x8000001  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=142.250.186.138 PROTO=TCP SPT=55298 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=142.250.186.138 PROTO=TCP SPT=55298 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=142.250.186.138 PROTO=TCP SPT=55298 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=142.250.186.138 PROTO=TCP SPT=55298 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=142.250.186.138 PROTO=TCP SPT=55298 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=142.250.186.138 PROTO=TCP SPT=55298 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=142.250.186.138 PROTO=TCP SPT=55298 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=142.250.186.138 PROTO=TCP SPT=55298 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=142.250.186.138 PROTO=TCP SPT=55298 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=142.250.186.138 PROTO=TCP SPT=55298 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.102  
DST=35.186.224.47 PROTO=TCP SPT=57700 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.100  
DST=35.186.224.47 PROTO=TCP SPT=57700 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.100  
DST=35.186.224.47 PROTO=TCP SPT=57700 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.100  
DST=35.186.224.47 PROTO=TCP SPT=57700 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.100  
DST=35.186.224.47 PROTO=TCP SPT=57700 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.100  
DST=35.186.224.47 PROTO=TCP SPT=57700 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.100  
DST=35.186.224.47 PROTO=TCP SPT=57700 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.100  
DST=35.186.224.47 PROTO=TCP SPT=57700 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 SRC=192.168.2.100  
DST=35.186.224.47 PROTO=TCP SPT=57691 DPT=443 MARK=0x3 DROP  
[WARNING][Firewall] 12-09-2021 06:32:23 TCP Scan SRC=35.186.224.25  
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57668 MARK=0x8000001  
[INFO][LAN] 12-09-2021 06:31:33 LAN sending RA to ff02::1  
[INFO][LAN] 12-09-2021 06:27:06 LAN sending RA to ff02::1  
[INFO][LAN] 12-09-2021 06:17:34 LAN sending RA to ff02::1  
[INFO][LAN] 12-09-2021 06:13:05 LAN sending RA to ff02::1  
[INFO][LAN] 12-09-2021 06:08:16 LAN sending RA to ff02::1
```


[WARNING][Firewall] 12-09-2021 05:54:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57691 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:54:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57681 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:54:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57691 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:54:16 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57687 MARK=0x8000001
[INFO][LAN] 12-09-2021 05:50:21 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 05:50:21 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 05:50:21 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 05:50:17 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 05:50:17 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 05:50:17 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 05:50:17 Received a packet
[NOTICE][LAN] 12-09-2021 05:50:16 wl1: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 05:50:16 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-09-2021 05:49:29 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 05:49:29 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 05:49:29 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 05:49:28 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 05:49:28 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 05:49:28 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 05:49:26 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 05:49:26 Received a packet
[NOTICE][LAN] 12-09-2021 05:49:25 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 05:49:24 wl1: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 05:49:01 ACS-D: Timestamp(ms):1639028941
ACS-Trigger:TIMER Selected Channel:#9 (0x1009)
[EMERG][LAN] 12-09-2021 05:49:01 WIFI 2.4G Channel has been changed
from channel 13 to 9.
[INFO][LAN] 12-09-2021 05:47:38 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 05:44:37 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 05:44:37 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 05:44:37 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 05:44:37 Arp reply received from the

requesting device itself.
[INFO][LAN] 12-09-2021 05:44:37 Received REQUEST from client ip [0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 05:44:37 Received a packet
[NOTICE][LAN] 12-09-2021 05:44:36 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 05:44:34 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 05:43:11 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 05:43:10 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 05:42:50 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 05:39:33 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 05:39:33 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 05:36:40 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 05:36:08 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 05:35:42 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 05:34:49 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 05:34:49 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 05:34:31 Successfully assign IP [192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time [86400]
[INFO][LAN] 12-09-2021 05:34:31 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 05:34:31 No valid arp replies for this address
[INFO][LAN] 12-09-2021 05:34:31 Arp reply received from the requesting device itself.
[INFO][LAN] 12-09-2021 05:34:31 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 05:34:31 Received REQUEST from client ip [0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-09-2021 05:34:31 Received a packet
[NOTICE][LAN] 12-09-2021 05:34:31 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[NOTICE][LAN] 12-09-2021 05:34:27 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 05:34:27 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 05:34:27 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57681 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:34:27 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57681 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:34:27 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57681 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:34:27 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57681 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:34:27 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57681 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 05:34:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57681 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:34:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57681 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:34:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57672 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:34:27 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57678 MARK=0x8000001
[INFO][LAN] 12-09-2021 05:30:24 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 05:28:05 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 05:27:45 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 05:24:11 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 05:24:10 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 05:23:33 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 05:23:33 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 05:23:33 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=38198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:23:33 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=56994 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:23:33 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=38198 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 05:22:22 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 05:19:00 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=38198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=56994 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=38198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=38198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=38198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=38198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=38198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=38198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=38198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=38198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=216.58.213.206 PROTO=TCP SPT=44172 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=56994 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=80.156.82.165 PROTO=TCP SPT=35582 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=80.158.36.25 PROTO=TCP SPT=41004 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=80.158.50.118 PROTO=TCP SPT=36168 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=56994 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=56994 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=56994 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=56994 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=56994 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=56994 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57672 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57672 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57672 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57672 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57672 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57672 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57662 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:19:00 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57670 MARK=0x8000001
[INFO][LAN] 12-09-2021 05:16:54 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 05:10:45 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 05:05:29 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 05:01:09 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 05:01:00 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 05:01:00 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 05:00:41 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 05:00:41 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 05:00:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57662 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:00:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57662 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:00:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57662 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 05:00:41 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=57656 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:00:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57662 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:00:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57662 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:00:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57662 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:00:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57662 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:00:41 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57652 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 05:00:41 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57630 MARK=0x8000001
[INFO][System] 12-09-2021 04:59:02 Sync up with NTP Server
successfully.
[INFO][LAN] 12-09-2021 04:53:42 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 04:53:32 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:53:32 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:53:10 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:53:10 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:50:04 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 04:50:04 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 04:50:04 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51364 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:50:04 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51362 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:50:04 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51366 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 04:47:44 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 04:41:48 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 04:41:47 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 04:41:27 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51364 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51362 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51366 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=57656 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57652 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=57656 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=57652 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57652 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=57656 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57652 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57652 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=57656 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=57656 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57652 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57643 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57652 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=57656 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.100
DST=104.21.51.164 PROTO=TCP SPT=57656 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 TCP Scan SRC=104.21.51.164
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57656 MARK=0x8000001
[EMERG][Firewall] 12-09-2021 04:41:27 DoS attack: SYN With Data
Attack from source: 167.114.158.102:40744
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51364 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51362 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51366 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=50264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51364 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51362 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51366 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51364 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51366 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51362 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51366 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51366 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102

DST=216.58.213.234 PROTO=TCP SPT=51362 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51364 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51364 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51362 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51366 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51366 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51362 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51364 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51364 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=51362 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=172.217.18.118 PROTO=TCP SPT=50910 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:41:27 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46458 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 04:32:10 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 04:30:38 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:30:38 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:30:16 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:30:16 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:29:53 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 04:29:53 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 04:29:29 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 04:29:29 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 04:29:29 SRC=192.168.2.102
DST=142.250.181.227 PROTO=TCP SPT=49836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:29:29 SRC=192.168.2.102
DST=142.250.181.227 PROTO=TCP SPT=49836 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 04:24:17 wl0: AP-STA-DISCONNECTED
68:2f:67:8a:e3:07
[WARNING][Firewall] 12-09-2021 04:24:17 SRC=192.168.2.102
DST=142.250.181.227 PROTO=TCP SPT=49836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:24:17 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57550 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 04:24:17 SRC=192.168.2.102
DST=142.250.181.227 PROTO=TCP SPT=49836 DPT=443 MARK=0x3 DROP


```
[WARNING][Firewall] 12-09-2021 04:24:17 SRC=192.168.2.102
DST=142.250.181.227 PROTO=TCP SPT=49836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:24:17 SRC=192.168.2.102
DST=142.250.181.227 PROTO=TCP SPT=49836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:24:17 SRC=192.168.2.102
DST=142.250.181.227 PROTO=TCP SPT=49836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:24:17 SRC=192.168.2.102
DST=142.250.181.227 PROTO=TCP SPT=49836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:24:17 SRC=192.168.2.102
DST=142.250.181.227 PROTO=TCP SPT=49836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:24:17 SRC=192.168.2.102
DST=142.250.181.227 PROTO=TCP SPT=49836 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 04:22:56 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:22:56 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:22:26 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:22:26 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 04:22:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57643 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:22:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57643 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:22:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57643 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:22:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57643 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:22:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57643 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:22:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57643 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:22:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:22:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57643 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:22:26 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57639 MARK=0x8000001
[INFO][LAN] 12-09-2021 04:22:19 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 04:18:15 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 04:18:10 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 04:18:09 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 04:18:09 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 04:18:09 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 04:18:09 Received a packet
[INFO][LAN] 12-09-2021 04:18:09 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 04:18:09 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 04:18:09 No valid arp replies for this
address
```

```
[INFO][LAN] 12-09-2021 04:18:06 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 04:18:06 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 04:18:06 Received a packet
[NOTICE][LAN] 12-09-2021 04:18:06 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 04:18:06 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 04:16:16 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 04:15:46 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:15:45 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:15:20 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 04:15:20 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 04:07:43 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 04:07:43 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 04:07:43 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 04:07:43 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 04:07:43 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 04:07:43 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 04:07:43 Received a packet
[NOTICE][LAN] 12-09-2021 04:07:42 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 04:07:42 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 04:07:42 SRC=192.168.2.102
DST=80.156.82.166 PROTO=TCP SPT=50546 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:07:42 SRC=192.168.2.102
DST=80.158.36.25 PROTO=TCP SPT=40862 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:07:42 SRC=192.168.2.102
DST=80.158.50.118 PROTO=TCP SPT=36026 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:07:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:07:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:07:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:07:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:07:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:07:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:07:42 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57622 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:07:42 SRC=192.168.2.100
```

DST=35.186.224.47 PROTO=TCP SPT=57636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 04:07:42 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57634 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 04:07:42 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46402 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 04:03:35 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 03:58:17 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 03:58:17 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46402 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 03:57:51 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 03:57:51 SRC=192.168.2.102
DST=142.250.184.202 PROTO=TCP SPT=54514 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:57:51 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46402 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 03:56:28 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 03:56:28 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 03:56:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46402 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:56:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46402 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:56:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46402 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:56:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46402 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:56:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46402 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:56:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46402 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 03:53:36 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 03:52:19 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 03:52:19 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 03:52:02 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 03:52:02 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 03:49:51 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 03:49:51 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 03:49:51 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 03:49:50 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 03:49:50 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 03:49:50 No valid arp replies for this
address

[INFO][LAN] 12-09-2021 03:49:48 Received REQUEST from client ip [0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 03:49:48 Received a packet
[NOTICE][LAN] 12-09-2021 03:49:47 wl1: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 03:49:41 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 03:49:17 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 03:48:48 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 03:47:00 Successfully assign IP [192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time [86400]
[INFO][LAN] 12-09-2021 03:47:00 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 03:47:00 No valid arp replies for this address
[INFO][LAN] 12-09-2021 03:47:00 Arp reply received from the requesting device itself.
[INFO][LAN] 12-09-2021 03:47:00 Received REQUEST from client ip [0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 03:47:00 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 03:47:00 Received a packet
[NOTICE][LAN] 12-09-2021 03:47:00 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 03:47:00 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 03:47:00 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57622 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:47:00 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57622 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:47:00 SRC=192.168.2.100 DST=17.248.172.108 PROTO=TCP SPT=57615 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:47:00 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57622 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:47:00 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57622 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:47:00 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57622 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:47:00 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57622 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:47:00 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57622 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:47:00 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57612 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:47:00 TCP Scan SRC=35.186.224.25 DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57591 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 03:47:00 SRC=192.168.2.100 DST=17.248.172.108 PROTO=TCP SPT=57615 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 03:45:13 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 03:45:13 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 03:44:57 wl0: AP-STA-CONNECTED

bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 03:44:57 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 03:44:36 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-09-2021 03:44:36 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 03:44:36 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 03:44:36 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 03:44:36 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 03:44:36 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-09-2021 03:44:36 Received a packet
[NOTICE][LAN] 12-09-2021 03:44:36 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-09-2021 03:37:47 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 03:31:59 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-09-2021 03:27:54 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 03:26:45 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 03:26:19 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57612 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=17.248.172.108 PROTO=TCP SPT=57615 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57612 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=17.248.172.108 PROTO=TCP SPT=57615 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57612 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=17.248.172.108 PROTO=TCP SPT=57615 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57612 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=17.248.172.108 PROTO=TCP SPT=57615 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57612 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=17.248.172.108 PROTO=TCP SPT=57615 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57612 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=17.248.172.108 PROTO=TCP SPT=57615 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57602 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 SRC=192.168.2.100
DST=17.248.172.108 PROTO=TCP SPT=57615 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:26:19 TCP Scan SRC=17.248.172.108

DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57615 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 03:26:19 TCP Scan SRC=172.217.19.74
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=50186 MARK=0x8000001
[INFO][LAN] 12-09-2021 03:20:23 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 03:16:32 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 03:10:49 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 03:10:49 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 03:10:48 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 03:10:48 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 03:10:27 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 03:10:19 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 03:10:18 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 03:10:18 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 03:09:59 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57602 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57602 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57602 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57602 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57602 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57602 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57602 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57594 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57599 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=52.38.158.138 PROTO=TCP SPT=56570 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=18.194.205.229 PROTO=TCP SPT=37240 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46186 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46188 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=92.122.22.140 PROTO=TCP SPT=44428 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57528 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=46186 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57594 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57585 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57592 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=52.213.57.192 PROTO=TCP SPT=52326 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=142.250.185.106 PROTO=TCP SPT=55694 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=142.250.186.118 PROTO=TCP SPT=40790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=52.213.57.192 PROTO=TCP SPT=52326 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=52.213.57.192 PROTO=TCP SPT=52326 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=52.213.57.192 PROTO=TCP SPT=52326 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=52.213.57.192 PROTO=TCP SPT=52326 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=52.213.57.192 PROTO=TCP SPT=52326 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=52.213.57.192 PROTO=TCP SPT=52326 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=52.213.57.192 PROTO=TCP SPT=52326 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=52.213.57.192 PROTO=TCP SPT=52326 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=52.177.138.113 PROTO=TCP SPT=56438 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 03:09:59 SRC=192.168.2.102
DST=52.49.141.8 PROTO=TCP SPT=35398 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 03:08:15 Successfully assign IP
[192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time
[86400]
[INFO][LAN] 12-09-2021 03:08:15 unicasting packet to client ciaddr
[INFO][LAN] 12-09-2021 03:08:15 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 03:08:15 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 03:08:15 Received REQUEST from client ip
[192.168.2.100] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-09-2021 03:08:15 Received a packet
[INFO][LAN] 12-09-2021 03:05:59 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 03:03:30 Successfully assign IP
[192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time
[86400]
[INFO][LAN] 12-09-2021 03:03:30 unicasting packet to client ciaddr
[INFO][LAN] 12-09-2021 03:03:30 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 03:03:30 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 03:03:30 Received REQUEST from client ip
[192.168.2.101] mac [68:2f:67:8a:e3:07]

[INFO][LAN] 12-09-2021 03:03:30 Received a packet
[INFO][LAN] 12-09-2021 02:57:17 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 02:47:58 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 02:40:18 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 02:40:18 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 02:39:54 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 02:39:54 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 02:39:34 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-09-2021 02:39:34 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 02:39:34 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 02:39:34 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 02:39:34 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 02:39:34 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-09-2021 02:39:34 Received a packet
[NOTICE][LAN] 12-09-2021 02:39:34 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-09-2021 02:39:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57585 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:39:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57585 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:39:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57585 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:39:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57585 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:39:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57585 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:39:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57585 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:39:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57585 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:39:34 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57575 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:39:34 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57552 MARK=0x8000001
[INFO][LAN] 12-09-2021 02:36:09 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 02:30:56 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 02:25:56 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 02:25:56 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 02:23:57 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.102
DST=80.158.36.25 PROTO=TCP SPT=40580 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.102

```
DST=80.158.50.118 PROTO=TCP SPT=35744 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57575 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57575 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57575 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57575 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57575 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57565 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57575 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 02:23:57 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57569 MARK=0x8000001
[INFO][LAN] 12-09-2021 02:23:07 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 02:16:42 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 02:10:35 wl0: AP-STA-CONNECTED
68:2f:67:8a:e3:07
[NOTICE][LAN] 12-09-2021 02:10:35 wl1: AP-STA-DISCONNECTED
68:2f:67:8a:e3:07
[INFO][LAN] 12-09-2021 02:07:05 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 02:07:05 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 02:07:05 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 02:07:05 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 02:07:05 unicasting packet to client yiaddr
```

[INFO][LAN] 12-09-2021 02:07:05 Received REQUEST from client ip [0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 02:07:05 Received a packet
[NOTICE][LAN] 12-09-2021 02:07:05 wl1: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 02:07:05 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-09-2021 02:06:42 Transmit reply to fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 02:06:42 Received information request from fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 02:06:42 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 02:06:39 Successfully assign IP [192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time [86400]
[INFO][LAN] 12-09-2021 02:06:39 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 02:06:39 No valid arp replies for this address
[INFO][LAN] 12-09-2021 02:06:39 Arp reply received from the requesting device itself.
[INFO][LAN] 12-09-2021 02:06:39 Received REQUEST from client ip [0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 02:06:39 Received a packet
[NOTICE][LAN] 12-09-2021 02:06:37 wl1: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 02:06:36 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-09-2021 02:05:30 Transmit reply to fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 02:05:30 Received information request from fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 02:05:30 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 02:05:29 Successfully assign IP [192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time [86400]
[INFO][LAN] 12-09-2021 02:05:29 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 02:05:29 No valid arp replies for this address
[INFO][LAN] 12-09-2021 02:05:27 Received REQUEST from client ip [0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 02:05:27 Received a packet
[NOTICE][LAN] 12-09-2021 02:05:26 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 02:05:24 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 02:05:09 wl1: AP-STA-CONNECTED
68:2f:67:8a:e3:07
[NOTICE][LAN] 12-09-2021 02:05:09 wl0: AP-STA-DISCONNECTED
68:2f:67:8a:e3:07
[INFO][LAN] 12-09-2021 02:04:13 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 02:02:42 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 02:02:12 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd

[NOTICE][LAN] 12-09-2021 01:57:07 wL0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:57:07 wL1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 01:57:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57565 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:57:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57565 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:57:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57565 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:57:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57565 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:57:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57565 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:57:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57565 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:57:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57565 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:57:07 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57555 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:57:07 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57560 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 01:57:07 SRC=192.168.2.102
DST=52.177.138.113 PROTO=TCP SPT=56358 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 01:55:46 wL1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:55:46 wL0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 01:55:40 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 01:55:10 wL0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:55:10 wL1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:54:29 wL1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:54:29 wL0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:54:24 wL0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:54:24 wL1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:54:13 wL1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:54:13 wL0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 01:54:13 SRC=192.168.2.102
DST=80.156.82.167 PROTO=TCP SPT=45308 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 01:52:36 wL0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:52:36 wL1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 01:50:38 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 01:50:38 Received information request from

```
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 01:50:38 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 01:50:38 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 01:50:38 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 01:50:38 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 01:50:38 Received a packet
[NOTICE][LAN] 12-09-2021 01:50:38 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 01:50:38 wl1: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-09-2021 01:50:26 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 01:50:26 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 01:50:25 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 01:50:24 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 01:50:24 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 01:50:24 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 01:50:22 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 01:50:22 Received a packet
[NOTICE][LAN] 12-09-2021 01:50:21 wl1: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 01:50:12 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-09-2021 01:45:22 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 01:45:22 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 01:45:22 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 01:45:22 Arp reply received from the
requesting device itself,
[INFO][LAN] 12-09-2021 01:45:22 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 01:45:22 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 01:45:22 Received a packet
[NOTICE][LAN] 12-09-2021 01:45:22 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 01:45:22 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 01:43:25 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:43:25 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:43:05 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:43:04 wl1: AP-STA-DISCONNECTED
```

bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 01:43:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57555 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:43:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57555 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:43:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57555 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:43:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57555 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:43:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57555 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:43:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57555 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:43:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:43:04 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57554 MARK=0x8000001
[INFO][LAN] 12-09-2021 01:41:28 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 01:39:29 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 01:39:04 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 01:39:04 SRC=192.168.2.102
DST=142.250.185.74 PROTO=TCP SPT=50436 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:39:04 SRC=192.168.2.102
DST=172.217.16.86 PROTO=TCP SPT=57764 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 01:34:49 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 01:34:47 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 01:34:47 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 01:34:47 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 01:34:47 Received a packet
[NOTICE][LAN] 12-09-2021 01:34:47 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 01:34:46 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 01:34:46 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 01:34:44 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 01:34:44 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 01:34:44 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 01:34:44 Received a packet
[INFO][LAN] 12-09-2021 01:34:44 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 01:34:44 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 01:34:44 No valid arp replies for this
address

[NOTICE][LAN] 12-09-2021 01:34:44 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 01:34:44 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 01:34:42 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 01:34:42 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 01:34:42 Received a packet
[NOTICE][LAN] 12-09-2021 01:34:42 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 01:34:42 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 01:30:16 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 01:25:29 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 01:24:59 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 01:24:12 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 01:24:12 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 01:24:12 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 01:24:12 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 01:24:12 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 01:24:12 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 01:24:12 Received a packet
[NOTICE][LAN] 12-09-2021 01:24:12 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 01:24:12 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 01:24:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:24:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:24:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:24:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:24:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:24:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:24:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57541 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:24:12 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57517 MARK=0x8000001
[INFO][LAN] 12-09-2021 01:22:18 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 01:19:32 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd

[NOTICE][LAN] 12-09-2021 01:18:57 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 01:15:47 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 01:13:06 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:13:06 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:12:41 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 01:12:41 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 01:12:26 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 01:12:22 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-09-2021 01:12:22 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 01:12:22 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 01:12:22 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 01:12:22 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-09-2021 01:12:22 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 01:12:22 Received a packet
[NOTICE][LAN] 12-09-2021 01:12:22 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-09-2021 01:10:51 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 01:10:51 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 01:10:51 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 01:10:48 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 01:10:48 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 01:10:48 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 01:10:48 Received a packet
[NOTICE][LAN] 12-09-2021 01:10:46 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 01:10:46 wl1: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-09-2021 01:10:27 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 01:10:27 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 01:10:27 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 01:10:23 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 01:10:20 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 01:10:20 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 01:10:20 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]

[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57541 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 TCP Scan SRC=35.186.224.47
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57523 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=49770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50872 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=49770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50872 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=49770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50872 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=49770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50872 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=49770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=49770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50872 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=49770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=49770 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=48012 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50872 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50872 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50872 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=216.58.213.234 PROTO=TCP SPT=50872 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45464 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45956 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45956 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45956 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45956 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45956 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45956 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45956 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45956 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45956 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=104.21.59.155 PROTO=TCP SPT=54768 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 01:07:04 SRC=192.168.2.102
DST=104.21.59.155 PROTO=TCP SPT=54770 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 01:05:16 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 00:58:20 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 00:56:08 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 00:56:08 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 00:53:48 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 00:53:28 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=53790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=53790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45914 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=53790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=53790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=53790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=53790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=53790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=53790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=53790 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45914 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57532 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57532 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57532 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57532 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57532 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57532 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57532 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57520 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57528 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45914 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45914 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45914 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45914 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45914 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45914 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:53:28 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45914 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 00:50:28 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 00:44:02 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 00:38:21 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 00:34:58 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 00:34:54 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 00:34:50 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-09-2021 00:34:50 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 00:34:50 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 00:34:50 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 00:34:50 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 00:34:50 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-09-2021 00:34:50 Received a packet
[NOTICE][LAN] 12-09-2021 00:34:50 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 00:34:44 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 00:34:22 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd

[WARNING][Firewall] 12-09-2021 00:34:22 SRC=192.168.2.102
DST=142.250.181.202 PROTO=TCP SPT=45014 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-09-2021 00:32:48 wl0: AP-STA-CONNECTED
68:2f:67:8a:e3:07
[NOTICE][LAN] 12-09-2021 00:32:48 wl1: AP-STA-DISCONNECTED
68:2f:67:8a:e3:07
[INFO][LAN] 12-09-2021 00:31:05 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 00:31:05 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 00:31:05 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 00:31:05 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 00:31:05 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 00:31:05 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 00:31:05 Received a packet
[NOTICE][LAN] 12-09-2021 00:31:05 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 00:31:05 wl1: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-09-2021 00:30:43 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 00:30:43 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 00:30:42 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 00:30:39 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 00:30:39 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 00:30:39 No valid arp replies for this
address
[INFO][LAN] 12-09-2021 00:30:39 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-09-2021 00:30:39 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 00:30:39 Received a packet
[NOTICE][LAN] 12-09-2021 00:30:37 wl1: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 00:30:33 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 00:30:00 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 00:29:40 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-09-2021 00:27:49 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 00:27:49 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 00:27:49 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 00:27:49 LAN sending RA to ff02::1

[INFO][LAN] 12-09-2021 00:27:49 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 00:27:49 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 00:27:49 Received a packet
[NOTICE][LAN] 12-09-2021 00:27:48 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 00:27:48 wl1: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-09-2021 00:27:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57520 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:27:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57520 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:27:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57520 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:27:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57520 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:27:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57520 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:27:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57520 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:27:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:27:48 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57518 MARK=0x8000001
[NOTICE][LAN] 12-09-2021 00:27:40 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 00:27:40 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 00:27:24 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 00:27:24 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-09-2021 00:27:24 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 00:27:22 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-09-2021 00:27:22 unicasting packet to client yiaddr
[INFO][LAN] 12-09-2021 00:27:22 No valid arp replies for this
address
[NOTICE][LAN] 12-09-2021 00:27:21 wl1: AP-STA-CONNECTED
68:2f:67:8a:e3:07
[NOTICE][LAN] 12-09-2021 00:27:21 wl0: AP-STA-DISCONNECTED
68:2f:67:8a:e3:07
[INFO][LAN] 12-09-2021 00:27:20 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-09-2021 00:27:20 Received a packet
[NOTICE][LAN] 12-09-2021 00:27:19 wl1: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 00:27:14 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-09-2021 00:26:42 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-09-2021 00:26:42 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-09-2021 00:26:17 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 00:26:11 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 00:26:11 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 00:26:00 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 00:26:00 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 00:25:44 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 00:25:44 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.102
DST=142.250.185.170 PROTO=TCP SPT=40310 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.102
DST=142.250.185.170 PROTO=TCP SPT=40310 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.102
DST=142.250.185.170 PROTO=TCP SPT=40310 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.102
DST=142.250.185.170 PROTO=TCP SPT=40310 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.102
DST=142.250.185.170 PROTO=TCP SPT=40310 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.102
DST=142.250.185.170 PROTO=TCP SPT=40310 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.102
DST=142.250.185.170 PROTO=TCP SPT=40310 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.102
DST=142.250.185.170 PROTO=TCP SPT=40310 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.102
DST=142.250.185.170 PROTO=TCP SPT=40310 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57504 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:25:44 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57477 MARK=0x8000001
[WARNING][Firewall] 12-09-2021 00:25:44 TCP Scan SRC=172.217.19.74

DST=178.10.236.179 PROTO=TCP SPT=443 DPT=49646 MARK=0x8000001
[INFO][LAN] 12-09-2021 00:16:19 LAN sending RA to ff02::1
[INFO][LAN] 12-09-2021 00:11:45 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 00:06:34 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 00:06:34 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 00:06:13 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-09-2021 00:06:13 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-09-2021 00:06:13 SRC=192.168.2.102
DST=216.58.213.206 PROTO=TCP SPT=43122 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:06:13 SRC=192.168.2.102
DST=74.125.108.104 PROTO=TCP SPT=40616 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:06:13 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:06:13 SRC=192.168.2.102
DST=74.125.13.72 PROTO=TCP SPT=47828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:06:13 SRC=192.168.2.102
DST=74.125.108.104 PROTO=TCP SPT=40616 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:06:13 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:06:13 SRC=192.168.2.102
DST=74.125.13.72 PROTO=TCP SPT=47828 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-09-2021 00:03:10 LAN sending RA to ff02::1
[NOTICE][LAN] 12-09-2021 00:01:07 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-09-2021 00:01:07 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.108.104 PROTO=TCP SPT=40616 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.13.72 PROTO=TCP SPT=47828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.108.104 PROTO=TCP SPT=40616 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.13.72 PROTO=TCP SPT=47828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.108.104 PROTO=TCP SPT=40616 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.13.72 PROTO=TCP SPT=47828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.108.104 PROTO=TCP SPT=40616 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.13.72 PROTO=TCP SPT=47828 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.13.72 PROTO=TCP SPT=47828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.108.104 PROTO=TCP SPT=40616 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.108.104 PROTO=TCP SPT=40616 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.13.72 PROTO=TCP SPT=47828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.13.72 PROTO=TCP SPT=47828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.108.104 PROTO=TCP SPT=40616 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.108.104 PROTO=TCP SPT=40616 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.13.72 PROTO=TCP SPT=47828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=38202 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=51130 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=38202 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-09-2021 00:01:07 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=51130 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 23:58:54 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:58:54 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 23:58:54 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=38202 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:53 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=51130 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:53 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=38202 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:53 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=51130 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 23:58:49 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 23:58:33 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:58:32 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=38202 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=51130 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102

DST=74.125.110.9 PROTO=TCP SPT=38202 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=51130 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=51130 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=38202 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=38202 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=51130 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=51130 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=38202 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=38202 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=51130 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.40 PROTO=TCP SPT=52140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.41 PROTO=TCP SPT=58070 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=53056 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:58:32 SRC=192.168.2.102
DST=74.125.110.40 PROTO=TCP SPT=52140 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 23:53:30 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.41 PROTO=TCP SPT=58070 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=53056 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.40 PROTO=TCP SPT=52140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.41 PROTO=TCP SPT=58070 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=53056 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.40 PROTO=TCP SPT=52140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.41 PROTO=TCP SPT=58070 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=53056 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.40 PROTO=TCP SPT=52140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102

DST=35.186.224.47 PROTO=TCP SPT=57504 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.41 PROTO=TCP SPT=58070 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=53056 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.40 PROTO=TCP SPT=52140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57504 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=53056 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.41 PROTO=TCP SPT=58070 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.40 PROTO=TCP SPT=52140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.100
DST=80.156.82.167 PROTO=TCP SPT=44984 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.40 PROTO=TCP SPT=52140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.41 PROTO=TCP SPT=58070 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=53056 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57504 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.40 PROTO=TCP SPT=52140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=53056 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.41 PROTO=TCP SPT=58070 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.40 PROTO=TCP SPT=52140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.110.41 PROTO=TCP SPT=58070 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.102
DST=74.125.108.105 PROTO=TCP SPT=53056 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57504 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57504 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57493 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57504 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:53:30 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57500 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 23:53:30 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=57492 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 23:52:46 w11: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 23:52:46 SRC=192.168.2.102
DST=74.125.160.7 PROTO=TCP SPT=48842 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:52:46 SRC=192.168.2.102

DST=74.125.160.7 PROTO=TCP SPT=48842 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:52:46 SRC=192.168.2.102
DST=74.125.160.7 PROTO=TCP SPT=48842 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:52:46 SRC=192.168.2.102
DST=74.125.160.7 PROTO=TCP SPT=48842 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:52:46 SRC=192.168.2.102
DST=74.125.160.7 PROTO=TCP SPT=48842 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:52:46 SRC=192.168.2.102
DST=74.125.160.7 PROTO=TCP SPT=48842 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:52:46 SRC=192.168.2.102
DST=74.125.160.7 PROTO=TCP SPT=48842 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:52:46 SRC=192.168.2.102
DST=74.125.160.7 PROTO=TCP SPT=48842 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:52:46 SRC=192.168.2.102
DST=74.125.160.7 PROTO=TCP SPT=48842 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:52:46 SRC=192.168.2.102
DST=74.125.160.7 PROTO=TCP SPT=48842 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:52:46 SRC=192.168.2.102
DST=23.63.149.28 PROTO=TCP SPT=49203 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:52:46 SRC=192.168.2.105
DST=17.248.173.17 PROTO=TCP SPT=49226 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 23:50:20 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-08-2021 23:50:20 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-08-2021 23:50:19 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 23:50:19 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 23:50:19 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 23:50:19 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 23:50:17 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 23:50:17 Received a packet
[NOTICE][LAN] 12-08-2021 23:50:15 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-08-2021 23:50:13 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-08-2021 23:50:13 SRC=192.168.2.102
DST=74.125.160.7 PROTO=TCP SPT=48810 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 23:50:04 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 23:50:04 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.160.7 PROTO=TCP SPT=48810 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34136 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=45748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.110.6 PROTO=TCP SPT=40224 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102

DST=74.125.160.6 PROTO=TCP SPT=45748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.110.6 PROTO=TCP SPT=40224 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.110.6 PROTO=TCP SPT=40224 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=45748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34136 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.110.7 PROTO=TCP SPT=34136 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=45748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.110.6 PROTO=TCP SPT=40224 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37966 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=33388 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60326 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37966 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=33388 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:50:04 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60326 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 23:49:36 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 23:46:21 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:46:21 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 23:46:21 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37966 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:21 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=33388 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:21 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60326 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 23:46:00 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:46:00 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37966 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=33388 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60326 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37966 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.108.103 PROTO=TCP SPT=33388 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60326 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=45640 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=46436 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=45640 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=46436 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=45640 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=46436 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=45640 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=46436 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=45640 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=46436 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=45640 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=46436 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=45640 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=44036 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60260 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=50824 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=173.194.165.135 PROTO=TCP SPT=41814 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=44036 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60260 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=50824 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:46:00 SRC=192.168.2.102
DST=173.194.165.135 PROTO=TCP SPT=41814 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 23:40:42 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:40:42 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac

[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=44036 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60260 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=50824 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=173.194.165.135 PROTO=TCP SPT=41814 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=44036 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60260 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=50824 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=173.194.165.135 PROTO=TCP SPT=41814 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=44036 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60260 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=50824 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:42 SRC=192.168.2.102
DST=173.194.165.135 PROTO=TCP SPT=41814 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 23:40:23 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:40:23 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=44036 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60260 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=50824 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=173.194.165.135 PROTO=TCP SPT=41814 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=173.194.165.135 PROTO=TCP SPT=41814 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=50824 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60260 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=44036 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=44036 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60260 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=50824 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=173.194.165.135 PROTO=TCP SPT=41814 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=173.194.165.135 PROTO=TCP SPT=41814 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=50824 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60260 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=44036 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.160.10 PROTO=TCP SPT=44036 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=60260 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=37900 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=74.125.110.39 PROTO=TCP SPT=50824 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=173.194.165.135 PROTO=TCP SPT=41814 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:40:23 SRC=192.168.2.102
DST=142.250.185.74 PROTO=TCP SPT=49444 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 23:39:37 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 23:37:40 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:37:40 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:36:40 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:36:40 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 23:35:32 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-08-2021 23:35:32 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 23:35:32 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 23:35:32 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 23:35:32 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 23:35:32 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-08-2021 23:35:32 Received a packet
[NOTICE][LAN] 12-08-2021 23:35:32 wl1: AP-STA-CONNECTED

0e:d3:bc:3c:3b:3d

[NOTICE][LAN] 12-08-2021 23:33:46 wl0: AP-STA-CONNECTED

6a:78:d9:7b:3e:cd

[WARNING][Firewall] 12-08-2021 23:33:46 SRC=192.168.2.102

DST=172.217.16.78 PROTO=TCP SPT=36226 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:46 SRC=192.168.2.102

DST=142.250.181.195 PROTO=TCP SPT=51322 DPT=80 MARK=0x3 DROP

[NOTICE][LAN] 12-08-2021 23:33:20 wl1: AP-STA-DISCONNECTED

6a:78:d9:7b:3e:cd

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=172.217.16.78 PROTO=TCP SPT=36226 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=142.250.181.195 PROTO=TCP SPT=51322 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=172.217.16.78 PROTO=TCP SPT=36226 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=142.250.181.195 PROTO=TCP SPT=51322 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=172.217.16.78 PROTO=TCP SPT=36226 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=142.250.181.195 PROTO=TCP SPT=51322 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=142.250.181.195 PROTO=TCP SPT=51322 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=172.217.16.78 PROTO=TCP SPT=36226 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=142.250.181.195 PROTO=TCP SPT=51322 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=172.217.16.78 PROTO=TCP SPT=36226 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=142.250.181.195 PROTO=TCP SPT=51322 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=172.217.16.78 PROTO=TCP SPT=36226 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=142.250.181.195 PROTO=TCP SPT=51322 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=172.217.16.78 PROTO=TCP SPT=36226 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=142.250.181.195 PROTO=TCP SPT=51322 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=172.217.16.78 PROTO=TCP SPT=36226 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=142.250.181.195 PROTO=TCP SPT=51322 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102

DST=172.217.16.78 PROTO=TCP SPT=36226 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=57493 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100

DST=17.253.79.202 PROTO=TCP SPT=57492 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=57493 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=57493 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100

[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100

DST=17.253.79.202 PROTO=TCP SPT=57492 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57493 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57493 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=57492 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57493 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57493 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=57492 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=57492 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57487 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102
DST=54.230.53.195 PROTO=TCP SPT=45856 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102
DST=54.230.53.195 PROTO=TCP SPT=45856 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102
DST=54.230.53.195 PROTO=TCP SPT=45856 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102
DST=172.67.4.50 PROTO=TCP SPT=49226 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102
DST=104.16.148.64 PROTO=TCP SPT=58196 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102
DST=104.16.148.64 PROTO=TCP SPT=58196 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:33:20 SRC=192.168.2.102
DST=104.16.148.64 PROTO=TCP SPT=58196 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 23:31:36 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:31:36 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:31:33 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 23:31:33 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 23:31:26 ACSD: Timestamp(ms):1639006287
ACS-Trigger:TIMER Selected Channel:#13 (0x100d)
[EMERG][LAN] 12-08-2021 23:31:26 WIFI 2.4G Channel has been changed
from channel 4 to 13.
[WARNING][Firewall] 12-08-2021 23:31:26 SRC=192.168.2.102
DST=92.122.21.240 PROTO=TCP SPT=51032 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:31:26 SRC=192.168.2.102
DST=92.122.21.240 PROTO=TCP SPT=51032 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:31:26 SRC=192.168.2.102
DST=92.122.21.240 PROTO=TCP SPT=51030 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:31:26 SRC=192.168.2.102
DST=92.122.21.240 PROTO=TCP SPT=51030 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 23:31:16 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 23:30:20 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-08-2021 23:30:20 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:28:54 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:28:54 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 23:26:42 Successfully assign IP
[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time
[86400]
[INFO][LAN] 12-08-2021 23:26:42 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 23:26:42 server_id = c0a80201
[INFO][LAN] 12-08-2021 23:26:42 Received REQUEST from client ip
[0.0.0.0] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 23:26:42 Received a packet
[INFO][LAN] 12-08-2021 23:26:42 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 23:26:42 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 23:26:42 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 23:26:42 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 23:26:42 Received a packet
[INFO][LAN] 12-08-2021 23:26:42 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 23:26:42 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 23:26:42 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 23:26:42 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 23:26:42 Received a packet
[INFO][LAN] 12-08-2021 23:26:42 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 23:26:42 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 23:26:42 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 23:26:42 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 23:26:42 Received a packet
[INFO][LAN] 12-08-2021 23:26:42 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 23:26:42 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 23:26:42 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 23:26:42 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 23:26:41 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 23:26:40 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 23:26:40 Received a packet
[NOTICE][LAN] 12-08-2021 23:26:40 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 23:20:16 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-08-2021 23:20:16 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=57472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:20:16 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57479 MARK=0x8000001
[INFO][LAN] 12-08-2021 23:20:11 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 23:10:50 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-08-2021 23:10:50 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-08-2021 23:10:50 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 23:10:50 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 23:10:50 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 23:10:50 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 23:10:50 Received a packet
[NOTICE][LAN] 12-08-2021 23:10:50 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-08-2021 23:10:50 wl1: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-08-2021 23:10:50 SRC=192.168.2.105
DST=23.63.149.28 PROTO=TCP SPT=49203 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:50 SRC=192.168.2.105
DST=17.248.173.17 PROTO=TCP SPT=49226 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 23:10:27 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-08-2021 23:10:27 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-08-2021 23:10:27 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 23:10:26 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 23:10:26 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 23:10:26 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 23:10:24 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 23:10:24 Received a packet
[NOTICE][LAN] 12-08-2021 23:10:22 wl1: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-08-2021 23:10:22 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=17.248.173.17 PROTO=TCP SPT=49207 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=23.63.149.28 PROTO=TCP SPT=49203 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=17.248.173.17 PROTO=TCP SPT=49226 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=17.248.173.17 PROTO=TCP SPT=49207 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=23.63.149.28 PROTO=TCP SPT=49203 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=17.248.173.17 PROTO=TCP SPT=49226 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=17.248.173.17 PROTO=TCP SPT=49241 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=35.186.224.18 PROTO=TCP SPT=49268 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=17.248.173.17 PROTO=TCP SPT=49245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=2.21.136.149 PROTO=TCP SPT=49199 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=17.248.173.17 PROTO=TCP SPT=49241 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=35.186.224.18 PROTO=TCP SPT=49268 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=2.21.136.149 PROTO=TCP SPT=49199 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=23.63.148.30 PROTO=TCP SPT=49239 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=2.21.136.149 PROTO=TCP SPT=49199 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=17.248.173.17 PROTO=TCP SPT=49245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 TCP Scan SRC=23.63.148.30
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=49239 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.105
DST=35.186.224.18 PROTO=TCP SPT=49268 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57472 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57463 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 23:10:22 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57441 MARK=0x8000001
[INFO][LAN] 12-08-2021 23:01:45 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 22:54:48 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 22:54:14 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 22:53:48 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 22:53:20 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 22:53:20 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 22:51:17 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd

[NOTICE][LAN] 12-08-2021 22:50:06 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 22:49:19 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 22:49:19 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[EMERG][Firewall] 12-08-2021 22:49:19 DoS attack: SYN With Data
Attack from source: 72.167.54.28:5173
[INFO][LAN] 12-08-2021 22:48:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 22:44:39 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-08-2021 22:44:39 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 22:44:39 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 22:44:39 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 22:44:39 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 22:44:39 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-08-2021 22:44:39 Received a packet
[NOTICE][LAN] 12-08-2021 22:44:39 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-08-2021 22:44:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57463 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:44:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57463 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:44:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57463 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:44:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57463 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:44:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57463 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:44:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57463 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:44:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57463 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:44:39 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57453 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:44:39 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57458 MARK=0x8000001
[INFO][LAN] 12-08-2021 22:43:20 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 22:40:19 Successfully assign IP
[192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time
[86400]
[INFO][LAN] 12-08-2021 22:40:19 unicasting packet to client ciaddr
[INFO][LAN] 12-08-2021 22:40:19 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 22:40:19 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 22:40:19 Received REQUEST from client ip
[192.168.2.100] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-08-2021 22:40:19 Received a packet
[NOTICE][LAN] 12-08-2021 22:39:04 wl1: AP-STA-DISCONNECTED

0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-08-2021 22:36:38 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 22:28:00 Transmit reply to
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-08-2021 22:28:00 Received information request from
fe80::1cc5:d297:7a7e:4f74%br0 on LAN
[INFO][LAN] 12-08-2021 22:28:00 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 22:27:59 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 22:27:59 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 22:27:59 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 22:27:57 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 22:27:57 Received a packet
[NOTICE][LAN] 12-08-2021 22:27:55 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-08-2021 22:25:50 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-08-2021 22:25:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57453 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:25:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57453 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:25:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57453 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:25:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57453 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:25:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57453 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:25:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57453 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:25:50 SRC=192.168.2.100
DST=17.167.225.11 PROTO=TCP SPT=57390 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:25:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57453 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:25:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57445 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:25:50 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57453 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:25:50 SRC=192.168.2.100
DST=17.167.225.11 PROTO=TCP SPT=57393 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:25:50 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57449 MARK=0x8000001
[INFO][LAN] 12-08-2021 22:23:08 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 22:18:50 Transmit reply to
fe80::1435:e640:1f7b:649f%br0 on LAN
[INFO][LAN] 12-08-2021 22:18:50 Received information request from
fe80::1435:e640:1f7b:649f%br0 on LAN
[INFO][LAN] 12-08-2021 22:18:50 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 22:18:46 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 22:18:46 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 22:18:46 server_id = c0a80201
[INFO][LAN] 12-08-2021 22:18:46 Received REQUEST from client ip

```
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 22:18:46 Received a packet
[INFO][LAN] 12-08-2021 22:18:45 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 22:18:45 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 22:18:45 Send OFFER of ip [192.168.2.105] to
client mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 22:18:45 Find a lease info, and use the
ip:6902a8c0
[INFO][LAN] 12-08-2021 22:18:45 Received DISCOVER from client mac
[10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 22:18:45 Received a packet
[INFO][LAN] 12-08-2021 22:18:45 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 22:18:45 Send OFFER of ip [192.168.2.105] to
client mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 22:18:45 Find a lease info, and use the
ip:6902a8c0
[INFO][LAN] 12-08-2021 22:18:45 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 22:18:43 Received DISCOVER from client mac
[10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 22:18:43 Received a packet
[NOTICE][LAN] 12-08-2021 22:18:41 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-08-2021 22:16:01 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-08-2021 22:14:58 Transmit reply to
fe80::10:236d:b57d:cdbd%br0 on LAN
[INFO][LAN] 12-08-2021 22:14:58 Received information request from
fe80::10:236d:b57d:cdbd%br0 on LAN
[INFO][LAN] 12-08-2021 22:14:58 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 22:14:57 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 22:14:57 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 22:14:57 server_id = c0a80201
[INFO][LAN] 12-08-2021 22:14:57 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 22:14:57 Received a packet
[INFO][LAN] 12-08-2021 22:14:56 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 22:14:56 Send OFFER of ip [192.168.2.105] to
client mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 22:14:56 Find a lease info, and use the
ip:6902a8c0
[INFO][LAN] 12-08-2021 22:14:56 Received DISCOVER from client mac
[10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 22:14:56 Received a packet
[INFO][LAN] 12-08-2021 22:14:56 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 22:14:56 Send OFFER of ip [192.168.2.105] to
client mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 22:14:56 Find a lease info, and use the
ip:6902a8c0
[INFO][LAN] 12-08-2021 22:14:56 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 22:14:54 LAN sending RA to ff02::1
```


[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=17.248.173.5 PROTO=TCP SPT=52880 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=104.21.10.77 PROTO=TCP SPT=52874 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=104.21.46.209 PROTO=TCP SPT=52882 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=17.248.173.5 PROTO=TCP SPT=52880 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=104.21.10.77 PROTO=TCP SPT=52874 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=104.21.46.209 PROTO=TCP SPT=52882 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=17.248.173.5 PROTO=TCP SPT=52880 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=104.21.10.77 PROTO=TCP SPT=52874 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=104.21.46.209 PROTO=TCP SPT=52882 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=17.248.173.5 PROTO=TCP SPT=52880 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=104.21.10.77 PROTO=TCP SPT=52874 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=104.21.46.209 PROTO=TCP SPT=52882 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=17.248.173.5 PROTO=TCP SPT=52880 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=104.21.10.77 PROTO=TCP SPT=52874 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=104.21.46.209 PROTO=TCP SPT=52882 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=17.248.173.5 PROTO=TCP SPT=52880 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=104.21.10.77 PROTO=TCP SPT=52874 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.105
DST=104.21.46.209 PROTO=TCP SPT=52882 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57445 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=17.167.225.11 PROTO=TCP SPT=57390 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=17.167.225.11 PROTO=TCP SPT=57393 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57445 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57445 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=17.167.225.11 PROTO=TCP SPT=57390 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57445 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=17.167.225.11 PROTO=TCP SPT=57393 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57445 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57445 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57435 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=17.167.225.11 PROTO=TCP SPT=57390 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57445 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=17.167.225.11 PROTO=TCP SPT=57393 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57444 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=17.167.225.11 PROTO=TCP SPT=57390 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 22:10:57 SRC=192.168.2.100
DST=17.167.225.11 PROTO=TCP SPT=57393 DPT=443 MARK=0x3 DROP
[INFO][System] 12-08-2021 22:10:34 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 22:05:30 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 21:59:56 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 21:54:42 Transmit reply to
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 21:54:42 Received information request from
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 21:54:42 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 21:54:42 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 21:54:42 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 21:54:42 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 21:54:42 Received a packet
[NOTICE][LAN] 12-08-2021 21:54:42 wl1: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-08-2021 21:54:42 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-08-2021 21:54:12 Transmit reply to
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 21:54:12 Received information request from
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 21:54:11 LAN sending RA to ff02::1


```
[INFO][LAN] 12-08-2021 21:54:09 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 21:54:09 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 21:54:09 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 21:54:09 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 21:54:09 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 21:54:09 Received a packet
[NOTICE][LAN] 12-08-2021 21:54:07 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-08-2021 21:54:05 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-08-2021 21:51:13 Transmit reply to
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 21:51:13 Received information request from
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 21:51:12 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 21:51:12 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 21:51:12 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 21:51:12 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 21:51:12 Received a packet
[NOTICE][LAN] 12-08-2021 21:51:12 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-08-2021 21:51:12 wl1: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-08-2021 21:50:50 Transmit reply to
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 21:50:50 Received information request from
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 21:50:49 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 21:50:46 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 21:50:46 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 21:50:46 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 21:50:46 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 21:50:46 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 21:50:46 Received a packet
[NOTICE][LAN] 12-08-2021 21:50:45 wl1: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-08-2021 21:50:45 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57435 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
```

DST=35.186.224.47 PROTO=TCP SPT=57435 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57435 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=17.248.172.204 PROTO=TCP SPT=57423 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57435 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57435 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57435 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57435 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57400 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57422 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=17.248.172.204 PROTO=TCP SPT=57423 DPT=443 MARK=0x3 DROP
[EMERG][Firewall] 12-08-2021 21:50:45 DoS attack: SYN With Data
Attack from source: 51.15.13.79:6280
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57422 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=17.248.172.204 PROTO=TCP SPT=57423 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57422 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57422 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=17.248.172.204 PROTO=TCP SPT=57423 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57422 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=17.248.172.204 PROTO=TCP SPT=57423 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57422 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57414 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=17.248.172.204 PROTO=TCP SPT=57423 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 TCP Scan SRC=17.248.172.204
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57423 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.105
DST=104.21.10.77 PROTO=TCP SPT=52793 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.105
DST=104.21.10.77 PROTO=TCP SPT=52793 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.105

DST=104.21.10.77 PROTO=TCP SPT=52793 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.105
DST=142.250.185.234 PROTO=TCP SPT=52767 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.105
DST=172.67.156.154 PROTO=TCP SPT=52773 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.105
DST=104.21.10.77 PROTO=TCP SPT=52793 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.105
DST=172.67.156.154 PROTO=TCP SPT=52773 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.105
DST=142.250.185.234 PROTO=TCP SPT=52767 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.105
DST=172.67.156.154 PROTO=TCP SPT=52773 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.105
DST=172.67.156.154 PROTO=TCP SPT=52773 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.105
DST=104.21.10.77 PROTO=TCP SPT=52793 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.105
DST=142.250.185.234 PROTO=TCP SPT=52767 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57414 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57414 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57414 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57414 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57414 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57403 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57414 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:50:45 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57409 MARK=0x8000001
[INFO][LAN] 12-08-2021 21:47:15 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 21:40:33 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 21:33:48 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 21:28:20 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 21:21:30 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 21:13:07 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 21:05:27 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-08-2021 21:05:27 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 21:05:27 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 21:05:27 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 21:05:27 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 21:05:27 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]

[INFO][LAN] 12-08-2021 21:05:27 Received a packet
[NOTICE][LAN] 12-08-2021 21:05:27 wlan1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-08-2021 21:05:27 SRC=192.168.2.101
DST=162.159.36.1 PROTO=TCP SPT=57492 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 21:05:27 TCP Scan SRC=23.63.148.30
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=56979 MARK=0x8000001
[INFO][LAN] 12-08-2021 21:04:12 LAN sending RA to ff02::1
[EMERG][LAN] 12-08-2021 21:00:12 WIFI 2.4G Channel has been changed
from channel 8 to 4.
[NOTICE][LAN] 12-08-2021 20:59:06 wlan1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-08-2021 20:59:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57403 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:59:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57403 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:59:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57403 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:59:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57403 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:59:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57403 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:59:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57392 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:59:06 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57403 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:59:06 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57402 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 20:59:06 SRC=192.168.2.100
DST=17.248.172.241 PROTO=TCP SPT=57338 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:59:06 SRC=192.168.2.100
DST=17.248.172.236 PROTO=TCP SPT=57337 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 20:58:51 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 20:55:08 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 20:45:34 Transmit reply to
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 20:45:34 Received information request from
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 20:45:33 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 20:45:33 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 20:45:33 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 20:45:33 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 20:45:33 Received a packet
[INFO][LAN] 12-08-2021 20:45:33 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 20:45:33 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 20:45:33 No valid arp replies for this
address

[INFO][LAN] 12-08-2021 20:45:30 Received REQUEST from client ip [0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 20:45:30 Received a packet
[NOTICE][LAN] 12-08-2021 20:45:28 wl0: AP-STA-CONNECTED 10:94:bb:d5:73:92
[EMERG][Firewall] 12-08-2021 20:45:28 DoS attack: SYN With Data Attack from source: 8.217.12.255:28816
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57392 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.241 PROTO=TCP SPT=57338 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.236 PROTO=TCP SPT=57337 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57392 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.241 PROTO=TCP SPT=57338 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.236 PROTO=TCP SPT=57337 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57392 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.241 PROTO=TCP SPT=57338 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.236 PROTO=TCP SPT=57337 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57392 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.241 PROTO=TCP SPT=57338 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.236 PROTO=TCP SPT=57337 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57392 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.241 PROTO=TCP SPT=57338 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.236 PROTO=TCP SPT=57337 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57392 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.241 PROTO=TCP SPT=57338 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.236 PROTO=TCP SPT=57337 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57392 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.241 PROTO=TCP SPT=57338 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.236 PROTO=TCP SPT=57337 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57392 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.241 PROTO=TCP SPT=57338 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.236 PROTO=TCP SPT=57337 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=57392 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.241 PROTO=TCP SPT=57338 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 SRC=192.168.2.100 DST=17.248.172.236 PROTO=TCP SPT=57337 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:45:28 TCP Scan SRC=17.248.172.241 DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57338 MARK=0x8000001
[INFO][LAN] 12-08-2021 20:38:05 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 20:31:50 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 20:23:40 LAN sending RA to ff02::1
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105 DST=3.122.81.23 PROTO=TCP SPT=52634 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57363 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 TCP Scan SRC=35.186.224.25
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57369 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=2.21.133.200 PROTO=TCP SPT=52010 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=2.21.133.200 PROTO=TCP SPT=52010 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=2.21.133.200 PROTO=TCP SPT=52010 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=185.60.217.28 PROTO=TCP SPT=52117 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=185.60.217.28 PROTO=TCP SPT=52117 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=185.60.217.28 PROTO=TCP SPT=52116 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=185.60.217.28 PROTO=TCP SPT=52116 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=185.60.217.28 PROTO=TCP SPT=52115 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=185.60.217.28 PROTO=TCP SPT=52115 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=185.60.217.28 PROTO=TCP SPT=52113 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=185.60.217.28 PROTO=TCP SPT=52113 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=2.21.133.200 PROTO=TCP SPT=52010 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=2.21.133.200 PROTO=TCP SPT=52010 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=2.21.133.200 PROTO=TCP SPT=52010 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=2.21.133.200 PROTO=TCP SPT=52010 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=2.21.133.200 PROTO=TCP SPT=52010 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=2.21.133.200 PROTO=TCP SPT=52010 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 20:20:19 SRC=192.168.2.105
DST=2.21.133.200 PROTO=TCP SPT=52010 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 20:15:40 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 20:07:43 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 20:00:31 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 19:52:14 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 19:44:38 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 19:39:31 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 19:35:56 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 19:31:18 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 19:25:19 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 19:18:18 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 19:09:43 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 19:04:08 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:58:40 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:50:00 LAN sending RA to ff02::1

```
[INFO][LAN] 12-08-2021 18:44:20 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:40:18 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-08-2021 18:40:18 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:40:18 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 18:40:18 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 18:40:17 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:40:17 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 18:40:17 Received a packet
[NOTICE][LAN] 12-08-2021 18:40:17 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 18:40:16 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=17.248.172.238 PROTO=TCP SPT=57301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=17.248.172.238 PROTO=TCP SPT=57301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=17.248.172.238 PROTO=TCP SPT=57301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=17.248.172.238 PROTO=TCP SPT=57301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57292 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57307 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=17.248.172.238 PROTO=TCP SPT=57301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=17.248.172.238 PROTO=TCP SPT=57301 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 TCP Scan SRC=172.67.182.162
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57309 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=57293 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:40:16 SRC=192.168.2.100
DST=17.248.172.238 PROTO=TCP SPT=57301 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 18:32:23 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:24:35 Transmit reply to
fe80::1050:173f:3ea0:6f76%br0 on LAN
```

[INFO][LAN] 12-08-2021 18:24:35 Received information request from fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 18:24:34 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:24:30 Successfully assign IP [192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time [86400]
[INFO][LAN] 12-08-2021 18:24:30 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:24:30 No valid arp replies for this address
[INFO][LAN] 12-08-2021 18:24:30 Arp reply received from the requesting device itself.
[INFO][LAN] 12-08-2021 18:24:29 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:24:29 Received REQUEST from client ip [0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 18:24:29 Received a packet
[NOTICE][LAN] 12-08-2021 18:24:29 wl0: AP-STA-CONNECTED 10:94:bb:d5:73:92
[NOTICE][LAN] 12-08-2021 18:24:29 wl1: AP-STA-DISCONNECTED 10:94:bb:d5:73:92
[INFO][LAN] 12-08-2021 18:18:38 Successfully assign IP [192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time [86400]
[INFO][LAN] 12-08-2021 18:18:38 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:18:38 No valid arp replies for this address
[INFO][LAN] 12-08-2021 18:18:38 Arp reply received from the requesting device itself.
[INFO][LAN] 12-08-2021 18:18:38 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:18:38 Received REQUEST from client ip [0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-08-2021 18:18:38 Received a packet
[NOTICE][LAN] 12-08-2021 18:18:38 wl1: AP-STA-CONNECTED 0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-08-2021 18:18:24 Transmit reply to fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 18:18:24 Received information request from fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 18:18:23 Successfully assign IP [192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time [86400]
[INFO][LAN] 12-08-2021 18:18:23 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:18:23 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:18:23 Received REQUEST from client ip [0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 18:18:23 Received a packet
[NOTICE][LAN] 12-08-2021 18:18:23 wl1: AP-STA-CONNECTED 10:94:bb:d5:73:92
[NOTICE][LAN] 12-08-2021 18:18:23 wl0: AP-STA-DISCONNECTED 10:94:bb:d5:73:92
[INFO][LAN] 12-08-2021 18:17:56 Transmit reply to fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 18:17:56 Received information request from fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 18:17:55 LAN sending RA to ff02::1

```
[INFO][LAN] 12-08-2021 18:17:52 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 18:17:52 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:17:52 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 18:17:52 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 18:17:52 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 18:17:52 Received a packet
[NOTICE][LAN] 12-08-2021 18:17:51 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[NOTICE][LAN] 12-08-2021 18:17:47 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=18.156.44.202 PROTO=TCP SPT=57259 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57292 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=57293 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57292 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=57293 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57292 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57292 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57292 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=57293 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57292 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57292 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=57293 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57292 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=57293 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=57293 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 18:17:47 TCP Scan SRC=23.63.148.30
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=57293 MARK=0x8000001
[NOTICE][LAN] 12-08-2021 18:15:05 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 18:13:55 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 18:13:55 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 18:11:22 Successfully assign IP
[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time
[86400]
```

```
[INFO][LAN] 12-08-2021 18:11:22 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:11:22 server_id = c0a80201
[INFO][LAN] 12-08-2021 18:11:22 Received REQUEST from client ip
[0.0.0.0] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 18:11:22 Received a packet
[INFO][LAN] 12-08-2021 18:11:22 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:11:22 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 18:11:22 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 18:11:22 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 18:11:22 Received a packet
[INFO][LAN] 12-08-2021 18:11:22 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:11:22 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 18:11:22 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 18:11:22 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 18:11:22 Received a packet
[INFO][LAN] 12-08-2021 18:11:22 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:11:22 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 18:11:22 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 18:11:22 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 18:11:22 Received a packet
[INFO][LAN] 12-08-2021 18:11:22 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:11:22 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 18:11:22 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 18:11:22 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 18:11:21 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:11:20 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 18:11:20 Received a packet
[NOTICE][LAN] 12-08-2021 18:11:20 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 18:08:06 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 18:08:06 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-08-2021 18:08:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:08:02 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-08-2021 18:08:02 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:08:02 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 18:08:02 Arp reply received from the
```


requesting device itself.
[INFO][LAN] 12-08-2021 18:08:02 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:08:02 Received REQUEST from client ip [0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-08-2021 18:08:02 Received a packet
[NOTICE][LAN] 12-08-2021 18:08:02 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-08-2021 18:07:58 Successfully assign IP [192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time [86400]
[INFO][LAN] 12-08-2021 18:07:58 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:07:58 server_id = c0a80201
[INFO][LAN] 12-08-2021 18:07:58 Received REQUEST from client ip [0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 18:07:58 Received a packet
[INFO][LAN] 12-08-2021 18:07:57 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:07:57 Send OFFER of ip [192.168.2.103] to client mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 18:07:57 Find a lease info, and use the ip:6702a8c0
[INFO][LAN] 12-08-2021 18:07:57 Received DISCOVER from client mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 18:07:57 Received a packet
[INFO][LAN] 12-08-2021 18:07:57 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 18:07:57 Send OFFER of ip [192.168.2.103] to client mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 18:07:57 Find a lease info, and use the ip:6702a8c0
[INFO][LAN] 12-08-2021 18:07:57 No valid arp replies for this address
[INFO][LAN] 12-08-2021 18:07:55 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 18:07:55 Received DISCOVER from client mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 18:07:55 Received a packet
[NOTICE][LAN] 12-08-2021 18:07:55 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 18:01:00 ACS-D: Timestamp(ms):1638986461 ACS-Trigger:NONACS Selected Channel:#48/80 (0xe32a)
[EMERG][LAN] 12-08-2021 18:00:59 WIFI 5G Channel has been changed from channel 100 to 48.
[EMERG][LAN] 12-08-2021 18:00:58 wl0: DFS WiFi radar detected on channel 106 going to channel 42
[INFO][LAN] 12-08-2021 17:59:36 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 17:55:29 ACS-D: Timestamp(ms):1638986130 ACS-Trigger:TIMER Selected Channel:#8 (0x1008)
[EMERG][LAN] 12-08-2021 17:55:29 WIFI 2.4G Channel has been changed from channel 1 to 8.
[NOTICE][LAN] 12-08-2021 17:54:42 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 17:54:24 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 17:54:23 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[NOTICE][LAN] 12-08-2021 17:53:52 wl0: AP-STA-CONNECTED

bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 17:53:51 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 17:53:50 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 17:53:50 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-08-2021 17:53:42 Successfully assign IP
[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time
[86400]
[INFO][LAN] 12-08-2021 17:53:42 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 17:53:42 server_id = c0a80201
[INFO][LAN] 12-08-2021 17:53:42 Received REQUEST from client ip
[0.0.0.0] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 17:53:42 Received a packet
[INFO][LAN] 12-08-2021 17:53:42 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 17:53:42 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 17:53:42 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 17:53:42 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 17:53:42 Received a packet
[INFO][LAN] 12-08-2021 17:53:42 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 17:53:41 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 17:53:41 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 17:53:41 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 17:53:39 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 17:53:39 Received a packet
[NOTICE][LAN] 12-08-2021 17:53:34 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 17:53:32 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 17:53:29 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 17:53:29 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 17:53:25 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 17:53:25 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 17:53:24 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 17:53:24 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 17:53:24 SRC=192.168.2.102
DST=2.22.241.24 PROTO=TCP SPT=35852 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:53:24 SRC=192.168.2.102
DST=2.22.241.24 PROTO=TCP SPT=35852 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:53:24 SRC=192.168.2.102

DST=2.22.241.24 PROTO=TCP SPT=35848 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:53:24 SRC=192.168.2.102
DST=2.22.241.24 PROTO=TCP SPT=35850 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:53:24 SRC=192.168.2.102
DST=2.22.241.24 PROTO=TCP SPT=35840 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:53:24 SRC=192.168.2.102
DST=2.22.241.24 PROTO=TCP SPT=35842 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:53:24 SRC=192.168.2.102
DST=2.22.241.24 PROTO=TCP SPT=35852 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:53:24 SRC=192.168.2.102
DST=92.122.22.147 PROTO=TCP SPT=42274 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 17:53:02 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 17:46:59 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 17:46:57 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-08-2021 17:46:57 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 17:46:57 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 17:46:57 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 17:46:57 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-08-2021 17:46:57 Received a packet
[NOTICE][LAN] 12-08-2021 17:46:57 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-08-2021 17:46:56 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-08-2021 17:46:56 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 17:46:56 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 17:46:56 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 17:46:56 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 17:46:56 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 17:46:56 Received a packet
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=57198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=57198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=57217 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=57198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=57217 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=57198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=57217 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57200 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=57215 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=57216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=57217 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57200 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=17.253.57.210 PROTO=TCP SPT=57191 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=57215 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=57216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=57198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=57217 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57200 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=17.253.57.210 PROTO=TCP SPT=57191 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=57198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=57215 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=57216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57200 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=57217 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=17.253.57.210 PROTO=TCP SPT=57191 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=57215 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=57216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57200 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=17.253.79.202 PROTO=TCP SPT=57198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=57217 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=57200 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=17.253.57.210 PROTO=TCP SPT=57191 DPT=80 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 17:46:56 wlo: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=57215 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:56 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=57216 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=37.252.173.27 PROTO=TCP SPT=41976 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=85.114.159.93 PROTO=TCP SPT=42010 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=53844 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 TCP Scan SRC=216.58.213.202
DST=178.10.236.179 PROTO=TCP SPT=443 DPT=45064 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=53844 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=53844 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=53844 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=53844 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=53844 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=53844 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=53844 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=53844 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=34.104.35.123 PROTO=TCP SPT=53844 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=53256 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.195 PROTO=TCP SPT=48022 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=52150 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.195 PROTO=TCP SPT=48022 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.195 PROTO=TCP SPT=48022 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=52150 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.195 PROTO=TCP SPT=48022 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.195 PROTO=TCP SPT=48022 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.195 PROTO=TCP SPT=48022 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.195 PROTO=TCP SPT=48022 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.195 PROTO=TCP SPT=48022 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.195 PROTO=TCP SPT=48022 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=52150 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=52150 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=52150 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=52.232.209.85 PROTO=TCP SPT=52462 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=52150 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=52150 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=52150 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=52150 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=52150 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=216.58.213.193 PROTO=TCP SPT=49698 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=172.217.19.74 PROTO=TCP SPT=45068 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=172.217.19.78 PROTO=TCP SPT=54200 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 17:46:55 SRC=192.168.2.102
DST=74.125.133.113 PROTO=TCP SPT=38424 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 17:45:58 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 17:41:13 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 17:32:24 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 17:25:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 17:18:52 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 17:12:27 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 17:04:05 LAN sending RA to ff02::1
[INFO][VoIP] 12-08-2021 16:58:47 Switch to primary proxy server
arcor.de on line 0
[INFO][LAN] 12-08-2021 16:58:36 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 16:58:20 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 16:58:04 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 16:58:04 Sync up with NTP Server
successfully.
[INFO][System] 12-08-2021 16:58:00 Sync up with NTP Server
successfully.
[INFO][VoIP] 12-08-2021 16:57:53 Send data/single wan update to
VGW,wan id 10,ifName is ppp10,ipv4 address 178.10.236.179,ipv6
address ,default_wan_id 10,wan type 1
[INFO][VoIP] 12-08-2021 16:57:53 line 371 ,wan 10 start do data wan
up
[INFO][VoIP] 12-08-2021 16:57:53 wanipv6 = ,size = 0
[INFO][VoIP] 12-08-2021 16:57:53 Voice binding wan_id is
10,default_wan_id is 10
[INFO][VoIP] 12-08-2021 16:57:53 Voice binding wan_id is
10,default_wan_id is 10,is_ipv6 = 0
[INFO][VoIP] 12-08-2021 16:57:53 wan 10 service_type =
DATA,VOIP,MGNT,IPTV bud_voip_wan_id = 10
[INFO][VoIP] 12-08-2021 16:57:53 Interface wan_ip is 178.10.236.179,
wan_ip_v6 ,is_ipv6 0 wan up id 10

```
[INFO] [LAN] 12-08-2021 16:57:53 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO] [LAN] 12-08-2021 16:57:53 adapter index 18
[INFO] [LAN] 12-08-2021 16:57:53 br0 (our ip) = 192.168.2.1
[INFO] [LAN] 12-08-2021 16:57:53 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO] [LAN] 12-08-2021 16:57:53 adapter index 18
[INFO] [LAN] 12-08-2021 16:57:53 br0 (our ip) = 192.168.2.1
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option timezone to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option t2 to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option t1 to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option lease to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option dns to existing
member of list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option dns to existing
member of list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option dns to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option router to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option subnet to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option timezone to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option t2 to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option t1 to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option lease to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option dns to list
[INFO] [LAN] 12-08-2021 16:57:53 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO] [LAN] 12-08-2021 16:57:53 adapter index 19
[INFO] [LAN] 12-08-2021 16:57:53 br1 (our ip) = 192.168.3.1
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option timezone to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option t2 to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option t1 to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option lease to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option hostname to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option dns to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option domain to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option router to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option router to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option subnet to list
[INFO] [LAN] 12-08-2021 16:57:53 Attaching option subnet to list
[INFO] [LAN] 12-08-2021 16:57:53 error on select
[INFO] [LAN] 12-08-2021 16:57:53 error on select
[INFO] [LAN] 12-08-2021 16:57:53 udhcp server receive signal 12
[INFO] [LAN] 12-08-2021 16:57:53 udhcp server receive signal 12
[INFO] [System] 12-08-2021 16:57:51 Starting MCPD OK.
[INFO] [System] 12-08-2021 16:57:51 Stopping MCPD OK.
[INFO] [UMTS] 12-08-2021 16:57:51 iPhone DNS Policy actived
[INFO] [VoIP] 12-08-2021 16:57:51 276 start wan service Voice
binding wan_id is 10
[INFO] [VoIP] 12-08-2021 16:57:51 Voice binding wan_id is 10
[INFO] [System] 12-08-2021 16:57:51 Starting NTP Client OK.
[INFO] [System] 12-08-2021 16:57:51 Sync up with NTP Server failed.
[INFO] [System] 12-08-2021 16:57:51 Stopping NTP Client OK.
[INFO] [Firewall] 12-08-2021 16:57:50 PortMapping Rules have been
flushed on WAN VDSL-DT.
```

[INFO][Firewall] 12-08-2021 16:57:50 DMZ Rules has been flushed on WAN VDSL-DT.
[INFO][Firewall] 12-08-2021 16:57:50 Static NAT Rules have been flushed on WAN VDSL-DT.
[INFO][System] 12-08-2021 16:57:50 Stopping HTTP redirect OK.
[INFO][DNS] 12-08-2021 16:57:50 DNSMasq proxy server disable redirect
[INFO][DNS] 12-08-2021 16:57:49 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-08-2021 16:57:49 Internet DNS ready.
[INFO][DNS] 12-08-2021 16:57:49 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-08-2021 16:57:49 Internet DNS ready.
[INFO][DNS] 12-08-2021 16:57:49 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-08-2021 16:57:49 Internet DNS ready.
[INFO][DNS] 12-08-2021 16:57:49 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-08-2021 16:57:49 Internet DNS ready.
[WARNING][DNS] 12-08-2021 16:57:49 ignoring nameserver 127.0.0.1 - local interface
[WARNING][DNS] 12-08-2021 16:57:49 ignoring nameserver ::1 - local interface
[INFO][DNS] 12-08-2021 16:57:49 Starting DNSMasq proxy server OK.
[INFO][DNS] 12-08-2021 16:57:49 Stopping DNSMasq proxy OK.
[INFO][System] 12-08-2021 16:57:49 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 16:57:48 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 16:57:48 LAN sending RA to ff02::1
[INFO][DNS] 12-08-2021 16:57:48 DNSMasq proxy server disable redirect
[INFO][VoIP] 12-08-2021 16:57:47 ignore useless wan down
[INFO][VoIP] 12-08-2021 16:57:47 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 8, is_ipv6 = 0, default_wan_id= 10
[INFO][VoIP] 12-08-2021 16:57:47 ===start stop voice wan
[INFO][UMTS] 12-08-2021 16:57:47 iPhone DNS Policy actived
[INFO][VoIP] 12-08-2021 16:57:47 Remove interface wan_id is 10, wan type 2.
[INFO][VoIP] 12-08-2021 16:57:47 VoIP WAN down, Voice trying to run in backup mode, try binding wan_id is 10
[INFO][VoIP] 12-08-2021 16:57:47 bud data ipv4 wan status 10, ipv6 wan status -1
[INFO][VoIP] 12-08-2021 16:57:47 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 10, is_ipv6 = 0, default_wan_id= 10
[INFO][VoIP] 12-08-2021 16:57:47 ===start stop voice wan
[INFO][System] 12-08-2021 16:57:46 Starting MCPD OK.
[INFO][VoIP] 12-08-2021 16:57:46 ignore useless wan down
[INFO][VoIP] 12-08-2021 16:57:46 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 8, is_ipv6 = 1, default_wan_id= 10
[INFO][VoIP] 12-08-2021 16:57:46 ===start stop voice wan
[INFO][System] 12-08-2021 16:57:46 Stopping MCPD OK.
[INFO][WAN] 12-08-2021 16:57:46 Stop WAN 8 IP Connection

[INFO][System] 12-08-2021 16:57:46 FSM---- Switch to Connect State.
[INFO][DNS] 12-08-2021 16:57:45 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 16:57:45 Internet DNS ready.
[INFO][DNS] 12-08-2021 16:57:45 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 16:57:45 Internet DNS ready.
[INFO][DNS] 12-08-2021 16:57:45 Internet DNS deactivated.
[WARNING][WAN] 12-08-2021 16:57:45 WAN default route add to ppp10
gateway 84.59.211.1.
[INFO][WAN] 12-08-2021 16:57:45 Data WAN11 Activated!
[INFO][WAN] 12-08-2021 16:57:45 bud update WAN11 status to 2.
[WARNING][WAN] 12-08-2021 16:57:44 WAN VDSL-DT is up, mode is PPPoE,
IP is 178.10.236.179.
[WARNING][WAN] 12-08-2021 16:57:44 WAN VDSL-DT is down.
[INFO][LAN] 12-08-2021 16:57:44 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 16:57:44 PPP CHAP MD5 authentication is
successful on WAN VDSL-DT
[INFO][LAN] 12-08-2021 16:57:44 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 16:57:44 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 16:57:44 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 16:57:44 PPPoE PADS has been received from
WAN VDSL-DT
[INFO][WAN] 12-08-2021 16:57:44 PPPoE PADR has been sent from WAN
VDSL-DT
[INFO][WAN] 12-08-2021 16:57:44 PPPoE PADO has been received from
WAN VDSL-DT, BRAS name is BLNCOS69101.
[INFO][WAN] 12-08-2021 16:57:44 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][WAN] 12-08-2021 16:57:44 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][System] 12-08-2021 16:57:36 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 16:57:32 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:31 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:31 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:31 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:30 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:30 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:29 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:29 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:28 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:28 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:28 DSL link up.
[INFO][WAN] 12-08-2021 16:57:27 PPPoE PADI has been sent from WAN
VDSL-DT
[EMERG][WAN] 12-08-2021 16:57:27 DSL link up.
[INFO][WAN] 12-08-2021 16:57:27 PPPoE PADI has been sent from WAN
VDSL-DATA
[EMERG][WAN] 12-08-2021 16:57:27 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:26 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:26 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:26 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:25 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:25 DSL link up.

[INFO][System] 12-08-2021 16:57:25 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 16:57:24 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:24 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:24 DSL link up.
[EMERG][WAN] 12-08-2021 16:57:23 DSL link up.
[INFO][System] 12-08-2021 16:57:15 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 16:57:07 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 16:57:05 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 16:56:59 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:59 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:59 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:58 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:58 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:57 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:57 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:56 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:56 DSL link up.
[INFO][System] 12-08-2021 16:56:56 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 16:56:55 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:55 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:54 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:54 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:54 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:53 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:53 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:52 DSL link up.
[INFO][LAN] 12-08-2021 16:56:51 LAN sending RA to ff02::1
[EMERG][WAN] 12-08-2021 16:56:49 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:49 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:49 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:48 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:48 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:48 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:47 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:46 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:46 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:46 DSL link up.
[INFO][System] 12-08-2021 16:56:45 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 16:56:45 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:43 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:42 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:41 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:41 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:41 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:40 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:40 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:40 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:39 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:39 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:39 DSL link up.
[EMERG][WAN] 12-08-2021 16:56:38 DSL link up.
[INFO][System] 12-08-2021 16:56:35 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 16:56:35 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 16:56:31 PPPoE PADI has been sent from WAN

VDSL-DT

[INFO][WAN] 12-08-2021 16:56:31 PPPoE PADI has been sent from WAN

VDSL-DATA

[INFO][System] 12-08-2021 16:56:26 FSM---- Switch to Connect State.

[INFO][LAN] 12-08-2021 16:56:18 LAN sending RA to ff02::1

[INFO][WAN] 12-08-2021 16:56:18 PPPoE PADI has been sent from WAN

VDSL-DT

[INFO][LAN] 12-08-2021 16:56:18 LAN sending RA to ff02::1

[INFO][LAN] 12-08-2021 16:56:18 LAN sending RA to ff02::1

[INFO][WAN] 12-08-2021 16:56:18 PPPoE PADI has been sent from WAN

VDSL-DATA

[INFO][LAN] 12-08-2021 16:56:18 LAN sending RA to ff02::1

[INFO][WAN] 12-08-2021 16:56:18 Start WAN 10 IP Connection

[INFO][WAN] 12-08-2021 16:56:18 WAN VDSL-DT has been started, PHY

link up

[INFO][LAN] 12-08-2021 16:56:18 LAN sending RA to ff02::1

[INFO][LAN] 12-08-2021 16:56:18 LAN sending RA to ff02::1

[INFO][LAN] 12-08-2021 16:56:17 LAN sending RA to ff02::1

[INFO][WAN] 12-08-2021 16:56:17 Start WAN 8 IP Connection

[INFO][WAN] 12-08-2021 16:56:17 WAN VDSL-DATA has been started, PHY

link up

[INFO][WAN] 12-08-2021 16:56:17 Start WAN 10 DSL Connection

[INFO][LAN] 12-08-2021 16:56:16 LAN sending RA to ff02::1

[INFO][LAN] 12-08-2021 16:56:16 LAN sending RA to ff02::1

[INFO][LAN] 12-08-2021 16:56:16 LAN sending RA to ff02::1

[INFO][WAN] 12-08-2021 16:56:16 Starting VDSL interface OK.

[INFO][WAN] 12-08-2021 16:56:16 Start WAN 4 DSL Connection

[INFO][WAN] 12-08-2021 16:56:16 Start WAN 8 DSL Connection

[EMERG][WAN] 12-08-2021 16:56:16 DSL link up.

[INFO][System] 12-08-2021 16:56:15 FSM---- Switch to Connect State.

[INFO][System] 12-08-2021 16:56:04 FSM---- Switch to Connect State.

[INFO][System] 12-08-2021 16:55:55 FSM---- Switch to Connect State.

[INFO][System] 12-08-2021 16:55:45 FSM---- Switch to Connect State.

[INFO][System] 12-08-2021 16:55:36 FSM---- Switch to Connect State.

[INFO][System] 12-08-2021 16:55:26 FSM---- Switch to Connect State.

[INFO][System] 12-08-2021 16:55:15 FSM---- Switch to Connect State.

[INFO][LAN] 12-08-2021 16:55:10 LAN sending RA to ff02::1

[INFO][System] 12-08-2021 16:55:05 FSM---- Switch to Connect State.

[INFO][LAN] 12-08-2021 16:54:54 LAN sending RA to ff02::1

[INFO][System] 12-08-2021 16:54:54 FSM---- Switch to Connect State.

[INFO][System] 12-08-2021 16:54:45 FSM---- Switch to Connect State.

[INFO][LAN] 12-08-2021 16:54:38 LAN sending RA to ff02::1

[INFO][System] 12-08-2021 16:54:34 FSM---- Switch to Connect State.

[EMERG][WAN] 12-08-2021 16:54:29 DSL link down.

[INFO][System] 12-08-2021 16:54:24 FSM---- Switch to Connect State.

[INFO][WAN] 12-08-2021 16:54:22 WAN VDSL-DT has been stopped, please check your PHY link

[INFO][LAN] 12-08-2021 16:54:22 LAN sending RA to ff02::1

[INFO][LAN] 12-08-2021 16:54:22 LAN sending RA to ff02::1

[INFO][WAN] 12-08-2021 16:54:22 Stopping VDSL interface OK.

[INFO][WAN] 12-08-2021 16:54:22 Stop WAN 10 DSL Connection

[INFO][LAN] 12-08-2021 16:54:22 LAN sending RA to ff02::1

[INFO][LAN] 12-08-2021 16:54:22 LAN sending RA to ff02::1

[INFO][LAN] 12-08-2021 16:54:22 LAN sending RA to ff02::1

[INFO][System] 12-08-2021 16:54:22 Starting HTTP redirect OK.
[INFO][DNS] 12-08-2021 16:54:22 DNSMasq proxy server enable redirect
[INFO][System] 12-08-2021 16:54:21 Stopping NTP Client OK.
[INFO][VoIP] 12-08-2021 16:54:21 VoIP WAN down, no available
connection
[INFO][VoIP] 12-08-2021 16:54:21 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-08-2021 16:54:21 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-08-2021 16:54:21 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-08-2021 16:54:21 ===start stop voice wan
[INFO][DNS] 12-08-2021 16:54:21 Internet DNS deactivated.
[INFO][LAN] 12-08-2021 16:54:21 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 16:54:21 Starting NTP Client OK.
[INFO][System] 12-08-2021 16:54:20 Sync up with NTP Server failed.
[INFO][System] 12-08-2021 16:54:20 Stopping NTP Client OK.
[INFO][VoIP] 12-08-2021 16:54:20 VoIP WAN down, no available
connection
[INFO][VoIP] 12-08-2021 16:54:20 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-08-2021 16:54:20 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-08-2021 16:54:20 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-08-2021 16:54:20 ===start stop voice wan
[INFO][DNS] 12-08-2021 16:54:20 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 16:54:20 Internet DNS ready.
[INFO][DNS] 12-08-2021 16:54:20 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][WAN] 12-08-2021 16:54:20 WAN VDSL-DATA has been stopped,
please check your PHY link
[INFO][DNS] 12-08-2021 16:54:20 Internet DNS ready.
[INFO][DNS] 12-08-2021 16:54:20 Internet DNS deactivated.
[INFO][System] 12-08-2021 16:54:19 Starting NTP Client OK.
[INFO][System] 12-08-2021 16:54:19 Sync up with NTP Server failed.
[INFO][System] 12-08-2021 16:54:19 Stopping NTP Client OK.
[INFO][VoIP] 12-08-2021 16:54:19 VoIP WAN down, no available
connection
[INFO][VoIP] 12-08-2021 16:54:19 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-08-2021 16:54:19 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-08-2021 16:54:19 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-08-2021 16:54:19 ===start stop voice wan
[INFO][WAN] 12-08-2021 16:54:19 Stop WAN 8 DSL Connection
[INFO][DNS] 12-08-2021 16:54:18 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 16:54:18 Internet DNS ready.

```
[INFO][DNS] 12-08-2021 16:54:18 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 16:54:18 Internet DNS ready.
[INFO][DNS] 12-08-2021 16:54:18 Internet DNS deactivated.
[INFO][WAN] 12-08-2021 16:54:18 Stop WAN 10 IP Connection
[INFO][DNS] 12-08-2021 16:54:18 Internet DNS deactivated.
[INFO][LAN] 12-08-2021 16:54:18 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 16:54:18 IPTV WAN11 DeActivated!
[INFO][WAN] 12-08-2021 16:54:18 bud update WAN11 status to 0.
[INFO][WAN] 12-08-2021 16:54:18 Stop WAN 4 DSL Connection
[INFO][LAN] 12-08-2021 16:54:17 LAN sending RA to ff02::1
[EMERG][WAN] 12-08-2021 16:54:17 DSL link down.
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=54.239.24.200 PROTO=TCP SPT=56750 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=199.232.189.140 PROTO=TCP SPT=56689 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56571 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:54:17 TCP Scan SRC=35.186.224.25
DST=88.73.97.30 PROTO=TCP SPT=443 DPT=56576 MARK=0x8000001
[INFO][LAN] 12-08-2021 16:49:21 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 16:39:32 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 16:31:33 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 16:22:41 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 16:22:33 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
```


[NOTICE][LAN] 12-08-2021 16:22:33 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=45726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.15.145.116 PROTO=TCP SPT=57434 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.28.83 PROTO=TCP SPT=57431 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57427 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=51.158.29.12 PROTO=TCP SPT=57424 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=3.127.63.9 PROTO=TCP SPT=57430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:22:33 SRC=192.168.2.101
DST=3.127.63.9 PROTO=TCP SPT=57432 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 16:20:00 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 16:20:00 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 16:19:40 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 16:19:40 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 16:17:37 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 16:17:34 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 16:17:34 w10: AP-STA-DISCONNECTED

bc:a5:8b:27:2d:ac

[WARNING][Firewall] 12-08-2021 16:17:34 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44282 DPT=443 MARK=0x3 DROP

[NOTICE][LAN] 12-08-2021 16:12:08 ACSD: Timestamp(ms):1638979929

ACS-Trigger:TIMER Selected Channel:#1 (0x1001)

[EMERG][LAN] 12-08-2021 16:12:08 WIFI 2.4G Channel has been changed from channel 2 to 1.

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44282 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44282 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44282 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44282 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44282 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44282 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44282 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44282 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44272 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44268 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44270 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=2.22.241.90 PROTO=TCP SPT=44282 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:12:08 SRC=192.168.2.102

DST=92.122.22.147 PROTO=TCP SPT=41812 DPT=443 MARK=0x3 DROP

[NOTICE][LAN] 12-08-2021 16:11:01 wl0: AP-STA-CONNECTED

bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-08-2021 16:11:01 wl1: AP-STA-DISCONNECTED

bc:a5:8b:27:2d:ac

[WARNING][Firewall] 12-08-2021 16:11:01 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=56571 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:11:01 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=56571 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:11:01 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=56571 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:11:01 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=56571 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:11:01 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=56571 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:11:01 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=56571 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:11:01 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=56563 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:11:01 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=56571 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 16:11:01 TCP Scan SRC=35.186.224.25

DST=88.73.97.30 PROTO=TCP SPT=443 DPT=56567 MARK=0x8000001
[INFO][LAN] 12-08-2021 16:10:16 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 16:08:54 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 16:08:54 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 16:03:57 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 16:03:27 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 16:03:27 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 16:03:27 SRC=192.168.2.101
DST=54.239.37.45 PROTO=TCP SPT=57260 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 16:01:40 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 16:01:40 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 16:01:40 TCP Scan SRC=142.250.181.202
DST=88.73.97.30 PROTO=TCP SPT=443 DPT=41296 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 16:01:40 SRC=192.168.2.101
DST=209.54.180.144 PROTO=TCP SPT=57316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:01:40 SRC=192.168.2.101
DST=209.54.180.144 PROTO=TCP SPT=57317 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 16:01:40 SRC=192.168.2.102
DST=40.70.161.7 PROTO=TCP SPT=55926 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 15:59:28 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 15:59:28 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=42142 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=42140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=42138 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=42142 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=42140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=42138 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.101
DST=212.83.160.162 PROTO=TCP SPT=57206 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.101
DST=212.129.3.112 PROTO=TCP SPT=57203 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=42142 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=42140 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=42138 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.102
DST=142.250.185.110 PROTO=TCP SPT=42142 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:59:28 SRC=192.168.2.102

[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=172.217.18.100 PROTO=TCP SPT=56865 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=172.217.18.100 PROTO=TCP SPT=56865 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=172.217.18.100 PROTO=TCP SPT=56865 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=172.217.18.100 PROTO=TCP SPT=56865 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=172.217.18.100 PROTO=TCP SPT=56865 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=56828 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:24:00 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 15:24:00 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 15:18:00 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 15:12:18 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-08-2021 15:12:18 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:12:18 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:12:18 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:12:18 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:12:18 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56844 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:12:18 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56847 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:12:18 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56845 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:12:18 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=56842 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 15:11:42 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92

[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=99.84.156.40 PROTO=TCP SPT=56728 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 TCP Scan SRC=172.217.19.78
DST=88.73.97.30 PROTO=TCP SPT=443 DPT=56413 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=35.161.164.34 PROTO=TCP SPT=56684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.101
DST=50.19.123.12 PROTO=TCP SPT=56694 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 15:11:42 SRC=192.168.2.102
DST=80.156.82.167 PROTO=TCP SPT=40366 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 15:09:30 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 15:03:45 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 14:55:35 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 14:55:35 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 14:55:00 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 14:55:00 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 14:54:50 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 14:54:17 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 14:54:17 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 14:53:55 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 14:53:55 wl0: AP-STA-DISCONNECTED

bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 14:52:49 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 14:52:49 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 14:50:52 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 14:50:51 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 14:50:44 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 14:48:05 ACSD: Timestamp(ms):1638974886
ACS-Trigger:TIMER Selected Channel:#2 (0x1002)
[EMERG][LAN] 12-08-2021 14:48:05 WIFI 2.4G Channel has been changed
from channel 13 to 2.
[NOTICE][LAN] 12-08-2021 14:46:59 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 14:46:59 TCP Scan SRC=142.250.181.197
DST=88.73.97.30 PROTO=TCP SPT=443 DPT=56467 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.95.125.22 PROTO=TCP SPT=56483 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=176.32.111.2 PROTO=TCP SPT=56463 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP

[NOTICE][LAN] 12-08-2021 14:46:59 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=37.252.161.190 PROTO=TCP SPT=56489 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.19.145.179 PROTO=TCP SPT=56393 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=34.243.93.43 PROTO=TCP SPT=56525 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=56530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.92.190.69 PROTO=TCP SPT=56553 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56505 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=52.63.169.13 PROTO=TCP SPT=56507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 TCP Scan SRC=142.250.181.197
DST=88.73.97.30 PROTO=TCP SPT=443 DPT=56452 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=104.108.145.8 PROTO=TCP SPT=56034 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.63.145.65 PROTO=TCP SPT=55944 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=104.108.145.8 PROTO=TCP SPT=56036 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=104.108.145.8 PROTO=TCP SPT=56032 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=2.23.94.81 PROTO=TCP SPT=55943 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=2.23.94.58 PROTO=TCP SPT=56058 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=2.23.94.75 PROTO=TCP SPT=56042 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=2.23.94.75 PROTO=TCP SPT=56041 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=23.58.218.229 PROTO=TCP SPT=56013 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56330 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56331 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56332 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56330 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56331 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56332 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56330 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56331 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56332 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.29.132.245 PROTO=TCP SPT=56225 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56330 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56331 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56332 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56332 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56330 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=185.86.138.122 PROTO=TCP SPT=56331 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=72.251.249.14 PROTO=TCP SPT=56305 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=72.251.249.14 PROTO=TCP SPT=56304 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.101
DST=72.251.249.9 PROTO=TCP SPT=56349 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:46:59 SRC=192.168.2.102
DST=216.58.213.238 PROTO=TCP SPT=33266 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 14:41:26 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 14:34:17 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 14:26:57 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 14:24:02 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 14:24:02 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=74.125.160.234 PROTO=TCP SPT=56133 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=52.95.126.138 PROTO=TCP SPT=55816 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101

DST=216.52.2.39 PROTO=TCP SPT=55864 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=142.250.185.129 PROTO=TCP SPT=55875 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 14:24:02 SRC=192.168.2.101
DST=51.158.28.83 PROTO=TCP SPT=55602 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 14:23:23 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 14:14:17 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 14:10:37 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 14:07:01 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:59:55 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 13:58:09 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:58:09 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 13:58:09 SRC=192.168.2.100
DST=18.156.44.202 PROTO=TCP SPT=56346 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:58:09 SRC=192.168.2.100
DST=18.156.44.202 PROTO=TCP SPT=56346 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:58:09 SRC=192.168.2.100
DST=18.156.44.202 PROTO=TCP SPT=56346 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:58:09 SRC=192.168.2.100
DST=18.156.44.202 PROTO=TCP SPT=56346 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:58:09 SRC=192.168.2.100
DST=18.156.44.202 PROTO=TCP SPT=56346 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:58:09 TCP Scan SRC=34.98.74.57
DST=88.73.97.30 PROTO=TCP SPT=443 DPT=56334 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 13:58:09 SRC=192.168.2.100
DST=18.156.44.202 PROTO=TCP SPT=56346 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:58:09 SRC=192.168.2.102
DST=142.250.185.225 PROTO=TCP SPT=60436 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:58:09 SRC=192.168.2.102
DST=142.250.181.234 PROTO=TCP SPT=45566 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:58:09 SRC=192.168.2.102
DST=74.125.133.139 PROTO=TCP SPT=36138 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:58:09 SRC=192.168.2.102
DST=142.250.186.150 PROTO=TCP SPT=60076 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:58:09 SRC=192.168.2.102
DST=2.22.241.72 PROTO=TCP SPT=54154 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:58:09 SRC=192.168.2.102
DST=92.122.22.147 PROTO=TCP SPT=41456 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 13:53:24 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:53:24 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:53:15 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:53:15 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:53:04 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:53:04 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 13:50:47 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 13:50:25 wl0: AP-STA-CONNECTED

bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:50:25 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:50:25 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:50:25 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:49:42 ACS-D: Timestamp(ms):1638971383
ACS-Trigger:TIMER Selected Channel:#13 (0x100d)
[EMERG][LAN] 12-08-2021 13:49:42 WIFI 2.4G Channel has been changed
from channel 8 to 13.
[NOTICE][LAN] 12-08-2021 13:48:36 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:48:36 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:48:26 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:48:26 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 13:48:26 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=60426 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:48:26 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=59910 DPT=80 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 13:47:53 w10: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:47:53 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 13:47:52 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=60426 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:52 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=59910 DPT=80 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 13:47:19 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:47:19 w10: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=60426 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=59910 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=60426 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=59910 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=60426 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=59910 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=60426 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=59910 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=60426 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=59910 DPT=80 MARK=0x3 DROP

DST=216.58.213.227 PROTO=TCP SPT=59910 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=60426 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=60426 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=59910 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=60426 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=59910 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:47:19 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=59910 DPT=80 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 13:46:41 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:46:41 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:45:53 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:45:53 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 13:45:53 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:45:53 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:45:53 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:45:53 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:45:53 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:45:53 SRC=192.168.2.101
DST=3.124.112.54 PROTO=TCP SPT=55327 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:45:53 SRC=192.168.2.101
DST=3.124.112.54 PROTO=TCP SPT=55331 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:45:53 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 13:44:05 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:44:05 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 13:44:05 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:44:05 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 13:44:01 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 13:43:32 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:43:32 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 13:43:32 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:43:32 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:43:32 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 13:43:32 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:43:32 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:43:32 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:43:32 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:43:32 SRC=192.168.2.101
DST=34.218.111.255 PROTO=TCP SPT=55289 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 13:42:54 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:42:54 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:40:45 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:40:44 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 13:40:44 SRC=192.168.2.101
DST=3.67.131.16 PROTO=TCP SPT=55256 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:40:44 SRC=192.168.2.101
DST=3.67.131.16 PROTO=TCP SPT=55255 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:40:44 SRC=192.168.2.101
DST=3.67.131.16 PROTO=TCP SPT=55254 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:40:44 SRC=192.168.2.101
DST=3.67.131.16 PROTO=TCP SPT=55254 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 13:40:27 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:40:27 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:40:23 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 13:40:23 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 13:40:18 Successfully assign IP
[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time
[86400]
[INFO][LAN] 12-08-2021 13:40:18 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 13:40:18 server_id = c0a80201
[INFO][LAN] 12-08-2021 13:40:18 Received REQUEST from client ip
[0.0.0.0] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 13:40:18 Received a packet
[INFO][LAN] 12-08-2021 13:40:18 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 13:40:18 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 13:40:18 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 13:40:18 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 13:40:18 Received a packet
[INFO][LAN] 12-08-2021 13:40:18 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 13:40:18 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 13:40:18 Find a lease info, and use the

```
ip:6602a8c0
[INFO][LAN] 12-08-2021 13:40:18 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 13:40:18 Received a packet
[INFO][LAN] 12-08-2021 13:40:18 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 13:40:18 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 13:40:18 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 13:40:18 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 13:40:18 Received a packet
[INFO][LAN] 12-08-2021 13:40:18 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 13:40:18 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 13:40:18 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 13:40:18 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 13:40:17 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:40:16 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 13:40:16 Received a packet
[NOTICE][LAN] 12-08-2021 13:40:16 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 13:40:06 Successfully assign IP
[192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time
[86400]
[INFO][LAN] 12-08-2021 13:40:06 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 13:40:06 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 13:40:06 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 13:40:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:40:06 Received REQUEST from client ip
[0.0.0.0] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-08-2021 13:40:06 Received a packet
[NOTICE][LAN] 12-08-2021 13:40:06 wl0: AP-STA-CONNECTED
68:2f:67:8a:e3:07
[WARNING][Firewall] 12-08-2021 13:40:06 SRC=192.168.2.100
DST=17.57.146.24 PROTO=TCP SPT=55942 DPT=5223 MARK=0x1 DROP
[INFO][LAN] 12-08-2021 13:36:19 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:32:41 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:32:25 LAN sending RA to ff02::1
[INFO][VoIP] 12-08-2021 13:32:20 Switch to primary proxy server
arcor.de on line 0
[INFO][LAN] 12-08-2021 13:32:09 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 13:32:06 Sync up with NTP Server
successfully.
[INFO][System] 12-08-2021 13:32:05 Sync up with NTP Server
successfully.
[INFO][VoIP] 12-08-2021 13:31:57 Send data/single wan update to
VGW,wan id 10,ifName is ppp10,ipv4 address 88.73.97.30,ipv6
address ,default_wan_id 10,wan type 1
```

```
[INFO][VoIP] 12-08-2021 13:31:57 line 371 ,wan 10 start do data wan
up
[INFO][VoIP] 12-08-2021 13:31:57 wanipv6 = ,size = 0
[INFO][VoIP] 12-08-2021 13:31:57 Voice binding wan_id is
10,default_wan_id is 10
[INFO][VoIP] 12-08-2021 13:31:57 Voice binding wan_id is
10,default_wan_id is 10,is_ipv6 = 0
[INFO][VoIP] 12-08-2021 13:31:57 wan 10 service_type =
DATA,VOIP,MGNT,IPTV bud_voip_wan_id = 10
[INFO][VoIP] 12-08-2021 13:31:57 Interface wan_ip is 88.73.97.30,
wan_ip_v6 ,is_ipv6 0 wan up id 10
[INFO][LAN] 12-08-2021 13:31:57 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-08-2021 13:31:57 adapter index 18
[INFO][LAN] 12-08-2021 13:31:57 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-08-2021 13:31:57 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-08-2021 13:31:57 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO][LAN] 12-08-2021 13:31:57 adapter index 19
[INFO][LAN] 12-08-2021 13:31:57 br1 (our ip) = 192.168.3.1
[INFO][LAN] 12-08-2021 13:31:57 Attaching option timezone to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option t2 to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option t1 to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option lease to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option dns to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option router to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option subnet to list
[INFO][LAN] 12-08-2021 13:31:57 error on select
[INFO][LAN] 12-08-2021 13:31:57 udhcp server receive signal 12
[INFO][LAN] 12-08-2021 13:31:57 adapter index 18
[INFO][LAN] 12-08-2021 13:31:57 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-08-2021 13:31:57 Attaching option timezone to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option t2 to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option t1 to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option lease to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option dns to existing
member of list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option dns to existing
member of list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option dns to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option router to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option subnet to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option timezone to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option t2 to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option t1 to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option lease to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option dns to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option hostname to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option domain to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option router to list
[INFO][LAN] 12-08-2021 13:31:57 Attaching option subnet to list
[INFO][LAN] 12-08-2021 13:31:57 error on select
[INFO][LAN] 12-08-2021 13:31:57 udhcp server receive signal 12
```


[INFO][System] 12-08-2021 13:31:55 Starting MCPD OK.
[INFO][System] 12-08-2021 13:31:55 Stopping MCPD OK.
[INFO][UMTS] 12-08-2021 13:31:55 iPhone DNS Policy actived
[INFO][VoIP] 12-08-2021 13:31:55 276 start wan service Voice
binding wan_id is 10
[INFO][VoIP] 12-08-2021 13:31:55 Voice binding wan_id is 10
[INFO][System] 12-08-2021 13:31:55 Starting NTP Client OK.
[INFO][System] 12-08-2021 13:31:55 Sync up with NTP Server failed.
[INFO][System] 12-08-2021 13:31:55 Stopping NTP Client OK.
[INFO][Firewall] 12-08-2021 13:31:55 PortMapping Rules have been
flushed on WAN VDSL-DT.
[INFO][Firewall] 12-08-2021 13:31:55 DMZ Rules has been flushed on
WAN VDSL-DT.
[INFO][Firewall] 12-08-2021 13:31:54 Static NAT Rules have been
flushed on WAN VDSL-DT.
[INFO][System] 12-08-2021 13:31:54 Stopping HTTP redirect OK.
[INFO][DNS] 12-08-2021 13:31:54 DNSMasq proxy server disable
redirect
[INFO][DNS] 12-08-2021 13:31:54 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 13:31:54 Internet DNS ready.
[INFO][DNS] 12-08-2021 13:31:54 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 13:31:54 Internet DNS ready.
[INFO][DNS] 12-08-2021 13:31:54 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 13:31:54 Internet DNS ready.
[INFO][DNS] 12-08-2021 13:31:54 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 13:31:54 Internet DNS ready.
[WARNING][DNS] 12-08-2021 13:31:54 ignoring nameserver 127.0.0.1 -
local interface
[WARNING][DNS] 12-08-2021 13:31:54 ignoring nameserver ::1 - local
interface
[INFO][DNS] 12-08-2021 13:31:54 Starting DNSMasq proxy server OK.
[INFO][DNS] 12-08-2021 13:31:54 Stopping DNSMasq proxy OK.
[INFO][LAN] 12-08-2021 13:31:53 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:31:53 LAN sending RA to ff02::1
[INFO][DNS] 12-08-2021 13:31:53 DNSMasq proxy server disable
redirect
[INFO][UMTS] 12-08-2021 13:31:52 iPhone DNS Policy actived
[INFO][VoIP] 12-08-2021 13:31:52 Remove interface wan_id is 10,wan
type 2.
[INFO][VoIP] 12-08-2021 13:31:52 VoIP WAN down, Voice trying to run
in backup mode, try binding wan_id is 10
[INFO][VoIP] 12-08-2021 13:31:52 bud data ipv4 wan status 10,ipv6
wan status -1
[INFO][VoIP] 12-08-2021 13:31:52 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-08-2021 13:31:52 ===start stop voice wan
[INFO][VoIP] 12-08-2021 13:31:52 ignore useless wan down
[INFO][VoIP] 12-08-2021 13:31:52 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =

```
0,default_wan_id= 10
[INFO][VoIP] 12-08-2021 13:31:52 ===start stop voice wan
[INFO][System] 12-08-2021 13:31:52 Starting MCPD OK.
[INFO][System] 12-08-2021 13:31:52 Stopping MCPD OK.
[INFO][VoIP] 12-08-2021 13:31:51 ignore useless wan down
[INFO][VoIP] 12-08-2021 13:31:51 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-08-2021 13:31:51 ===start stop voice wan
[INFO][WAN] 12-08-2021 13:31:50 Stop WAN 8 IP Connection
[INFO][DNS] 12-08-2021 13:31:50 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 13:31:50 Internet DNS ready.
[INFO][DNS] 12-08-2021 13:31:50 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 13:31:50 Internet DNS ready.
[INFO][DNS] 12-08-2021 13:31:50 Internet DNS deactivated.
[INFO][System] 12-08-2021 13:31:49 FSM---- Switch to Connect State.
[WARNING][WAN] 12-08-2021 13:31:49 WAN default route add to ppp0
gateway 84.59.211.1.
[INFO][WAN] 12-08-2021 13:31:49 Data WAN11 Activated!
[INFO][WAN] 12-08-2021 13:31:49 bud update WAN11 status to 2.
[WARNING][WAN] 12-08-2021 13:31:48 WAN VDSL-DT is up, mode is PPPoE,
IP is 88.73.97.30.
[WARNING][WAN] 12-08-2021 13:31:48 WAN VDSL-DT is down.
[INFO][LAN] 12-08-2021 13:31:48 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 13:31:48 PPP CHAP MD5 authentication is
successful on WAN VDSL-DT
[INFO][LAN] 12-08-2021 13:31:48 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:31:48 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:31:48 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 13:31:48 PPPoE PADS has been received from
WAN VDSL-DT
[INFO][WAN] 12-08-2021 13:31:48 PPPoE PADR has been sent from WAN
VDSL-DT
[INFO][WAN] 12-08-2021 13:31:48 PPPoE PADO has been received from
WAN VDSL-DT, BRAS name is BLNCOS69101.
[INFO][WAN] 12-08-2021 13:31:48 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][WAN] 12-08-2021 13:31:48 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][System] 12-08-2021 13:31:41 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:31:32 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 13:31:27 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 13:31:22 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:31:13 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 13:31:11 LAN sending RA to ff02::1
[EMERG][WAN] 12-08-2021 13:31:04 DSL link up.
[EMERG][WAN] 12-08-2021 13:31:03 DSL link up.
[INFO][System] 12-08-2021 13:31:03 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 13:31:03 DSL link up.
[EMERG][WAN] 12-08-2021 13:31:02 DSL link up.
[EMERG][WAN] 12-08-2021 13:31:02 DSL link up.
[EMERG][WAN] 12-08-2021 13:31:02 DSL link up.
```

[EMERG] [WAN] 12-08-2021 13:31:01 DSL link up.
[EMERG] [WAN] 12-08-2021 13:31:01 DSL link up.
[EMERG] [WAN] 12-08-2021 13:31:01 DSL link up.
[EMERG] [WAN] 12-08-2021 13:31:01 DSL link up.
[EMERG] [WAN] 12-08-2021 13:31:01 DSL link up.
[EMERG] [WAN] 12-08-2021 13:31:00 DSL link up.
[EMERG] [WAN] 12-08-2021 13:31:00 DSL link up.
[EMERG] [WAN] 12-08-2021 13:31:00 DSL link up.
[EMERG] [WAN] 12-08-2021 13:31:00 DSL link up.
[EMERG] [WAN] 12-08-2021 13:31:00 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:59 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:59 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:58 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:58 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:57 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:57 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:56 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:56 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:56 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:55 DSL link up.
[INFO] [LAN] 12-08-2021 13:30:55 LAN sending RA to ff02::1
[EMERG] [WAN] 12-08-2021 13:30:55 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:54 DSL link up.
[INFO] [System] 12-08-2021 13:30:54 FSM---- Switch to Connect State.
[EMERG] [WAN] 12-08-2021 13:30:54 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:53 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:53 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:52 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:52 DSL link up.
[INFO] [WAN] 12-08-2021 13:30:52 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO] [WAN] 12-08-2021 13:30:52 PPPoE PADI has been sent from WAN
VDSL-DATA
[EMERG] [WAN] 12-08-2021 13:30:51 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:51 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:51 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:50 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:50 DSL link up.
[EMERG] [WAN] 12-08-2021 13:30:49 DSL link up.
[INFO] [System] 12-08-2021 13:30:44 FSM---- Switch to Connect State.
[INFO] [LAN] 12-08-2021 13:30:39 LAN sending RA to ff02::1
[INFO] [LAN] 12-08-2021 13:30:39 LAN sending RA to ff02::1
[INFO] [WAN] 12-08-2021 13:30:39 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO] [WAN] 12-08-2021 13:30:39 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO] [LAN] 12-08-2021 13:30:38 LAN sending RA to ff02::1
[INFO] [LAN] 12-08-2021 13:30:38 LAN sending RA to ff02::1
[INFO] [LAN] 12-08-2021 13:30:38 LAN sending RA to ff02::1
[INFO] [LAN] 12-08-2021 13:30:38 LAN sending RA to ff02::1
[INFO] [LAN] 12-08-2021 13:30:38 LAN sending RA to ff02::1
[INFO] [LAN] 12-08-2021 13:30:38 LAN sending RA to ff02::1
[INFO] [WAN] 12-08-2021 13:30:38 Start WAN 10 IP Connection

[INFO][WAN] 12-08-2021 13:30:38 WAN VDSL-DT has been started, PHY link up
[INFO][WAN] 12-08-2021 13:30:38 Start WAN 8 IP Connection
[INFO][WAN] 12-08-2021 13:30:38 WAN VDSL-DATA has been started, PHY link up
[INFO][LAN] 12-08-2021 13:30:38 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 13:30:37 Start WAN 10 DSL Connection
[INFO][LAN] 12-08-2021 13:30:37 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:30:37 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:30:37 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 13:30:37 Starting VDSL interface OK.
[INFO][WAN] 12-08-2021 13:30:37 Start WAN 8 DSL Connection
[INFO][WAN] 12-08-2021 13:30:36 Start WAN 4 DSL Connection
[EMERG][WAN] 12-08-2021 13:30:36 DSL link up.
[INFO][System] 12-08-2021 13:30:33 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:30:23 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:30:14 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:30:03 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:29:52 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:29:43 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:29:33 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:29:24 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:29:14 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 13:29:06 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 13:29:04 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:28:54 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 13:28:50 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 13:28:43 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 13:28:33 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 13:28:32 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 13:28:25 DSL link down.
[INFO][System] 12-08-2021 13:28:22 FSM---- Switch to Connect State.
[INFO][WAN] 12-08-2021 13:28:17 WAN VDSL-DT has been stopped, please check your PHY link
[INFO][LAN] 12-08-2021 13:28:17 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:28:17 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 13:28:17 Stopping VDSL interface OK.
[INFO][WAN] 12-08-2021 13:28:17 Stop WAN 10 DSL Connection
[INFO][LAN] 12-08-2021 13:28:17 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:28:17 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 13:28:16 WAN VDSL-DATA has been stopped, please check your PHY link
[INFO][WAN] 12-08-2021 13:28:16 Stop WAN 8 DSL Connection
[INFO][System] 12-08-2021 13:28:16 Starting HTTP redirect OK.
[INFO][LAN] 12-08-2021 13:28:16 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:28:16 LAN sending RA to ff02::1
[INFO][DNS] 12-08-2021 13:28:16 DNSMasq proxy server enable redirect
[INFO][WAN] 12-08-2021 13:28:16 PPPoE PADI has been sent from WAN VDSL-DATA
[INFO][WAN] 12-08-2021 13:28:16 PPPoE PADI has been sent from WAN VDSL-DT
[INFO][VoIP] 12-08-2021 13:28:16 VoIP WAN down, no available connection
[INFO][VoIP] 12-08-2021 13:28:16 Remove interface wan_id is 10,wan

type 1.
[INFO][VoIP] 12-08-2021 13:28:16 bud data ipv4 wan status -1,ipv6 wan status -1
[INFO][VoIP] 12-08-2021 13:28:16 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 = 0,default_wan_id= 10
[INFO][VoIP] 12-08-2021 13:28:16 ===start stop voice wan
[INFO][DNS] 12-08-2021 13:28:15 Internet DNS deactivated.
[INFO][System] 12-08-2021 13:28:15 Starting HTTP redirect OK.
[INFO][DNS] 12-08-2021 13:28:15 DNSMasq proxy server enable redirect
[INFO][WAN] 12-08-2021 13:28:15 Stop WAN 4 DSL Connection
[INFO][LAN] 12-08-2021 13:28:15 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:28:15 LAN sending RA to ff02::1
[INFO][VoIP] 12-08-2021 13:28:15 ignore useless wan down
[INFO][VoIP] 12-08-2021 13:28:15 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 = 0,default_wan_id= 10
[INFO][VoIP] 12-08-2021 13:28:15 ===start stop voice wan
[INFO][VoIP] 12-08-2021 13:28:15 VoIP WAN down, no available connection
[INFO][VoIP] 12-08-2021 13:28:15 Remove interface wan_id is 10,wan type 1.
[INFO][VoIP] 12-08-2021 13:28:15 bud data ipv4 wan status -1,ipv6 wan status -1
[INFO][VoIP] 12-08-2021 13:28:15 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 = 1,default_wan_id= 10
[INFO][VoIP] 12-08-2021 13:28:15 ===start stop voice wan
[INFO][VoIP] 12-08-2021 13:28:14 ignore useless wan down
[INFO][VoIP] 12-08-2021 13:28:14 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 = 1,default_wan_id= 10
[INFO][VoIP] 12-08-2021 13:28:14 ===start stop voice wan
[INFO][DNS] 12-08-2021 13:28:14 Internet DNS deactivated.
[INFO][WAN] 12-08-2021 13:28:14 Stop WAN 10 IP Connection
[INFO][WAN] 12-08-2021 13:28:14 Stop WAN 8 IP Connection
[INFO][LAN] 12-08-2021 13:28:14 LAN sending RA to ff02::1
[EMERG][WAN] 12-08-2021 13:28:14 DSL link down.
[INFO][System] 12-08-2021 13:28:12 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 13:28:09 DSL link up.
[EMERG][WAN] 12-08-2021 13:28:05 DSL link up.
[EMERG][WAN] 12-08-2021 13:28:04 DSL link up.
[EMERG][WAN] 12-08-2021 13:28:03 DSL link up.
[EMERG][WAN] 12-08-2021 13:28:02 DSL link up.
[INFO][System] 12-08-2021 13:28:02 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 13:28:00 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:59 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:58 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:57 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:56 DSL link up.
[INFO][LAN] 12-08-2021 13:27:55 LAN sending RA to ff02::1
[EMERG][WAN] 12-08-2021 13:27:55 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:53 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:52 DSL link up.

[EMERG][WAN] 12-08-2021 13:27:51 DSL link up.
[INFO][System] 12-08-2021 13:27:51 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 13:27:50 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:48 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:47 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:46 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:44 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:43 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:42 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:41 DSL link up.
[INFO][System] 12-08-2021 13:27:41 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 13:27:39 DSL link up.
[INFO][LAN] 12-08-2021 13:27:39 LAN sending RA to ff02::1
[EMERG][WAN] 12-08-2021 13:27:38 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:37 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:35 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:34 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:32 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:31 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:30 DSL link up.
[INFO][System] 12-08-2021 13:27:29 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 13:27:28 DSL link up.
[EMERG][WAN] 12-08-2021 13:27:27 DSL link up.
[INFO][LAN] 12-08-2021 13:27:23 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 13:27:20 FSM---- Switch to Connect State.
[INFO][WAN] 12-08-2021 13:27:20 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-08-2021 13:27:20 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-08-2021 13:27:10 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 13:27:07 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 13:27:07 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-08-2021 13:27:07 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][LAN] 12-08-2021 13:27:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:27:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:27:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:27:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:27:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:27:06 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 13:27:06 Start WAN 10 IP Connection
[INFO][WAN] 12-08-2021 13:27:06 Start WAN 8 IP Connection
[INFO][WAN] 12-08-2021 13:27:06 WAN VDSL-DATA has been started, PHY
link up
[INFO][WAN] 12-08-2021 13:27:06 WAN VDSL-DT has been started, PHY
link up
[INFO][LAN] 12-08-2021 13:27:05 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:27:05 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 13:27:05 Start WAN 10 DSL Connection
[INFO][LAN] 12-08-2021 13:27:05 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 13:27:05 Starting VDSL interface OK.
[INFO][WAN] 12-08-2021 13:27:05 Start WAN 4 DSL Connection
[INFO][WAN] 12-08-2021 13:27:04 Start WAN 8 DSL Connection

```
[EMERG][WAN] 12-08-2021 13:27:04 DSL link up.
[INFO][System] 12-08-2021 13:27:01 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:26:52 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:26:41 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:26:31 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:26:20 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:26:09 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:25:58 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:25:49 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:25:38 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 13:25:31 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 13:25:29 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:25:20 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:25:10 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:24:59 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:24:50 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:24:40 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:24:30 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:24:19 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:24:10 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:23:59 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:23:50 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:23:39 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:23:30 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:23:21 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:23:12 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:23:01 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:22:50 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:22:41 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:22:31 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:22:22 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 13:22:14 DSL link down.
[INFO][System] 12-08-2021 13:22:13 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:22:03 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 13:22:02 DSL link down.
[INFO][System] 12-08-2021 13:21:54 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:21:44 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:21:34 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:21:25 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:21:14 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:21:05 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:20:54 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:20:43 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:20:33 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:20:24 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:20:14 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:20:04 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:19:55 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:19:44 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:19:35 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:19:27 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:19:17 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 13:19:06 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 13:19:05 LAN sending RA to ff02::1
```

[EMERG][WAN] 12-08-2021 13:19:04 DSL link down.
[INFO][System] 12-08-2021 13:18:57 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 13:18:49 LAN sending RA to ff02::1
[EMERG][WAN] 12-08-2021 13:18:47 DSL link down.
[INFO][System] 12-08-2021 13:18:47 FSM---- Switch to Connect State.
[NOTICE][LAN] 12-08-2021 13:18:46 wl0: AP-STA-DISCONNECTED
68:2f:67:8a:e3:07
[INFO][System] 12-08-2021 13:18:37 FSM---- Switch to Connect State.
[NOTICE][LAN] 12-08-2021 13:18:37 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 13:18:33 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 13:18:27 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 13:18:24 DSL link down.
[INFO][System] 12-08-2021 13:18:17 FSM---- Switch to Connect State.
[INFO][WAN] 12-08-2021 13:18:17 WAN VDSL-DT has been stopped, please
check your PHY link
[INFO][LAN] 12-08-2021 13:18:17 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:18:17 LAN sending RA to ff02::1
[WARNING][Firewall] 12-08-2021 13:18:17 SRC=192.168.2.101
DST=35.162.31.154 PROTO=TCP SPT=54818 DPT=443 MARK=0x3 DROP
[INFO][WAN] 12-08-2021 13:18:17 Stopping VDSL interface OK.
[INFO][WAN] 12-08-2021 13:18:17 Stop WAN 10 DSL Connection
[INFO][LAN] 12-08-2021 13:18:17 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:18:17 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 13:18:17 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 13:18:17 Starting HTTP redirect OK.
[INFO][DNS] 12-08-2021 13:18:17 DNSMasq proxy server enable redirect
[INFO][System] 12-08-2021 13:18:16 Stopping NTP Client OK.
[INFO][VoIP] 12-08-2021 13:18:16 VoIP WAN down, no available
connection
[INFO][VoIP] 12-08-2021 13:18:16 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-08-2021 13:18:16 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-08-2021 13:18:16 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-08-2021 13:18:16 ===start stop voice wan
[INFO][DNS] 12-08-2021 13:18:16 Internet DNS deactivated.
[INFO][LAN] 12-08-2021 13:18:16 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 13:18:15 Starting NTP Client OK.
[INFO][System] 12-08-2021 13:18:15 Sync up with NTP Server failed.
[INFO][System] 12-08-2021 13:18:15 Stopping NTP Client OK.
[INFO][VoIP] 12-08-2021 13:18:15 VoIP WAN down, no available
connection
[INFO][VoIP] 12-08-2021 13:18:15 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-08-2021 13:18:15 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-08-2021 13:18:15 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-08-2021 13:18:15 ===start stop voice wan
[INFO][WAN] 12-08-2021 13:18:15 WAN VDSL-DATA has been stopped,

please check your PHY link

[INFO][DNS] 12-08-2021 13:18:15 Internet DNS Servers 176.95.16.250, 176.95.16.251.

[INFO][DNS] 12-08-2021 13:18:14 Internet DNS ready.

[INFO][DNS] 12-08-2021 13:18:14 Internet DNS Servers 176.95.16.250, 176.95.16.251.

[INFO][DNS] 12-08-2021 13:18:14 Internet DNS ready.

[INFO][DNS] 12-08-2021 13:18:14 Internet DNS deactivated.

[INFO][System] 12-08-2021 13:18:14 Starting NTP Client OK.

[INFO][System] 12-08-2021 13:18:14 Sync up with NTP Server failed.

[INFO][WAN] 12-08-2021 13:18:14 Stop WAN 8 DSL Connection

[INFO][System] 12-08-2021 13:18:14 Stopping NTP Client OK.

[INFO][LAN] 12-08-2021 13:18:14 LAN sending RA to ff02::1

[INFO][VoIP] 12-08-2021 13:18:14 VoIP WAN down, no available connection

[INFO][VoIP] 12-08-2021 13:18:14 Remove interface wan_id is 10,wan type 1.

[INFO][VoIP] 12-08-2021 13:18:14 bud data ipv4 wan status -1,ipv6 wan status -1

[INFO][VoIP] 12-08-2021 13:18:14 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 = 1,default_wan_id= 10

[INFO][VoIP] 12-08-2021 13:18:14 ===start stop voice wan

[INFO][DNS] 12-08-2021 13:18:13 Internet DNS Servers 176.95.16.250, 176.95.16.251.

[INFO][DNS] 12-08-2021 13:18:13 Internet DNS ready.

[INFO][DNS] 12-08-2021 13:18:13 Internet DNS Servers 176.95.16.250, 176.95.16.251.

[INFO][DNS] 12-08-2021 13:18:13 Internet DNS ready.

[INFO][DNS] 12-08-2021 13:18:13 Internet DNS deactivated.

[INFO][WAN] 12-08-2021 13:18:13 Stop WAN 4 DSL Connection

[INFO][DNS] 12-08-2021 13:18:13 Internet DNS deactivated.

[INFO][WAN] 12-08-2021 13:18:13 Stop WAN 10 IP Connection

[INFO][WAN] 12-08-2021 13:18:13 IPTV WAN11 DeActivated!

[INFO][WAN] 12-08-2021 13:18:13 bud update WAN11 status to 0.

[INFO][LAN] 12-08-2021 13:18:13 LAN sending RA to ff02::1

[EMERG][WAN] 12-08-2021 13:18:13 DSL link down.

[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101

DST=23.111.9.57 PROTO=TCP SPT=54814 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101

DST=54.218.98.189 PROTO=TCP SPT=54792 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101

DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101

DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101

DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101

DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101

DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101

DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.102

DST=185.60.217.20 PROTO=TCP SPT=47198 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=47200 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.102
DST=185.60.217.20 PROTO=TCP SPT=47202 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=152.228.211.201 PROTO=TCP SPT=54781 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=68.183.60.108 PROTO=TCP SPT=54738 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=89.187.169.47 PROTO=TCP SPT=54762 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=23.111.9.57 PROTO=TCP SPT=54748 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=23.111.9.57 PROTO=TCP SPT=54705 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=68.183.60.108 PROTO=TCP SPT=54693 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=54.216.252.255 PROTO=TCP SPT=54717 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.101
DST=54.204.238.15 PROTO=TCP SPT=54702 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56276 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56276 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56276 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56276 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56276 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56276 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 13:18:13 TCP Scan SRC=35.186.224.25
DST=188.96.64.199 PROTO=TCP SPT=443 DPT=56274 MARK=0x8000001
[INFO][LAN] 12-08-2021 13:11:29 LAN sending RA to ff02::1

[INFO][LAN] 12-08-2021 13:03:25 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 12:59:39 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 12:59:39 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=54608 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=68.183.60.108 PROTO=TCP SPT=54561 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.216.252.255 PROTO=TCP SPT=54569 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.216.252.255 PROTO=TCP SPT=54570 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=143.244.208.14 PROTO=TCP SPT=54580 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.108.144.209 PROTO=TCP SPT=54596 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.108.144.209 PROTO=TCP SPT=54595 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.108.144.209 PROTO=TCP SPT=54596 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.108.144.209 PROTO=TCP SPT=54595 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.121.76.81 PROTO=TCP SPT=54597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.108.144.209 PROTO=TCP SPT=54596 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101

DST=104.108.144.209 PROTO=TCP SPT=54596 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.108.144.209 PROTO=TCP SPT=54595 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.121.76.81 PROTO=TCP SPT=54597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.108.144.209 PROTO=TCP SPT=54596 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.108.144.209 PROTO=TCP SPT=54595 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.121.76.81 PROTO=TCP SPT=54597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.121.76.81 PROTO=TCP SPT=54597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.108.144.209 PROTO=TCP SPT=54596 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=104.108.144.209 PROTO=TCP SPT=54595 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=143.244.208.14 PROTO=TCP SPT=54598 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=185.60.216.52 PROTO=TCP SPT=54547 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=185.60.216.52 PROTO=TCP SPT=54547 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=68.183.60.108 PROTO=TCP SPT=54511 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.216.252.255 PROTO=TCP SPT=54521 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.216.252.255 PROTO=TCP SPT=54524 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.216.252.255 PROTO=TCP SPT=54523 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.204.238.15 PROTO=TCP SPT=54515 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.102
DST=185.60.217.54 PROTO=TCP SPT=35470 DPT=5222 MARK=0x1 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=23.111.9.57 PROTO=TCP SPT=54527 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=68.183.60.108 PROTO=TCP SPT=54097 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.145.178.105 PROTO=TCP SPT=54503 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.216.252.255 PROTO=TCP SPT=54457 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.216.252.255 PROTO=TCP SPT=54466 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=54.204.238.15 PROTO=TCP SPT=54109 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=51.77.109.136 PROTO=TCP SPT=54496 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=51.77.109.136 PROTO=TCP SPT=54496 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=51.77.109.136 PROTO=TCP SPT=54496 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101

DST=142.250.186.40 PROTO=TCP SPT=54289 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=142.250.186.99 PROTO=TCP SPT=54305 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=142.250.181.227 PROTO=TCP SPT=54306 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=152.228.211.201 PROTO=TCP SPT=54448 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=18.64.79.30 PROTO=TCP SPT=54349 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=142.250.74.194 PROTO=TCP SPT=54294 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=142.250.185.163 PROTO=TCP SPT=54301 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=142.250.184.206 PROTO=TCP SPT=54302 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=52.222.138.129 PROTO=TCP SPT=54343 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=65.9.83.60 PROTO=TCP SPT=54344 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=142.250.186.40 PROTO=TCP SPT=54289 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=18.64.79.30 PROTO=TCP SPT=54349 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=142.250.186.99 PROTO=TCP SPT=54305 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=142.250.181.227 PROTO=TCP SPT=54306 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=152.228.211.201 PROTO=TCP SPT=54448 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=142.250.74.194 PROTO=TCP SPT=54294 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=142.250.185.163 PROTO=TCP SPT=54301 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=18.64.79.30 PROTO=TCP SPT=54349 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=142.250.184.206 PROTO=TCP SPT=54302 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:59:39 SRC=192.168.2.101
DST=52.222.138.129 PROTO=TCP SPT=54343 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 12:56:25 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 12:46:27 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 12:41:07 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 12:36:35 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 12:33:16 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 12:33:16 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 12:33:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56102 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:33:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56102 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:33:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56102 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:33:16 SRC=192.168.2.100

DST=35.186.224.47 PROTO=TCP SPT=56102 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:33:16 TCP Scan SRC=13.107.43.14
DST=188.96.64.199 PROTO=TCP SPT=443 DPT=56260 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 12:33:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56102 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:33:16 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56102 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:33:16 SRC=192.168.2.100
DST=2.16.192.242 PROTO=TCP SPT=38726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:33:16 SRC=192.168.2.100
DST=2.16.192.242 PROTO=TCP SPT=38726 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:33:16 SRC=192.168.2.100
DST=2.16.192.242 PROTO=TCP SPT=38680 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 12:29:44 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 12:26:25 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 12:25:09 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=216.58.213.227 PROTO=TCP SPT=58922 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=172.217.16.78 PROTO=TCP SPT=59438 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=216.58.213.227 PROTO=TCP SPT=58922 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=172.217.16.78 PROTO=TCP SPT=59438 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=216.58.213.227 PROTO=TCP SPT=58922 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=172.217.16.78 PROTO=TCP SPT=59438 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=216.58.213.227 PROTO=TCP SPT=58922 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=172.217.16.78 PROTO=TCP SPT=59438 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=216.58.213.227 PROTO=TCP SPT=58922 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=172.217.16.78 PROTO=TCP SPT=59438 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=216.58.213.227 PROTO=TCP SPT=58922 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=172.217.16.78 PROTO=TCP SPT=59438 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=216.58.213.227 PROTO=TCP SPT=58922 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.100
DST=172.217.16.78 PROTO=TCP SPT=59438 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=58922 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:25:09 SRC=192.168.2.102
DST=216.58.213.227 PROTO=TCP SPT=58922 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 12:23:02 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 12:13:45 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-08-2021 12:13:45 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 12:13:45 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 12:13:45 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 12:13:45 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 12:13:45 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-08-2021 12:13:45 Received a packet
[NOTICE][LAN] 12-08-2021 12:13:45 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-08-2021 12:13:45 SRC=192.168.2.100
DST=54.80.48.227 PROTO=TCP SPT=56216 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:13:45 SRC=192.168.2.100
DST=54.80.48.227 PROTO=TCP SPT=56218 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:13:45 SRC=192.168.2.100
DST=54.80.48.227 PROTO=TCP SPT=56217 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:13:45 SRC=192.168.2.100
DST=54.80.48.227 PROTO=TCP SPT=56215 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:13:45 SRC=192.168.2.100
DST=52.48.69.36 PROTO=TCP SPT=56221 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:13:45 SRC=192.168.2.100
DST=52.50.27.147 PROTO=TCP SPT=56211 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:13:45 SRC=192.168.2.100
DST=52.50.27.147 PROTO=TCP SPT=56212 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:13:45 SRC=192.168.2.100
DST=3.233.145.243 PROTO=TCP SPT=56165 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:13:45 SRC=192.168.2.100
DST=54.70.9.247 PROTO=TCP SPT=56158 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 12:11:39 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-08-2021 12:11:39 SRC=192.168.2.105
DST=185.33.221.53 PROTO=TCP SPT=49272 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 12:09:32 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 12:07:09 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 12:07:09 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 12:07:09 SRC=192.168.2.105
DST=172.217.16.70 PROTO=TCP SPT=65368 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:07:09 SRC=192.168.2.105
DST=172.217.16.70 PROTO=TCP SPT=65368 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:07:09 SRC=192.168.2.105
DST=172.217.16.70 PROTO=TCP SPT=65368 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:07:09 SRC=192.168.2.105
DST=172.217.16.70 PROTO=TCP SPT=65368 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 12:07:09 SRC=192.168.2.101
DST=35.162.31.154 PROTO=TCP SPT=53796 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:07:09 SRC=192.168.2.101
DST=172.67.72.95 PROTO=TCP SPT=53803 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:07:09 SRC=192.168.2.101
DST=35.186.224.25 PROTO=TCP SPT=53795 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:07:09 SRC=192.168.2.101
DST=172.67.72.95 PROTO=TCP SPT=53803 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:07:09 SRC=192.168.2.101
DST=35.186.224.25 PROTO=TCP SPT=53795 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:07:09 SRC=192.168.2.101
DST=172.67.72.95 PROTO=TCP SPT=53803 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:07:09 SRC=192.168.2.101
DST=35.186.224.25 PROTO=TCP SPT=53795 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:07:09 SRC=192.168.2.101
DST=35.162.31.154 PROTO=TCP SPT=53796 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:07:09 TCP Scan SRC=142.250.110.188
DST=188.96.64.199 PROTO=TCP SPT=5228 DPT=53793 MARK=0x8000001
[NOTICE][LAN] 12-08-2021 12:04:12 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 12:04:12 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 12:04:12 SRC=192.168.2.105
DST=142.250.186.67 PROTO=TCP SPT=65011 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:04:12 SRC=192.168.2.105
DST=142.250.186.67 PROTO=TCP SPT=65011 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:04:12 SRC=192.168.2.105
DST=142.250.186.67 PROTO=TCP SPT=65011 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:04:12 SRC=192.168.2.105
DST=142.250.186.67 PROTO=TCP SPT=65011 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 12:02:17 Transmit reply to
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 12:02:17 Received information request from
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 12:02:16 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 12:02:13 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 12:02:13 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 12:02:13 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 12:02:13 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 12:02:13 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 12:02:13 Received a packet
[NOTICE][LAN] 12-08-2021 12:02:12 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=2.23.176.165 PROTO=TCP SPT=56088 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=142.250.181.195 PROTO=TCP SPT=56031 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=2.23.176.165 PROTO=TCP SPT=56088 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=2.23.176.165 PROTO=TCP SPT=56088 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56091 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=2.23.94.82 PROTO=TCP SPT=56072 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56091 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=56078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=2.23.176.165 PROTO=TCP SPT=56088 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56091 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56079 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56091 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=2.23.176.165 PROTO=TCP SPT=56088 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56091 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56091 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=2.23.176.165 PROTO=TCP SPT=56088 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56091 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56091 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=2.23.176.165 PROTO=TCP SPT=56088 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 12:02:12 TCP Scan SRC=2.23.176.165
DST=188.96.64.199 PROTO=TCP SPT=443 DPT=56088 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 12:02:12 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=56078 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 11:56:40 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 11:48:20 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 11:44:29 Successfully assign IP
[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time
[86400]
[INFO][LAN] 12-08-2021 11:44:29 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 11:44:29 server_id = c0a80201
[INFO][LAN] 12-08-2021 11:44:29 Received REQUEST from client ip
[0.0.0.0] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:44:29 Received a packet
[INFO][LAN] 12-08-2021 11:44:29 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 11:44:29 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:44:29 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 11:44:29 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:44:29 Received a packet
[INFO][LAN] 12-08-2021 11:44:29 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 11:44:29 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:44:29 Find a lease info, and use the

ip:6602a8c0
[INFO][LAN] 12-08-2021 11:44:29 Received DISCOVER from client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:44:29 Received a packet
[INFO][LAN] 12-08-2021 11:44:29 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 11:44:29 Send OFFER of ip [192.168.2.102] to client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:44:29 Find a lease info, and use the ip:6602a8c0
[INFO][LAN] 12-08-2021 11:44:29 Received DISCOVER from client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:44:29 Received a packet
[INFO][LAN] 12-08-2021 11:44:29 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 11:44:28 Send OFFER of ip [192.168.2.102] to client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:44:28 Find a lease info, and use the ip:6602a8c0
[INFO][LAN] 12-08-2021 11:44:28 No valid arp replies for this address
[INFO][LAN] 12-08-2021 11:44:27 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 11:44:26 Received DISCOVER from client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:44:26 Received a packet
[NOTICE][LAN] 12-08-2021 11:44:26 wl0: AP-STA-CONNECTED bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 11:40:41 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 11:33:02 wl1: AP-STA-DISCONNECTED 0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=2.23.94.82 PROTO=TCP SPT=56072 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=56079 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=23.63.148.30 PROTO=TCP SPT=56078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=2.23.94.82 PROTO=TCP SPT=56072 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=56079 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=23.63.148.30 PROTO=TCP SPT=56078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=2.23.94.82 PROTO=TCP SPT=56072 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=56079 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=23.63.148.30 PROTO=TCP SPT=56078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=2.23.94.82 PROTO=TCP SPT=56072 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=56079 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=23.63.148.30 PROTO=TCP SPT=56078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=2.23.94.82 PROTO=TCP SPT=56072 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100 DST=35.186.224.47 PROTO=TCP SPT=56065 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=56079 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100
DST=2.23.94.82 PROTO=TCP SPT=56072 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=56078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100
DST=2.23.94.82 PROTO=TCP SPT=56072 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 TCP Scan SRC=2.23.94.82
DST=188.96.64.199 PROTO=TCP SPT=443 DPT=56072 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100
DST=104.107.217.63 PROTO=TCP SPT=56057 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100
DST=2.19.244.28 PROTO=TCP SPT=56056 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:33:02 SRC=192.168.2.100
DST=104.107.217.63 PROTO=TCP SPT=56054 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 11:32:30 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 11:26:46 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 11:26:30 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=64749 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP


```
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:26:30 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 11:24:01 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 11:24:01 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:24:01 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:24:01 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:24:01 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:24:01 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:24:01 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:24:01 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:24:01 SRC=192.168.2.105
DST=185.33.221.11 PROTO=TCP SPT=64700 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:24:01 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=64688 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 11:23:10 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 11:23:10 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 11:22:57 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 11:22:56 Successfully assign IP
[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time
[86400]
[INFO][LAN] 12-08-2021 11:22:56 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 11:22:56 server_id = c0a80201
[INFO][LAN] 12-08-2021 11:22:56 Received REQUEST from client ip
[0.0.0.0] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:22:56 Received a packet
[INFO][LAN] 12-08-2021 11:22:55 Successfully assign IP
[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time
[86400]
[INFO][LAN] 12-08-2021 11:22:55 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 11:22:55 server_id = c0a80201
[INFO][LAN] 12-08-2021 11:22:55 Received REQUEST from client ip
[0.0.0.0] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:22:55 Received a packet
[INFO][LAN] 12-08-2021 11:22:54 Successfully assign IP
[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time
[86400]
[INFO][LAN] 12-08-2021 11:22:54 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 11:22:54 server_id = c0a80201
[INFO][LAN] 12-08-2021 11:22:54 Received REQUEST from client ip
[0.0.0.0] mac [bc:a5:8b:27:2d:ac]
```

[INFO][LAN] 12-08-2021 11:22:54 Received a packet
[INFO][LAN] 12-08-2021 11:22:54 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 11:22:54 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:22:54 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 11:22:54 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:22:54 Received a packet
[INFO][LAN] 12-08-2021 11:22:54 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 11:22:54 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:22:54 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-08-2021 11:22:54 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 11:22:54 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 11:22:52 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-08-2021 11:22:52 Received a packet
[NOTICE][LAN] 12-08-2021 11:22:48 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 11:22:47 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 11:22:21 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 11:22:21 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 11:22:20 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 11:22:20 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 11:22:20 SRC=192.168.2.105
DST=3.125.186.73 PROTO=TCP SPT=64659 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:22:20 SRC=192.168.2.105
DST=3.125.186.73 PROTO=TCP SPT=64654 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:22:20 SRC=192.168.2.105
DST=3.125.186.73 PROTO=TCP SPT=64658 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:22:20 SRC=192.168.2.105
DST=3.125.186.73 PROTO=TCP SPT=64656 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:22:20 SRC=192.168.2.105
DST=3.125.186.73 PROTO=TCP SPT=64657 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:22:20 SRC=192.168.2.105
DST=18.203.197.143 PROTO=TCP SPT=64647 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:22:20 SRC=192.168.2.105
DST=18.203.197.143 PROTO=TCP SPT=64641 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:22:20 SRC=192.168.2.105
DST=54.72.239.169 PROTO=TCP SPT=64663 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:22:20 SRC=192.168.2.102
DST=185.151.204.13 PROTO=TCP SPT=42240 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 11:17:55 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 11:17:55 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac

[WARNING][Firewall] 12-08-2021 11:17:55 SRC=192.168.2.102
DST=185.151.204.13 PROTO=TCP SPT=42240 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:17:55 SRC=192.168.2.102
DST=185.151.204.13 PROTO=TCP SPT=42240 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:17:55 SRC=192.168.2.102
DST=185.151.204.13 PROTO=TCP SPT=42240 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 11:17:45 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 11:16:01 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 11:16:01 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=53714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=53714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=53714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=53714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=53714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=53714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=5.135.141.80 PROTO=TCP SPT=53706 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=53714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=5.135.141.80 PROTO=TCP SPT=53706 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=72.251.241.196 PROTO=TCP SPT=53707 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.104 PROTO=TCP SPT=53647 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53696 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=2.23.94.49 PROTO=TCP SPT=53631 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=5.135.141.80 PROTO=TCP SPT=53706 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=72.251.241.196 PROTO=TCP SPT=53707 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.104 PROTO=TCP SPT=53647 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53696 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=2.23.94.49 PROTO=TCP SPT=53631 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101

DST=185.86.139.114 PROTO=TCP SPT=53696 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=2.23.94.49 PROTO=TCP SPT=53631 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=53714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=5.135.141.80 PROTO=TCP SPT=53706 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.104 PROTO=TCP SPT=53647 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53696 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=72.251.241.196 PROTO=TCP SPT=53707 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=2.23.94.49 PROTO=TCP SPT=53631 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=53714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=5.135.141.80 PROTO=TCP SPT=53706 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.104 PROTO=TCP SPT=53647 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53696 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=72.251.241.196 PROTO=TCP SPT=53707 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=2.23.94.49 PROTO=TCP SPT=53631 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=5.135.141.80 PROTO=TCP SPT=53706 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.104 PROTO=TCP SPT=53647 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53696 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=53714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=72.251.241.196 PROTO=TCP SPT=53707 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=2.23.94.49 PROTO=TCP SPT=53631 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=5.135.141.80 PROTO=TCP SPT=53706 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.104 PROTO=TCP SPT=53647 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:16:01 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53696 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 11:14:40 wlan0: AP-STA-CONNECTED

bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 11:14:40 wlan1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=72.251.241.196 PROTO=TCP SPT=53707 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=2.23.94.49 PROTO=TCP SPT=53631 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=53714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=5.135.141.80 PROTO=TCP SPT=53706 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=185.86.139.104 PROTO=TCP SPT=53647 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53696 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=72.251.241.196 PROTO=TCP SPT=53707 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=2.23.94.49 PROTO=TCP SPT=53631 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=53714 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=5.135.141.80 PROTO=TCP SPT=53706 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=185.86.139.104 PROTO=TCP SPT=53647 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53696 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=72.251.241.196 PROTO=TCP SPT=53707 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=2.23.94.49 PROTO=TCP SPT=53631 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=62.149.0.72 PROTO=TCP SPT=53720 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=185.86.139.104 PROTO=TCP SPT=53647 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=185.33.220.244 PROTO=TCP SPT=53670 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=185.239.172.66 PROTO=TCP SPT=53717 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53696 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=185.86.139.114 PROTO=TCP SPT=53712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=2.23.94.49 PROTO=TCP SPT=53631 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=72.251.241.196 PROTO=TCP SPT=53703 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101
DST=72.251.241.196 PROTO=TCP SPT=53707 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:14:40 SRC=192.168.2.101

DST=178.250.0.151 PROTO=TCP SPT=63897 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63897 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63897 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63897 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63897 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63897 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63897 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63897 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63883 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 11:02:45 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 11:02:33 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 10:55:42 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-08-2021 10:55:42 w11: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=63836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:55:42 SRC=192.168.2.105
DST=2.16.192.145 PROTO=TCP SPT=63832 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 10:55:11 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 10:54:47 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 10:54:47 w10: AP-STA-DISCONNECTED

[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=62802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=62802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=62802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=62802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.105
DST=185.33.220.240 PROTO=TCP SPT=62806 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.105
DST=178.250.0.151 PROTO=TCP SPT=62802 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=23.3.65.39 PROTO=TCP SPT=34618 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=23.3.65.39 PROTO=TCP SPT=34618 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=23.3.65.39 PROTO=TCP SPT=34542 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=23.3.65.39 PROTO=TCP SPT=34542 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=23.3.65.39 PROTO=TCP SPT=34548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=23.3.65.39 PROTO=TCP SPT=34548 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=54.230.205.93 PROTO=TCP SPT=40170 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=54.230.205.93 PROTO=TCP SPT=40170 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=54.230.205.93 PROTO=TCP SPT=40170 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=93.184.221.225 PROTO=TCP SPT=53470 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=93.184.221.225 PROTO=TCP SPT=53470 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=93.184.221.225 PROTO=TCP SPT=53470 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:37:53 SRC=192.168.2.102
DST=93.184.221.225 PROTO=TCP SPT=53470 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 10:29:30 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 10:29:30 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 10:29:15 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 10:29:12 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 10:29:12 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 10:28:51 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 10:28:51 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 10:28:51 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53320 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 10:25:57 wl0: AP-STA-CONNECTED

DST=99.84.156.14 PROTO=TCP SPT=53287 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:25:57 SRC=192.168.2.101
DST=99.84.156.14 PROTO=TCP SPT=53287 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:25:57 SRC=192.168.2.101
DST=99.84.156.14 PROTO=TCP SPT=53287 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:25:57 SRC=192.168.2.101
DST=99.84.156.14 PROTO=TCP SPT=53287 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:25:57 SRC=192.168.2.101
DST=99.84.156.14 PROTO=TCP SPT=53287 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:25:57 SRC=192.168.2.101
DST=99.84.156.14 PROTO=TCP SPT=53287 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:25:57 SRC=192.168.2.101
DST=99.84.156.14 PROTO=TCP SPT=53287 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:25:57 SRC=192.168.2.101
DST=99.84.156.14 PROTO=TCP SPT=53287 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:25:57 SRC=192.168.2.101
DST=99.84.156.14 PROTO=TCP SPT=53287 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:25:57 SRC=192.168.2.101
DST=18.185.164.146 PROTO=TCP SPT=62178 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:25:57 SRC=192.168.2.105
DST=2.16.192.242 PROTO=TCP SPT=61158 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:25:57 SRC=192.168.2.105
DST=104.244.36.20 PROTO=TCP SPT=62269 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 10:25:50 Successfully assign IP
[192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time
[86400]
[INFO][LAN] 12-08-2021 10:25:50 unicasting packet to client ciaddr
[INFO][LAN] 12-08-2021 10:25:50 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 10:25:48 Received REQUEST from client ip
[192.168.2.100] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-08-2021 10:25:48 Received a packet
[INFO][LAN] 12-08-2021 10:23:11 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 10:17:54 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 10:17:54 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 10:17:54 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:17:54 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:17:54 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:17:54 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:17:54 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:17:54 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:17:54 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:17:54 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:17:54 SRC=192.168.2.101

DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:17:54 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:17:54 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 10:17:24 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 10:15:57 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 10:15:57 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=53246 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=3.214.112.227 PROTO=TCP SPT=53234 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=34.227.179.12 PROTO=TCP SPT=53250 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=50850 DPT=443 MARK=0x3 DROP
[EMERG][Firewall] 12-08-2021 10:15:57 DoS attack: SYN With Data
Attack from source: 178.239.21.133:5103
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53245 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.105
DST=216.52.2.48 PROTO=TCP SPT=62029 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=54.218.45.2 PROTO=TCP SPT=53194 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.105
DST=2.23.181.145 PROTO=TCP SPT=61849 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.105
DST=2.23.181.145 PROTO=TCP SPT=61849 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.102
DST=216.58.212.138 PROTO=TCP SPT=46480 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.105
DST=52.198.4.47 PROTO=TCP SPT=61530 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.101
DST=35.203.55.194 PROTO=TCP SPT=53172 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.105
DST=124.146.215.43 PROTO=TCP SPT=61507 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.105
DST=85.114.159.118 PROTO=TCP SPT=61510 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:15:57 SRC=192.168.2.105
DST=2.16.192.242 PROTO=TCP SPT=61174 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 10:10:56 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 10:09:27 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 10:09:26 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=104.21.46.209 PROTO=TCP SPT=55946 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55945 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=104.21.46.209 PROTO=TCP SPT=55948 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=104.21.46.209 PROTO=TCP SPT=55946 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55945 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55945 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=104.21.46.209 PROTO=TCP SPT=55946 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=104.21.46.209 PROTO=TCP SPT=55948 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55945 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=104.21.46.209 PROTO=TCP SPT=55946 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55945 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55945 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=104.21.46.209 PROTO=TCP SPT=55946 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=104.21.46.209 PROTO=TCP SPT=55948 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.100
DST=104.21.46.209 PROTO=TCP SPT=55946 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 TCP Scan SRC=35.186.224.25

DST=54.237.58.113 PROTO=TCP SPT=53078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53077 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53072 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53075 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53076 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.101
DST=54.237.58.113 PROTO=TCP SPT=53077 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.101
DST=52.95.125.22 PROTO=TCP SPT=53002 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 10:09:26 SRC=192.168.2.102
DST=172.217.19.78 PROTO=TCP SPT=51540 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 10:02:18 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 09:58:49 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 09:58:49 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 09:58:43 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 09:58:43 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 09:58:10 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 09:58:10 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 09:57:34 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 09:57:33 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 09:57:11 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 09:57:11 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 09:57:11 SRC=192.168.2.101
DST=52.95.115.255 PROTO=TCP SPT=52844 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 09:57:03 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 09:48:59 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 09:48:59 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.101
DST=67.27.233.252 PROTO=TCP SPT=52717 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.101
DST=67.27.233.252 PROTO=TCP SPT=52721 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.102
DST=142.250.185.202 PROTO=TCP SPT=34208 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.102

DST=142.250.184.195 PROTO=TCP SPT=41776 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.101
DST=185.29.132.241 PROTO=TCP SPT=52750 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.101
DST=52.205.167.202 PROTO=TCP SPT=52917 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.101
DST=52.49.53.128 PROTO=TCP SPT=52923 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.101
DST=37.252.173.215 PROTO=TCP SPT=52929 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.101
DST=72.251.249.14 PROTO=TCP SPT=52930 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.101
DST=54.144.144.142 PROTO=TCP SPT=52896 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=185.86.138.142 PROTO=TCP SPT=60573 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:48:59 SRC=192.168.2.105
DST=34.107.254.252 PROTO=TCP SPT=52769 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 09:48:54 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 09:42:00 Transmit reply to
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 09:42:00 Received information request from
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 09:41:59 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 09:41:55 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 09:41:52 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 09:41:52 unicasting packet to client yiaddr

[INFO][LAN] 12-08-2021 09:41:52 No valid arp replies for this address
[INFO][LAN] 12-08-2021 09:41:52 Arp reply received from the requesting device itself.
[INFO][LAN] 12-08-2021 09:41:52 Received REQUEST from client ip [0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 09:41:52 Received a packet
[NOTICE][LAN] 12-08-2021 09:41:50 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-08-2021 09:41:48 Successfully assign IP [192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time [86400]
[INFO][LAN] 12-08-2021 09:41:48 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 09:41:48 No valid arp replies for this address
[INFO][LAN] 12-08-2021 09:41:48 Arp reply received from the requesting device itself.
[INFO][LAN] 12-08-2021 09:41:48 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 09:41:48 Received REQUEST from client ip [0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-08-2021 09:41:48 Received a packet
[NOTICE][LAN] 12-08-2021 09:41:48 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[NOTICE][LAN] 12-08-2021 09:41:47 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-08-2021 09:41:47 SRC=192.168.2.101
DST=212.129.3.112 PROTO=TCP SPT=52649 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:41:47 SRC=192.168.2.101
DST=212.129.3.112 PROTO=TCP SPT=52648 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:41:47 SRC=192.168.2.101
DST=212.129.3.112 PROTO=TCP SPT=52645 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:41:47 SRC=192.168.2.101
DST=212.129.3.112 PROTO=TCP SPT=52646 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:41:47 SRC=192.168.2.101
DST=212.129.3.112 PROTO=TCP SPT=52647 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:41:47 SRC=192.168.2.101
DST=51.15.145.116 PROTO=TCP SPT=52635 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:41:47 SRC=192.168.2.101
DST=51.15.145.116 PROTO=TCP SPT=52636 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:41:47 SRC=192.168.2.102
DST=80.156.82.166 PROTO=TCP SPT=42712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:41:47 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:41:47 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:41:47 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:41:47 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 09:36:37 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 09:27:36 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 09:27:33 Successfully assign IP [192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time [86400]

[INFO][LAN] 12-08-2021 09:27:33 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 09:27:33 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 09:27:33 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 09:27:33 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-08-2021 09:27:33 Received a packet
[NOTICE][LAN] 12-08-2021 09:27:33 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-08-2021 09:27:33 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-08-2021 09:27:33 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 09:27:33 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 09:27:33 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 09:27:33 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 09:27:33 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 09:27:33 Received a packet
[NOTICE][LAN] 12-08-2021 09:27:32 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52596 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52595 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52594 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52593 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.101
DST=54.204.149.76 PROTO=TCP SPT=52597 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=48988 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=44550 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=44550 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=48988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=44550 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.102
DST=142.250.186.106 PROTO=TCP SPT=44550 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=48988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=48988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.102
DST=142.250.181.206 PROTO=TCP SPT=48988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:27:32 SRC=192.168.2.102
DST=142.250.184.234 PROTO=TCP SPT=42500 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 09:26:53 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 09:17:33 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 09:07:47 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 09:02:43 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 09:02:43 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 09:02:43 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=52519 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:02:43 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=52521 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:02:43 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=52522 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:02:43 SRC=192.168.2.101
DST=52.2.204.41 PROTO=TCP SPT=52520 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:02:43 SRC=192.168.2.102
DST=142.250.186.170 PROTO=TCP SPT=58316 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:02:43 SRC=192.168.2.102
DST=216.58.212.170 PROTO=TCP SPT=41650 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:02:43 SRC=192.168.2.102
DST=142.250.185.138 PROTO=TCP SPT=57568 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:02:43 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=52447 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:02:43 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=52444 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 09:02:43 SRC=192.168.2.101
DST=52.1.200.181 PROTO=TCP SPT=52446 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 09:01:44 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 08:57:36 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 08:48:50 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 08:42:37 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 08:38:40 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 08:38:40 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101

DST=34.193.51.162 PROTO=TCP SPT=52354 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52353 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52351 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52354 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52353 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52351 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52354 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52353 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52351 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52354 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52353 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52351 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52354 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52349 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52350 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52347 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52351 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=34.193.51.162 PROTO=TCP SPT=52353 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.102
DST=52.177.138.113 PROTO=TCP SPT=48672 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=99.84.156.52 PROTO=TCP SPT=52134 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=99.84.156.84 PROTO=TCP SPT=52141 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=35.162.31.154 PROTO=TCP SPT=52161 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=216.58.212.144 PROTO=TCP SPT=52144 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101

DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52083 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52081 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=50.19.123.12 PROTO=TCP SPT=52088 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=52.41.122.159 PROTO=TCP SPT=52084 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=142.250.74.202 PROTO=TCP SPT=59532 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:38:40 SRC=192.168.2.101
DST=142.250.186.182 PROTO=TCP SPT=56336 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 08:34:24 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 08:26:09 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 08:21:36 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 08:13:19 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 08:10:17 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 08:10:17 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 08:10:17 SRC=192.168.2.101
DST=52.95.126.160 PROTO=TCP SPT=51896 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:10:17 SRC=192.168.2.101
DST=52.46.154.242 PROTO=TCP SPT=51810 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:10:17 SRC=192.168.2.101
DST=185.33.221.14 PROTO=TCP SPT=52038 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 08:09:00 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 08:07:35 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac

[NOTICE][LAN] 12-08-2021 08:07:35 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 08:07:12 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 08:07:12 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 08:07:08 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 08:07:08 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 08:07:02 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 08:07:02 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 08:06:53 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 08:06:53 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.86.139.58 PROTO=TCP SPT=52023 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.33.220.100 PROTO=TCP SPT=52024 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=72.251.249.9 PROTO=TCP SPT=52022 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.33.220.100 PROTO=TCP SPT=52018 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=52.209.207.101 PROTO=TCP SPT=51996 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=51684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=51684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=54.36.115.153 PROTO=TCP SPT=51684 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=104.108.145.8 PROTO=TCP SPT=51213 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=104.108.145.8 PROTO=TCP SPT=51270 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.66 PROTO=TCP SPT=51139 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=216.52.2.48 PROTO=TCP SPT=51582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=3.120.56.129 PROTO=TCP SPT=51180 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=185.29.134.248 PROTO=TCP SPT=51210 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=52.86.185.173 PROTO=TCP SPT=51200 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=34.243.93.43 PROTO=TCP SPT=51332 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=18.185.182.242 PROTO=TCP SPT=51325 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=34.253.69.203 PROTO=TCP SPT=51294 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=51318 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=51317 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=51319 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=3.222.103.45 PROTO=TCP SPT=51321 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=50.112.44.42 PROTO=TCP SPT=51284 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=3.216.88.24 PROTO=TCP SPT=51112 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.102
DST=185.60.217.54 PROTO=TCP SPT=50404 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.102
DST=185.60.217.54 PROTO=TCP SPT=50404 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.102
DST=185.60.217.54 PROTO=TCP SPT=50404 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.102
DST=185.60.217.54 PROTO=TCP SPT=50404 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.102
DST=185.60.217.54 PROTO=TCP SPT=50404 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 08:06:53 SRC=192.168.2.101
DST=93.184.220.29 PROTO=TCP SPT=59274 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 08:01:41 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 07:55:43 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 07:48:17 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 07:44:25 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 07:41:28 Successfully assign IP
[192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time
[86400]
[INFO][LAN] 12-08-2021 07:41:28 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 07:41:28 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 07:41:28 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 07:41:28 Received REQUEST from client ip
[0.0.0.0] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-08-2021 07:41:28 Received a packet
[NOTICE][LAN] 12-08-2021 07:41:28 wl0: AP-STA-CONNECTED
68:2f:67:8a:e3:07
[NOTICE][LAN] 12-08-2021 07:41:28 wl1: AP-STA-DISCONNECTED
68:2f:67:8a:e3:07
[EMERG][Firewall] 12-08-2021 07:41:28 DoS attack: SYN With Data
Attack from source: 92.118.161.33:60687
[WARNING][Firewall] 12-08-2021 07:41:28 SRC=192.168.2.102
DST=79.125.89.125 PROTO=TCP SPT=55526 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:41:28 SRC=192.168.2.102
DST=52.49.211.202 PROTO=TCP SPT=56140 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:41:28 SRC=192.168.2.102
DST=52.49.211.202 PROTO=TCP SPT=56140 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 07:36:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 07:31:03 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 07:21:08 LAN sending RA to ff02::1
[WARNING][Firewall] 12-08-2021 07:20:11 SRC=192.168.2.102
DST=52.49.211.202 PROTO=TCP SPT=56140 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 07:20:11 SRC=192.168.2.102
DST=52.49.211.202 PROTO=TCP SPT=56140 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:20:11 SRC=192.168.2.102
DST=52.49.211.202 PROTO=TCP SPT=56140 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:20:11 SRC=192.168.2.102
DST=52.49.211.202 PROTO=TCP SPT=56140 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:20:11 SRC=192.168.2.102
DST=52.49.211.202 PROTO=TCP SPT=56140 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:20:11 SRC=192.168.2.102
DST=52.49.211.202 PROTO=TCP SPT=56140 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:20:11 SRC=192.168.2.102
DST=52.49.211.202 PROTO=TCP SPT=56140 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:20:11 SRC=192.168.2.102
DST=52.232.209.85 PROTO=TCP SPT=48962 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:20:11 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=40264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:20:11 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=41412 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:20:11 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=40264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:20:11 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=41412 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 07:13:52 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 07:10:54 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=40264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=41412 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=185.60.217.54 PROTO=TCP SPT=32986 DPT=5222 MARK=0x1 DROP
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=40264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=41412 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 07:10:54 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=41412 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=40264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=40264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=41412 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=41412 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=142.250.184.195 PROTO=TCP SPT=41412 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=40264 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102
DST=80.156.82.166 PROTO=TCP SPT=42338 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 07:10:54 SRC=192.168.2.102

[EMERG][Firewall] 12-08-2021 06:34:16 DoS attack: SYN With Data
Attack from source: 8.218.241.100:8000
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.103
DST=34.237.73.95 PROTO=TCP SPT=64253 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.103
DST=34.237.73.95 PROTO=TCP SPT=64253 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.103
DST=34.237.73.95 PROTO=TCP SPT=64253 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.103
DST=34.237.73.95 PROTO=TCP SPT=64253 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.103
DST=34.237.73.95 PROTO=TCP SPT=64253 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.102
DST=172.217.19.78 PROTO=TCP SPT=51078 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57602 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57602 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57602 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57602 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57602 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57602 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57602 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57602 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 06:34:16 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57602 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 06:32:37 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 06:22:41 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 06:19:09 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 06:11:43 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 06:04:36 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 06:04:36 wl0: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-08-2021 06:03:48 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-08-2021 06:03:48 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 06:03:48 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 06:03:48 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 06:03:48 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 06:03:48 Received REQUEST from client ip

```
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-08-2021 06:03:48 Received a packet
[NOTICE][LAN] 12-08-2021 06:03:48 wlan1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-08-2021 06:01:35 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 05:59:52 wlan1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-08-2021 05:59:52 SRC=192.168.2.100
DST=17.57.146.69 PROTO=TCP SPT=55409 DPT=5223 MARK=0x1 DROP
[INFO][LAN] 12-08-2021 05:53:02 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:48:43 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:38:53 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:32:58 LAN sending RA to ff02::1
[INFO][VoIP] 12-08-2021 05:29:14 Switch to primary proxy server
arcor.de on line 0
[INFO][LAN] 12-08-2021 05:29:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:28:50 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 05:28:45 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 05:28:34 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 05:28:32 Sync up with NTP Server
successfully.
[INFO][System] 12-08-2021 05:28:32 Sync up with NTP Server
successfully.
[INFO][VoIP] 12-08-2021 05:28:24 Send data/single wan update to
VGW,wan id 10,ifName is ppp10,ipv4 address 188.96.64.199,ipv6
address ,default_wan_id 10,wan type 1
[INFO][VoIP] 12-08-2021 05:28:24 line 371 ,wan 10 start do data wan
up
[INFO][VoIP] 12-08-2021 05:28:24 wanipv6 = ,size = 0
[INFO][VoIP] 12-08-2021 05:28:24 Voice binding wan_id is
10,default_wan_id is 10
[INFO][VoIP] 12-08-2021 05:28:24 Voice binding wan_id is
10,default_wan_id is 10,is_ipv6 = 0
[INFO][VoIP] 12-08-2021 05:28:24 wan 10 service_type =
DATA,VOIP,MGNT,IPTV bud_voip_wan_id = 10
[INFO][VoIP] 12-08-2021 05:28:24 Interface wan_ip is 188.96.64.199,
wan_ip_v6 ,is_ipv6 0 wan up id 10
[INFO][LAN] 12-08-2021 05:28:24 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO][LAN] 12-08-2021 05:28:24 adapter index 19
[INFO][LAN] 12-08-2021 05:28:24 br1 (our ip) = 192.168.3.1
[INFO][LAN] 12-08-2021 05:28:24 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-08-2021 05:28:24 adapter index 18
[INFO][LAN] 12-08-2021 05:28:24 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-08-2021 05:28:24 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-08-2021 05:28:24 adapter index 18
[INFO][LAN] 12-08-2021 05:28:24 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-08-2021 05:28:24 Attaching option timezone to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option t2 to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option t1 to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option timezone to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option lease to list
```

[INFO][LAN] 12-08-2021 05:28:24 Attaching option t2 to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option dns to existing member of list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option t1 to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option dns to existing member of list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option dns to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option router to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option subnet to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option timezone to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option t2 to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option t1 to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option lease to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option dns to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option hostname to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option lease to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option domain to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option dns to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option router to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option router to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option subnet to list
[INFO][LAN] 12-08-2021 05:28:24 Attaching option subnet to list
[INFO][LAN] 12-08-2021 05:28:24 error on select
[INFO][LAN] 12-08-2021 05:28:24 error on select
[INFO][LAN] 12-08-2021 05:28:24 udhcp server receive signal 12
[INFO][LAN] 12-08-2021 05:28:24 udhcp server receive signal 12
[INFO][System] 12-08-2021 05:28:22 Starting MCPD OK.
[INFO][System] 12-08-2021 05:28:22 Stopping MCPD OK.
[INFO][UMTS] 12-08-2021 05:28:22 iPhone DNS Policy actived
[INFO][VoIP] 12-08-2021 05:28:22 276 start wan service Voice binding wan_id is 10
[INFO][VoIP] 12-08-2021 05:28:22 Voice binding wan_id is 10
[INFO][System] 12-08-2021 05:28:22 Starting NTP Client OK.
[INFO][System] 12-08-2021 05:28:22 Sync up with NTP Server failed.
[INFO][System] 12-08-2021 05:28:22 Stopping NTP Client OK.
[INFO][Firewall] 12-08-2021 05:28:21 PortMapping Rules have been flushed on WAN VDSL-DT.
[INFO][Firewall] 12-08-2021 05:28:21 DMZ Rules has been flushed on WAN VDSL-DT.
[INFO][Firewall] 12-08-2021 05:28:21 Static NAT Rules have been flushed on WAN VDSL-DT.
[INFO][System] 12-08-2021 05:28:21 Stopping HTTP redirect OK.
[INFO][DNS] 12-08-2021 05:28:21 DNSMasq proxy server disable redirect
[INFO][DNS] 12-08-2021 05:28:21 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-08-2021 05:28:21 Internet DNS ready.
[INFO][DNS] 12-08-2021 05:28:21 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-08-2021 05:28:21 Internet DNS ready.
[INFO][DNS] 12-08-2021 05:28:21 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-08-2021 05:28:21 Internet DNS ready.
[INFO][DNS] 12-08-2021 05:28:21 Internet DNS Servers 176.95.16.250,

176.95.16.251.
[INFO][DNS] 12-08-2021 05:28:21 Internet DNS ready.
[WARNING][DNS] 12-08-2021 05:28:21 ignoring nameserver 127.0.0.1 -
local interface
[WARNING][DNS] 12-08-2021 05:28:21 ignoring nameserver ::1 - local
interface
[INFO][DNS] 12-08-2021 05:28:21 Starting DNSMasq proxy server OK.
[INFO][DNS] 12-08-2021 05:28:21 Stopping DNSMasq proxy OK.
[ERROR][System] 12-08-2021 05:28:20 TR069 connects to ACS server
failed, couldn't resolve.
[INFO][DNS] 12-08-2021 05:28:19 DNSMasq proxy server disable
redirect
[INFO][System] 12-08-2021 05:28:19 FSM---- Switch to Connect State.
[INFO][UMTS] 12-08-2021 05:28:18 iPhone DNS Policy actived
[INFO][VoIP] 12-08-2021 05:28:18 Remove interface wan_id is 10,wan
type 2.
[INFO][VoIP] 12-08-2021 05:28:18 VoIP WAN down, Voice trying to run
in backup mode, try binding wan_id is 10
[INFO][VoIP] 12-08-2021 05:28:18 bud data ipv4 wan status 10,ipv6
wan status -1
[INFO][VoIP] 12-08-2021 05:28:18 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-08-2021 05:28:18 ===start stop voice wan
[INFO][LAN] 12-08-2021 05:28:18 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:28:18 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 05:28:18 Starting MCPD OK.
[INFO][System] 12-08-2021 05:28:18 Stopping MCPD OK.
[INFO][DNS] 12-08-2021 05:28:17 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 05:28:17 Internet DNS ready.
[INFO][DNS] 12-08-2021 05:28:17 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-08-2021 05:28:17 Internet DNS ready.
[INFO][DNS] 12-08-2021 05:28:17 Internet DNS deactivated.
[ERROR][System] 12-08-2021 05:28:17 TR069 connects to ACS server
failed, couldn't resolve.
[INFO][VoIP] 12-08-2021 05:28:17 ignore useless wan down
[INFO][VoIP] 12-08-2021 05:28:17 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-08-2021 05:28:17 ===start stop voice wan
[WARNING][WAN] 12-08-2021 05:28:16 WAN default route add to ppp10
gateway 84.59.211.1.
[INFO][VoIP] 12-08-2021 05:28:16 ignore useless wan down
[INFO][VoIP] 12-08-2021 05:28:16 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-08-2021 05:28:16 ===start stop voice wan
[INFO][WAN] 12-08-2021 05:28:15 Stop WAN 8 IP Connection
[INFO][WAN] 12-08-2021 05:28:15 Data WAN11 Activated!
[INFO][WAN] 12-08-2021 05:28:15 bud update WAN11 status to 2.
[INFO][System] 12-08-2021 05:28:15 FSM---- Switch to Connect State.
[WARNING][WAN] 12-08-2021 05:28:14 WAN VDSL-DT is up, mode is PPPoE,

IP is 188.96.64.199.

[WARNING][WAN] 12-08-2021 05:28:14 WAN VDSL-DT is down.
[INFO][LAN] 12-08-2021 05:28:14 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 05:28:14 PPP CHAP MD5 authentication is
successful on WAN VDSL-DT
[INFO][LAN] 12-08-2021 05:28:14 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:28:14 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:28:14 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 05:28:14 PPPoE PADS has been received from
WAN VDSL-DT
[INFO][WAN] 12-08-2021 05:28:14 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-08-2021 05:28:14 PPPoE PADR has been sent from WAN
VDSL-DT
[INFO][WAN] 12-08-2021 05:28:14 PPPoE PADO has been received from
WAN VDSL-DT, BRAS name is BLNCOS69101.
[INFO][WAN] 12-08-2021 05:28:14 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-08-2021 05:28:05 FSM---- Switch to Connect State.
[INFO][WAN] 12-08-2021 05:27:57 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-08-2021 05:27:57 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-08-2021 05:27:56 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 05:27:45 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 05:27:36 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 05:27:35 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 05:27:26 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 05:27:20 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 05:27:16 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 05:27:06 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 05:27:04 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 05:27:01 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-08-2021 05:27:01 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-08-2021 05:26:56 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 05:26:48 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:26:48 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 05:26:48 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-08-2021 05:26:48 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][LAN] 12-08-2021 05:26:48 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:26:48 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:26:47 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:26:47 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:26:47 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:26:47 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:26:47 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 05:26:47 Start WAN 8 IP Connection
[INFO][WAN] 12-08-2021 05:26:47 Start WAN 10 IP Connection
[INFO][WAN] 12-08-2021 05:26:47 WAN VDSL-DATA has been started, PHY
link up
[INFO][WAN] 12-08-2021 05:26:47 WAN VDSL-DT has been started, PHY

link up

```
[INFO][System] 12-08-2021 05:26:47 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 05:26:47 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 05:26:46 Start WAN 4 DSL Connection
[INFO][LAN] 12-08-2021 05:26:46 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:26:46 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 05:26:46 Start WAN 8 DSL Connection
[INFO][LAN] 12-08-2021 05:26:46 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 05:26:46 Starting VDSL interface OK.
[INFO][WAN] 12-08-2021 05:26:46 Start WAN 10 DSL Connection
[EMERG][WAN] 12-08-2021 05:26:45 DSL link up.
[INFO][System] 12-08-2021 05:26:38 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 05:26:28 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 05:26:18 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 05:26:07 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 05:25:56 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 05:25:45 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 05:25:37 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 05:25:36 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 05:25:27 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 05:25:21 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 05:25:18 FSM---- Switch to Connect State.
[INFO][System] 12-08-2021 05:25:08 FSM---- Switch to Connect State.
[INFO][LAN] 12-08-2021 05:25:05 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 05:24:59 FSM---- Switch to Connect State.
[EMERG][WAN] 12-08-2021 05:24:57 DSL link down.
[INFO][WAN] 12-08-2021 05:24:49 WAN VDSL-DT has been stopped, please
check your PHY link
[INFO][LAN] 12-08-2021 05:24:49 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:24:49 LAN sending RA to ff02::1
[INFO][WAN] 12-08-2021 05:24:49 Stopping VDSL interface OK.
[INFO][WAN] 12-08-2021 05:24:49 Stop WAN 10 DSL Connection
[INFO][LAN] 12-08-2021 05:24:49 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:24:49 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:24:49 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 05:24:49 Starting HTTP redirect OK.
[INFO][DNS] 12-08-2021 05:24:49 DNSMasq proxy server enable redirect
[INFO][System] 12-08-2021 05:24:49 Stopping NTP Client OK.
[INFO][System] 12-08-2021 05:24:49 FSM---- Switch to Connect State.
[INFO][VoIP] 12-08-2021 05:24:48 VoIP WAN down, no available
connection
[INFO][VoIP] 12-08-2021 05:24:48 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-08-2021 05:24:48 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-08-2021 05:24:48 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-08-2021 05:24:48 ===start stop voice wan
[INFO][DNS] 12-08-2021 05:24:48 Internet DNS deactivated.
[INFO][LAN] 12-08-2021 05:24:48 LAN sending RA to ff02::1
[INFO][System] 12-08-2021 05:24:48 Starting NTP Client OK.
[INFO][System] 12-08-2021 05:24:48 Sync up with NTP Server failed.
[INFO][System] 12-08-2021 05:24:48 Stopping NTP Client OK.
```

[INFO][VoIP] 12-08-2021 05:24:47 VoIP WAN down, no available connection
[INFO][VoIP] 12-08-2021 05:24:47 Remove interface wan_id is 10,wan type 1.
[INFO][VoIP] 12-08-2021 05:24:47 bud data ipv4 wan status -1,ipv6 wan status -1
[INFO][VoIP] 12-08-2021 05:24:47 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 = 0,default_wan_id= 10
[INFO][VoIP] 12-08-2021 05:24:47 ===start stop voice wan
[INFO][DNS] 12-08-2021 05:24:47 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-08-2021 05:24:47 Internet DNS ready.
[INFO][DNS] 12-08-2021 05:24:47 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-08-2021 05:24:47 Internet DNS ready.
[INFO][DNS] 12-08-2021 05:24:47 Internet DNS deactivated.
[INFO][WAN] 12-08-2021 05:24:47 WAN VDSL-DATA has been stopped, please check your PHY link
[INFO][System] 12-08-2021 05:24:46 Starting NTP Client OK.
[INFO][System] 12-08-2021 05:24:46 Sync up with NTP Server failed.
[INFO][System] 12-08-2021 05:24:46 Stopping NTP Client OK.
[INFO][VoIP] 12-08-2021 05:24:46 VoIP WAN down, no available connection
[INFO][VoIP] 12-08-2021 05:24:46 Remove interface wan_id is 10,wan type 1.
[INFO][VoIP] 12-08-2021 05:24:46 bud data ipv4 wan status -1,ipv6 wan status -1
[INFO][VoIP] 12-08-2021 05:24:46 Voice binding wan_id is 10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 = 1,default_wan_id= 10
[INFO][VoIP] 12-08-2021 05:24:46 ===start stop voice wan
[INFO][WAN] 12-08-2021 05:24:46 Stop WAN 8 DSL Connection
[INFO][LAN] 12-08-2021 05:24:46 LAN sending RA to ff02::1
[INFO][DNS] 12-08-2021 05:24:46 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-08-2021 05:24:46 Internet DNS ready.
[INFO][DNS] 12-08-2021 05:24:45 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-08-2021 05:24:45 Internet DNS ready.
[INFO][DNS] 12-08-2021 05:24:45 Internet DNS deactivated.
[INFO][DNS] 12-08-2021 05:24:45 Internet DNS deactivated.
[INFO][WAN] 12-08-2021 05:24:45 Stop WAN 10 IP Connection
[INFO][WAN] 12-08-2021 05:24:45 IPTV WAN11 DeActivated!
[INFO][WAN] 12-08-2021 05:24:45 bud update WAN11 status to 0.
[INFO][WAN] 12-08-2021 05:24:45 Stop WAN 4 DSL Connection
[INFO][LAN] 12-08-2021 05:24:45 LAN sending RA to ff02::1
[EMERG][WAN] 12-08-2021 05:24:45 DSL link down.
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.102 DST=172.217.16.78 PROTO=TCP SPT=57422 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.102 DST=172.217.16.78 PROTO=TCP SPT=57422 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.102 DST=172.217.16.78 PROTO=TCP SPT=57422 DPT=80 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57422 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57422 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57422 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57422 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57422 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57422 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55875 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55868 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55875 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55867 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55875 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55875 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55875 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55875 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55875 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55863 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 TCP Scan SRC=35.186.224.25
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=55843 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55867 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.102
DST=142.250.181.246 PROTO=TCP SPT=47996 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 TCP Scan SRC=142.250.181.234
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=42360 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55868 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55863 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55867 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55868 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55863 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55867 DPT=443 MARK=0x3 DROP

```
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55863 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55868 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55863 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55867 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55863 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55868 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55863 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55867 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55863 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55868 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55853 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55867 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55868 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55867 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 TCP Scan SRC=23.63.148.30
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=55867 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.102
DST=142.250.185.170 PROTO=TCP SPT=59672 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 05:24:45 SRC=192.168.2.102
DST=142.250.186.138 PROTO=TCP SPT=45674 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 05:19:46 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:15:48 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:11:25 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:06:59 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 05:00:09 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 04:56:32 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 04:51:40 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 04:45:34 wl0: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[INFO][LAN] 12-08-2021 04:45:12 Transmit reply to
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 04:45:12 Received information request from
fe80::1050:173f:3ea0:6f76%br0 on LAN
[INFO][LAN] 12-08-2021 04:45:11 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 04:45:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 04:45:06 Successfully assign IP
[192.168.2.105] to client mac [10:94:bb:d5:73:92], lease time
[86400]
[INFO][LAN] 12-08-2021 04:45:06 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 04:45:06 No valid arp replies for this
```

address

```
[INFO][LAN] 12-08-2021 04:45:04 Received REQUEST from client ip
[0.0.0.0] mac [10:94:bb:d5:73:92]
[INFO][LAN] 12-08-2021 04:45:04 Received a packet
[NOTICE][LAN] 12-08-2021 04:45:02 wl0: AP-STA-CONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55853 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55853 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55853 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55853 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55853 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55853 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55853 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55853 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55846 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 TCP Scan SRC=35.186.224.25
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=55849 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.103
DST=54.77.160.229 PROTO=TCP SPT=57716 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57272 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57272 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57272 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57272 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57272 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57272 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57272 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57272 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57272 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57272 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57272 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55846 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55846 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55846 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55846 DPT=443 MARK=0x3 DROP
```

[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55846 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55846 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55846 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 TCP Scan SRC=35.186.224.25
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=55845 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55827 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55836 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 TCP Scan SRC=35.186.224.25
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=55809 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55827 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55827 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55827 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55827 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55827 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55827 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55820 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55827 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 04:45:02 TCP Scan SRC=35.186.224.25
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=55823 MARK=0x8000001
[INFO][LAN] 12-08-2021 04:42:03 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 04:36:42 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 04:32:13 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 04:27:01 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 04:17:38 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 04:09:33 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 04:03:50 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 03:57:53 LAN sending RA to ff02::1

[WARNING][Firewall] 12-08-2021 03:23:38 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57192 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:23:38 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57192 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:23:38 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57192 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:23:38 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57192 DPT=80 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 03:23:38 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 03:23:38 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57192 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 03:22:02 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 03:18:14 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 03:18:10 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-08-2021 03:18:10 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 03:18:10 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 03:18:10 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 03:18:10 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 03:18:10 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 03:18:10 Received a packet
[NOTICE][LAN] 12-08-2021 03:18:10 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 03:17:36 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 03:17:36 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55813 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:17:36 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55813 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:17:36 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55798 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:17:36 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55813 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:17:36 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55813 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:17:36 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55813 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:17:36 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55813 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:17:36 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55813 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:17:36 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55813 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:17:36 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55803 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 03:17:36 TCP Scan SRC=35.186.224.25
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=55811 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 03:17:36 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55798 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 03:15:26 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 03:10:48 LAN sending RA to ff02::1

[INFO][LAN] 12-08-2021 03:03:40 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 02:59:35 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-08-2021 02:59:35 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 02:59:35 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 02:59:35 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 02:59:35 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 02:59:35 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 02:59:35 Received a packet
[NOTICE][LAN] 12-08-2021 02:59:34 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 02:58:49 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 02:58:49 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57130 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:58:49 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57130 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 02:56:32 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 02:56:27 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-08-2021 02:56:27 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 02:56:27 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 02:56:27 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 02:56:27 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 02:56:27 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 02:56:27 Received a packet
[NOTICE][LAN] 12-08-2021 02:56:27 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 02:56:27 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57130 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:56:27 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57130 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:56:27 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57130 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:56:27 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57130 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:56:27 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57130 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:56:27 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57130 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:56:27 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57130 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:56:27 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57130 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:56:27 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57130 DPT=80 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 02:55:48 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd

[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.102
DST=142.250.186.150 PROTO=TCP SPT=56572 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55803 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55798 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55803 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55798 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55803 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55803 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55798 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55803 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55803 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55798 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55794 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55803 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=2.19.213.32 PROTO=TCP SPT=55798 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:55:48 TCP Scan SRC=2.19.213.32
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=55798 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 02:55:48 SRC=192.168.2.100
DST=17.248.173.12 PROTO=TCP SPT=55781 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 02:51:38 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-08-2021 02:51:37 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 02:51:37 SRC=192.168.2.102
DST=142.250.186.74 PROTO=TCP SPT=39580 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 02:49:38 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 02:42:29 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 02:42:25 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-08-2021 02:42:25 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 02:42:25 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 02:42:25 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 02:42:24 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 02:42:24 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 02:42:24 Received a packet
[NOTICE][LAN] 12-08-2021 02:42:24 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd

[WARNING][Firewall] 12-08-2021 02:41:42 SRC=192.168.2.102
DST=54.72.5.132 PROTO=TCP SPT=38510 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 02:36:32 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 02:27:03 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 02:23:27 wlan1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 02:23:27 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57072 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:23:27 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57072 DPT=80 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 02:22:53 wlan1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57072 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57072 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57072 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57072 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57072 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57072 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=57072 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=2.19.213.26 PROTO=TCP SPT=55784 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55782 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=2.19.213.26 PROTO=TCP SPT=55784 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55782 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=55765 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55764 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55782 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=2.19.213.26 PROTO=TCP SPT=55784 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55782 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55782 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=2.19.213.26 PROTO=TCP SPT=55784 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55782 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55770 DPT=443 MARK=0x3 DROP

[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=55765 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55764 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=172.67.142.25 PROTO=TCP SPT=55775 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=2.19.213.64 PROTO=TCP SPT=55765 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55764 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 02:22:53 TCP Scan SRC=2.19.213.64
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=55765 MARK=0x8000001
[INFO][LAN] 12-08-2021 02:20:17 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 02:12:40 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 02:05:07 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 02:00:08 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 01:59:44 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 01:59:44 TCP Scan SRC=142.250.185.170
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=60248 MARK=0x8000001
[INFO][LAN] 12-08-2021 01:55:08 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-08-2021 01:55:08 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 01:55:08 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 01:55:08 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 01:55:08 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 01:55:08 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 01:55:08 Received a packet
[NOTICE][LAN] 12-08-2021 01:55:08 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 01:55:08 SRC=192.168.2.102
DST=163.171.128.27 PROTO=TCP SPT=42310 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-08-2021 01:54:23 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 01:53:30 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 01:53:02 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 01:52:01 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 01:52:01 SRC=192.168.2.102
DST=142.250.186.138 PROTO=TCP SPT=46214 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:52:01 SRC=192.168.2.102
DST=216.58.212.150 PROTO=TCP SPT=40614 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 01:51:37 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 01:51:22 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 01:48:41 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd


```
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=56852 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=56852 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=56852 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.102
DST=142.250.185.142 PROTO=TCP SPT=36044 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 TCP Scan SRC=142.250.74.202
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=58494 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55738 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55738 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55738 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55738 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55738 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55586 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55738 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=35.186.224.47 PROTO=TCP SPT=55738 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 SRC=192.168.2.100
DST=23.63.148.30 PROTO=TCP SPT=55739 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:48:21 TCP Scan SRC=23.63.148.30
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=55739 MARK=0x8000001
[INFO][LAN] 12-08-2021 01:43:16 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 01:37:04 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 01:29:46 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 01:20:06 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 01:10:52 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-08-2021 01:10:52 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 01:10:52 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 01:10:52 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 01:10:52 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 01:10:52 Received REQUEST from client ip
```

[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 01:10:52 Received a packet
[NOTICE][LAN] 12-08-2021 01:10:52 w11: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 01:10:28 w11: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 01:10:28 TCP Scan SRC=142.250.185.227
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=39784 MARK=0x8000001
[NOTICE][LAN] 12-08-2021 01:08:01 w11: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 01:08:01 w10: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-08-2021 01:07:49 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 01:07:47 w11: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=38152 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=38152 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=38152 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=38152 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=38152 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=38152 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=38152 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=38152 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=38152 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=38152 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.70 PROTO=TCP SPT=38152 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=80.158.50.118 PROTO=TCP SPT=55120 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=51946 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=173.194.165.138 PROTO=TCP SPT=32876 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=57800 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=51946 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=173.194.165.138 PROTO=TCP SPT=32876 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.110.9 PROTO=TCP SPT=57800 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.110.10 PROTO=TCP SPT=51946 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=173.194.165.138 PROTO=TCP SPT=32876 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102

DST=74.125.108.104 PROTO=TCP SPT=60122 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.108.104 PROTO=TCP SPT=60122 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.108.104 PROTO=TCP SPT=60122 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 TCP Scan SRC=185.60.217.20
DST=178.0.238.193 PROTO=TCP SPT=443 DPT=43452 MARK=0x8000001
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=173.194.165.140 PROTO=TCP SPT=35430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=173.194.165.140 PROTO=TCP SPT=35430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=173.194.165.140 PROTO=TCP SPT=35430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=173.194.165.140 PROTO=TCP SPT=35430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=173.194.165.140 PROTO=TCP SPT=35430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=173.194.165.140 PROTO=TCP SPT=35430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=173.194.165.140 PROTO=TCP SPT=35430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=173.194.165.140 PROTO=TCP SPT=35430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=173.194.165.140 PROTO=TCP SPT=35430 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=47146 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=37098 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=47146 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=37098 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=47146 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=37098 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=47146 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=37098 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.13.74 PROTO=TCP SPT=47146 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=37098 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 01:07:46 SRC=192.168.2.102
DST=74.125.160.6 PROTO=TCP SPT=37098 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 00:57:57 LAN sending RA to ff02::1

[INFO][LAN] 12-08-2021 00:48:56 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 00:43:05 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 00:38:01 LAN sending RA to ff02::1
[NOTICE][LAN] 12-08-2021 00:36:01 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 00:35:36 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 00:35:36 SRC=192.168.2.102
DST=142.250.186.118 PROTO=TCP SPT=59450 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 00:35:36 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=56100 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 00:35:36 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=56100 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 00:35:36 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=56100 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 00:35:36 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=56100 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 00:35:36 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=56100 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 00:35:36 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=56100 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 00:35:36 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=56100 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 00:35:36 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=56100 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 00:35:36 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=56100 DPT=80 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 00:31:15 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 00:25:21 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 00:18:09 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-08-2021 00:18:09 unicasting packet to client yiaddr
[INFO][LAN] 12-08-2021 00:18:09 No valid arp replies for this
address
[INFO][LAN] 12-08-2021 00:18:09 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-08-2021 00:18:09 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 00:18:09 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-08-2021 00:18:09 Received a packet
[NOTICE][LAN] 12-08-2021 00:18:09 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-08-2021 00:17:31 wl0: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-08-2021 00:17:31 SRC=192.168.2.102
DST=142.250.185.118 PROTO=TCP SPT=43988 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-08-2021 00:17:31 SRC=192.168.2.102
DST=142.250.185.78 PROTO=TCP SPT=51628 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-08-2021 00:16:58 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 00:08:25 LAN sending RA to ff02::1
[INFO][LAN] 12-08-2021 00:00:12 LAN sending RA to ff02::1

DST=172.217.16.78 PROTO=TCP SPT=54958 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=172.217.16.78 PROTO=TCP SPT=54958 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=142.250.186.99 PROTO=TCP SPT=40990 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=142.250.186.99 PROTO=TCP SPT=40990 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=142.250.186.99 PROTO=TCP SPT=40990 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=142.250.186.99 PROTO=TCP SPT=40990 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=142.250.186.99 PROTO=TCP SPT=40990 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=142.250.186.99 PROTO=TCP SPT=40990 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=142.250.186.99 PROTO=TCP SPT=40990 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=142.250.186.99 PROTO=TCP SPT=40990 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=142.250.186.99 PROTO=TCP SPT=40990 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=193.135.9.67 PROTO=TCP SPT=44682 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=217.182.199.66 PROTO=TCP SPT=58788 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:22:59 SRC=192.168.2.102
DST=54.154.120.184 PROTO=TCP SPT=37404 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-07-2021 23:20:58 LAN sending RA to ff02::1
[NOTICE][LAN] 12-07-2021 23:16:45 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-07-2021 23:14:12 Successfully assign IP
[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time
[86400]
[INFO][LAN] 12-07-2021 23:14:12 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 23:14:12 server_id = c0a80201
[INFO][LAN] 12-07-2021 23:14:12 Received REQUEST from client ip
[0.0.0.0] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 23:14:12 Received a packet
[INFO][LAN] 12-07-2021 23:14:12 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 23:14:12 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 23:14:12 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-07-2021 23:14:12 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 23:14:12 Received a packet
[INFO][LAN] 12-07-2021 23:14:12 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 23:14:12 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 23:14:12 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-07-2021 23:14:12 Received DISCOVER from client mac

DST=13.107.42.14 PROTO=TCP SPT=50074 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:14:03 SRC=192.168.2.102
DST=142.250.186.35 PROTO=TCP SPT=44712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:14:03 SRC=192.168.2.102
DST=142.250.186.35 PROTO=TCP SPT=44712 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:14:03 SRC=192.168.2.102
DST=13.107.42.14 PROTO=TCP SPT=50074 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:14:03 SRC=192.168.2.102
DST=173.194.165.137 PROTO=TCP SPT=57914 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:14:03 SRC=192.168.2.103
DST=54.228.140.140 PROTO=TCP SPT=59221 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:14:03 SRC=192.168.2.102
DST=142.250.184.202 PROTO=TCP SPT=43582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:14:03 SRC=192.168.2.102
DST=173.194.165.137 PROTO=TCP SPT=57914 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:14:03 SRC=192.168.2.102
DST=142.250.184.202 PROTO=TCP SPT=43582 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:14:03 SRC=192.168.2.102
DST=173.194.165.137 PROTO=TCP SPT=57914 DPT=443 MARK=0x3 DROP
[INFO][LAN] 12-07-2021 23:13:41 LAN sending RA to ff02::1
[INFO][VoIP] 12-07-2021 23:13:38 Switch to primary proxy server
arcor.de on line 0
[INFO][LAN] 12-07-2021 23:13:25 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:13:09 LAN sending RA to ff02::1
[INFO][System] 12-07-2021 23:13:07 Sync up with NTP Server
successfully.
[INFO][System] 12-07-2021 23:13:05 Sync up with NTP Server
successfully.
[INFO][VoIP] 12-07-2021 23:12:57 Send data/single wan update to
VGW,wan id 10,ifName is ppp10,ipv4 address 178.0.238.193,ipv6
address ,default_wan_id 10,wan type 1
[INFO][VoIP] 12-07-2021 23:12:57 line 371 ,wan 10 start do data wan
up
[INFO][VoIP] 12-07-2021 23:12:57 wanipv6 = ,size = 0
[INFO][VoIP] 12-07-2021 23:12:57 Voice binding wan_id is
10,default_wan_id is 10
[INFO][VoIP] 12-07-2021 23:12:57 Voice binding wan_id is
10,default_wan_id is 10,is_ipv6 = 0
[INFO][VoIP] 12-07-2021 23:12:57 wan 10 service_type =
DATA,VOIP,MGNT,IPTV bud_voip_wan_id = 10
[INFO][VoIP] 12-07-2021 23:12:57 Interface wan_ip is 178.0.238.193,
wan_ip_v6 ,is_ipv6 0 wan up id 10
[INFO][LAN] 12-07-2021 23:12:57 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO][LAN] 12-07-2021 23:12:57 adapter index 19
[INFO][LAN] 12-07-2021 23:12:57 br1 (our ip) = 192.168.3.1
[INFO][LAN] 12-07-2021 23:12:57 Attaching option timezone to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option t2 to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option t1 to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option lease to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option dns to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option router to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option subnet to list
[INFO][LAN] 12-07-2021 23:12:57 error on select

```
[INFO][LAN] 12-07-2021 23:12:57 udhcp server receive signal 12
[INFO][LAN] 12-07-2021 23:12:57 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-07-2021 23:12:57 adapter index 18
[INFO][LAN] 12-07-2021 23:12:57 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-07-2021 23:12:57 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-07-2021 23:12:57 adapter index 18
[INFO][LAN] 12-07-2021 23:12:57 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-07-2021 23:12:57 Attaching option timezone to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option t2 to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option t1 to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option lease to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option dns to existing
member of list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option dns to existing
member of list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option dns to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option router to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option subnet to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option timezone to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option t2 to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option t1 to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option lease to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option dns to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option hostname to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option domain to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option router to list
[INFO][LAN] 12-07-2021 23:12:57 Attaching option subnet to list
[INFO][LAN] 12-07-2021 23:12:57 error on select
[INFO][LAN] 12-07-2021 23:12:57 udhcp server receive signal 12
[INFO][System] 12-07-2021 23:12:55 Starting MCPD OK.
[INFO][System] 12-07-2021 23:12:55 Stopping MCPD OK.
[INFO][UMTS] 12-07-2021 23:12:55 iPhone DNS Policy actived
[INFO][VoIP] 12-07-2021 23:12:55 276 start wan service Voice
binding wan_id is 10
[INFO][VoIP] 12-07-2021 23:12:55 Voice binding wan_id is 10
[INFO][System] 12-07-2021 23:12:55 Starting NTP Client OK.
[INFO][System] 12-07-2021 23:12:55 Sync up with NTP Server failed.
[INFO][System] 12-07-2021 23:12:55 Stopping NTP Client OK.
[INFO][Firewall] 12-07-2021 23:12:55 PortMapping Rules have been
flushed on WAN VDSL-DT.
[INFO][Firewall] 12-07-2021 23:12:54 DMZ Rules has been flushed on
WAN VDSL-DT.
[INFO][Firewall] 12-07-2021 23:12:54 Static NAT Rules have been
flushed on WAN VDSL-DT.
[INFO][System] 12-07-2021 23:12:54 Stopping HTTP redirect OK.
[INFO][DNS] 12-07-2021 23:12:54 DNSMasq proxy server disable
redirect
[INFO][DNS] 12-07-2021 23:12:54 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-07-2021 23:12:54 Internet DNS ready.
[INFO][DNS] 12-07-2021 23:12:54 Internet DNS Servers 176.95.16.250,
176.95.16.251.
```

[INFO][DNS] 12-07-2021 23:12:54 Internet DNS ready.
[INFO][DNS] 12-07-2021 23:12:54 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-07-2021 23:12:54 Internet DNS ready.
[INFO][DNS] 12-07-2021 23:12:54 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-07-2021 23:12:54 Internet DNS ready.
[WARNING][DNS] 12-07-2021 23:12:54 ignoring nameserver 127.0.0.1 -
local interface
[WARNING][DNS] 12-07-2021 23:12:54 ignoring nameserver ::1 - local
interface
[INFO][DNS] 12-07-2021 23:12:54 Starting DNSMasq proxy server OK.
[INFO][DNS] 12-07-2021 23:12:54 Stopping DNSMasq proxy OK.
[INFO][System] 12-07-2021 23:12:53 FSM---- Switch to Connect State.
[INFO][LAN] 12-07-2021 23:12:53 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:12:53 LAN sending RA to ff02::1
[INFO][DNS] 12-07-2021 23:12:53 DNSMasq proxy server disable
redirect
[INFO][UMTS] 12-07-2021 23:12:52 iPhone DNS Policy actived
[INFO][VoIP] 12-07-2021 23:12:52 Remove interface wan_id is 10,wan
type 2.
[INFO][VoIP] 12-07-2021 23:12:52 VoIP WAN down, Voice trying to run
in backup mode, try binding wan_id is 10
[INFO][VoIP] 12-07-2021 23:12:52 bud data ipv4 wan status 10,ipv6
wan status -1
[INFO][VoIP] 12-07-2021 23:12:52 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-07-2021 23:12:52 ===start stop voice wan
[INFO][VoIP] 12-07-2021 23:12:52 ignore useless wan down
[INFO][VoIP] 12-07-2021 23:12:52 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-07-2021 23:12:52 ===start stop voice wan
[INFO][System] 12-07-2021 23:12:51 Starting MCPD OK.
[INFO][System] 12-07-2021 23:12:51 Stopping MCPD OK.
[INFO][VoIP] 12-07-2021 23:12:51 ignore useless wan down
[INFO][VoIP] 12-07-2021 23:12:51 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 8,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-07-2021 23:12:51 ===start stop voice wan
[INFO][DNS] 12-07-2021 23:12:51 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-07-2021 23:12:50 Internet DNS ready.
[INFO][DNS] 12-07-2021 23:12:50 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-07-2021 23:12:50 Internet DNS ready.
[INFO][DNS] 12-07-2021 23:12:50 Internet DNS deactivated.
[INFO][WAN] 12-07-2021 23:12:50 Stop WAN 8 IP Connection
[WARNING][WAN] 12-07-2021 23:12:50 WAN default route add to ppp10
gateway 84.59.211.1.
[INFO][WAN] 12-07-2021 23:12:50 Data WAN11 Activated!
[INFO][WAN] 12-07-2021 23:12:50 bud update WAN11 status to 2.
[WARNING][WAN] 12-07-2021 23:12:49 WAN VDSL-DT is up, mode is PPPoE,

IP is 178.0.238.193.
[WARNING][WAN] 12-07-2021 23:12:49 WAN VDSL-DT is down.
[INFO][LAN] 12-07-2021 23:12:49 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 23:12:49 PPP CHAP MD5 authentication is
successful on WAN VDSL-DT
[INFO][LAN] 12-07-2021 23:12:49 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:12:49 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:12:49 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 23:12:49 PPPOE PADS has been received from
WAN VDSL-DT
[INFO][WAN] 12-07-2021 23:12:49 PPPOE PADR has been sent from WAN
VDSL-DT
[INFO][WAN] 12-07-2021 23:12:49 PPPOE PADO has been received from
WAN VDSL-DT, BRAS name is BLNCOS69101.
[INFO][WAN] 12-07-2021 23:12:49 PPPOE PADI has been sent from WAN
VDSL-DT
[INFO][WAN] 12-07-2021 23:12:49 PPPOE PADI has been sent from WAN
VDSL-DATA
[INFO][System] 12-07-2021 23:12:45 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 23:12:35 FSM---- Switch to Connect State.
[INFO][WAN] 12-07-2021 23:12:32 PPPOE PADI has been sent from WAN
VDSL-DT
[INFO][WAN] 12-07-2021 23:12:32 PPPOE PADI has been sent from WAN
VDSL-DATA
[INFO][System] 12-07-2021 23:12:24 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 23:12:13 FSM---- Switch to Connect State.
[INFO][LAN] 12-07-2021 23:12:11 LAN sending RA to ff02::1
[INFO][System] 12-07-2021 23:12:03 FSM---- Switch to Connect State.
[INFO][LAN] 12-07-2021 23:11:55 LAN sending RA to ff02::1
[INFO][System] 12-07-2021 23:11:54 FSM---- Switch to Connect State.
[EMERG][WAN] 12-07-2021 23:11:53 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:53 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:52 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:52 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:51 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:51 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:50 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:50 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:50 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:50 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:49 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:49 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:48 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:48 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:47 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:47 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:46 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:46 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:45 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:45 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:45 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:44 DSL link up.
[EMERG][WAN] 12-07-2021 23:11:44 DSL link up.
[INFO][System] 12-07-2021 23:11:44 FSM---- Switch to Connect State.
[INFO][LAN] 12-07-2021 23:11:39 LAN sending RA to ff02::1

[INFO][WAN] 12-07-2021 23:11:36 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][WAN] 12-07-2021 23:11:36 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][System] 12-07-2021 23:11:33 FSM---- Switch to Connect State.
[INFO][LAN] 12-07-2021 23:11:23 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 23:11:23 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][WAN] 12-07-2021 23:11:23 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][LAN] 12-07-2021 23:11:22 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:11:22 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:11:22 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:11:22 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:11:22 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:11:22 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:11:22 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 23:11:22 Start WAN 10 IP Connection
[INFO][WAN] 12-07-2021 23:11:22 Start WAN 8 IP Connection
[INFO][WAN] 12-07-2021 23:11:22 WAN VDSL-DT has been started, PHY
link up
[INFO][WAN] 12-07-2021 23:11:22 WAN VDSL-DATA has been started, PHY
link up
[INFO][System] 12-07-2021 23:11:22 FSM---- Switch to Connect State.
[INFO][WAN] 12-07-2021 23:11:21 Start WAN 4 DSL Connection
[INFO][LAN] 12-07-2021 23:11:21 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 23:11:21 Start WAN 10 DSL Connection
[INFO][LAN] 12-07-2021 23:11:21 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:11:21 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 23:11:21 Starting VDSL interface OK.
[INFO][WAN] 12-07-2021 23:11:21 Start WAN 8 DSL Connection
[EMERG][WAN] 12-07-2021 23:11:20 DSL link up.
[INFO][System] 12-07-2021 23:11:10 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 23:11:00 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 23:10:49 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 23:10:39 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 23:10:30 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 23:10:20 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 23:10:11 FSM---- Switch to Connect State.
[INFO][LAN] 12-07-2021 23:10:09 LAN sending RA to ff02::1
[INFO][System] 12-07-2021 23:10:01 FSM---- Switch to Connect State.
[INFO][LAN] 12-07-2021 23:09:53 LAN sending RA to ff02::1
[INFO][System] 12-07-2021 23:09:52 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 23:09:48 User 'vodafone' login
successfully via HTTP from 192.168.2.100
[INFO][System] 12-07-2021 23:09:42 FSM---- Switch to Connect State.
[INFO][LAN] 12-07-2021 23:09:37 LAN sending RA to ff02::1
[INFO][System] 12-07-2021 23:09:33 FSM---- Switch to Connect State.
[EMERG][WAN] 12-07-2021 23:09:28 DSL link down.
[INFO][System] 12-07-2021 23:09:23 FSM---- Switch to Connect State.
[INFO][WAN] 12-07-2021 23:09:21 WAN VDSL-DT has been stopped, please
check your PHY link
[INFO][LAN] 12-07-2021 23:09:21 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:09:21 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 23:09:21 Stopping VDSL interface OK.

[INFO][WAN] 12-07-2021 23:09:21 Stop WAN 10 DSL Connection
[INFO][LAN] 12-07-2021 23:09:21 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:09:21 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 23:09:21 LAN sending RA to ff02::1
[INFO][System] 12-07-2021 23:09:21 Starting HTTP redirect OK.
[INFO][DNS] 12-07-2021 23:09:20 DNSMasq proxy server enable redirect
[INFO][System] 12-07-2021 23:09:20 Stopping NTP Client OK.
[INFO][VoIP] 12-07-2021 23:09:20 VoIP WAN down, no available
connection
[INFO][VoIP] 12-07-2021 23:09:20 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-07-2021 23:09:20 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-07-2021 23:09:20 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-07-2021 23:09:20 ===start stop voice wan
[INFO][DNS] 12-07-2021 23:09:20 Internet DNS deactivated.
[INFO][LAN] 12-07-2021 23:09:20 LAN sending RA to ff02::1
[INFO][System] 12-07-2021 23:09:19 Starting NTP Client OK.
[INFO][System] 12-07-2021 23:09:19 Sync up with NTP Server failed.
[INFO][System] 12-07-2021 23:09:19 Stopping NTP Client OK.
[INFO][VoIP] 12-07-2021 23:09:19 VoIP WAN down, no available
connection
[INFO][VoIP] 12-07-2021 23:09:19 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-07-2021 23:09:19 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-07-2021 23:09:19 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
0,default_wan_id= 10
[INFO][VoIP] 12-07-2021 23:09:19 ===start stop voice wan
[INFO][DNS] 12-07-2021 23:09:18 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-07-2021 23:09:18 Internet DNS ready.
[INFO][DNS] 12-07-2021 23:09:18 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][WAN] 12-07-2021 23:09:18 WAN VDSL-DATA has been stopped,
please check your PHY link
[INFO][DNS] 12-07-2021 23:09:18 Internet DNS ready.
[INFO][DNS] 12-07-2021 23:09:18 Internet DNS deactivated.
[INFO][System] 12-07-2021 23:09:18 Starting NTP Client OK.
[INFO][System] 12-07-2021 23:09:18 Sync up with NTP Server failed.
[INFO][System] 12-07-2021 23:09:18 Stopping NTP Client OK.
[INFO][VoIP] 12-07-2021 23:09:18 VoIP WAN down, no available
connection
[INFO][VoIP] 12-07-2021 23:09:18 Remove interface wan_id is 10,wan
type 1.
[INFO][VoIP] 12-07-2021 23:09:18 bud data ipv4 wan status -1,ipv6
wan status -1
[INFO][VoIP] 12-07-2021 23:09:18 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 10,is_ipv6 =
1,default_wan_id= 10
[INFO][VoIP] 12-07-2021 23:09:18 ===start stop voice wan

DST=142.250.185.99 PROTO=TCP SPT=60546 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=142.250.185.99 PROTO=TCP SPT=60546 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=142.250.185.99 PROTO=TCP SPT=60546 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=142.250.185.99 PROTO=TCP SPT=60546 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=49474 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=49474 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.210.4.61 PROTO=TCP SPT=41044 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=49474 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=49474 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=49474 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=49474 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=49474 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=49474 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=74.125.110.42 PROTO=TCP SPT=49474 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.210.4.61 PROTO=TCP SPT=41044 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.210.4.61 PROTO=TCP SPT=41044 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.210.4.61 PROTO=TCP SPT=41044 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.210.4.61 PROTO=TCP SPT=41044 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.210.4.61 PROTO=TCP SPT=41044 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.210.4.61 PROTO=TCP SPT=41044 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.210.4.61 PROTO=TCP SPT=41044 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.210.4.61 PROTO=TCP SPT=41044 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.210.4.61 PROTO=TCP SPT=41044 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.210.4.61 PROTO=TCP SPT=41044 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.210.4.61 PROTO=TCP SPT=41044 DPT=80 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 23:04:42 SRC=192.168.2.102
DST=52.16.169.139 PROTO=TCP SPT=34528 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-07-2021 22:49:44 wlo: AP-STA-DISCONNECTED
10:94:bb:d5:73:92
[WARNING][Firewall] 12-07-2021 22:49:44 SRC=192.168.2.105
DST=142.250.184.234 PROTO=TCP SPT=59020 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-07-2021 22:49:39 wlo: AP-STA-CONNECTED

10:94:bb:d5:73:92
[NOTICE][LAN] 12-07-2021 22:36:06 wl0: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[NOTICE][LAN] 12-07-2021 22:35:34 wl1: AP-STA-DISCONNECTED
6a:78:d9:7b:3e:cd
[WARNING][Firewall] 12-07-2021 22:35:34 SRC=192.168.2.103
DST=17.253.36.119 PROTO=TCP SPT=59065 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 22:35:34 SRC=192.168.2.103
DST=17.253.36.119 PROTO=TCP SPT=59065 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 22:35:34 SRC=192.168.2.103
DST=17.253.36.119 PROTO=TCP SPT=59065 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 22:35:34 SRC=192.168.2.103
DST=17.253.36.119 PROTO=TCP SPT=59065 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 22:35:34 SRC=192.168.2.103
DST=17.253.36.119 PROTO=TCP SPT=59065 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 22:35:34 SRC=192.168.2.103
DST=17.253.36.119 PROTO=TCP SPT=59065 DPT=443 MARK=0x3 DROP
[WARNING][Firewall] 12-07-2021 22:35:34 SRC=192.168.2.103
DST=17.253.36.119 PROTO=TCP SPT=59065 DPT=443 MARK=0x3 DROP
[NOTICE][LAN] 12-07-2021 22:25:52 ACS-D: Timestamp(ms):1638915953
ACS-Trigger:TXDLY Selected Channel:#10 (0x100a)
[EMERG][LAN] 12-07-2021 22:25:52 WIFI 2.4G Channel has been changed
from channel 7 to 10.
[NOTICE][LAN] 12-07-2021 22:25:51 ACS-D: Timestamp(ms):1638915952
ACS-Trigger:TXDLY Selected Channel:#10 (0x100a)
[INFO][LAN] 12-07-2021 22:25:24 Successfully assign IP
[192.168.2.104] to client mac [0e:d3:bc:3c:3b:3d], lease time
[86400]
[INFO][LAN] 12-07-2021 22:25:24 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:25:24 server_id = c0a80201
[INFO][LAN] 12-07-2021 22:25:24 Received REQUEST from client ip
[0.0.0.0] mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-07-2021 22:25:24 Received a packet
[INFO][LAN] 12-07-2021 22:25:23 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:25:23 Send OFFER of ip [192.168.2.104] to
client mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-07-2021 22:25:23 Find a lease info, and use the
ip:6802a8c0
[INFO][LAN] 12-07-2021 22:25:23 Received DISCOVER from client mac
[0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-07-2021 22:25:23 Received a packet
[INFO][LAN] 12-07-2021 22:25:23 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:25:23 Send OFFER of ip [192.168.2.104] to
client mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-07-2021 22:25:23 Find a lease info, and use the
ip:6802a8c0
[INFO][LAN] 12-07-2021 22:25:23 No valid arp replies for this
address
[INFO][LAN] 12-07-2021 22:25:21 Received DISCOVER from client mac
[0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-07-2021 22:25:21 Received a packet
[NOTICE][LAN] 12-07-2021 22:25:21 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[WARNING][Firewall] 12-07-2021 22:25:21 SRC=192.168.2.100

DST=93.184.220.66 PROTO=TCP SPT=49835 DPT=443 MARK=0x3 DROP
[INFO][VoIP] 12-07-2021 22:21:59 Switch to primary proxy server
arcor.de on line 0
[INFO][System] 12-07-2021 22:21:24 Sync up with NTP Server
successfully.
[INFO][System] 12-07-2021 22:21:22 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 22:21:21 Sync up with NTP Server
successfully.
[INFO][LAN] 12-07-2021 22:21:17 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:21:17 Send OFFER of ip [192.168.2.104] to
client mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-07-2021 22:21:17 Find a lease info, and use the
ip:6802a8c0
[INFO][LAN] 12-07-2021 22:21:17 No valid arp replies for this
address
[NOTICE][LAN] 12-07-2021 22:21:17 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[ERROR][System] 12-07-2021 22:21:16 TR069 connects to ACS server
failed, http error 503.
[INFO][LAN] 12-07-2021 22:21:15 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:21:15 Received DISCOVER from client mac
[0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-07-2021 22:21:15 Received a packet
[NOTICE][LAN] 12-07-2021 22:21:15 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[INFO][System] 12-07-2021 22:21:15 No permission to get
wps20_enable, access right: 0x08.
[INFO][VoIP] 12-07-2021 22:21:14 Send data/single wan update to
VGW,wan id 10,ifName is ppp10,ipv4 address 188.98.17.104,ipv6
address ,default_wan_id 10,wan type 1
[INFO][VoIP] 12-07-2021 22:21:14 line 371 ,wan 10 start do data wan
up
[INFO][VoIP] 12-07-2021 22:21:14 wanipv6 = ,size = 0
[INFO][VoIP] 12-07-2021 22:21:14 Voice binding wan_id is
10,default_wan_id is 10
[INFO][VoIP] 12-07-2021 22:21:14 Voice binding wan_id is
10,default_wan_id is 10,is_ipv6 = 0
[INFO][VoIP] 12-07-2021 22:21:14 wan 10 service_type =
DATA,VOIP,MGNT,IPTV bud_voip_wan_id = 10
[INFO][VoIP] 12-07-2021 22:21:14 Interface wan_ip is 188.98.17.104,
wan_ip_v6 ,is_ipv6 0 wan up id 10
[INFO][LAN] 12-07-2021 22:21:13 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO][LAN] 12-07-2021 22:21:13 adapter index 19
[INFO][LAN] 12-07-2021 22:21:13 br1 (our ip) = 192.168.3.1
[INFO][LAN] 12-07-2021 22:21:13 Attaching option timezone to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option t2 to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option t1 to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option lease to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option dns to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option router to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option subnet to list
[INFO][LAN] 12-07-2021 22:21:13 error on select
[INFO][LAN] 12-07-2021 22:21:13 udhcp server receive signal 12

```
[INFO][LAN] 12-07-2021 22:21:13 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-07-2021 22:21:13 adapter index 18
[INFO][LAN] 12-07-2021 22:21:13 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-07-2021 22:21:13 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO][LAN] 12-07-2021 22:21:13 adapter index 18
[INFO][LAN] 12-07-2021 22:21:13 br0 (our ip) = 192.168.2.1
[INFO][LAN] 12-07-2021 22:21:13 Attaching option timezone to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option t2 to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option t1 to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option lease to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option dns to existing
member of list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option dns to existing
member of list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option dns to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option router to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option subnet to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option timezone to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option t2 to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option t1 to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option lease to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option dns to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option hostname to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option domain to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option router to list
[INFO][LAN] 12-07-2021 22:21:13 Attaching option subnet to list
[INFO][LAN] 12-07-2021 22:21:13 error on select
[INFO][LAN] 12-07-2021 22:21:13 udhcp server receive signal 12
[INFO][System] 12-07-2021 22:21:12 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 22:21:12 Starting MCPD OK.
[INFO][System] 12-07-2021 22:21:12 Stopping MCPD OK.
[INFO][UMTS] 12-07-2021 22:21:12 iPhone DNS Policy actived
[INFO][VoIP] 12-07-2021 22:21:12 276 start wan service Voice
binding wan_id is 10
[INFO][VoIP] 12-07-2021 22:21:12 Voice binding wan_id is 10
[INFO][System] 12-07-2021 22:21:12 Starting NTP Client OK.
[INFO][System] 12-07-2021 22:21:11 Sync up with NTP Server failed.
[INFO][System] 12-07-2021 22:21:11 Stopping NTP Client OK.
[INFO][Firewall] 12-07-2021 22:21:11 PortMapping Rules have been
flushed on WAN VDSL-DT.
[INFO][Firewall] 12-07-2021 22:21:11 DMZ Rules has been flushed on
WAN VDSL-DT.
[INFO][Firewall] 12-07-2021 22:21:10 Static NAT Rules have been
flushed on WAN VDSL-DT.
[INFO][System] 12-07-2021 22:21:10 Stopping HTTP redirect OK.
[INFO][DNS] 12-07-2021 22:21:10 DNSMasq proxy server disable
redirect
[INFO][DNS] 12-07-2021 22:21:10 Internet DNS Servers 176.95.16.250,
176.95.16.251.
[INFO][DNS] 12-07-2021 22:21:10 Internet DNS ready.
[INFO][DNS] 12-07-2021 22:21:10 Internet DNS Servers 176.95.16.250,
176.95.16.251.
```

[INFO][DNS] 12-07-2021 22:21:10 Internet DNS ready.
[WARNING][DNS] 12-07-2021 22:21:10 ignoring nameserver 127.0.0.1 - local interface
[WARNING][DNS] 12-07-2021 22:21:10 ignoring nameserver ::1 - local interface
[INFO][DNS] 12-07-2021 22:21:10 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-07-2021 22:21:10 Internet DNS ready.
[INFO][DNS] 12-07-2021 22:21:10 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-07-2021 22:21:10 Internet DNS ready.
[INFO][DNS] 12-07-2021 22:21:10 Starting DNSMasq proxy server OK.
[INFO][DNS] 12-07-2021 22:21:10 Stopping DNSMasq proxy OK.
[INFO][LAN] 12-07-2021 22:21:09 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:21:09 LAN sending RA to ff02::1
[INFO][DNS] 12-07-2021 22:21:09 DNSMasq proxy server disable redirect
[INFO][System] 12-07-2021 22:21:08 FSM---- Switch to Connect State.
[INFO][UMTS] 12-07-2021 22:21:08 iPhone DNS Policy actived
[INFO][VoIP] 12-07-2021 22:21:08 ignore useless wan down
[INFO][VoIP] 12-07-2021 22:21:08 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 8, is_ipv6 = 0, default_wan_id= 10
[INFO][VoIP] 12-07-2021 22:21:08 ===start stop voice wan
[INFO][VoIP] 12-07-2021 22:21:08 Remove interface wan_id is 10, wan type 2.
[INFO][VoIP] 12-07-2021 22:21:08 VoIP WAN down, Voice trying to run in backup mode, try binding wan_id is 10
[INFO][VoIP] 12-07-2021 22:21:08 bud data ipv4 wan status 10, ipv6 wan status -1
[INFO][VoIP] 12-07-2021 22:21:08 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 10, is_ipv6 = 0, default_wan_id= 10
[INFO][VoIP] 12-07-2021 22:21:08 ===start stop voice wan
[INFO][System] 12-07-2021 22:21:08 Starting MCPD OK.
[INFO][System] 12-07-2021 22:21:07 Stopping MCPD OK.
[INFO][VoIP] 12-07-2021 22:21:07 ignore useless wan down
[INFO][VoIP] 12-07-2021 22:21:07 Voice binding wan_id is 10, binding_1 wan_id = 10, stop wan_id is 8, is_ipv6 = 1, default_wan_id= 10
[INFO][VoIP] 12-07-2021 22:21:07 ===start stop voice wan
[INFO][WAN] 12-07-2021 22:21:07 Stop WAN 8 IP Connection
[INFO][DNS] 12-07-2021 22:21:06 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-07-2021 22:21:06 Internet DNS ready.
[INFO][DNS] 12-07-2021 22:21:06 Internet DNS Servers 176.95.16.250, 176.95.16.251.
[INFO][DNS] 12-07-2021 22:21:06 Internet DNS ready.
[INFO][DNS] 12-07-2021 22:21:06 Internet DNS deactivated.
[WARNING][WAN] 12-07-2021 22:21:06 WAN default route add to ppp10 gateway 84.59.211.1.
[INFO][WAN] 12-07-2021 22:21:06 Data WAN11 Activated!
[INFO][WAN] 12-07-2021 22:21:06 bud update WAN11 status to 2.
[WARNING][WAN] 12-07-2021 22:21:06 WAN VDSL-DT is up, mode is PPPoE,

IP is 188.98.17.104.

```
[WARNING][WAN] 12-07-2021 22:21:06 WAN VDSL-DT is down.
[INFO][LAN] 12-07-2021 22:21:06 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 22:21:06 PPP CHAP MD5 authentication is
successful on WAN VDSL-DT
[INFO][LAN] 12-07-2021 22:21:06 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:21:06 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:21:06 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 22:21:06 PPPoE PADS has been received from
WAN VDSL-DT
[INFO][WAN] 12-07-2021 22:21:06 PPPoE PADR has been sent from WAN
VDSL-DT
[INFO][WAN] 12-07-2021 22:21:06 PPPoE PADO has been received from
WAN VDSL-DT, BRAS name is BLNCOS69101.
[INFO][WAN] 12-07-2021 22:21:06 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-07-2021 22:21:06 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-07-2021 22:20:59 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 22:20:48 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 22:20:38 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 22:20:27 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 22:20:18 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 22:20:09 FSM---- Switch to Connect State.
[INFO][WAN] 12-07-2021 22:20:00 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-07-2021 22:20:00 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-07-2021 22:20:00 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 22:19:51 FSM---- Switch to Connect State.
[INFO][WAN] 12-07-2021 22:19:43 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-07-2021 22:19:43 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-07-2021 22:19:41 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 22:19:30 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 22:19:21 FSM---- Switch to Connect State.
[INFO][System] 12-07-2021 22:19:10 FSM---- Switch to Connect State.
[EMERG][WAN] 12-07-2021 22:19:09 DSL link up.
[EMERG][WAN] 12-07-2021 22:19:08 DSL link up.
[EMERG][WAN] 12-07-2021 22:19:07 DSL link up.
[EMERG][WAN] 12-07-2021 22:19:05 DSL link up.
[EMERG][WAN] 12-07-2021 22:19:04 DSL link up.
[EMERG][WAN] 12-07-2021 22:19:03 DSL link up.
[EMERG][WAN] 12-07-2021 22:19:02 DSL link up.
[INFO][System] 12-07-2021 22:19:01 FSM---- Switch to Connect State.
[EMERG][WAN] 12-07-2021 22:19:00 DSL link up.
[EMERG][WAN] 12-07-2021 22:18:59 DSL link up.
[EMERG][WAN] 12-07-2021 22:18:58 DSL link up.
[EMERG][WAN] 12-07-2021 22:18:56 DSL link up.
[EMERG][WAN] 12-07-2021 22:18:55 DSL link up.
[INFO][System] 12-07-2021 22:18:52 FSM---- Switch to Connect State.
[INFO][WAN] 12-07-2021 22:18:47 PPPoE PADI has been sent from WAN
VDSL-DATA
```

[INFO][WAN] 12-07-2021 22:18:47 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][System] 12-07-2021 22:18:47 User 'vodafone' login
successfully via HTTP from 192.168.2.100
[NOTICE][LAN] 12-07-2021 22:18:45 wl0: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[NOTICE][LAN] 12-07-2021 22:18:45 wl1: AP-STA-DISCONNECTED
bc:a5:8b:27:2d:ac
[INFO][System] 12-07-2021 22:18:43 FSM---- Switch to Connect State.
[INFO][LAN] 12-07-2021 22:18:41 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:38 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:37 Successfully assign IP
[192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time
[86400]
[INFO][LAN] 12-07-2021 22:18:37 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:18:37 Received REQUEST from client ip
[0.0.0.0] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-07-2021 22:18:37 Received a packet
[INFO][LAN] 12-07-2021 22:18:37 Successfully assign IP
[192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time
[86400]
[INFO][LAN] 12-07-2021 22:18:36 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:18:36 Received REQUEST from client ip
[0.0.0.0] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-07-2021 22:18:36 Received a packet
[NOTICE][LAN] 12-07-2021 22:18:36 wl0: AP-STA-CONNECTED
50:ed:3c:2f:b6:42
[INFO][LAN] 12-07-2021 22:18:35 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:35 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 22:18:34 PPPoE PADI has been sent from WAN
VDSL-DATA
[INFO][WAN] 12-07-2021 22:18:34 PPPoE PADI has been sent from WAN
VDSL-DT
[INFO][LAN] 12-07-2021 22:18:34 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:34 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:34 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:34 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:34 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:34 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 22:18:34 Start WAN 10 IP Connection
[INFO][WAN] 12-07-2021 22:18:34 WAN VDSL-DT has been started, PHY
link up
[INFO][LAN] 12-07-2021 22:18:34 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 22:18:34 Start WAN 8 IP Connection
[INFO][WAN] 12-07-2021 22:18:34 WAN VDSL-DATA has been started, PHY
link up
[INFO][System] 12-07-2021 22:18:33 FSM---- Switch to Connect State.
[INFO][WAN] 12-07-2021 22:18:33 Start WAN 4 DSL Connection
[INFO][LAN] 12-07-2021 22:18:33 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:33 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:33 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 22:18:33 Starting VDSL interface OK.
[INFO][WAN] 12-07-2021 22:18:33 Start WAN 8 DSL Connection
[INFO][LAN] 12-07-2021 22:18:32 LAN sending RA to ff02::1

```
[INFO][LAN] 12-07-2021 22:18:32 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:32 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 22:18:32 Start WAN 10 DSL Connection
[INFO][LAN] 12-07-2021 22:18:32 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:32 LAN sending RA to ff02::1
[EMERG][WAN] 12-07-2021 22:18:32 DSL link up.
[NOTICE][LAN] 12-07-2021 22:18:19 wl1: AP-STA-DISCONNECTED
50:ed:3c:2f:b6:42
[INFO][LAN] 12-07-2021 22:18:18 Successfully assign IP
[192.168.2.100] to client mac [50:ed:3c:2f:b6:42], lease time
[86400]
[INFO][LAN] 12-07-2021 22:18:18 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:18:18 No valid arp replies for this
address
[INFO][LAN] 12-07-2021 22:18:18 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-07-2021 22:18:18 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:18 Received REQUEST from client ip
[0.0.0.0] mac [50:ed:3c:2f:b6:42]
[INFO][LAN] 12-07-2021 22:18:18 Received a packet
[NOTICE][LAN] 12-07-2021 22:18:18 wl1: AP-STA-CONNECTED
50:ed:3c:2f:b6:42
[INFO][LAN] 12-07-2021 22:18:06 Successfully assign IP
[192.168.2.102] to client mac [bc:a5:8b:27:2d:ac], lease time
[86400]
[INFO][LAN] 12-07-2021 22:18:06 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:18:06 server_id = c0a80201
[INFO][LAN] 12-07-2021 22:18:06 Received REQUEST from client ip
[0.0.0.0] mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 22:18:06 Received a packet
[INFO][LAN] 12-07-2021 22:18:06 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:18:06 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 22:18:06 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-07-2021 22:18:06 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 22:18:06 Received a packet
[INFO][LAN] 12-07-2021 22:18:06 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:18:06 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 22:18:06 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-07-2021 22:18:06 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 22:18:06 Received a packet
[INFO][LAN] 12-07-2021 22:18:06 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:18:06 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 22:18:06 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-07-2021 22:18:06 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 22:18:06 Received a packet
```


[INFO][LAN] 12-07-2021 22:18:06 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:18:06 Send OFFER of ip [192.168.2.102] to
client mac [bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 22:18:06 Find a lease info, and use the
ip:6602a8c0
[INFO][LAN] 12-07-2021 22:18:06 No valid arp replies for this
address
[INFO][LAN] 12-07-2021 22:18:05 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:18:04 Received DISCOVER from client mac
[bc:a5:8b:27:2d:ac]
[INFO][LAN] 12-07-2021 22:18:04 Received a packet
[NOTICE][LAN] 12-07-2021 22:18:04 wl1: AP-STA-CONNECTED
bc:a5:8b:27:2d:ac
[INFO][LAN] 12-07-2021 22:17:59 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:17:44 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:17:44 Send OFFER of ip [192.168.2.104] to
client mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-07-2021 22:17:44 Find a lease info, and use the
ip:6802a8c0
[INFO][LAN] 12-07-2021 22:17:44 Received DISCOVER from client mac
[0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-07-2021 22:17:44 Received a packet
[INFO][LAN] 12-07-2021 22:17:44 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:17:44 Send OFFER of ip [192.168.2.104] to
client mac [0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-07-2021 22:17:44 Find a lease info, and use the
ip:6802a8c0
[INFO][LAN] 12-07-2021 22:17:44 No valid arp replies for this
address
[NOTICE][LAN] 12-07-2021 22:17:44 wl1: AP-STA-DISCONNECTED
0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-07-2021 22:17:43 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:17:42 Received DISCOVER from client mac
[0e:d3:bc:3c:3b:3d]
[INFO][LAN] 12-07-2021 22:17:42 Received a packet
[NOTICE][LAN] 12-07-2021 22:17:42 wl1: AP-STA-CONNECTED
0e:d3:bc:3c:3b:3d
[INFO][LAN] 12-07-2021 22:17:39 Successfully assign IP
[192.168.2.103] to client mac [6a:78:d9:7b:3e:cd], lease time
[86400]
[INFO][LAN] 12-07-2021 22:17:39 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:17:39 No valid arp replies for this
address
[INFO][LAN] 12-07-2021 22:17:39 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-07-2021 22:17:39 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:17:39 Received REQUEST from client ip
[0.0.0.0] mac [6a:78:d9:7b:3e:cd]
[INFO][LAN] 12-07-2021 22:17:39 Received a packet
[NOTICE][LAN] 12-07-2021 22:17:39 wl1: AP-STA-CONNECTED
6a:78:d9:7b:3e:cd
[INFO][LAN] 12-07-2021 22:17:35 Successfully assign IP
[192.168.2.101] to client mac [68:2f:67:8a:e3:07], lease time
[86400]

```
[INFO][LAN] 12-07-2021 22:17:35 unicasting packet to client yiaddr
[INFO][LAN] 12-07-2021 22:17:35 No valid arp replies for this
address
[INFO][LAN] 12-07-2021 22:17:35 Arp reply received from the
requesting device itself.
[INFO][LAN] 12-07-2021 22:17:35 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:17:35 Received REQUEST from client ip
[0.0.0.0] mac [68:2f:67:8a:e3:07]
[INFO][LAN] 12-07-2021 22:17:35 Received a packet
[NOTICE][LAN] 12-07-2021 22:17:35 wl1: AP-STA-CONNECTED
68:2f:67:8a:e3:07
[INFO][LAN] 12-07-2021 22:17:30 LAN sending RA to ff02::1
[EMERG][LAN] 12-07-2021 22:17:27 WIFI 2.4G Channel has been changed
from channel 1 to 7.
[NOTICE][LAN] 12-07-2021 22:17:26 ACS-D: Timestamp(ms):1619555734
ACS-Trigger:INIT Selected Channel:#7 (0x1007)
[EMERG][LAN] 12-07-2021 22:17:23 WIFI 5G Channel has been changed
from channel 36 to 100.
[EMERG][LAN] 12-07-2021 22:17:23 WIFI 5G band width has been changed
to 80M.
[NOTICE][LAN] 12-07-2021 22:17:22 ACS-D: Timestamp(ms):1619555729
ACS-Trigger:INIT Selected Channel:#100/80 (0xe06a)
[INFO][VoIP] 12-07-2021 22:17:17 VoIP service running at Apr 27
20:35:25 2021
[INFO][VoIP] 12-07-2021 22:17:17 VoIP call manager
v02.01.00_01.10a.2021-04-27,20:04
[INFO][VoIP] 12-07-2021 22:17:17 Starting VoIP OK.
[NOTICE][LAN] 12-07-2021 22:17:16 ACS-D: acsd start...
[INFO][LAN] 12-07-2021 22:17:14 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:17:14 LAN sending RA to ff02::1
[NOTICE][LAN] 12-07-2021 22:17:14 wl1: AP-ENABLED
[NOTICE][LAN] 12-07-2021 22:17:14 wl1: interface state
COUNTRY_UPDATE->ENABLED
[ERROR][LAN] 12-07-2021 22:17:14 Using interface wl1 with hwaddr
d0:b6:6f:6d:11:11 and ssid "Vodafone-438213"
[NOTICE][LAN] 12-07-2021 22:17:14 wl1: interface state
UNINITIALIZED->COUNTRY_UPDATE
[NOTICE][LAN] 12-07-2021 22:17:14 rfkill: Cannot open RFKILL control
device
[ERROR][LAN] 12-07-2021 22:17:14 Configuration file: /tmp/
wl1_hapd.conf
[INFO][VoIP] 12-07-2021 22:17:13 VoIP Starting ...
[INFO][VoIP] 12-07-2021 22:17:13 Ringing schedule conf file is
empty!
[INFO][VoIP] 12-07-2021 22:17:13 FXS_Number=*1
[INFO][VoIP] 12-07-2021 22:17:13 ReadGlobalSipConf ret=-2
[INFO][VoIP] 12-07-2021 22:17:13 Info Center Config Init...
[INFO][LAN] 12-07-2021 22:17:12 LAN sending RA to ff02::1
[NOTICE][LAN] 12-07-2021 22:17:12 wl0: AP-ENABLED
[NOTICE][LAN] 12-07-2021 22:17:12 wl0: interface state
COUNTRY_UPDATE->ENABLED
[INFO][LAN] 12-07-2021 22:17:12 LAN sending RA to ff02::1
[ERROR][LAN] 12-07-2021 22:17:11 Using interface wl0 with hwaddr
d0:b6:6f:6d:11:10 and ssid "Vodafone-438213"
```



```
[INFO][LAN] 12-07-2021 22:17:07 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:17:07 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:17:07 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:17:07 LAN sending RA to ff02::1
[INFO][LAN] 12-07-2021 22:17:07 LAN sending RA to ff02::1
[INFO][WAN] 12-07-2021 22:17:07 Stop WAN 13 IP Connection
[INFO][WAN] 12-07-2021 22:17:07 WAN 4 Triggers Switching Partner To
Stop Success
[INFO][VoIP] 12-07-2021 22:17:06 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:06 ignore useless wan down
[INFO][VoIP] 12-07-2021 22:17:06 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 6,is_ipv6 =
0,default_wan_id= -1
[INFO][VoIP] 12-07-2021 22:17:06 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:06 ===start stop voice wan
[INFO][VoIP] 12-07-2021 22:17:06 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:06 ignore useless wan down
[INFO][VoIP] 12-07-2021 22:17:06 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 6,is_ipv6 =
1,default_wan_id= -1
[INFO][VoIP] 12-07-2021 22:17:06 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:06 ===start stop voice wan
[INFO][WAN] 12-07-2021 22:17:06 Stop WAN 6 IP Connection
[INFO][VoIP] 12-07-2021 22:17:06 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:06 ignore useless wan down
[INFO][VoIP] 12-07-2021 22:17:06 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 7,is_ipv6 =
0,default_wan_id= -1
[INFO][VoIP] 12-07-2021 22:17:06 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:06 ===start stop voice wan
[INFO][VoIP] 12-07-2021 22:17:05 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:05 ignore useless wan down
[INFO][VoIP] 12-07-2021 22:17:05 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 7,is_ipv6 =
1,default_wan_id= -1
[INFO][VoIP] 12-07-2021 22:17:05 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:05 ===start stop voice wan
[INFO][WAN] 12-07-2021 22:17:05 Stop WAN 7 IP Connection
[INFO][VoIP] 12-07-2021 22:17:05 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:05 ignore useless wan down
[INFO][VoIP] 12-07-2021 22:17:05 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 11,is_ipv6 =
0,default_wan_id= -1
[INFO][VoIP] 12-07-2021 22:17:05 cal_voip_get_binding_interface_id
line 4385 wan id -1
```

```
[INFO][VoIP] 12-07-2021 22:17:05 ===start stop voice wan
[INFO][VoIP] 12-07-2021 22:17:04 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:04 ignore useless wan down
[INFO][VoIP] 12-07-2021 22:17:04 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 11,is_ipv6 =
1,default_wan_id= -1
[INFO][VoIP] 12-07-2021 22:17:04 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:04 ===start stop voice wan
[INFO][WAN] 12-07-2021 22:17:04 bud update WAN9 status to 0.
[INFO][WAN] 12-07-2021 22:17:04 Stop WAN 11 IP Connection
[INFO][VoIP] 12-07-2021 22:17:04 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:04 ignore useless wan down
[INFO][VoIP] 12-07-2021 22:17:04 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 9,is_ipv6 =
0,default_wan_id= -1
[INFO][VoIP] 12-07-2021 22:17:04 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:04 ===start stop voice wan
[INFO][VoIP] 12-07-2021 22:17:03 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:03 ignore useless wan down
[INFO][VoIP] 12-07-2021 22:17:03 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 9,is_ipv6 =
1,default_wan_id= -1
[INFO][VoIP] 12-07-2021 22:17:03 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:03 ===start stop voice wan
[INFO][WAN] 12-07-2021 22:17:03 Stop WAN 9 IP Connection
[INFO][WAN] 12-07-2021 22:17:03 bud update WAN11 status to 0.
[INFO][WAN] 12-07-2021 22:17:03 bud update WAN4 status to 0.
[INFO][WAN] 12-07-2021 22:17:02 bud update WAN1 status to 0.
[INFO][VoIP] 12-07-2021 22:17:02 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:02 ignore useless wan down
[INFO][VoIP] 12-07-2021 22:17:02 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 1,is_ipv6 =
0,default_wan_id= -1
[INFO][VoIP] 12-07-2021 22:17:02 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:02 ===start stop voice wan
[INFO][VoIP] 12-07-2021 22:17:02 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:02 ignore useless wan down
[INFO][VoIP] 12-07-2021 22:17:02 Voice binding wan_id is
10,binding_1 wan_id = 10,stop wan_id is 1,is_ipv6 =
1,default_wan_id= -1
[INFO][VoIP] 12-07-2021 22:17:02 cal_voip_get_binding_interface_id
line 4385 wan id -1
[INFO][VoIP] 12-07-2021 22:17:02 ===start stop voice wan
[INFO][WAN] 12-07-2021 22:17:01 Stop WAN 1 IP Connection
[INFO][System] 12-07-2021 22:17:00 Starting MCPD OK.
```

```
[INFO] [LAN] 12-07-2021 22:16:57 adapter hardware address
d0:b6:6f:6d:11:1f
[INFO] [LAN] 12-07-2021 22:16:57 adapter index 19
[INFO] [LAN] 12-07-2021 22:16:57 br1 (our ip) = 192.168.3.1
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option timezone to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option t2 to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option t1 to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option lease to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option dns to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option router to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option subnet to list
[INFO] [LAN] 12-07-2021 22:16:57 error on select
[INFO] [LAN] 12-07-2021 22:16:57 udhcp server receive signal 12
[INFO] [LAN] 12-07-2021 22:16:57 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO] [LAN] 12-07-2021 22:16:57 adapter index 18
[INFO] [LAN] 12-07-2021 22:16:57 br0 (our ip) = 192.168.2.1
[INFO] [LAN] 12-07-2021 22:16:57 adapter hardware address
d0:b6:6f:6d:11:0f
[INFO] [LAN] 12-07-2021 22:16:57 adapter index 18
[INFO] [LAN] 12-07-2021 22:16:57 br0 (our ip) = 192.168.2.1
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option timezone to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option t2 to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option t1 to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option lease to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option dns to existing
member of list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option dns to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option router to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option subnet to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option timezone to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option t2 to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option t1 to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option lease to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option dns to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option hostname to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option domain to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option router to list
[INFO] [LAN] 12-07-2021 22:16:57 Attaching option subnet to list
[INFO] [LAN] 12-07-2021 22:16:57 error on select
[INFO] [LAN] 12-07-2021 22:16:57 udhcp server receive signal 12
[INFO] [System] 12-07-2021 22:16:54 Starting HTTP redirect OK.
[INFO] [DNS] 12-07-2021 22:16:54 DNSMasq proxy server enable redirect
[INFO] [System] 12-07-2021 22:16:54 Starting HTTP OK.
[INFO] [Firewall] 12-07-2021 22:16:51 Local Fragment Flood detect has
been enabled on WAN ADSL-DATA.
[INFO] [Firewall] 12-07-2021 22:16:51 Local Smurf Detect has been
enabled on WAN ADSL-DATA.
[INFO] [Firewall] 12-07-2021 22:16:51 Local Winnuke Detect has been
enabled on WAN ADSL-DATA.
[INFO] [Firewall] 12-07-2021 22:16:51 Local TCP FIN Flood Detect has
been enabled on WAN ADSL-DATA.
[INFO] [Firewall] 12-07-2021 22:16:51 Local TCP SYN Flood Detect has
been enabled on WAN ADSL-DATA.
```

[INFO][Firewall] 12-07-2021 22:16:51 Local ICMP Flood Detect has been enabled on WAN ADSL-DATA.
[INFO][Firewall] 12-07-2021 22:16:51 Forward UDP Flood Detect has been enabled on WAN ADSL-DATA.
[INFO][Firewall] 12-07-2021 22:16:51 Local UDP Flood Detect has been enabled on WAN ADSL-DATA.
[INFO][Firewall] 12-07-2021 22:16:49 Local Fragment Flood detect has been enabled on WAN ADSL-DT.
[INFO][Firewall] 12-07-2021 22:16:49 Local Smurf Detect has been enabled on WAN ADSL-DT.
[INFO][Firewall] 12-07-2021 22:16:49 Local Winnuke Detect has been enabled on WAN ADSL-DT.
[INFO][Firewall] 12-07-2021 22:16:49 Local TCP FIN Flood Detect has been enabled on WAN ADSL-DT.
[INFO][Firewall] 12-07-2021 22:16:49 Local TCP SYN Flood Detect has been enabled on WAN ADSL-DT.
[INFO][Firewall] 12-07-2021 22:16:49 Local ICMP Flood Detect has been enabled on WAN ADSL-DT.
[INFO][Firewall] 12-07-2021 22:16:49 Forward UDP Flood Detect has been enabled on WAN ADSL-DT.
[INFO][Firewall] 12-07-2021 22:16:49 Local UDP Flood Detect has been enabled on WAN ADSL-DT.
[INFO][Firewall] 12-07-2021 22:16:46 Local Fragment Flood detect has been enabled on WAN VDSL-DATA.
[INFO][Firewall] 12-07-2021 22:16:46 Local Smurf Detect has been enabled on WAN VDSL-DATA.
[INFO][Firewall] 12-07-2021 22:16:46 Local Winnuke Detect has been enabled on WAN VDSL-DATA.
[INFO][Firewall] 12-07-2021 22:16:46 Local TCP FIN Flood Detect has been enabled on WAN VDSL-DATA.
[INFO][Firewall] 12-07-2021 22:16:46 Local TCP SYN Flood Detect has been enabled on WAN VDSL-DATA.
[INFO][Firewall] 12-07-2021 22:16:46 Local ICMP Flood Detect has been enabled on WAN VDSL-DATA.
[INFO][Firewall] 12-07-2021 22:16:46 Forward UDP Flood Detect has been enabled on WAN VDSL-DATA.
[INFO][Firewall] 12-07-2021 22:16:46 Local UDP Flood Detect has been enabled on WAN VDSL-DATA.
[EMERG][WAN] 12-07-2021 22:16:46 DSL link down.
[INFO][Firewall] 12-07-2021 22:16:44 Local Fragment Flood detect has been enabled on WAN VDSL-DT.
[INFO][Firewall] 12-07-2021 22:16:44 Local Smurf Detect has been enabled on WAN VDSL-DT.
[INFO][Firewall] 12-07-2021 22:16:44 Local Winnuke Detect has been enabled on WAN VDSL-DT.
[INFO][Firewall] 12-07-2021 22:16:44 Local TCP FIN Flood Detect has been enabled on WAN VDSL-DT.
[INFO][Firewall] 12-07-2021 22:16:44 Local TCP SYN Flood Detect has been enabled on WAN VDSL-DT.
[INFO][Firewall] 12-07-2021 22:16:44 Local ICMP Flood Detect has been enabled on WAN VDSL-DT.
[INFO][Firewall] 12-07-2021 22:16:44 Forward UDP Flood Detect has been enabled on WAN VDSL-DT.
[INFO][Firewall] 12-07-2021 22:16:44 Local UDP Flood Detect has been

enabled on WAN VDSL-DT.
[INFO][Firewall] 12-07-2021 22:16:43 Local Fragment Flood detect has been enabled on WAN FTTH-IPTV.
[INFO][Firewall] 12-07-2021 22:16:43 Local Smurf Detect has been enabled on WAN FTTH-IPTV.
[INFO][Firewall] 12-07-2021 22:16:43 Local Winnuke Detect has been enabled on WAN FTTH-IPTV.
[INFO][Firewall] 12-07-2021 22:16:43 Local TCP FIN Flood Detect has been enabled on WAN FTTH-IPTV.
[INFO][Firewall] 12-07-2021 22:16:43 Local TCP SYN Flood Detect has been enabled on WAN FTTH-IPTV.
[INFO][Firewall] 12-07-2021 22:16:43 Local ICMP Flood Detect has been enabled on WAN FTTH-IPTV.
[INFO][Firewall] 12-07-2021 22:16:43 Forward UDP Flood Detect has been enabled on WAN FTTH-IPTV.
[INFO][Firewall] 12-07-2021 22:16:43 Local UDP Flood Detect has been enabled on WAN FTTH-IPTV.
[INFO][Firewall] 12-07-2021 22:16:41 Local Fragment Flood detect has been enabled on WAN FTTH-DATA.
[INFO][Firewall] 12-07-2021 22:16:41 Local Smurf Detect has been enabled on WAN FTTH-DATA.
[INFO][Firewall] 12-07-2021 22:16:41 Local Winnuke Detect has been enabled on WAN FTTH-DATA.
[INFO][Firewall] 12-07-2021 22:16:41 Local TCP FIN Flood Detect has been enabled on WAN FTTH-DATA.
[INFO][Firewall] 12-07-2021 22:16:41 Local TCP SYN Flood Detect has been enabled on WAN FTTH-DATA.
[INFO][Firewall] 12-07-2021 22:16:41 Local ICMP Flood Detect has been enabled on WAN FTTH-DATA.
[INFO][Firewall] 12-07-2021 22:16:41 Forward UDP Flood Detect has been enabled on WAN FTTH-DATA.
[INFO][Firewall] 12-07-2021 22:16:41 Local UDP Flood Detect has been enabled on WAN FTTH-DATA.
[INFO][Firewall] 12-07-2021 22:16:40 Local Frament Flood Detect has been enabled on LAN.
[INFO][Firewall] 12-07-2021 22:16:40 Local Smurf Detect has been enabled on LAN.
[INFO][Firewall] 12-07-2021 22:16:40 Local LAN Source Detect has been enabled.
[INFO][Firewall] 12-07-2021 22:16:40 Local Winnuke Detect has been enabled on LAN.
[INFO][Firewall] 12-07-2021 22:16:40 Local ICMP Flood Detect has been enabled on LAN.
[INFO][Firewall] 12-07-2021 22:16:40 Local UDP Flood Detect has been enabled on LAN.
[INFO][Firewall] 12-07-2021 22:16:40 UDP Bomb Detect has been enabled.
[INFO][Firewall] 12-07-2021 22:16:40 TCP Syn With Data Detect has been enabled.
[INFO][Firewall] 12-07-2021 22:16:40 IP Broadcast Source Detect has been enabled.
[INFO][Firewall] 12-07-2021 22:16:40 IP Land Detect has been enabled.
[INFO][Firewall] 12-07-2021 22:16:40 Port Scan Per IP Flood Detect

has been enabled.

[INFO][Firewall] 12-07-2021 22:16:40 TCP FIN Per IP Flood Detect has been enabled.

[INFO][Firewall] 12-07-2021 22:16:40 TCP SYN Per IP Flood Detect has been enabled.

[INFO][Firewall] 12-07-2021 22:16:40 ICMP Per IP Flood Detect has been enabled.

[INFO][Firewall] 12-07-2021 22:16:40 UDP Per IP Flood Detect has been enabled.

[INFO][Firewall] 12-07-2021 22:16:40 IP Spoof Detect has been enabled.

[INFO][Firewall] 12-07-2021 22:16:40 Firewall Block Detect has been enabled.

[INFO][Firewall] 12-07-2021 22:16:40 Firewall Level has been set to Low.

[INFO][Firewall] 12-07-2021 22:16:40 Forward L2TP Rule has been flushed.

[INFO][Firewall] 12-07-2021 22:16:40 Forward PPTP Rule has been flushed.

[WARNING][DNS] 12-07-2021 22:16:40 ignoring nameserver 127.0.0.1 - local interface

[WARNING][DNS] 12-07-2021 22:16:40 ignoring nameserver ::1 - local interface

[INFO][DNS] 12-07-2021 22:16:40 Not a property wan_id.

[INFO][DNS] 12-07-2021 22:16:40 Not a property wan_id.

[INFO][DNS] 12-07-2021 22:16:40 Starting DNSMasq proxy server OK.

[INFO][LAN] 12-07-2021 22:16:40 Starting RADVD Server OK.

[INFO][LAN] 12-07-2021 22:16:40 LAN sending RA to ff02::1

[INFO][LAN] 12-07-2021 22:16:39 Starting DHCPV6 Server OK.

[INFO][LAN] 12-07-2021 22:16:37 Opening listen socket on 0x00000000:67 br0

[INFO][LAN] 12-07-2021 22:16:37 adapter hardware address d0:b6:6f:6d:11:0f

[INFO][LAN] 12-07-2021 22:16:37 adapter index 18

[INFO][LAN] 12-07-2021 22:16:37 br0 (our ip) = 192.168.2.1

[ERROR][LAN] 12-07-2021 22:16:37 Unable to open /var/udhcpd14.leases for reading

[INFO][LAN] 12-07-2021 22:16:37 adapter hardware address d0:b6:6f:6d:11:0f

[INFO][LAN] 12-07-2021 22:16:37 adapter index 18

[INFO][LAN] 12-07-2021 22:16:37 br0 (our ip) = 192.168.2.1

[INFO][LAN] 12-07-2021 22:16:37 Read 0 leases

[INFO][LAN] 12-07-2021 22:16:37 no_of_ifaces:2

[INFO][LAN] 12-07-2021 22:16:37 Attaching option timezone to list

[INFO][LAN] 12-07-2021 22:16:37 Attaching option t2 to list

[INFO][LAN] 12-07-2021 22:16:37 Attaching option t1 to list

[INFO][LAN] 12-07-2021 22:16:37 Attaching option lease to list

[INFO][LAN] 12-07-2021 22:16:37 Attaching option dns to existing member of list

[INFO][LAN] 12-07-2021 22:16:37 Attaching option dns to list

[INFO][LAN] 12-07-2021 22:16:37 Attaching option router to list

[INFO][LAN] 12-07-2021 22:16:37 Attaching option subnet to list

[INFO][LAN] 12-07-2021 22:16:37 Attaching option timezone to list

[INFO][LAN] 12-07-2021 22:16:37 Attaching option t2 to list

```
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option t1 to list
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option lease to list
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option dns to list
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option hostname to list
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option domain to list
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option router to list
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option subnet to list
[INFO] [LAN] 12-07-2021 22:16:37 Opening listen socket on
0x00000000:67 br1
[INFO] [LAN] 12-07-2021 22:16:37 adapter hardware address
fe:0b:48:ff:5d:62
[INFO] [LAN] 12-07-2021 22:16:37 adapter index 19
[INFO] [LAN] 12-07-2021 22:16:37 br1 (our ip) = 192.168.3.1
[INFO] [LAN] 12-07-2021 22:16:37 Read 0 leases
[INFO] [LAN] 12-07-2021 22:16:37 no_of_ifaces:1
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option timezone to list
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option t2 to list
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option t1 to list
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option lease to list
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option dns to list
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option router to list
[INFO] [LAN] 12-07-2021 22:16:37 Attaching option subnet to list
[INFO] [LAN] 12-07-2021 22:16:37 udhcp server (v0.9.7) started
[INFO] [LAN] 12-07-2021 22:16:37 udhcp server (v0.9.7) started
[INFO] [LAN] 12-07-2021 22:16:37 Starting DHCP Server OK.
[EMERG] [WAN] 12-07-2021 22:16:34 DSL link down.
[INFO] [WAN] 12-07-2021 22:16:33 Starting DSL PHY OK.
[INFO] [System] 12-07-2021 22:16:31 Starting TR069 OK.
[INFO] [System] 12-07-2021 22:16:31 Boot up successfully, duration is
21 seconds, reboot cause is PowerOff
[WARNING] [System] 12-07-2021 22:16:31 No TR069 Client Registered
```